



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Lonpac Insured's Veh No : YP5153D

Date of Accident : 18 June 2019

Mr Low Kim Seng

Date : 22 June 2019

Estimate To Repair SLD3873P - Toyota Harrier 2.0 Elegance CVT 2WD
Chassis No : ZSU600082381

LKK - Marcus

24/06/19 1100h

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	right headlamp	\$ 3,300.00
02	1 pc	front bumper	\$ 1,465.00
03	1 pc	front bumper side retainer right	\$ 120.00
04	1 pc	front bumper side absorber foam	\$ 37.00
			\$ 4,922.00
Less 30 %			\$ 1,476.60
			\$ 3,445.40
<u>LABOUR & MISC. CHARGES</u>			
01		To check electrical lighting concerned.	\$ 80.00
02		To rust-proofing of the affected areas.	\$ 80.00
03		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 400.00
04		Putty and spray painting of the affected portion.	\$ 400.00
			\$ 960.00
Total			\$ 4,405.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

NOT Affect
LKK
Zhi Hui Anthony

24/6/19