

Date of Accident : 18 June 2019



TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Date : 22 June 2019

Estimate To Repair SLD3873P - Toyota Harrier 2.0 Elegance CVT 2WD
Chassis No : ZSU600082381

29/06/190 1100h

S/No	Quantity	Description	Amount
		LIST ITEMS	
01	1 pc	right headlamp	\$ 3,300.00
02	1 pc	front bumper	\$ 1,465.00
03	1 pc	front bumper side retainer right	\$ 120.00
04	1 pc	front bumper side absorber foam	\$ 37.00
			\$ 4,922.00
		Less 30% 25%	\$ 1,476.60
			\$ 3,445.40
		LABOUR & MISC. CHARGES	
01		To check electrical lighting concerned.	\$ 80.00
02		To rust-proofing of the affected areas.	\$ 117 80.00
03		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 400.00
04		Putty and spray painting of the affected portion.	\$ 400.00
			\$ 960.00
		Total	\$ 4,405.40

NOT ATTACHED

L/L

Zhang, H. B. Attorney

2 dy.

K/S \$2800/-

24/6/19

Insurance Company is to be notified
The following conditions apply:

- To be covered after spray painting
- To be covered after (24/6/19) survey resurvey
- To be covered after (24/6/19) confirmation
- To be covered on "Without Prejudice" basis
- No legal action is allowed
- Supplies and materials must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

p- 4181
3135.75
3554.75
202

2844