

ASS. REC. BY: Hwee Jie

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OO / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC 4154C Yr Regn: 27/11/2013Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius c.c. 1798Colour: maroon A/C: Insured / Std / NI / NASp. Reading: 717128 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKN36U405725957Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Chilles

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 17/6/19 D.O.I. 21/6/19Survey held at SmtDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

	<u>06/19/2064</u>
	<u>40: 91,300 (320: 92,264.66 (3.7%))</u>
	<u>SCL 7889 H</u>
	<u>SKF 5565 S</u>

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ _____)

Survey Fee:

Transportation: _____ \$ + RS _____ \$

☐ : Interview (\$ _____)

Photos

☐ : Tech. Invs (\$ _____)

Others

☐ : Weekend (\$ _____)

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)



Case Details

Case Reference Number : TAX/06/19/2064
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHC4154C

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-7385-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 17/06/2019 12:20 AM
 Vehicle Age(In Months) : 67

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

BOM Type	Coating Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval				
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.95	Replace	DEF
One Time Key In	Main			BUMPER CLIPS	10	1.81	18.10	25.00	12.08	Replace	10	12.08	Replace	nec
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	0	0	Check	x NH
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER LH	1	139.60	139.60	25.00	104.70	Replace	0	0	Not Give	nn
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	0	0	Not Give	nn
One Time Key In	Main			ANTENNA, ELECTRICAL LOWER REAR	1	157.40	157.40	10.00	141.56	Replace	0	0	Not Give	nn
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.00	Replace	Shondal
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	nec
One Time Key In	Main			BUMPER LIP COVER RR/LH	1	72.20	72.20	25.00	54.15	Replace	0	0	Not Give	nn
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	0	0	Not Give	nn

Total Spare Part Cost 2,025.86

Surveyor Total 656.03

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 1,621.49

Final Sur Total 524.82

SMRT Recommendation											Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dia(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks	
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	0	0	Not Give *	} nn	
One Time Key In	Main			BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	25.00	71.10	Replace	0	0	Not Give *		
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	0	0	Not Give *		
One Time Key In	Main			UNDER COVER SUBASSY, RR FLOOR	1	514.50	514.50	25.00	385.88	Replace	0	0	Not Give *		
One Time Key In	Main			TAIL LAMP BRACKET, RH	1	30.70	30.70	25.00	23.02	Replace	0	0	Check *		
Total Spare Part Cost									2,026.86	Surveyor Total		656.03			
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20			
Final Spare Part Cost									1,621.49	Final Sur Total		524.82			

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	338.00	200	
Total:			338.00	200.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY BUMPER BEAM	180.00	0	
Total:			558.00	200.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
2	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20	
3	Main	TO REMOVE AND REFIT WIRE HARDESS	300.00	0	
Total:			480.00	40.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
4	Main	TO WASH AND VACUUM	60.00	0	
Total:			460.00	40.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	1,621.49	524.82
Total Labour Cost	338.00	200.00
Total Spray Painting	558.00	200.00
Other	480.00	40.00
Overall Total	2,977.49	964.82
Lump Sum Repair Option	✓	✓
Lump Sum Total	3,000.00	950.00
Surveyor Approved Amount		950.00
No of Repair Days*	3	2
Remarks	-	PS repair, photo after paint.
Surveyor Name		Hwee Jie
Signature		
Survey Date	21/06/2019	

Save

Clear

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REQUEST FOR SUPPLYMENT PARTS

WEGA ENGINEERING PTE LTD				
Contractor:				
Accident Case Number	7AX/06/19/2064		Date of Collection	21.6.19
Vehicle No	SHC 4154C		Date of Request	22.6.19
Vehicle Model	70707A PRIUS		Number of Days to Extend (if any)	1 X DAYS
S/N	Part Number	Part Description	Quantity	Unit Price
	2296,97,98,99	Bumper Reinforcement Decal		\$205.70 ✓
	2300,01,02,03 04	Arm Sub Assy LR Bumper RH		\$139.60 ✓
	2605,06,07	To Repair End Panel		\$250.00
		To Respray End Panel		\$180.00

DO \$154.28
BT \$107.70
100
100

Please submit photographs for damaged parts

I, (Name)

(Position)

Do solemnly and sincerely declare that:- Supplemental Parts are raised for replacement for the aforesaid vehicle.

Signature of person making this declaration
(To be signed in front of an authorised witness)

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff		
Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Notice
Photo Submitted	YES / NO	Date of submission

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1908-2099	Invoice Number	
Quotation Date	08.05.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$338.00	\$200.00
TO REPAIR RR END PANEL	\$250.00	\$100.00
Total Labour	\$588.00	\$300.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$100.00
Total Spray Painting & Panel Beating	\$738.00	\$300.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$20.00
TO REMOVE AND REFIT WIRE HARDESS	\$200.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$460.00	\$40.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace
		52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace
		52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Check
		52016-47030	ARM SUB-ASSY, RR BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Not Given
		52015-47050	ARM SUB-ASSY, RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Not Given
		89997-30070	ANTENNA, ELECTRICAL LOWER REAR	0.00	\$157.40	0.00	\$0.00	Replace	Not Given
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace
		76088-47020	BUMPER LIP COVER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Not Given
		76087-47020	BUMPER LIP COVER RR/RH	0.00	\$118.10	0.00	\$0.00	Replace	Not Given
		76891-47020	BUMPER LIP REAR	0.00	\$228.90	0.00	\$0.00	Replace	Not Given
		52576-47020	BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given
		52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given
		58308-47011	UNDER COVER SUBASSY, RR FLOOR	0.00	\$514.50	0.00	\$0.00	Replace	Not Given

		52562-47010	TAIL LAMP BRACKET, RH	0.00	\$30.70	0.00	\$0.00	Replace	Check	X
Total					\$2,496.51		\$656.03			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52023-12240	BUMPER REINFORCEMENT REAR	1.00	\$205.70	25.00	\$154.28	Replace	Replace
		52016-47030	ARM SUB-ASSY, RR BUMPER RH	1.00	\$139.60	25.00	\$104.70	Replace	Replace
Total					345.30		258.98		

915.01

- 202

732.01

+ 300.00

+ 340.00

1372.01

L/S \$1350/-

Section A - Accident Details

Registration Number	SHC4154C
Case Reference Number	TAX/06/19/2064
Registration Date	29/11/2013
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	RANI D/O KRISHNASAMY
Type of Accident	Others
Accident Date and Time	17/5/2019 8:20 AM
Accident Reported Date and Time	18/5/2019 9:13 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24102056
Special Instruction to ARC, if any	RIGHT REAR PORTION
Prepared Date and Time	21/5/2019 8:31 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$558.00	\$300.00
Total Spray Cost	\$738.00	\$300.00
Total Spare Part Cost	\$1,828.66	\$732.01
Total Other Cost	\$460.00	\$40.00
TOTAL COST	\$3,614.66	\$1,372.01
Lump Sum Total	\$3,600.00	\$1,360.00 (L/S)
Number of Repair Days	4.0	3.0
Prepared / Adjusted By	Tuck Foo Kok	Hwee Jie (LKK) / AIG
ARC / Surveyor Sign Off Date	21/05/2019 1:50 PM	21/05/2019 11:16 AM
Signature		
Remarks	1/5 repair, photo after paint.	

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	5369K

Vehicle Details

Vehicle No.:	SHC4154C
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Jun 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2013
Engine No.:	22R1389493
Chassis No.:	JTDKN36U405705957
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$33,120.00
Original Registration Date:	29 Nov 2013
First Registration Date:	29 Nov 2013
Transfer Count:	0
Actual ARF Paid:	\$8,368.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Nov 2021
PARF Rebate Amount:	\$5,857.00

Intended COE Rebate Details

COE Expiry Date:	28 Nov 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$63,297.00
COE Rebate Amount:	\$19,208.00
Total Rebate Amount:	\$25,065.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 24 Jun 2019

OK

Asher Sng (LKKAuto)

From: Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis) <LeeGek@smrt.com.sg>
Sent: Monday, 2 September 2019 11:44 AM
To: CS A Team; Admin A
Subject: LOD Re: Accident on 17/6/2019 involving SHC 4154C & SKF 5565S (AIG's insured)
Our Ref: TAX/06/19/2064/lg
Attachments: TAX 06 19 2064.pdf

Dear All,

We quantify our claim as follows:-

Cost of Repair	\$1350.00
Loss of Rental	\$471.87 (4.5 days x \$104.86)
Loss of Income	\$270.00 (4.5 day x \$60.00)
LTA Search Fee	\$7.00
Total	\$2098.87

We enclose the following documents:

- 1) Repair invoice
- 2) Proof of rental rate
- 3) GIA report
- 4) Accident vehicle laid-up report
- 5) LTA search

Please let us have your offer soon. Thanks.

Regards

Tan Lee Gek (DID: 6866 2647)

Claims Department

SMRT Automotive Services Pte Ltd





Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC3/AIG19011100/Jea3

12 JUL 2019

MESENAS STEVEN JOSEPH
72 FARRER RD
#02-02
SINGAPORE 268851

Dear Sir/Madam,

ACCIDENT INVOLVING SKF 5565S AND SHC 4154C ON 17/06/2019

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Asher
Case Handler
DID: 6841 6051
FAX: 6741 4108
Email: Ashersng@lkkauto.com

c.c. *AIG Asia Pacific Insurance Pte Ltd*
(Motor Claims Dept)

AUTHORIZATION TO ACT
(AIG Asia Pacific - Express Third Party Claim)

I, SMRT TAXIS PTE LTD (the third party claimant") of 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705 (address), owner of SHC 4154C (vehicle no.) hereby authorize SMRT AUTOMOTIVE SERVICES PTE LTD ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no SHC 4154C that was damaged pursuant to the accident which occurred on 17/06/2019 (date) along FARRER ROAD (GALLOP GABLES) (location) involving vehicle no/s SKF 5565S ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of SMRT TAXIS PTE LTD.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 2 (day) of October (month) 2019 (year)



Signed by "the third party claimant"
(with chop if applicable)



Signed by "the workshop"
(with chop)

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, SMRT AUTOMOTIVE SERVICES PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$2,050.00 (Global Sum) for vehicle no. SHC 4154C that was damaged pursuant to the accident which occurred on 17/06/2019 (date) along FARRER ROAD (GALLOP GABLES) involving vehicle no/s SKF 5565S.

This is pursuant to the inspection conducted on 21/06/2019 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner SMRT TAXIS PTE LTD ("the third party claimant") of vehicle no. SHC 4154C make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SHC 4154C (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 2 (day) of October (month) 2019 (year)



OHJ

Signed by appointed surveyor



Signed by "the workshop" (with chop)

*** This Discharge Voucher applies only to the claimant's claim or his property damage and will not affect his personal injuries claim and/or uninsured losses claim in a later date. Further, the settlement terms herein should not be used as an evidence to prejudice to the claimant's personal injuries claim and/or other uninsured losses claim arising of the subject matter in this action.



SMRT Automotive Services Pte Ltd
251 North Bridge Road Singapore 179102
Tel: 65 63311000 Fax: 65 63340247

Tax Invoice

GST Reg No. : MR-8500001-7
CRN : 199004280Z
Invoice No. : IV190800310
Date : 20.08.2019
Vehicle No. : SHC4154C
Your Ref No. : TAX/06/19/2064
Our Ref No. : 24102056
Terms : 30 Days

Customer Code: 3000063

SMRT TAXIS PTE LTD

Block Unit

60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705



Description	Qty	Unit Cost	Add / (Discount) Amount	Amount
LUMP SUM AMOUNT FOR REPAIR AS PER SURVEYOR'S RECOMMENDATION	1.00			\$ 1,350.00
GRAND TOTAL				\$ 1,350.00

Remark :

Make/Model : TOYOTA PRIUS
Accident Date : 17.06.2019

N.B. Payment by cheque should be crossed and
made payable to 'SMRT Automotive Services Pte Ltd'.
No receipt will be issued unless requested.

Authorised Signature
for SMRT Automotive Services Pte Ltd



SMRT Taxis Pte Ltd

MEMORANDUM

To: Claims Dept

Our Ref: TAX/06/19/2064

From: SMRT Taxis Pte Ltd

Date: 25/6/2019

**ACCIDENT INVOLVING SHC4154C AND SKF5565S ON 17/6/2019
8:20 AM ALONG FARRER ROAD (GALLOP GABLES).**

This is to confirm that the daily rental rate for SHC4154C is \$104.86 per day.

Please proceed to recover any rental loss from the third party as a result of the above accident.

Thank you.

Yours sincerely
SMRT TAXIS PTE LTD



for Manager



Laid Up Report

Accident Start Date : 17/06/2019

Accident End Date : 18/07/2019

Date Generated : 18/07/2019

User Name : LeeGek

Case Reference Number	Vehicle Registration Number	Company Type	Vehicle Make	Vehicle Model	Job Card Number	Date and Time (Accident Repair)	Date and Time (Repair Completed)
TAX006/18/2014	SHC4154C	SMRT Taxis Pte Ltd	TOYOTA	PRIUS	24102056	20/06/2019 10:55 AM	24/06/2019 4:12 PM

Enquire Transaction History

Log Date/Time:	19 Jun 2019 / 09:32:29	Transaction Amount:	\$7.49
Asset Type:	Vehicle		
Asset ID:	SKF55655	Channel:	External Agency
Transaction Type:	18.32 Insurance Enquiry (GIRQ Payment)	Business Transaction Reference No.:	20190619095229147501
User ID:	ESASRAHO - BALQISH BINTE ABDUL HALIL		

Search Date / Time: 17 Jun 2019 09:13:00 /
 Insurance Company: AUG-ASIA PACIFIC INSURANCE PTE. LTD.
 Information displayed is correct as at the log date and time.

[Enquire Related Logs](#)

[Back to List](#)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Jun 2019 Edit Reg		21 Jun 2019 00:00 Edit Adj Rpt	S\$1,350.00 Edit Estimates	S\$1,350.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	MESENAS STEVEN JOSEPH, ID: S1746439F, Tel: +6599999999								
Main Claimant:	SMRT TAXIS PTE LTD, Co. Reg. No.: 198905369K								
Vehicle Reg. No.:	SHC4154C	Date of Loss:	17/06/2019 08:00 - :59 [66 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 2471278248SG	Policy/Cover Note No.:	1800148828 (Comprehensive) Coverage: 14/12/2018 - 13/12/2019						
Vehicle Reg. No. (Insured):	SKF5565S	Policy No. (Claimant):	D-19093197MFSH						
		Excess:							
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com								
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Final Rpt due 03/07/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (04/07/2019): AIGENCRYPT [EXTERNAL] Re: No Policy Found - AIG_SG (25/06/2019): No Policy Found									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHC4154C (2471278248SG)
[SKF5565S]
TP
SMRT TAXIS PTE LTD
Jun 17 2019 8:00AM
[MESENAS STEVEN JOSEPH]
SMRT Automotive Services Pte Ltd

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View	View in Browser
------------------	---------------	--------------------	--------------	--------------	------	-----------------

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	1	Edit	

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	19/08/19 19:22	Odometer Reading	1	Load JPG	☒
2	19/08/19 19:22	Chassis Number	1	Load JPG	☒
3	19/08/19 19:22	General View	1	Load JPG	☒
4	19/08/19 19:22	General View	1	Load JPG	☒
5	19/08/19 19:22	General View	1	Load JPG	☒
6	19/08/19 19:22	General View	1	Load JPG	☒
7	19/08/19 19:22	General View	1	Load JPG	☒
8	19/08/19 19:22	General View	1	Load JPG	☒
9	19/08/19 19:22	General View	1	Load JPG	☒
10	19/08/19 19:22	General View	1	Load JPG	☒
11	19/08/19 19:22	General View	1	Load JPG	☒
12	19/08/19 19:22	General View	1	Load JPG	☒
13	19/08/19 19:22	General View	1	Load JPG	☒
14	19/08/19 19:23	General View	1	Load JPG	☒
15	19/08/19 19:23	General View	1	Load JPG	☒
16	19/08/19 19:23	General View	1	Load JPG	☒
17	19/08/19 19:23	General View	1	Load JPG	☒
18	19/08/19 19:23	Photographs of Damaged Items	1	Load JPG	☒
19	19/08/19 19:23	Photographs of Damaged Items	1	Load JPG	☒
20	19/08/19 19:23	Photographs of Damaged Items	1	Load JPG	☒
21	19/08/19 19:23	Photographs of Damaged Items	1	Load JPG	☒
22	19/08/19 19:23	Photographs of Damaged Items	1	Load JPG	☒
23	19/08/19 19:23	Photographs of Damaged Items	1	Load JPG	☒
24	19/08/19 19:23	Photographs of Damaged Items	1	Load JPG	☒
25	19/08/19 19:23	Photographs of Damaged Items	1	Load JPG	☒
26	19/08/19 19:23	Photographs of Damaged Items	1	Load JPG	☒
27	19/08/19 19:23	Photographs of Damaged Items	1	Load JPG	☒
28	19/08/19 19:23	Photographs of Damaged Items	1	Load JPG	☒
29	19/08/19 19:23	Photographs of Damaged Items	1	Load JPG	☒
30	19/08/19 19:23	After Repair Photo	1	Load JPG	☒
31	19/08/19 19:23	After Repair Photo	1	Load JPG	☒
32	19/08/19 19:23	After Repair Photo	1	Load JPG	☒

Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	25/06/19 09:54	TP ESTIMATE - MARKED	1	Load PDF	
2	25/06/19 09:54	TP GIA REPORT	1	Load PDF	
3	04/07/19 09:49	LTA search	1	Load PDF	
4	04/07/19 09:49	TP GIA REPORT - AMENDED	1	Load PDF	
5	12/07/19 12:27	LETTER TO OI	1	Load PDF	
6	16/10/19 09:33	WORKSHOP INVOICE	1	Load PDF	

Letters/Correspondences					1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
7	16/10/19 09:33	AUTHORISATION TO ACT FORM		Load PDF		
8	16/10/19 09:33	Release Voucher		Load PDF		
9	16/10/19 09:33	RENTAL RECEIPT		Load PDF		
10	16/10/19 09:33	RENTAL MILEAGE		Load PDF		
11	16/10/19 09:33	LOD		Load PDF		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print	
1	04/07/19 16:27	OI GIA REPORT		Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKF5565S (Insd veh)	Model:	TOYOTA PRIUS TAXI 1.8 (A)
	SHC4154C (TP veh)		
Date of Accident:	17/06/2019		

Global Sum Settlement	[X] Yes	[] No
Repair Estimate	\$	4,702.30
Final Repair Cost	\$	2,050.00
Loss of Use	\$	4.50 days at \$50.00 per day
Rental (if any)	\$	4.50 days
LTA / GIA Search Fee	\$	
Others:	\$	
	\$	
Final Settlement Sum (Global Sum)	\$	2,050.00

Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	SMRT Taxis Pte Ltd	\$	2,050.00
2)		\$	
3)		\$	
4)		\$	

JOANNE LEE KHANG MIN

16 Oct
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19011100/JEA3Q2

Date: 16/10/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800148828
 Claimant SHC4154C Insured Vehicle No : SKF5565S
 Vehicle No : SHC4154C
 Date of Loss: 17/06/2019 Nature of Claim: TP Claim No: 2471278248SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC4154C
 Make & Model: TOYOTA PRIUS TAXI, 1.8 (A) Engine No: 2ZR1389493
 Reg. Date: 29/11/2013 (Man. Year: 2013) Chassis No: JTDKN36U405705957
 Colour: Maroon Odometer: 717128 km
 Engine Capacity: 1798 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Chilles 6 mm Rear Left Side: Chilles 6 mm
 Front Right Side: Chilles 6 mm Rear Right Side: Chilles 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,916.30	915.01	2,001.29	68.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,786.00	640.00	1,146.00	64.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,702.30	1,555.01	3,147.29	66.93
Approved Total (Overridden) (S\$)		1,350.00		
Nett Amount (S\$)	4,702.30	1,350.00	3,352.30	71.29
+ Loss of Use (4.5 x S\$50.00/day) (S\$)		225.00		
+ Car Rental (4.5 x S\$104.86/day) (S\$)		471.87		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		2,053.87		
Global Sum Settlement (S\$)		2,050.00		

INSPECTION

Date of Assignment: 21/06/2019
 Date Inspected: 21/06/2019 Inspected At: SMRT Automotive Services Pte Ltd (Woodlands)
 60 Woodlands Industrial Park E4
 Singapore 757705

Estimated Period of Repair: 2.0 days

Adjuster: ONG HWEE JIE**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER REAR (DISC 25%)	Deformed	458.60 F	*343.95 F
2	1		*BUMPER CLIPS (DISC 25%) (10 PCS)	Necessary	16.10 F	*12.08 F
3	1		*BUMPER REINFORCEMENT REAR (DISC 25%)	Dented	205.70 F	*154.28 F
4	1		*ARM SUB-ASSY ,RR BUMPER RH (DISC 25%)	Bent	139.60 F	*104.70 F
5	1		*SENSOR REVERSE (SN)	Shorted	180.00 F	*180.00 F
6	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
7	1		*BUMPER REINFORCEMENT REAR	Not Necessary	205.70 F	*- F
8	1		*ARM SUB-ASSY ,RR BUMPER LH	Not Necessary	139.60 F	*- F
9	1		*ARM SUB-ASSY ,RR BUMPER RH	Not Necessary	139.60 F	*- F
10	1		*ANTENNA ,ELECTRICAL LOWER REAR	Not Necessary	157.40 F	*- F
11	1		*BUMPER LIP COVER RR/LH	Not Necessary	72.20 F	*- F
12	1		*BUMPER LIP COVER RR/RH	Not Necessary	118.10 F	*- F
13	1		*BUMPER LIP REAR	Not Necessary	228.90 F	*- F
14	1		*BUMPER SIDE RETAINER RR/LH	Not Necessary	94.80 F	*- F
15	1		*BUMPER SIDE RETAINER RR/RH	Not Necessary	94.80 F	*- F
16	1		*UNDER COVER SUBASSY ,RR FLOOR	Not Necessary	514.50 F	*- F
17	1		*TAIL LAMP BRACKET ,RH	Not Necessary	30.70 F	*- F
				Total Parts (S\$)	2,916.30	915.01

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	588.00	300.00
2	SPRAY PAINT	New	738.00	300.00
3	TO CHECL WIRING AND SYSTEM FUNCTION	New	80.00	20.00
4	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	20.00
5	TO REMOVE AND REFIT WIRE HARNESS	New	200.00	0.00
6	TO WASH AND VACUUM	New	60.00	0.00
Gross Labour Cost (S\$)			1,786.00	640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >