



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD

INV No. AC2100479

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX
SINGAPORE 069110

INV Date 22/01/2021
Reference CC4/EQI19011116/T1pa3q2
Code EQI

PROFESSIONAL SERVICE FEE

Vehicle No. SLN 7956E
Insured Veh. GBA 9374H
Claim No. DM19HO01757-JG
Policy No. DMPCHQ18-005852
Accident Date 20/06/2019
Inspection Date 26/06/2019

Description	Total
Survey Inspection	300.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	300.00
GST (7%)	21.00
Grand Total	321.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD 5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Ref: CC4/EQI19011116/T1pa3q2 Date: 22/01/2021 Code: EQI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBA 9374H	Veh. Inspected	SLN 7956E	
Policy No.	DMPCHQ18-005852	Coverage (\$)	0.00	
Claim No.	DM19HO01757-JG	Excess (\$)	0.00	
Assign From	JOEL GOH	Assign Date	24/06/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDKB3FU003558489	Colour	SILVER	
Odometer	120753 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	PIRELLI	6 mm	
L/H Front Tyre	195/65 R15	PIRELLI	6 mm	
R/H Rear Tyre	195/65 R15	PIRELLI	6 mm	
L/H Rear Tyre	195/65 R15	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/06/2019	Inspection Date	26/06/2019	
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			9 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 7956E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SUNDRIES (SN)	NECESSARY	100.00	50.00
2	SETS SEALANT (SN)	NECESSARY	200.00	200.00
1	REINFORCEMENT (SN)	BENT	332.70	332.70
1	COVER ,RR BUMPER (SN)	DEFORMED	442.60	442.60
1	RETAINER ,RR BUMPER (SN)	NECESSARY	116.50	116.50
1	RETAINER ,RR BUMPER (SN)	SERVICEABLE	117.70	-
1	FILLER ,RR BUMPER (SN)	DEFORMED	123.70	123.70
1	FILLER ,RR BUMPER (SN)	DEFORMED	123.70	123.70
1	GUARD ,RR BUMPER (SN)	DEFORMED	576.30	576.30
10	PIECE ,RR BUMPER (SN)	NECESSARY	41.00	41.00
1	PANEL SUB-ASSY ,BODY (SN)	BENT	650.30	650.30
1	PANEL SUB-ASSY ,BACK (SN)	BENT	1,147.80	1,147.80
1	GLASS SUB-ASSY ,BACK (SN)	NOT NECESSARY	1,624.20	-
1	GLASS SUB-ASSY ,BACK (SN)	NOT NECESSARY	746.50	-
1	DAM,WINDOW GLASS (SN)	NECESSARY	28.90	28.90
3	SIKA 182010 SIKA TACK GOI (BLA) (SN)	NECESSARY	324.00	324.00
2	SIKA 207. G+P ADHESIVE PRIMER (SN)	NECESSARY	400.00	400.00
1	BACK SENSOR SILVER METALLIC 1F (SN)	NOT WORKING	169.60	169.60
1	COVER ,RR BUMPER (SN)	DEFORMED	15.40	15.40
1	GARNISH SUB-ASSY (SN)	CRACKED	925.60	925.60
1	PLATE ,LUGGAGE (SN)	NECESSARY	47.90	47.90
1	PLATE ,LUGGAGE COMPT (SN)	NECESSARY	54.60	54.60
1	PLATE ,LUGGAGE COMPT (SN)	NECESSARY	54.60	54.60
1	LENS & BODY ,RR (SN)	NOT NECESSARY	451.80	-
1	LENS & BODY ,RR (SN)	NOT NECESSARY	443.30	-
1	COVER ,DECK TRIM ,RR (SN)	NOT NECESSARY	126.70	-
1	BOX ,DECK FLOOR ,RR (SN)	NOT NECESSARY	105.80	-
1	BOX ,DECK FLOOR ,LH (SN)	NOT NECESSARY	313.00	-
1	BOX ,DECK FLOOR ,RH (SN)	NOT NECESSARY	313.60	-
1	LOCK ASSY ,BACK DOOR (SN)	BENT	467.00	467.00
1	COVER ,RR BODY (SN) (ADDITIONAL)	DEFORMED	229.90	229.90

Report Ref No. CC4/EQ19011116/T1pa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	COVER ,FLOOR UNDER (SN) (ADDITIONAL)	DEFORMED	241.90	241.90
1	MOULDING BACK DOOR (SN) (ADDITIONAL)	DEFORMED	30.70	30.70
			11,087.30	6,794.70
	LABOUR			
	TOWING CHARGES.		180.00	180.00
	CHK REAR WIRING SYSTEM AND CONDCUT WATER TEST.		180.00	180.00
	DRILL HOLE TO INSTALL REVERSE SENSOR .		180.00	180.00
	REMOVE BOOT INTERIOR TO ASSIST REPAIR.		360.00	360.00
	REMOVE TAIL GTAE COMPONENTS TO TRANSFER ONTO NEW DOOR .		360.00	360.00
	REPLACE REAR W/SCREEN GLASS TO ASSIST REPAIR .		450.00	450.00
	REPLACE TAIL-GATE RECTANGLE GLASS TO ASSIST REPAIR.		270.00	270.00
	REMOVE ALL NECESSARY DAMAGED PARTS TO REPLACE ,REPAIR ,STRAIGHTEN REAR BUMPER ,TAIL-GATE ,TAIL-LAMP PANEL AND AFFECTED PORTION OF CAR.		4,320.00	2,880.00
	SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.		3,540.00	2,360.00
			9,840.00	7,220.00
GRAND TOTAL			20,927.30	14,014.70
RECOMMENDED COST OF REPAIRS				14,014.70

Report Ref No. CC4/EQI19011116/T1pa3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLN 7956E

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLN 7956E

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

