



Borneo Motors (Singapore) Pte Ltd

Online Service Booking :  
www.toyota.com.sgToyota Bodycare Centre  
No. 2 Pandan Crescent  
Singapore 128462  
Tel no.: 6631 1188  
Customer DetailReg No : 196700086Z  
T Reg No : MR-8500000-9

## ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account &amp; more!


Account Detail	Account No	M/S Grab Rentals Pte Ltd 6 Shenton Way #38-01 Oue Downtown Singapore 068809 Work: 65703925
THIRD PARTY CLAIM	S1000020 / TPCLAIM	
	Document No	
	Document Date	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	AHXBW	Q3	18/05/2017	SLN7956E	0	46146	65DS/SLN7956E
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		

MTDKB3FU003558489	2ZRS047355	60	Francis Cher T S	--/--/----	0.00	--/--/----	0.00
-------------------	------------	----	------------------	------------	------	------------	------

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-GRAB SUNDRIES - FLASH ARRIVE: 21/06/19 1.30PM				50. 100.00
2	Z	BP-SUNDRY SUNDRIES				
		T/P INS. :				
		T/P VEH : 6BA 9374H				
		ACC DATE : 21.06.19				
		BY :				
3	Z	TW TOWING CHARGES				✓ 180.00
4	Z	BP-SLANT SUPPLY SEALANT (NETT)				✓ 200.00
		(2 sets)				
5	B	BP-LAB2 CHK REAR WIRING SYSTEM AND CONDUCT				✓ 180.00
		WATER TEST.				
6	B	BP-LAB2 DRILL HOLE TO INSTALL REVERSE SENSOR.				✓ 180.00
7	B	BP-LAB2 REMOVE BOOT INTERIOR TO ASSIST REPAIR.				✓ 360.00
8	B	BP-LAB2 REMOVE TAIL GTAE COMPONENTS TO				✓ 360.00
		TRANSFER ONTO NEW DOOR.				
9	B	BP-LAB2 REPLACE REAR W/SCREEN GLASS				✓ 450.00
		TO ASSIST REPAIR.				
10	B	BP-LAB2 REPLACE TAIL-GATE RECTANGLE GLASS				✓ 270.00
		TO ASSIST REPAIR.				

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	Tan Guan 174954951
	<div data-bbox="550 1556 1061 1960" data-label="Text"> <p><b>LKK Auto Consultants hence notify the Repairer of the following:</b></p> <ul style="list-style-type: none"> <li>To resurvey before/after spray painting</li> <li>To display damaged part(s) during resurvey</li> <li>Parts prices are subject to confirmation</li> <li>Third party survey is on a "Without Prejudice" basis</li> <li>No illegal modification(s) is allowed</li> <li>Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> </div>	Labour	Ready before paint.
		Materials	09 days
			Amount Due

3938740

3938740

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED  
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO

SLN7956E

CUSTOMER

SIGNATURE  
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Inchcape

Borneo Motor



Borneo Motors (Singapore) Pte Ltd

Online Service Booking:  
www.toyota.com.sgToyota Bodycare Centre  
No. 2 Pandan Crescent  
Singapore 128462  
Tel no.: 6631 1188o Reg No : 196700086Z  
ST Reg No : MR-8500000-9

## ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account &amp; more!

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM	S1000020 / TPCLAIM	M/S Grab Rentals Pte Ltd 6 Shenton Way #38-01 Oue Downtown Singapore 068809  Work: 65703925
	Document No	
	Document Date	
	0	
	24/06/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	AHXEBW	Q3	18/05/2017	SLN7956E	0	46146	65DS/SLN7956E
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		

JTDKB3FU003558489 2ZRS047355 60 Francis Cher T S --/--/---- 0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
11	B	BP-LAB2 REMOVE ALL NECESSARY DAMAGED PARTS <i>2w</i> TO REPLACE, REPAIR, STRAIGHTEN REAR BUMPER, TAIL-GATE, TAIL-LAMP PANEL AND AFFECTED PORTION OF CAR.				2830 4320.00
12	B	BP-RES2 SPRAY PAINT ON DAMAGED AFFECTED <i>590</i> PORTION OF CAR.				2360 3540.00
13	1	T52023-47030 REINFORCEMENT	1.00	332.70		bt ✓ 332.70
14	2	T52159-47913 COVER, RR BUMPER	1.00	442.60		de ✓ 442.60
15	3	T52576-47040 RETAINER, RR BUMPER	1.00	116.50		ne ✓ 116.50
16	4	T52575-47040 RETAINER, RR BUMPER	1.00	117.70		XSV ✓ 117.70
17	5	T52566-47900 FILLER, RR BUMPER	1.00	123.70		de ✓ 123.70
18	6	T52565-47900 FILLER, RR BUMPER	1.00	123.70		de ✓ 123.70
19	7	T52453-47010 GUARD, RR BUMPER,	1.00	576.30		de ✓ 576.30
20	8	S52161-OK040 PIECE, RR BUMPER	10.00	4.10		ne ✓ 41.00
21	9	T58307-47090 PANEL SUB-ASSY, BODY	1.00	650.30		bt ✓ 650.30
22	0	T67005-47540 PANEL SUB-ASSY, BACK <i>tailgate</i>	1.00	1147.80		bt ✓ 1147.80
23	1	T68105-47291 GLASS SUB-ASSY, BACK	1.00	1624.20		an x 1624.20
24	2	T64801-47031 GLASS SUB-ASSY, BACK	1.00	746.50		an x 746.50
25	3	L56117-50140 DAM, WINDOW GLASS	1.00	28.90		ne ✓ 28.90
26	4	T21000-20 SIKA 182010 SIKA TACK GO! (BLA	3.00	108.00		ne ✓ 324.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Materials	
		Lubrication/Fluid	Amount Due
		Others	

PLEASE TEAR ALONG PERFORATED LINE

3938741

O SECURITY GUARD

3938741

PLEASE ALLOW THE UNDERMENTIONED  
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 24/06/2019  
TIME 12:32

VEHICLE NO

SLN7956E

CUSTOMER

SIGNATURE  
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Inchcape

Borneo Motors

Toyota Bodycare Centre  
No. 2 Pandan Crescent  
Singapore 128462  
Tel no.: 6631 1188o Reg No : 196700086Z  
ST Reg No : MR-8500000-9

## ESTIMATE


Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account &amp; more!

Account Detail		Account No	Customer Detail	
THIRD PARTY CLAIM		S1000020 / TPCLAIM	M/S Grab Rentals Pte Ltd 6 Shenton Way #38-01 Oue Downtown Singapore 068809  Work: 65703925	
		Document No		
		Document Date		
		0		
		24/06/2019		

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	AHXEBW	Q3	18/05/2017	SLN7956E	0	46146	65DS/SLN7956E
Chassis No		Engine No	Terms	Service Engineer	Vehicle In	Collected On	

JTDKB3FU003558489 2ZRS047355 60 Francis Cher T S --/--/---- 0.00 --/--/---- 0.00

L	Cd	Job/Parts Description		Qty	Unit Price	Disc %	Amount
27	5	T21000-22	SIKA 207. G+P ADHESIVE PRIMER	2.00	200.00		400.00
28	6	SPC507-47001 23	BACK SENSOR SILVER METALLIC 1F	1.00	169.60		169.60
29	7	T52169-47020	COVER, RR BUMPER,	1.00	15.40		15.40
30	8	T76801-47110 B0	GARNISH SUB-ASSY,	1.00	925.60		925.60
31	9	T75403-48010	PLATE, LUGGAGE	1.00	47.90		47.90
32	0	T75441-47130	PLATE, LUGGAGE COMPT	1.00	54.60		54.60
33	1	T75442-47130	PLATE, LUGGAGE COMPT	1.00	54.60		54.60
34	2	T81551-47283	LENS & BODY, RR	1.00	451.80		451.80
35	3	T81561-47153	LENS & BODY, RR	1.00	443.30		443.30
36	4	T64716-47130 C0	COVER, DECK TRIM, RR	1.00	126.70		126.70
37	5	T64993-47110	BOX, DECK FLOOR, RR	1.00	105.80		105.80
38	6	T64997-47060	BOX, DECK FLOOR, LH	1.00	313.00		313.00
39	7	T64995-47050	BOX, DECK FLOOR, RH	1.00	313.60		313.60
40	8	T69350-47050	LOCK ASSY, BACK DOOR	1.00	467.00		467.00
*Supplementary Parts							
		T66259-47010	COVER, RR BODY	1.00	229.90		229.90
		T58399-47030	COVER, FLOOR UNDER,	1.00	241.90		241.90
		T75571-47011	MOULDING, BACK DOOR	1.00	30.70		30.70
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.							

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	20,424.80
		Labour 10,284.80	GST 7.00% 1,429.74
		Materials 10,140.00	Less 0.00
		Lubrication/Fluid 0.00	
		Others 0.00	
		0.00	Amount Due 21,854.54

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED  
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 24/06/2019  
TIME 12:32

VEHICLE NO

SLN7956E

CUSTOMER

SIGNATURE  
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Inchcape

Borneo Motors