

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
LAI KIT LOONG (LI JIELONG)	Cust No/Name	KCV11339/LAI KIT LOONG (LI JIELONG)
25 MILTONIA CLOSE	Reg No/Reg Date	SFW1126Y / 22/05/201
#11-12	Date In/Mileage	/ 0
SINGAPORE 768060	Chassis No	MMBSTA13AKH001846
Contact No	Engine No	3A92UHT1685
	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	W05 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KCV11339	CRDVCH	18/06/2019/ 16:07		465 / Tay Jian Ye	41185			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								1100.00
TO RENEW FRT BUMPER, AND RENEW FRT RADIATOR								
E PNT98000								840.00
PAINT WORK SPRAY FRT BUMPER								
A 54900099								50.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								
A 10028901								200.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
M SUNDRY								50.00
TO RENEW FRT NUMBER PLATE								
M SUNDRY								50.00
SUNDRIES								
M GRILLE,RADIATOR					1.00	548.00	00.00	548.00
M MARK,THREE-DIA					1.00	51.00	00.00	51.00
M REINFORCEMENT,FR BUMPER					1.00	462.00	00.00	462.00
M FACE,FR BUMPER					1.00	696.00	00.00	696.00
P CLIP,FR BUMPER					10.00	3.00	00.00	30.00
M HEADLAMP ASSY,LH					1.00	654.00	00.00	654.00
M HEADLAMP ASSY,RH					1.00	654.00	00.00	654.00
SURVEYOR NAME : _____								
SURVEYOR SIGNATURE : _____								
DATE : _____								
REMARKS : _____								

Confirm & accepted by

	Nett	5,385.00
7% GST on	5385.00	376.95
Total Payable		5,761.95

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.