

22/03/2002

ASS. REC. BY:

REF: CS/SMO1911137/T1Vd302

Special Instruction:

Surveyor: Tan Aih

**ASSIGNMENT (Office)**

From (Person): Hwang Shiang Yi

of SMO

Date/Time: 25.6.19 8.51 a.m

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SJJ 1974L

Insured: SFM 5319J

at Workshop m/s Fixmate Auto

Tel: 82632225

of 8 Kaki Bukit Ave 4 #02-37

Policy No: D19MTPV01001187

Claim No: CMTD1903008

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 22.6.19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 25.6.19 9.11 a.m

Person Contacted: Ah Chai

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SFM 5319J: CC4/AIG16018037/Kyb392 D.O.A: 21/09/2016
	SJJ 1974L: ✓
26/6/19	Informed Shiang Yi pending workshop est by merimen
15/8/19	@ 4.51pm LS \$3800 confirmed with Ah Chai (Ref 10,565.92, 7490)
15/8/19	Send preli revised via merimen

Tanjiluh

REF:

SMD

ASSIGNMENT

WE 2028 Aug  
2008 Sep

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / CVA / INV / MV: \_\_\_\_\_

To inspect Vehicle No: \_\_\_\_\_

at Work/Shop no/s: \_\_\_\_\_

of: \_\_\_\_\_

Incured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Incured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record): \_\_\_\_\_

Make of Veh: \_\_\_\_\_

(Policy Condition): \_\_\_\_\_

Remark: The veh had commenced its repair at the time of inspection.

Val. of Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? Yes or No

GIA / PR Score: \_\_\_\_\_ Consistent? Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lump Sum: \_\_\_\_\_ % 3Val: Yes or No

CA / REV / REP. / 24 HRS: \_\_\_\_\_

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

NE	OS
X	

Veh No: **SJJ1974L** in Resp: \_\_\_\_\_

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Honda Spear** or **1799**

Colour: **Blue** or **251255** A/C: Incured / Std / Nil / NA

Sp/Reading: **251255** T/Rdies: Incured / Std / Nil / NA

Eng/No: **JHMRN 684085205298**

G/No: \_\_\_\_\_

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / A/Rim / STD A/Rim or

Tyre Size: **205/45R17**

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

YOYO YORO or

Front: \_\_\_\_\_ Rear: **6** mm

R/Ral: **6** mm R/Ral: **6** mm

L/Ral: **6** mm L/Ral: **6** mm

D.O.A: \_\_\_\_\_ D.O.I: **25/4/19R 530pm**

Survey held at: **Fixmate Auto #02457**

Des. of Damages: Frl / Rear / O/S / H/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 16 AUG 2019

Date/Time, File Pass to? ☐ : Proft. Report

1) ☐ : Final Report

Days Of Repair: **5**

Resurvey No. of Trip: **2**

Survey Fee: **350**

Transportation: **11**

Other: **361**

Report Format: **Merimen**

Lump Sum / L.B.E: **38001/2**

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Inv (\$)

☐ Weekend (\$)

15/8 - typist

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Jun 2019		25 Jun 2019 08:51 Assign				<b>New Assignment</b> Cancel Case

  

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

  

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	TAN KEE SENG, ID: S0095894H	
Main Claimant:	YONG FONG LING, ID: S1682308B	
Vehicle Reg. No.:	SJJ1974L	Date of Loss: 22/06/2019 19:00 - :59
Claim Type:	TP / CMTD1903008	Policy/Cover Note No.: D19MTPV01001187 (Comprehensive)
Vehicle Reg. No. (Insured):	SFM5319J	Policy No. (Claimant):
		Excess:
Repairer:	Fixmate Auto Pte Ltd - Kaki Bukit (HQ) 8 KAKI BUKIT AVENUE 4, #02-37 PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel:	
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang Yi - 6329 5205]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 04/07/2019]	
Adj Asg. Remarks:	WS: 82632225 AH CHAI -PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT - NO TP SAS SUBMITTED	

  

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

  

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sompoo Insurance Singapore Pte. Ltd.  
50 Raffles Place  
#05-01/06, Singapore Land Tower  
Singapore 048623

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Hwang Shiang Yi

Date: 15 Aug 2019

**Preliminary Advice**

Insured Vehicle No : SFM5319J

TP Vehicle No : SJJ1974L

Make : HONDA STREAM

Date of Inspection : 25/6/2019

Inspection At : FIXMATE PTE LTD

Accident Date : 22/06/2019

Assignment Date : 25/06/2019

Est. Duration of Repair : 5

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,365.92
Revised Amount	:S\$	3,800.00 (LUMP SUM)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,800.00

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

**Remarks**

( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( X ) Other comments :The above survey was conducted on a 'Without Prejudice' basis.

## View Sent Message

This mail is associated with :

**\*SJJ1974L (CMTD1903008)**

**[SFM5319J]**

TP

YONG FONG LING

Jun 22 2019 7:00PM

[TAN KEE SENG]

Fixmate Auto Pte Ltd - Kaki Bukit

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

**From** LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on **26/06/2019 12:11 PM.**

**To** shiangyi.hwang@sompo.com.sg

**Subject** TP SRUVEY SJJ 1974L

Dear Shiang Yi,

Please be informed that we have inspected the vehicle SJJ 1974L on 25/6/2019.

We are pending estimate from repairer.

Best Regards,

Veron Chen

### DOCUMENTS SUMMARY

There are no documents.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid

### ACCIDENT STATEMENT

Date Of Report	24/06/2019 13:13
Date Of Accident	22/06/2019 19:00
Exact Location Of Accident	VICTORIA STREET
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJJ1974L
<b>Insured/Policyholder</b>	
Name Of Registered Owner	YONG FONG LING
NRIC No	S1682308B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98267033
Alternative Phone No	OTHERS-98267033

### Vehicle Particulars

Manufacturer	HONDA
Model	STREAM 1.8L A

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5097670404-01
Cover Note Number	

### Driver

Name of Driver	YONG TECK YEONG
NRIC No	S7210624E
Date Of Birth	24/03/1972
Occupation	OUTDOOR
Date Of Driving Pass	11/08/1992
Driving Experience	26 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92312633
Fax Number	
Contact Number	
Email Address	TECKYEONG9372@GMAIL.COM

Address	BLK 115 JURONG EAST STREET 13 #09-372
Postcode	600115
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SIBLING
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	AFTER RAIN
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : GRAB PASSENGER
	GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	JURONG WEST NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 700 CORPORATION ROAD , POSTCODE: 649818 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2689999 - FAX NO: 62672438
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

AS PER POLICE REPORT No.T/20190624/2045;

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SFM5319J
Vehicle Make/Model/Colour	MERCEDES BENZ / C 180 BLUEEFFICIENCY
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	YONG TECK YEONG
NRIC/Passport Number	S0095894H
Contact Number	96431088
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name

YONG TECK YEONG

Approximate Age

47

Injuries Sustain

Injured person in which vehicle?

SJJ1974L

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

Address

BLK 115 JURONG EAST STREET 13 #09-372

Postcode

600115



SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:



Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

**IDAC KAKI BUKIT (VAC)**

Reporting Centre  
Name: 23 Kaki Bukit Ave 4  
Singapore 415933  
NRIC/TEL: 67416697 Fax: 67492305  
Email: [vackb@singnet.com.sg](mailto:vackb@singnet.com.sg)

# FIXMATE PTE LTD

BLK 8 , KAKI BUKIT AVE 4,#04-06, PREMIER@KAKI BUKIT  
Singapore(415875)

## VEHICLE REPAIR ESTIMATE

Insurance Company: SOMPO INSURANCE SINGAPORE PTE LTD  
(MOTOR CLAIMS DEPARTMENT)

Address: 50, RAFFLES PLACE ,#05-01/06  
SINGAPORE LAND TOWER,S(048623)

Telephone: 64616555 Fax: 62257947

Email: [motorsurvey@sompo.com.sg](mailto:motorsurvey@sompo.com.sg)

Make/ Model : HONDA STREAM RN6

Date: 24.06.2019

Chassis No : JHMRN68408S205298

Vehicle No: SJJ1974L

Date/Time of Accide: 22.06.2019/ 1915

### Materials Cost/ Spare Parts Cost

#### TO BE COMPLETED BY SERVICE ADVISOR

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$		FINAL PRICE \$
1	TAILGATE 903	1	\$ 1,045.20	bt ✓	\$ 1,045.20
2	TAILGATE DAMPER	2	\$ 136.30	X nn	\$ 272.60
3	TAILGATE HINGES	2	\$ 53.80	X nn	\$ 107.60
4	TAILGATE INNER LOCK	1	\$ 189.50	bt ✓	\$ 189.50
5	TAILGATE LOCK CATCH	1	\$ 45.80	X nn	\$ 45.80
6	TAILGATE WEATHERSTRIP	1	\$ 186.50	cut ✓	\$ 186.50
7	TAILGATE LOGO	1	\$ 75.30	nei ✓	\$ 75.30
8	TAILGATE OUTER GARNISH	1	\$ 202.90	X nn	\$ 202.90
9	TAILGATE NUMBER PLATE LAMPS	2	\$ 57.90	X nn	\$ 115.80
10	TAILGATE OUTER HANDLE	1	\$ 83.40	X nn	\$ 83.40
11	TAILGATE WINDSCREEN MOLDING	1	\$ 87.60	nei ✓	\$ 87.60
12	TAILGATE WINDSCREEN INNER SEAL	1	\$ 60.00	nei ✓	\$ 60.00
13	TAILGATE INNER TRIM	1	\$ 235.60	cut ✓	\$ 235.60
14	TAILGATE TOP TRIM	1	\$ 102.50	nn X nn	\$ 102.50
15	TAILGATE SIDE TRIM	2	\$ 78.20	X nn	\$ 156.40
16	TAILGATE POCKET HANDLE	1	\$ 59.60	de ✓	\$ 59.60
17	TAILAMP 385.50	21	\$ 485.60	LH-cut ✓	\$ 971.20 RH-X
18	TAILAMP COVERS	2	\$ 36.60	X nn	\$ 73.20
19	TAILAMP PANELS	2	\$ 402.10	Rx	\$ 804.20
20	TAILAMP BOTTOM RETAINERS	21	\$ 39.30	LH-de ✓	\$ 78.60 RH-X
21	END PANEL ASSY (OUTER)	1	\$ 405.20	Rp	\$ 405.20
22	END PANEL ASSY (BOTTOM)	1	\$ 198.60	Rp	\$ 198.60
23	END PANEL TOP TRIM	1	\$ 175.40	de ✓	\$ 175.40
24	REAR FENDER COWLING	21	\$ 186.90	LH-mis ✓	\$ 373.80 RH-X
25	REAR FENDER INNER TRIM	2	\$ 195.60	X nn	\$ 391.20
26	REAR FLOOR PANEL	1	\$ 1,045.00	X nn	\$ 1,045.00
27	REAR FLOOR PANEL TOP BOARD	2	\$ 202.60	X nn	\$ 405.20
28	REAR FLOOR PANEL TOOL SPONGE	1	\$ 186.30	X nn	\$ 186.30
29	REAR BUMPER 654	1	\$ 789.10	de ✓	\$ 789.10
30	REAR BUMPER RETAINERS	21	\$ 56.80	LH nei ✓	\$ 113.60 RH-X

31	REAR BUMPER TOWING COVER	1	\$ 45.60	de	\$ 45.60
32	REAR BUMPER STAY	2	\$ 35.40	X m	\$ 70.80
33	REAR BUMPER RETAINERS	21	\$ 62.50	LH-de	\$ 125.00
34	REAR SILENCER BOX	1	\$ 745.60	X m	\$ 745.60
35	REAR SILENCER BOX MOUNTING	2	\$ 48.00	X m	\$ 96.00
<b>Total List Price Cost</b>					<b>\$ 10,119.90</b>
<b>PARTS DISCOUNT 20%</b>					<b>\$ 8,095.92</b>

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$		FINAL PRICE \$
1	REAR BUMPER CLIP	1 SET	\$ 30.00	REL	\$ 30.00
2	TAILGATE GLASS SEALANTS	2	\$ 80.00	60 REL	\$ 80.00
3	END PANEL SEALANTS	2	\$ 80.00	X m	\$ 80.00
4	REAR NUMBER PLATE WITH CASING	1 SET	\$ 50.00	X m	\$ 50.00
5	REAR FLOOR PANEL INSULATOR PAD	1 SET	\$ 200.00	X m	\$ 200.00
6	TAILAMPS CLIPS	2 SET	\$ 60.00	30 REL	\$ 60.00
7	REVERSE SENSORS	1 SET	\$ 250.00	200 nm	\$ 250.00
8	END PANEL GARNISH TRIM CLIPS	1 SET	\$ 30.00	160 REL	\$ 30.00
9	REAR FENDER INNER TRIM CLIPS	2 SET	\$ 60.00	X m	\$ 60.00
10	REAR FENDER INNER COWLING CLIPS	2 SET	\$ 60.00	10 REL	\$ 60.00
<b>Total Special Nett Items</b>					<b>\$ 900.00</b>

Labour Works/ Panel Beating Related Works		Quotation
<b>Job Scope</b>		
TO RENEW, REPAIR, REALIGN DAMAGED PARTS, REPLACE, BEAT AND WELD		\$ 2,000.00
<b>Spray Painting</b>		
<b>Job Scope</b>		
TO RESPRAY AFFECTED AREAS		\$ 2,000.00
<b>Others Cost (Accident Repair Related Expenses)</b>		
<b>Job Scope</b>		
TO TUFFCOAT AFFECTED AREA		\$ 200.00
TO REMOVE/ REFIT REAR INTERIOR UPHOSTERY		\$ 180.00
TO REMOVE/ REFIT REAR WINDSCREEN		\$ 180.00
TO CONDUCT WIRING CHECK AND RESET TO ITS PRE-ACCIDENT CONDITION		\$ 120.00
LABOUR TO APPLY SEALANTS TO THE AFFECTED AREAS		\$ 180.00
TO REMOVE/ REFIT / REPLACE REAR SILENCER BOX		\$ 150.00
TO REMOVE /REFIT/ REPLACE REAR SENSOR AND DISTANCE SETTLING		\$ 180.00
TO REMOVE/ REFIT AND REPLACE TAILGATE MECHANISM		\$ 180.00
<b>Total Others Cost</b>		\$ 1,370.00
<b>GRAND TOTAL</b>		<b>\$ 14,365.92</b>

FIXMATE PTE LTD

Person Incharge: AH CHAI  
Direct Contact: +65 82632225/93727000  
Email: tfyong1966@gmail.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

4792.48  
469 3800.  
5 days  
Tanjik 27495749  
wp  
Resurvey after repair  
surelkkauto.com

**Veron Chen (LKKAuto)**

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Thursday, 15 August 2019 11:20 AM  
**To:** Yong Teck Far; SUR  
**Subject:** RE: stream SJJ1974L estimate  
**Attachments:** MARKING.pdf

Dear Sir,

WITHOUT PREJUDICE

Offer Lump Sum \$3800 @ 5 working days

PARTS-\$3403.10 (less 20%)=\$2722.48  
SN-\$340  
LABOUR-\$1730  
TOTAL-\$4792.48 (less 20%)=3833.98

Please check and confirm

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Yong Teck Far <tfyong1966@gmail.com>  
**Sent:** Friday, 2 August 2019 11:07 AM  
**To:** SUR <sur@lkkauto.com>  
**Subject:** Fwd: stream SJJ1974L estimate

----- Forwarded message -----

发件人 : apexi HKS <apexih@yahoo.com.sg>  
Date: 2019年8月2日周五 上午10:37  
Subject: stream SJJ1974L estimate  
To: [tfyong1966@gmail.com](mailto:tfyong1966@gmail.com) <[tfyong1966@gmail.com](mailto:tfyong1966@gmail.com)>

bro..for your reference

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Jun 2019		25 Jun 2019 08:51 <a href="#">Edit Adj Rpt</a>	<b>S\$3,800.00</b> <a href="#">Edit Estimates</a>	<b>S\$3,800.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

  

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>TAN KEE SENG</b> , ID: S0095894H								
Main Claimant:	<b>YONG FONG LING</b> , ID: S1682308B								
Vehicle Reg. No.:	<b>SJJ1974L</b>	Date of Loss:	22/06/2019 19:00 - :59 [129 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / CMTD1903008</b>	Policy/Cover Note No.:	D19MTPV01001187 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SFM5319J</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Fixmate Auto Pte Ltd - Kaki Bukit (HQ)</b> 8 KAKI BUKIT AVENUE 4, #02-37 PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel:								
Handling Insurer:	<b>Sompo Insurance Singapore Pte. Ltd. (HQ)</b> - Tel: 6461 6555 ... [Handled by <b>Hwang Shiang YI</b> - 6329 5205]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... [Final Rpt due 04/07/2019]								
Adj Asg. Remarks:	WS: 82632225 AH CHAI -PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT -NO TP SAS SUBMITTED								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SJJ1974L (CMTD1903008)

[SFM5319J]

TP

YONG FONG LING

Jun 22 2019 7:00PM

[TAN KEE SENG]

Fixmate Auto Pte Ltd - Kaki Bukit

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser		
Assessment Reports							1 per page		<input checked="" type="checkbox"/>		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	15/08/19 17:04	Adjuster Immediate Advice					1	Load HTM			
Photos/Images							3 per page		<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	15/08/19 11:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
2	15/08/19 11:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
3	15/08/19 11:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
4	15/08/19 11:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
5	15/08/19 11:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
6	15/08/19 11:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
7	15/08/19 11:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
8	15/08/19 11:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
9	15/08/19 11:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
10	15/08/19 11:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
11	15/08/19 11:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
12	15/08/19 11:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
13	15/08/19 11:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
14	15/08/19 11:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
15	15/08/19 11:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
16	15/08/19 11:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
17	15/08/19 11:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
18	15/08/19 11:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
19	15/08/19 11:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
20	15/08/19 11:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
21	15/08/19 11:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
22	15/08/19 11:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
23	15/08/19 11:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
24	15/08/19 11:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
25	15/08/19 11:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
26	15/08/19 11:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
27	15/08/19 11:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
28	15/08/19 11:06	General View					1	Load JPG	<input checked="" type="checkbox"/>		
29	15/08/19 11:06	Reinspection Photo					1	Load JPG	<input checked="" type="checkbox"/>		
30	15/08/19 11:06	Reinspection Photo					1	Load JPG	<input checked="" type="checkbox"/>		
31	15/08/19 11:06	Reinspection Photo					1	Load JPG	<input checked="" type="checkbox"/>		
32	15/08/19 11:06	Reinspection Photo					1	Load JPG	<input checked="" type="checkbox"/>		
33	15/08/19 11:06	Reinspection Photo					1	Load JPG	<input checked="" type="checkbox"/>		
34	15/08/19 11:06	Reinspection Photo					1	Load JPG	<input checked="" type="checkbox"/>		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	15/08/19 11:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
36	15/08/19 11:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
37	15/08/19 11:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
38	15/08/19 11:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
39	15/08/19 11:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
40	15/08/19 11:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
41	15/08/19 11:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
42	15/08/19 11:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
43	15/08/19 11:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
44	15/08/19 11:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
45	15/08/19 11:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
46	15/08/19 11:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
47	15/08/19 11:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
48	15/08/19 11:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
49	15/08/19 11:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
50	15/08/19 11:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
51	15/08/19 11:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
52	15/08/19 11:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
53	15/08/19 11:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
54	15/08/19 11:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
55	15/08/19 11:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
56	15/08/19 11:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
57	15/08/19 11:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
58	15/08/19 11:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
59	15/08/19 11:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
60	15/08/19 11:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
61	15/08/19 11:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
62	15/08/19 11:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
63	15/08/19 11:07	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
64	15/08/19 11:07	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
65	15/08/19 11:07	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
66	15/08/19 11:07	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
67	15/08/19 11:07	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
68	15/08/19 11:07	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
69	15/08/19 11:07	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	24/06/19 16:22	Pre-Repair Survey	Load PDF	
2	25/06/19 08:52	Pre-Repair Survey - LKK/MARCUS	Load PDF	
3	23/08/19 11:21	PD LOD W ENCLS DT 19.08.19 FR RIAZ LLC - SFM5319J PD LOD W ENCLS DT 19.08.19 FR RIAZ LLC - SFM5319J	Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.



# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19011137/T1VD3E2

Date: 03/09/2019

### REFERENCE

Handling Insurer: Sompo Insurance Singapore Pte. Ltd. Policy No: D19MTPV01001187

**Claimant Vehicle No :** SJJ1974L **Insured Vehicle No :** SFM5319J

Date of Loss: 22/06/2019 Nature of Claim: TP Claim No: CMTD1903008

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJJ1974L**  
 Make & Model: HONDA STREAM, 1.8 (A) Engine No: R18A12805313  
 Reg. Date: 04/09/2008 (Man. Year: 2008) Chassis No: JHMRN68408S205298  
 Colour: Blue Odometer: 251255 km  
 Engine Capacity: 1799 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/40 R17 Rear Tyre Size: 205/40 R17  
 Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm  
 Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,995.92	3,062.48	5,933.44	65.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,370.00	1,730.00	3,640.00	67.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>14,365.92</b>	<b>4,792.48</b>	<b>9,573.44</b>	<b>66.64</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,800.00</b>		
<b>Nett Amount (S\$)</b>	<b>14,365.92</b>	<b>3,800.00</b>	<b>10,565.92</b>	<b>73.55</b>

### INSPECTION

Date of Assignment: 25/06/2019

Date Inspected: 25/06/2019 Inspected At:

 Fixmate Auto Pte Ltd - Kaki Bukit (HQ)  
 8 KAKI BUKIT AVENUE 4, #02-37  
 PREMIER @ KAKI BUKIT  
 Singapore 415875

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 03 Sep 2019)
<b>Parts:</b>	M1-MPV	HONDA STREAM 1.8 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJJ1974L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,045.20 FL	*903.00 FL
2	2		*TAILGATE DAMPER	Not Necessary	272.60 FL	*- FL
3	2		*TAILGATE HINGES	Not Necessary	107.60 FL	*- FL
4	1		*TAILGATE INNER LOCK	Bent	189.50 FL	*189.50 FL
5	1		*TAILGATE LOCK CATCH	Not Necessary	45.80 FL	*- FL
6	1		*TAILGATE WEATHERSTRIP	Cut	186.50 FL	*186.50 FL
7	1		*TAILGATE LOGO	Necessary	75.30 FL	*75.30 FL
8	1		*TAILGATE OUTER GARNISH	Not Necessary	202.90 FL	*- FL
9	2		*TAILGATE NUMBER PLATE LAMPS	Not Necessary	115.80 FL	*- FL
10	1		*TAILGATE OUTER HANDLE	Not Necessary	83.40 FL	*- FL
11	1		*TAILGATE WINDSCREEN MOLDING	Necessary	87.60 FL	*87.60 FL
12	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	60.00 FL	*60.00 FL
13	1		*TAILGATE INNER TRIM	Cracked	235.60 FL	*235.60 FL
14	1		*TAILGATE TOP TRIM	Not Necessary	102.50 FL	*- FL
15	2		*TAILGATE SIDE TRIM	Not Necessary	156.40 FL	*- FL
16	1		*TAILGATE POCKET HANDLE	Deformed	59.60 FL	*59.60 FL
17	1		*TAILLAMP	N/S Cut / O/S Not Necessary	971.20 FL	*385.50 FL
18	2		*TAILLAMP COVERS	Not Necessary	73.20 FL	*- FL
19	2		*TAILLAMP PANELS	Repair	804.20 FL	*- FL
20	1		*TAILLAMP BOTTOM RETAINERS	N/S Deformed / O/S Not Necessary	78.60 FL	*39.30 FL
21	1		*END PANEL ASSY (OUTER)	Repair	405.20 FL	*- FL
22	1		*END PANEL ASSY (BOTTOM)	Repair	198.60 FL	*- FL
23	1		*END PANEL TOP TRIM	Deformed	175.40 FL	*175.40 FL
24	1		*REAR FENDER COWLING	N/S Missing/O/S Not Necessary	373.80 FL	*186.90 FL
25	2		*REAR FENDER INNER TRIM	Not Necessary	391.20 FL	*- FL
26	1		*REAR FLOOR PANEL	Not Necessary	1,045.00 FL	*- FL
27	2		*REAR FLOOR PANEL TOP BOARD	Not Necessary	405.20 FL	*- FL
28	1		*REAR FLOOR PANEL TOOL SPONGE	Not Necessary	186.30 FL	*- FL
29	1		*REAR BUMPER	Deformed	789.10 FL	*654.00 FL
30	1		*REAR BUMPER RETAINERS	N/S Necessary/O/S Not Necessary	113.60 FL	*56.80 FL
31	1		*REAR BUMPER TOWING COVER	Deformed	45.60 FL	*45.60 FL
32	2		*REAR BUMPER STAY	Not Necessary	70.80 FL	*- FL
33	1		*REAR BUMPER RETAINERS	N/S Deformed/O/S Not Necessary	125.00 FL	*62.50 FL
34	1		*REAR SILENCER BOX	Not Necessary	745.60 FL	*- FL
35	2		*REAR SILENCER BOX MOUNTING	Not Necessary	96.00 FL	*- FL
36	1		*SET REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
37	2		*TAILGATE GLASS SEALANTS	Necessary	80.00 FS	*60.00 FS
38	2		*END PANEL SEALANTS	Not Necessary	80.00 FS	*- FS
39	1		*SET REAR NUMBER PLATE WITH CASING	Not Necessary	50.00 FS	*- FS
40	1		*SET REAR FLOOR PANEL INSULATOR PAD	Not Necessary	200.00 FS	*- FS
41	2		*SET TAILLAMPS CLIPS	Necessary	60.00 FS	*30.00 FS
42	1		*SET REVERSE SENSORS	Not Working	250.00 FS	*200.00 FS
43	1		*SET END PANEL GARNISH TRIM CLIPS	Necessary	30.00 FS	*10.00 FS
44	2		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	60.00 FS	*- FS
45	2		*SET REAR FENDER INNER COWLING CLIPS	Necessary	60.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>11,019.90</b>	<b>3,743.10</b>
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	<b>2,023.98</b>	<b>680.62</b>
<b>Total Parts (S\$)</b>	<b>8,995.92</b>	<b>3,062.48</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO RENEW, REPAIR, REALIGN DAMAGED PARTS, REPLACE, BEAT AND WELD	New	2,000.00	700.00
2	TO RESPRAY AFFECTED AREAS	New	2,000.00	700.00
3	TO TUFFCOAT AFFECTED AREA	New	200.00	30.00
4	TO REMOVE / REFIT REAR INTERIOR UPHOLSTERY	New	180.00	60.00
5	TO REMOVE / REFIT REAR WINDSCREEN	New	180.00	120.00
6	TO CONDUCT WIRING CHECK AND RESET TO ITS PRE-ACCIDENT CONDITION	New	120.00	30.00
7	LABOUR TO APPLY SEALANTS TO THE AFFECTED AREAS	New	180.00	0.00
8	TO REMOVE / REFIT / REPLACE REAR SILENCER BOX	New	150.00	0.00
9	TO REMOVE / REFIT / REPLACE REAR SENSOR AND DISTANCE SETTLING	New	180.00	30.00
10	TO REMOVE / REFIT AND REPLACE TAILGATE MECHANISM	New	180.00	60.00
<b>Gross Labour Cost (S\$)</b>			<b>5,370.00</b>	<b>1,730.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >