

ASS. REC. BY:

REF: CS/SMO1901138/kqd3n2

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Agnes Chan Shu Hui

of

SMD

Date/Time: 25.6.19 8.45a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLV 9122P

Insured: SMD 6382H

at Workshop m/s Yee Auto

Tel: 64575768 / 64577675 Mr. Tang

of 160 Sin Ming Drive #02-17

Policy No: DIBM TRENT000720

Claim No: CMTD1903003

Sum Insured:

Excess:

Make of Veh:

D.O.A. 23.6.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 25.6.19 9.18a.m

Person Contacted: Mr Tan

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SMD 6382H: ✓
	SLV 9122P: ✓
26/6/19 @	11.10pm revised to Agnes Chan via Messenger.
5/8	✓ 1 Lm @ 4 Pool email & confirmed (Red 88621.80, 64%)

ASSIGNMENT

From: Date: 25.6.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLV 9122P

at Workshop m/s Yee Auto

of 160 Sin Ming Drive #02-17

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 07 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLV 9122P Yr Regn: 01, 18

Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes 3 C.C. 1496

Colour: M.D. Gray A/C: Insured / Std / NI / NA

Sp. Reading: 30202 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JN6BN22A8J0194596

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 23/6/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Acc o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 14 AUG 2019

Date/Time, File Pass to/

☐ : Preli. Report

☐ : Final Report

Date/Time, File Return to/

2)

Days Of Repair: 7

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

G + RS, SI

Photos

Others

TOTAL

Report Format: MER-TP

Lump Sum / I.B.I. (\$) 4900

350

11

361

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sampo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: CHAN SHU HUI AGNES

Date: 26 Jun 2019

Preliminary Advice

Insured Vehicle No	: SMD6382H	Accident Date	: 23/06/2019
TP Vehicle No	: SLV9122P	Assignment Date	: 25/06/2019
Make	:	Est. Duration of Repair	: 7.00
Date of Inspection	: 25/06/2019		
Inspection At	: YEE AUTO PTE LTD (HQ) 160 SIN MING DRIVE, #02-17 SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,521.80
Revised Amount	:S\$	6,400.20
Check Items (Estimated)	:S\$	1,335.30
Total	:S\$	7,735.50

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY ASSIST TO ADD IN THE MAKE & MODEL OF VEHICLE SLV 9122P : MAZDA 3 SEDAN 1.5 AT

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Jun 2019		25 Jun 2019 08:45 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	HITACHI CAPITAL ASIA PACIFIC PTE. LTD., Co. Reg. No.: 199400399N								
Main Claimant:	AILEEN TOH CHAI HOONG, ID: S7631437C								
Vehicle Reg. No.:	SLV9122P	Date of Loss:	23/06/2019 00:00 - :59						
Claim Type:	TP / CMTD1903003	Policy/Cover Note No.:	D18MTRENT000720 (Comprehensive)						
Vehicle Reg. No. (Insured):	SMD6382H	Policy No. (Claimant):							
		Excess:							
Repairer:	Yee Auto Pte Ltd (HQ) 160 SIN MING DRIVE, #02-17 SIN MING AUTOCITY, 575722 Sin Ming - Tel: 64575768								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 04/07/2019]								
Adj Asg. Remarks:	WS: YEE AUTO 6457 5768 -PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT -NO TP SAS SUBMITTED								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1437C
Vehicle Details	
Vehicle No.:	SLV9122P
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Jun 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 SEDAN 1.5 AT EU6
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	P520486747
Chassis No.:	JM6BN22A8J0194596
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$15,125.00
Original Registration Date:	22 Jan 2018
First Registration Date:	22 Jan 2018
Transfer Count:	0
Actual ARF Paid:	\$15,125.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Jan 2028
PARF Rebate Amount:	\$11,343.00
Intended COE Rebate Details	
COE Expiry Date:	21 Jan 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$36,890.00
COE Rebate Amount:	\$31,614.00
Total Rebate Amount:	\$42,957.00

The information contained herein is correct as at 26 Jun 2019

OK

(Draft)

MLHM19081558 / Lai Hui (Meng Kee) Motor Pte Ltd - Sin Ming
ENTRY DATE & TIME: 24/06/2019 10:33
SUBMITTED BY: [To Be Confirmed]

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Date Of Report	24/06/2019 10:33
Date Of Accident	23/06/2019 16:40
Exact Location Of Accident	SLE/CTE TOWARDS YIO CHU KANG
Country/State of Loss	SINGAPORE
Vehicle Registration Number	SLV9122P
Insured/Policyholder	
Name Of Registered Owner	AILEEN TOH CHAI HOONG
NRIC No	S7631437C
Email Address	MUSIQUESG@ME.COM
Mobile Phone No	(LOCAL) +65-97389512
Alternative Phone No	Others-97389512
Vehicle Particulars	
Manufacturer	MAZDA
Model	3
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800010895
Cover Note Number	
Driver	
Name of Driver	AILEEN TOH CHAI HOONG
NRIC No	S7631437C
Date Of Birth	01/10/1976
Occupation	INDOOR
Date Of Driving Pass	23/09/2015
Driving Experience	3 YEARS AND 9 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97389512
Fax Number	
Contact Number	OTHERS-97389512
EMail Address	MUSIQUESG@ME.COM

Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (Including own vehicle) involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2
Passenger 1 Name: CLARENCE TEO KAI XUAN
Gender: Male

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

Vehicle Registration Number SMD6382H

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 24 JUN 2019


Driver's Signature
(If driver is not the policyholder)
Date & Time: 24 JUN 2019


Reporting Centre Personnel's Signature
Name: Jenny Lim
NRIC/FIN No.: S6927273H

SKETCH PLAN (A) SLV9122P

(B) SMD 6382H

PIE (TUAS)

SLE/CTE

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 23/06/2019 at 16:37pm. I was travelling my vehicle (A) SLV9122P along SLE/CTE towards Yio Chu Kang. Traffic was heavy in front of my vehicle slow down & stop. I also slow down and stop suddenly vehicle (B) SMD 6382H hit my rear portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

24 JUN 2019

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopte ltd@gmail.com

Registration No: 201719251W GST No: 201719251W

M/S : Somp Insurance Singapore Pte Ltd
50 Raffles Place
#03-03 Singapore Land Tower
Singapore 048623

Estimate No: ES1900023

Date: 24 Jun 2019

Policy No:

Veh Reg No: SLV9122P

Make/Model: MAZDA MAZDA3
SEDAN 1.5 AT EU6

Chassis No: JM6BN22A8J0194596

Engine No: P520486747

Reg. Date: 22/01/2018

ATTN: Motor Claim Department

Your Ref No: -

Claim Type: Third Party

Accident Date: 23/06/2019

TP Veh Reg No: SMD6382H

Not Authorized

Recovery B4 claim

7 days

11 Sep @ 4900h

Estimate Repair Cost to Vehicle No :SLV9122P

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
Net Price				
1 REAR TYRE RIM - RH	600.00	1 PC	<i>Sn</i> 600.00	<i>X</i>
2 REAR WINDSCREEN SEALANT	120.00	1 PC	<i>sn</i> 120.00	<i>40sn</i>
3 REVERSE SENSOR	500.00	1 PC	<i>sn</i> 500.00	<i>X</i>
			1,220.00	1,220.00
Spare Parts				
4 REAR BOOT LID	1,255.00	1 PC	<i>R</i> 1,255.00	<i>X</i>
5 REAR BOOT LID EMBLEM 'LOGO'	89.60	1 PC	<i>sn</i> 89.60	<i>✓</i>
6 REAR BOOT LID EMBLEM 'MAZDA 3'	92.90	1 PC	<i>sn</i> 92.90	<i>✓</i>
7 REAR BOOT LID EMBLEM 'SKY CITY TECHNOLOGY'	95.10	1 PC	<i>sn</i> 95.10	<i>✓</i>
8 REAR BOOT LID WEATHERSTRIP	198.20	1 PC	<i>sn</i> 198.20	<i>X</i>
9 REAR BUMPER	1,055.00	1 PC	<i>R</i> 1,055.00	<i>✓</i>
10 REAR BUMPER CLIPS	70.00	1 SET	<i>sn</i> 70.00	<i>✓</i>
11 REAR BUMPER REFLECTOR - RH	128.00	1 PC	<i>cm</i> 128.00	<i>✓</i>
12 REAR BUMPER REINFORCEMENT	468.20	1 PC	<i>B</i> 468.20	<i>✓</i>
13 REAR BUMPER SIDE RETAINER - LH	93.00	1 PC	<i>sn</i> 93.00	<i>X</i>
14 REAR BUMPER SIDE RETAINER - RH	93.00	1 PC	<i>cm</i> 93.00	<i>✓</i>
15 REAR BUMPER TOWING COVER	32.50	1 PC	<i>mt</i> 32.50	<i>✓</i>
16 REAR END PANEL <i>506</i>	798.00	1 PC	<i>R</i> 798.00	<i>✓</i>
17 REAR FENDER AIR VENT - RH	69.10	1 PC	<i>cm</i> 69.10	<i>✓</i>
18 REAR FENDER INNER SHIELD - RH	96.80	1 PC	<i>dis/ht</i> 96.80	<i>✓</i>
19 REAR FENDER INNER SHIELD CLIP	50.00	1 SET	<i>sn</i> 50.00	<i>✓</i>
20 REAR WINDSCREEN MOULDING	168.00	1 PC	<i>sn</i> 168.00	<i>✓</i>
21 REAR TAIL LAMP - RH <i>849.60</i>	869.00	1 PC	<i>sn</i> 869.00	<i>✓</i>
22 EXHAUST MUFFLER	785.00	1 PC	<i>n</i> 785.00	<i>X</i>
23 REAR FENDER - RH <i>1174.20</i>	1,450.30	1 PC	<i>Bu</i> 1,450.30	<i>✓</i>
24 REAR FENDER INNER TRIMBOARD - RH	395.10	1 PC	<i>sn</i> 395.10	<i>X</i>
			8,351.80	8,351.80
Labour				
25 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	1,800.00	1 JOB	1,800.00	<i>1000</i>
26 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,500.00	1 JOB	1,500.00	<i>800</i>
27 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	150.00	1 JOB	150.00	<i>300</i>
28 TO REMOVE/REFIT REAR WINDSCREEN TO FACILITATE REPAIRS.	200.00	1 JOB	200.00	<i>1200</i>

208



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopteltd@gmail.com

Registration No: 201719251W GST No: 201719251W

M/S : Somp Insurance Singapore Pte Ltd
50 Raffles Place
#03-03 Singapore Land Tower
Singapore 048623

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 23/06/2019
TP Veh Reg No: SMD6382H

Estimate No: ES1900023
Date: 24 Jun 2019
Policy No:
Veh Reg No: SLV9122P
Make/Model: MAZDA MAZDA3
SEDAN 1.5 AT EU6
Chassis No: JM6BN22A8J0194596
Engine No: P520486747
Reg. Date: 22/01/2018

Estimate Repair Cost to Vehicle No :SLV9122P

Description	U/Price	Quantity	List Price	Amount
			SS	SS
29 TO REMOVE/REFIT REAR CUSHION SEAT, SPEAKER BOARD, ROOF UPHOLSTERY TO FACILITATE REPAIRS.	120.00	1 PC	120.00	100
30 TO CHECK WIRING FUNCTIONS.	60.00	1 JOB	60.00	20
31 WHEEL ALIGNMENT	120.00	1 T	120.00	X
			3,950.00	3,950.00
			Total	SS 13,521.80
			Add GST @ 7%	946.53
			Total Amount Payable	SS 14,468.33

TOTAL: SINGAPORE DOLLAR FOURTEEN THOUSAND FOUR HUNDRED SIXTY EIGHT AND CENTS THIRTY THREE ONLY

For Yee Auto Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19011138/KQD3N2

Date: 15/08/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTRENT000720
Claimant Vehicle No :	SLV9122P	Insured Vehicle No :	SMD6382H
Date of Loss:	23/06/2019	Nature of Claim:	TP
		Claim No:	CMTD1903003

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV9122P	Engine No:	P520486747
Make & Model:	MAZDA 3, 1.5 (A)	Chassis No:	JM6BN22A8J0194596
Reg. Date:	22/01/2018 (Man. Year: 2017)	Odometer:	30202 km
Colour:	Metallic Dark Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	9,571.80	4,070.40	5,501.40	57.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,950.00	2,070.00	1,880.00	47.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	13,521.80	6,140.40	7,381.40	54.59
Approved Total (Overridden) (\$\$)		4,900.00		
(\$\$)	13,521.80	4,900.00	8,621.80	63.76
+ GST 7.00/7.00% (\$\$)	946.53	343.00	603.53	63.76
Nett Amount (\$\$)	14,468.33	5,243.00	9,225.33	63.76

INSPECTION

Date of Assignment:	25/06/2019	
Date Inspected:	25/06/2019 Inspected At:	Yee Auto Pte Ltd (HQ) 160 SIN MING DRIVE, #02-17 SIN MING AUTOCITY Singapore 575722

Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 15 Aug 2019)
Parts: 144	MAZDA 3 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLV9122P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BOOT LID	Repair	1,255.00 F	*- FL
2	1	*REAR BOOT LID EMBLEM LOGO	Necessary	89.60 F	*89.60 FL
3	1	*REAR BOOT LID EMBLEM MAZDA 3	Necessary	92.90 F	*92.90 FL
4	1	*REAR BOOT LID EMBLEM SKY CITY TECHNOLOGY	Necessary	95.10 F	*95.10 FL
5	1	*REAR BOOT LID WEATHERSTRIP	Serviceable	198.20 F	*- FL
6	1	*REAR BUMPER	Bent	1,055.00 F	*1,055.00 FL
7	1	*SET REAR BUMPER CLIPS	Necessary	70.00 F	*70.00 FL
8	1	*REAR BUMPER REFLECTOR-RH	Cracked	128.00 F	*128.00 FL
9	1	*REAR BUMPER REINFORCEMENT	Bent	468.20 F	*468.20 FL
10	1	*REAR BUMPER SIDE RETAINER-LH	Serviceable	93.00 F	*- FL
11	1	*REAR BUMPER SIDE RETAINER-RH	Cracked	93.00 F	*93.00 FL
12	1	*REAR BUMPER TOWING COVER	Missing	32.50 F	*32.50 FL
13	1	*REAR END PANEL	Bent	798.00 F	*506.00 FL
14	1	*REAR FENDER AIR VENT-RH	Cracked	69.10 F	*69.10 FL
15	1	*REAR FENDER INNER SHIELD-RH	Distorted/Cut	96.80 F	*96.80 FL
16	1	*SET REAR FENDER INNER SHIELD CLIP	Necessary	50.00 F	*50.00 FL
17	1	*REAR WINDSCREEN MOULDING	Necessary	168.00 F	*168.00 FL
18	1	*REAR TAIL LAMP-RH	Mtg Cracked	869.00 F	*849.60 FL
19	1	*EXHAUST MUFFLER	Repair	785.00 F	*- FL
20	1	*REAR FENDER-RH	Buckled	1,450.30 F	*1,174.20 FL
21	1	*REAR FENDER INNER TRIMBOARD-RH	Serviceable	395.10 F	*- FL
22	1	*REAR TYRE RIM-RH	Serviceable	600.00 FS	*- FS
23	1	*REAR WINDSCREEN SEALANT	Necessary	120.00 FS	*40.00 FS
24	1	*REVERSE SENSOR	Serviceable	500.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,571.80	5,078.00
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	1,007.60
Total Parts (\$\$)	9,571.80	4,070.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE DAMAGED PARTS,PANEL BEAT WHERE NECESSARY	New	1,800.00	1,000.00
2	TO PUTTY,APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION	New	1,500.00	800.00
3	TO APPLY RUST-PROOFING ON REPAIRED,REPLACED PANEL	New	150.00	30.00
4	TO REMOVE/REFIT REAR WINDSCREEN TO FACILITATE REPAIRS	New	200.00	120.00
5	TO REMOVE/REFIT REAR CUSHION SEAT,SPEAKER BOARD,ROOF UPHOLSTERY TO FACILITATE REPAIRS	New	120.00	100.00
6	TO CHECK WIRING FUNCTIONS	New	60.00	20.00
7	WHEEL ALIGNMENT	New	120.00	0.00
Gross Labour Cost (\$\$)			3,950.00	2,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >