

SUPPLEMENTARY

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

35.87 00.00

4.12 00.00

00.00

3.17

ESTIMATE FOR SLB92G

CHINA TAIPING INSURANCE (S) PTE LTD ATTN: MOTOR CLAIM DEPARTMENT 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909 62222366

Account No Terms Date/Time Printed CSE

	Venicle & Document information
WIP No	34364
Reg No/Reg Date	SLB92G / 28/04/2016
Date In/Mileage	02/07/2019/-135508
Chassis No	WDD2120842B304676
Engine No	27492030571582
Make/Model	MB/MB E 200 2.0 SEDAN (W212) "EDITION E"
Colour/Trim	029 992 Selenite Gr/ 042 241 Leather Bla

Vehicle & Document Information

WC000	0668 Credit	15/07/2019/	19:20	СН	371 / Go	Chee Han				DESCRIPTION OF THE PARTY OF THE
		Description	of Goods	/ Services	(国)	KWE WE	Qty	Unit Price	Disc%	Amount +
M BP P D	NSUN DLLCY NOZACC DATE RIVE IN TP VEH NO	: 5108912817 DMBER 18-6-2	// 1/\ 6 019 // GV	20.9 28.5M	HINA TAIPING	AL	. TA	A II	W	OICE
В	ATE IN/DATE SURVE Y/AUTHRIZED ON :	Y: 2-7-2019 1 : 24-6-2019 17	130 // Ta 24 // Ire	ne Tay -	CHINA TAIPING	i .	1.00	29.47	00.00	de /29.47
X F	OVERING IXTURE						1 80	9.58	00.00	ne 9.58 nee 62.11
X S	AP TOP				3.4.	n.	2.00	8.01 2.83	00.00	ne 16.02 ne 39.62

Operator

Go Chee Han DID: 6771 4336 HP: 9181 7717 Email: cheehan.go@cyclecarriage.com.sg Cycle & Carriage Industries Pte Ltd Customer Service Centre - Pandan Loop

Confirmed & accepted by

RIVET

RIVET

SURFACE GASKET

RIVETED NUT

Χ

X

X

Nett

257.70

12.68

nei 71.74

nu 16.48

7% GST on

257.70 18.04

Total Payable

275.74

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worm or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.coni.sg