

ASS. REC. BY:

REF: CS/FCI/19011143/T1td3n2

Special Instruction:

(rws)

Surveyor: Tautiky

ASSIGNMENT (Office)

From (Person): Karntan

of FCI

Date/Time: 24/6/19 @ 5.48pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SCM 3020T

Insured: SH 8896L

at Workshop n/s Performance Motor
of 303 Alexandra Road

Tel: 6319 0174

Policy No:

Claim No: D19003944 MFSH

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 15.6.2019

CA / REV / REP. / REV 24 HRS

"rup"

H.O.D. Endorsement:

Date/Time: 25.6.19 9.42a.m

Person Contacted: (Caroline)

Vehicle-IN (OUT)

Date/Time	Action/Instruction (✓) Estimate
	SH8896L: ✓
	SCM 3020T: CS/CTI/7002555/T1gh3F2 D.O.A: 27/01/2017
	8/7@3:29pm- Revised via email preli advse.

ASS. / EQ. BY: Taufiq

REF: FCI

ASSIGNMENT

From: _____ Date: 26/6/19

Veh No: SCM3020T Yr Regn: 241 Dec

Estimated Cost: _____

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD: TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: SCM 3020T

Make: BMW 730 c.c. 2996

at Workshop m/s: Performance
of 303 Alexandra Road

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 122309 T/Radio: Insured / Std / NI / NA

Insured: _____

Eng/No: WBAKB22010C95/35

Policy No. _____

C/No: _____

Claims No. _____

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: _____ Excess: _____

Steering: In order / Jammed / Leaked / Burnt or


(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh: Before 12pm
Inthirun

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)



Remark: The veh had commenced its repair at the time of inspection.

Tyre Size: F: 215/45R19

R: u u

Bal. or Market Value: _____

BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

IDAC Accident Rpt: _____ Consistent? : Yes or No

Front 6 Rear 6

R/Bal. _____ mm R/Bal. _____ mm

GIA / PR Seen: _____ Consistent? : Yes or No

L/Bal. 6 mm L/Bal. 0 mm

Est. Repairs: _____ days Res.: Yes or No

D.O.A. _____ D.O.I. 26/6/19

Lum Sum: _____ % 3 Val.: Yes or No

Survey held at PML 26/6/19

CA / REV / REP. / 24 HRS wp

Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>3/10</u>	<u>\$ 4106.05, 3 day e-mail to Slaven</u> <u>(Red. 1676.35; 28%)</u>

RECEIVED 04 OCT 2019

Date/Time, File Pass to? : Prefi. Report

Days Of Repair: 3

1) 3/10 Typist. : Final Report

Resurvey No. of Trip: 2

Date/Time, File Return to?

Survey Fee:	<u>140</u>
Transportation:	<u>50</u>
S + RS: \$	<u>50+50</u>
Fluoro	<u>31</u>
Other:	
TOTAL	<u>321</u>

2)

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech. Invt (\$)

: West end (\$)

Report Format: TP

Estim Sum / I.B. (\$): 4106.05



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19003944MFSH

Date: 8/7/2019

Our Ref: CS/FCI19011143/T1td3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SCM 3020T

Please be informed that we had conducted the inspection of the abovementioned vehicle 26/6/2019 at the premises of M/s Performance Motor have the following to report: -

Workshop Estimate Amount	: S\$ <u>5,782.40</u>
Revised Estimate Amount	: S\$ <u>3,947.30</u>
"Check" Items Amount	: S\$ <u>1,279.05</u>
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Taufikh

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	17-06-2019	Our Ref No. D19003944MFSH
Accident Date	15-06-2019	Claim Type. Third Party
Insured Vehicle	SH8896L	Third Party Vehicle. SCM3020T
Survey Location	303 ALEXANDRA ROAD SIME DARBY PERFORMANCE CENTRE	
Contact Person.	CAROLINE	
Contact No.	63190174/ 0	Fax No. 64794601
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PERFORMANCE MOTORS LIMITED	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 8 July 2019 3:29 PM
To: Admin-D (LKKAuto); 'CWS Motor Claims'; assignments
Cc: 'Karen Tan'; SUR
Subject: RE: SURVEY ASSESSMENT - D19003944MFSH/1
Attachments: PRELI ADVISED SCM 3020T.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SCM 3020T**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 25 June 2019 9:56 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19003944MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 24 June 2019 5:48 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19003944MFSH/1

Denise Tay (LKKAuto)

From: Sharon Heng L K <sharon.heng.leekun@simedarby.com.sg>
Sent: Thursday, 3 October 2019 1:58 PM
To: Taufikh (LKKAuto)
Cc: Denise Tay (LKKAuto)
Subject: RE: DIRECT SETTLEMENT FINAL REPORT - SCM3020T

Dear Taufikh

Thanks very much.

Best Regards

Sharon Heng
Performance Motors Ltd
Body & Paint
DID : 63190123
Fax : 64743229

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

-----Original Message-----

From: Taufikh (LKKAuto) [mailto:Taufikh@lkkauto.com]
Sent: Thursday, 3 October, 2019 1:14 PM
To: Sharon Heng L K
Cc: Denise Tay (LKKAuto)
Subject: RE: DIRECT SETTLEMENT FINAL REPORT - SCM3020T

Hi Sharon,

COR \$4106.05 , 3 days.

Regards
Taufikh
Lkk Auto

-----Original Message-----

From: Sharon Heng L K [mailto:sharon.heng.leekun@simedarby.com.sg]
Sent: Sunday, 29 September 2019 3:31 PM

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559M GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



*Survey & repair
26.06 @ 10am
** Survey before 12pm*

GST REG. NO : M2 - 0020081 - X

21 JUN 2019

E S T I M A T E

Estimate No. : **b1 51642** Page No. : 1 of 4
Date Estimated : **21/06/2019**
Prepared By : **Inthiran A/L Thurasamy**

<p>- ESTIMATE REPAIR FOR - Chan Chuen Beng (Zeng Junming) 36 Marlene Avenue Singapore 556665</p>	<p>- ACCOUNT - 303 MS First Capital Insurance Limited 6 Raffles Quay #21-00 Singapore 048580</p>
-----------------------------------------------------------------------------------------------------------------------------------------------	-----------------------------------------------------------------------------------------------------------------------------------------------------

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SCM3020T	C951315	08/12/2011	730LiA	0

DESCRIPTION	VALUE		
To replace rear bumper and attachments.	850 1,275.00		
Painting rear bumper.	934 1,038.00		
To check electrical wiring systems and lightings at the rear section for proper function.	150 177.00		
Sundries.	80.00		
Total Labour 1: 2,570.00			
DESCRIPTION	QTY	PRIC	VALUE
RR BUMPER CARRIER	1	865.65	865.65
RR BUMPER ADAPTER	1	44.60	44.60
REAR BUMPER TRIM PRIMED	1	239.15	239.15
RR BUMPER (PDC)	1	1,674.00	1,674.00
DECOUPLING RING PDC TORQUE CONVERTE	4	5.05	20.20
BUMPER PDC SENSOR (475 BLACK SAPPHI	1	368.80	368.80
Total Parts :			3,212.40

LKR Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____
Date & Time 21/6/19 Excess S\$ _____
Surveyor's Name Tan Jiah Sign [Signature]
Surveyor's Tel 97445749 Authorised Yes / No _____
Authorised Date _____ Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No Yes PML Yes / No _____
Surveyor's E-mail tan.jiah@lkr.com
No. of Working Days Recommend 3 days

Labour 1	2,570.00
Parts	3,212.40
Labour 2	0.00
Excess	0.00
Total GST @ 7%	404.77
Grand Total	6,187.17

**** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY****
**** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE ****

5782.40

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg No. 197401559W / GST Reg No. M2-00200B1-X



Final Report

Estimate No. : **b1 51642**
Date Estimated : **21/06/2019**
Prepared By : **Inthiran A/L Thurasamy**

- ESTIMATE REPAIR FOR -
Chan Chuen Beng (Zeng Junming)
36 Marlene Avenue

- ACCOUNT - 303
MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

Singapore 556665

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SCM3020T	WBAKB22010C9515	08/12/2011	730LiA	0

DESCRIPTION	ACCOUNT: ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments	850.00	0	850.00
To respray rear bumper	934.00	0	934.00
To check electrical wiring systems and lightings at the rear section for proper function.	150.00	0	150.00
Sundries.	80.00	0	80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# RR BUMPER ADAPTER	44.60	1	0	44.60
REAR BUMPER TRIM PRIMED	239.15	1	0	239.15
RR BUMPER (PDC)	1,674.00	1	0	1,674.00
# COVERING REAR RIGHT	134.30	1	0	134.30 <i>Carde</i>
#				
#				

SUPPLEMENTARY ITEMS

Total Labour :	2,014.00
Total Parts :	2,092.05
Total Repair Costs less Excess:	4,106.05
GST @7%:	287.42
Grand Total :	4,393.47

NO	JOB ORDER	DATE	BY
FAY TO C/C NO	<i>Tan Jiah LKK</i>	<i>29/9/19</i>	<i>3</i>
FAY TO FAX NO			
FAY TO C/C NO			
FAY TO FAX NO			

CAR RENTAL - \$256.80

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : **b1 51642**
Date Estimated : **21/06/2019**
Prepared By : **Inthiran A/L Thurasamy**

- ESTIMATE REPAIR FOR -
Chan Chuen Beng (Zeng Junming)
36 Marlene Avenue

- ACCOUNT - 303
MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

Singapore 556665

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SCM3020T	WBAKB22010C9511	08/12/2011	730LiA	0

DESCRIPTION	ACCOUNT:		DISC. %	NETT
	ORIGINAL PRICE			

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# # COVERING REAR RIGHT # #	134.30	1	0	134.30 <i>de</i>

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	134.30
Total Labour & Parts :	134.30



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19011143/T1td3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 07-10-2019	
		Code : FC12	
1. Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	SH 8896L	Veh. Inspected
			SCM 3020T
	Policy No.		Coverage (\$)
			0.00
	Claim No.	D19003944MFSH	Excess (\$)
			0.00
	Assign From	KARENT	Assign Date
			24/06/2019
2. Vehicle Particulars & Condition			
	Make & Model	BMW 730	c.c
			2996
	Engine No.	HIDDEN	Year of Reg.
			2011
	Chassis No.	WBAKB22010C951315	Colour
			BLACK
	Odometer	122309	Steering
			IN ORDER
	Brakes	IN ORDER	Modification
			SPORTS RIM
	General	GOOD	
3. Conditions of Tyres			
		Size	Make
			Balance
	R/H Front Tyre	215/45 R19	DUNLOP
			6 mm
	L/H Front Tyre	215/45 R19	DUNLOP
			6 mm
	R/H Rear Tyre	215/45 R19	DUNLOP
			6 mm
	L/H Rear Tyre	215/45 R19	DUNLOP
			6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
DAMAGES SEE DETAILS.			
5. General Information			
	Accident Date	15/06/2019	Inspection Date
			26/06/2019
	Survey held at	PERFORMANCE MOTORS LTD	
		303 ALEXANDRA ROAD	
		SINGAPORE 159941	
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT.			
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.			
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCM 3020T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	RR BUMPER CARRIER (SN)	NOT NECESSARY	865.65	-
1	RR BUMPER ADAPTER (SN)	DEFORMED	44.60	44.60
1	REAR BUMPER TRIM PRIMED (SN)	DEFORMED	239.15	239.15
1	RR BUMPER (PDC)(SN)	DEFORMED	1,674.00	1,674.00
4	DECOUPLING RING PDC TORQUE CONVERTE (SN)	NOT NECESSARY	20.20	-
1	BUMPER PDC SENSOR (475 BLACK SAPPHI)(SN)	NOT NECESSARY	368.80	-
1	SUNDRIES (SN)	NECESSARY	80.00	80.00
1	COVERING REAR RIGHT (ADDITIONAL)(SN)	DEFORMED	134.30	134.30
			3,426.70	2,172.05
	LABOUR			
	TO REPLACE REAR BUMPER AND ATTACHMENTS.		1,275.00	850.00
	PAINTING REAR BUMPER.		1,038.00	934.00
	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION.		177.00	150.00
			2,490.00	1,934.00
	GRAND TOTAL		5,916.70	4,106.05
RECOMMENDED COST OF REPAIRS				4,106.05

Report Ref No. CS/FC119011143/T1td3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.