

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 759T**AAD1906-202***Not Notified*
11 Sep 2014, 150k

25 JUN 2019

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHF 759T

VF1ABL15AUC283369

RENAULT

LATITUDE

21.6.19

AUTO & GENERAL

30/6/2016

		PART		LIST
1	1	BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46 <i>✓</i>
2	1	BUMPER LOWER REAR	\$	<i>SL</i> 768.84 <i>X</i>
3	1	BUMPER BRACKET CTR REAR	\$	<i>SL</i> 113.47 <i>X</i>
4	1	BUMPER BRACKET SIDE RH REAR	\$	<i>SL</i> 135.97 <i>X</i>
5	1	BUMPER RETAINER RH REAR	\$	<i>DIY</i> 44.99 <i>✓</i>
6	1	BUMPER REFLECTOR RH	\$	<i>SL</i> 43.61 <i>X</i>
7	1	BUMPER BRACKET SIDE LH REAR	\$	<i>SL</i> 135.97 <i>X</i>
8	1	BUMPER RETAINER LH REAR	\$	<i>DIY</i> 44.99 <i>✓</i>
9	1	BUMPER REFLECTOR LH	\$	<i>SL</i> 43.61 <i>✓</i>
10	1	BUMPER BEAM REAR	\$	<i>N</i> 777.52 <i>✓</i>
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>N</i> 225.95 <i>✓</i>
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>N</i> 225.95 <i>✓</i>
13	1	BOOT REAR	\$	<i>N</i> 2,872.68 <i>✓</i>
14	1	BOOT REFLECTOR LAMP LH	\$	<i>SL</i> 493.35 <i>✓</i>
15	1	BOOT REFLECTOR LAMP RH	\$	<i>SL</i> 493.35 <i>✓</i>
16	1	FENDER PANEL INNER TRIM REAR LH	\$	<i>SL</i> 671.45 <i>✓</i>
17	1	FENDER PANEL REAR LH	\$	<i>Bu</i> 3,299.13 <i>✓</i>
18	1	WHEELARCH REAR LH	\$	<i>SL</i> 543.47 <i>X</i>
19	1	WHEEL HOUSING PANEL REAR LH	\$	<i>N</i> 4,682.09 <i>X</i>
20	1	CHASSIS PANEL REAR LH	\$	<i>N</i> 3,766.43 <i>X</i>
21	1	FENDER PANEL INNER TRIM REAR RH	\$	<i>SL</i> 671.45 <i>X</i>
22	1	FENDER PANEL REAR RH	\$	<i>Bu</i> 3,299.13 <i>✓</i>
23	1	WHEELARCH REAR RH	\$	<i>SL</i> 543.47 <i>X</i>
24	1	WHEEL HOUSING PANEL REAR RH	\$	<i>N</i> 4,682.09 <i>✓</i>
25	1	CHASSIS PANEL REAR RH	\$	<i>N</i> 3,766.43 <i>✓</i>
26	1	TAILLAMP RH	\$	<i>SL</i> 552.55 <i>✓</i>
27	1	TAILLAMP PANEL RH	\$	<i>N</i> 986.70 <i>✓</i>
28	1	TAILLAMP LH	\$	<i>SL</i> 552.55 <i>✓</i>
29	1	TAILLAMP PANEL LH	\$	<i>N</i> 986.70 <i>✓</i>
30	1	OUTER PANEL REAR (End Panel)	\$	<i>N</i> 1,471.77 <i>✓</i>

Trans-cab Auto Services Pte Ltd**AAD1906-202**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 759T

31	1	OUTER PANEL REAR (End Panel)TRIM	\$	SL	404.56	
32	1	EXHAUST REAR	\$	N	7,489.05	
33	1	EXHAUST CAP REAR	\$	N	230.49	
34	1	FUEL FLAP L70Y	\$	SL	343.57	
35	1	DOOR PANEL REAR RH	\$	N	2,844.66	
36	1	DOOR HANDLE OUTER REAR RH	\$	SL	126.49	
37	1	DOOR HANDLE CAP REAR RH	\$	SL	35.52	
38	1	DOOR HANDLE SEAL REAR RH	\$	SL	7.89	
39	1	DOOR HANDLE COVER REAR RH	\$	SL	13.22	
40	1	DOOR HANDLE MODULE REAR RH	\$	SL	133.60	
41	1	DOOR WHEATHESTRIIP REAR RH	\$	SL	410.66	
42	1	DOOR PANEL REAR LH	\$	N	2,844.66	
43	1	DOOR HANDLE OUTER REAR LH	\$	SL	126.49	
44	1	DOOR HANDLE CAP REAR LH	\$	SL	35.52	
45	1	DOOR HANDLE SEAL REAR LH	\$	SL	7.89	
46	1	DOOR HANDLE COVER REAR LH	\$	SL	13.22	
47	1	DOOR HANDLE MODULE REAR LH	\$	SL	133.60	
48	1	DOOR WHEATHESTRIIP REAR LH	\$	SL	410.66	
49	1	BUMPER COVER FRT	\$	Bu	1,259.42	
50	1	BUMPER SPOILER FRT	\$	SL	181.75	X
51	1	BUMPER ABSORBER FRT	\$	SL	394.68	X
52	1	BUMPER RETAINER FRT LH	\$	DII SL	151.41	
53	1	BUMPER SUPPORT FRT	\$	SL	123.88	
54	1	BUMPER RETAINER FRT RH	\$	SL	150.77	
55	1	BUMPER SUPPORT FRT	\$	SL	123.88	
56	1	BUMPER UNDERTRAY FRT	\$	SL	472.83	
57	1	BUMPER GRILLE LOWER FRT	\$	SL	266.80	
58	1	BUMPER FOG LAMP GRILLE LH	\$	SL	207.21	
59	1	BUMPER FOG LAMP GRILLE RH	\$	SL	207.21	
60	1	BUMPER BEAM FRT	\$	N	914.08	
61	1	TOW COVER FRT	\$	SL	28.61	
62	1	RADIATOR GRILLE	\$	SL	1,707.78	
63	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	SL	225.36	
64	1	RADIATOR GRILLE FRAME	\$	SL	1,353.75	
65	1	FRAME FULL SUPPORT PANEL	\$	SL	615.90	
66	1	FRAME FULL SUPPORT BRACKET	\$	N	89.79	
67	1	FRONT BRACE PANEL	\$	N	177.22	
68	1	HEADLAMP LH	\$	SL	1,184.43	

Trans-cab Auto Services Pte Ltd**AAD1906-202**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 759T

69	1	HEADLAMP RH	\$	<i>SL</i>	1,184.43	X
70	1	HEADLAMP PANEL FRT LH	\$	<i>N</i>	152.15	X
71	1	HEADLAMP PANEL FRT RH	\$	<i>N</i>	152.15	X
72	1	BONNET	\$	<i>SL</i>	1,941.63	✓
73	1	BONNET INSULATOR	\$	<i>SL</i>	405.73	} X
74	1	BONNET STRUT LH	\$	<i>SL</i>	88.61	
75	1	BONNET STRUT RH	\$	<i>SL</i>	88.61	
76	1	BONNET HINGE LH	\$	<i>N</i>	348.31	
77	1	BONNET HINGE RH	\$	<i>N</i>	348.31	
78	1	BONNET LOCK	\$	<i>N</i>	305.48	
79	1	BONNET CABLE	\$	<i>SL</i>	119.19	
80	1	BONNET CABLE COVER	\$	<i>SL</i>	161.03	
81	1	BONNET SEAL OUTER	\$	<i>SL</i>	92.36	} X
82	1	BONNET SEAL INNER	\$	<i>SL</i>	157.28	
83	1	FENDER PANEL FRT LH	\$	<i>SL</i>	783.83	✓
84	1	WHEELARCH FRT LH	\$	<i>SL</i>	278.84	X
85	1	FENDER BRACKET LOWER LH	\$	<i>SL</i>	15.79	X
86	1	FENDER INSULATOR LH	\$	<i>SL</i>	130.84	X
87	1	WHEEL HOUSING PANEL FRNT LH	\$	<i>N</i>	4,682.09	X
88	1	WHEEL HOUSING PANEL FRNT RH	\$	<i>N</i>	4,682.09	X
89	1	FENDER INSULATOR RH	\$	<i>SL</i>	130.84	X
90	1	FENDER PANEL FRT RH	\$	<i>SL</i>	783.83	✓
91	1	WHEELARCH FRT RH	\$	<i>SL</i>	278.84	X
92	1	FENDER BRACKET LOWER RH	\$	<i>SL</i>	15.79	X
93	1	WIPER RESERVOIR	\$	<i>SL</i>	348.25	} X
94	1	WIPER RESERVOIR NECK	\$	<i>SL</i>	136.11	
95	1	WIPER RESERVOIR MOTOR	\$	<i>SL</i>	270.06	
96	1	AIR CLEANER LOWER	\$	<i>SL</i>	271.26	
97	1	AIR CLEANER HOSE	\$	<i>SL</i>	76.14	} X
98	1	BASE BATTERY TRAY	\$	<i>SL</i>	363.40	
99	1	AIR CLEANER BOX	\$	<i>SL</i>	464.20	
100	1	SUBFRAME OUTER FRT	\$	<i>SL</i>	2,652.45	} X
101	1	SUBFRAME BRACKET OUTER LH	\$	<i>N</i>	92.36	
102	1	SUBFRAME BRACKET OUTER RH	\$	<i>N</i>	92.36	} X
103	1	LOWER ARM LH L70Y	\$	<i>SL</i>	685.76	
104	1	KNUCKLE ARM LH L70Y	\$	<i>SL</i>	846.98	
105	1	ABSORBER FRT LH L70Y	\$	<i>SL</i>	360.54	X
106	1	DRIVESHAFT LH	\$	<i>N</i>	1,747.45	X

Trans-cab Auto Services Pte Ltd**AAD1906-202**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 759T

107	1	STABILIZER BAR FRT	\$	Sh	604.65	
108	1	LOWER ARM RH L70Y	\$	Sh	685.76	X
109	1	KNUCKLE ARM RH L70Y	\$	Sh	846.98	X
110	1	ABSORBER FRT RH L70Y	\$	Sh	360.54	X
111	1	DRIVESHAFT RH	\$	Sh	1,747.45	X
112	2	STABILIZER LINK FRT	\$	Sh	117.22	X
113	1	ROCKER PANEL INNER GARNISH RH	\$	Sh	466.51	X
114	1	ROCKER PANEL INNER RH	\$	Sh	1,024.79	X
115	1	ROCKER PANEL CENTER RH	\$	Sh	990.25	
116	1	ROCKER PANEL OUTER RH	\$	Sh	1,184.99	
117	1	AUTO COMPUTER	\$	Sh	5,032.17	
118	1	INJECTION COMPUTER	\$	Sh	4,706.30	
119	1	RHD HYDRAULIC POWER(ROCK&PINION)	\$	Sh	5,154.52	
120	1	STEERING PUMP ELECTRIC L70Y	\$	Sh	2,306.90	
121	1	STEERING PINION RACK L70Y	\$	Sh	4,413.11	
122	1	DOOR PANEL FRT RH	\$	Sh	2,844.66	
123	1	DOOR HANDLE OUTER FRT RH	\$	Sh	477.76	
124	1	DOOR HANDLE COVER FRT RH	\$	Sh	13.22	
125	1	DOOR HANDLE MODULE FRT RH	\$	Sh	133.60	
127	1	DOOR WHEATHESTRIP FRONT RH	\$	Sh	410.66	
128	1	DOOR SEAL FRONT RH	\$	Sh	162.02	
129	1	DOOR MIRROR ASSY RH	\$	Sh	1,483.40	
130	1	DOOR HARNESS WIRE RH	\$	Sh	2,670.00	
131	1	DOOR PANEL FRT LH	\$	Sh	2,844.66	
132	1	DOOR HANDLE OUTER FRT LH	\$	Sh	477.76	
133	1	DOOR HANDLE COVER FRT LH	\$	Sh	13.22	
134	1	DOOR HANDLE MODULE FRT LH	\$	Sh	133.60	
135	1	DOOR WHEATHESTRIP FRONT LH	\$	Sh	410.66	
136	1	DOOR MIRROR ASSY LH	\$	Sh	1,483.40	
137	1	DOOR HARNESS WIRE LH	\$	Sh	2,670.00	
138	1	DOOR HINGE UPPER LH	\$	Sh	261.28	
139	1	DOOR HINGE LOWER LH	\$	Sh	300.55	
140	1	DOOR CHECK FRT LH	\$	Sh	194.77	
141	1	DOOR LOCK FRT LH	\$	Sh	908.75	
142	1	DOOR CATCH FRT LH	\$	Sh	131.23	

TOTAL	\$	136,855.38
10%	\$	13,685.54
	\$	123,169.84

Trans-cab Auto Services Pte Ltd**AAD1906-202**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 759T**Special Nett**

1	1SET PARKING AID	\$	Sh	700.00	X
2	1SET REAR BUMPER CLIP	\$	na	66.00	✓
3	1SET BUMPER BRACKET CTR CLIP	\$	na	33.00	✓
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	} X
5	1SET BUMPER RETAINER RH CLIP RR	\$	na	20.00	
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	
7	1SET BUMPER RETAINER CLIP LH RR	\$	na	20.00	
8	1SET BUMPER LOWER REAR RIVET	\$	na	22.00	
9	1SET BUMPER LOWER REAR CLIP	\$	na	66.00	
10	1 EXHAUST MOUNTING REAR	\$	Sh	17.82	
11	1SET FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	
12	1SET FENDER WHEELARCH REAR LH CLIP	\$	na	35.00	
13	1 FENDER INNER TRIM CLIP LH	\$	na	28.00	
14	1 FENDER INNER TRIM CLIP RH	\$	na	28.00	
15	1 TAILLAMP CLIP RH	\$	na	5.00	} X
16	1 TAILLAMP CLIP LH	\$	na	5.00	
17	2 REAR WINDSCREEN SEALANT	\$	na	80.00	40.00
18	1 WINDSCREEN MOULDING	\$	na	100.00	✓
19	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	30.00
20	1SET RADIATOR GRILLE FRAME CLIP	\$	na	52.00	X
21	1SET BUMPER CLIP FRT	\$	na	66.00	✓
22	1 BUMPER BRACKET CLIP FRT LH	\$	na	12.00	} X
23	1 BUMPER SUPPORT CLIP FRT LH	\$	na	10.50	
24	1 BUMPER BRACKET CLIP FRT RH	\$	na	12.00	
25	1 BUMPER SUPPORT CLIP FRT RH	\$	na	10.50	
26	1SET RADIATOR GRILLE SCREW	\$	Sh	16.00	
27	1SET BUMPER GRILLE LOWER CLIP	\$	na	69.00	
28	1SET FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00	
29	2 FRAME FULL SUPPORT PANEL NUT	\$	na	20.00	
30	1 FRONT LEFT TYRE	\$	Sh	330.00	
31	1 FRONT LEFT TYRE RIM	\$	Sh	380.00	
32	2 FRAME FULL SUPPORT PANEL STUD	\$	Sh	30.00	} X
33	1 Windscreen moulding	\$	na	100.00	
34	1 FRONT WINDSCREEN SEALANT	\$	na	253.80	
35	1 FRONT WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
36	1SET Front licence plate with holder	\$	Sh	80.00	
37	1 WHEELARCH CLIP FRT LH	\$	na	30.50	

Trans-cab Auto Services Pte Ltd**AAD1906-202**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 759T

38	1	WHEELARCH CLIP FRT RH	\$	na	30.50	}	X
39	2	BONNET STRUT L70Y	\$	na	88.61		
40	6	BONNET INSULATOR CLIP L70Y	\$	na	7.30		
41	2	BONNET CABLE COVER SCREW L70Y	\$	na	10.85		
42	2	BONNET CABLE CLIP L70Y	\$	na	6.31		
43	1	REAR LEFT TYRE	\$	sn	330.00	}	X
44	1	REAR LEFT TYRE RIM	\$	sn	380.00		
45	1	FRONT RIGHT TYRE	\$	sn	330.00		
46	1	FRONT RIGHT TYRE RIM	\$	sn	380.00		
47	1	REAR RIGHT TYRE	\$	sn	330.00		
48	1	REAR RIGHT TYRE RIM	\$	sn	380.00	}	X
49	1	REAR RH DOOR STICKER '6555-3333'	\$	na	80.00		
50	1	REAR LH DOOR STICKER '6555-3333'	\$	na	80.00		
51	1	FRONT LH DOOR STICKER 'Trans-Cab'	\$	na	80.00		
52	1	FRONT LH DOOR STICKER 'Classic'	\$	na	80.00		
53	1	FRONT RH DOOR STICKER 'Trans-Cab'	\$	na	80.00	}	X
54	1	FRONT RH DOOR STICKER 'Classic'	\$	na	80.00		
55	1	DOOR CHECK BOLT	\$	sn	22.69		
56	1	DOOR GUIDE SCREW	\$	sn	10.85		
57	1	DOOR HINGE BOLT	\$	sn	10.85		
58	1	DOOR HINGE NUT LH	\$	sn	14.60	}	X
59	1	DOOR CHECK NUT	\$	sn	3.75		
60	1	DOOR LOCK SCREW L70Y	\$	sn	6.12		
61	1	DOOR CATCH SCREW L70Y	\$	sn	10.06		

TOTAL	\$	5,855.63
--------------	-----------	-----------------

TOTAL PARTS	\$	129,025.47
--------------------	-----------	-------------------

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	7,500.00	242d
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	7,500.00	160d
To Rust-Proofing Of The Affected Areas.	\$	170.00	15d
To reinstall rear bumper parking sensor.	\$	170.00	60d

Trans-cab Auto Services Pte Ltd**AAD1906-202**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 759T

	To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	380.00	601
55	To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	170.00 X
56	To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	170.00 X
	To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	170.00 X
	To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00	1001
	To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	1201
	Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	380.00 X
	Towing Fees.	\$	150.00	501
	To repair and realign rear exhaust pipe.	\$	170.00	170.00 X
	To Check Electrical Lighting Concerned.	\$	170.00	401
	To check steering geometry and computer wheel alignment	\$	220.00	601
	To apply paint protection system (PPS) maintain and enhancement	\$	380.00	380.00 X
	To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	380.00 X
	To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	340.00	340.00 X

Trans-cab Auto Services Pte Ltd**AAD1906-202**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 759T

To transfer of front bumper fittings, attachment and perform water seepage test.	\$	na	180.00	X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	na	380.00	X
To transfer of tire, rim and on wheel balancing.	\$		170.00	2a
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	na	180.00	X
To remove and refit air bag system and reset vehicle warning indicators.	\$	na	480.00	X
To transfer of front windscreen fittings and conduct water seepage test.	\$	na	170.00	X
To transfer of front bonnet fittings, attachment and perform water seepage test.	\$	na	180.00	X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$		380.00	X
To transfer of Front Door fittings, attachment and perform water seepage test.	\$		360.00	6a
To check ABS and brake efficiency, final checking and testing.	\$		380.00	X
To transfer of Rear Door fittings, attachment and perform water seepage test.	\$	na	360.00	X

TOTAL \$ 22,190.00**Over All Total \$ 151,215.47****Repair Days (PART BY PART)****30 DAYS****16 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: