

ASS. REC. BY:

REF: CS/AG119011150/kvcl3n2

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Ivy Rattila

of AGI

Date/Time: 25.6.19 8.57a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHF 759T

Insured: SJX 884X

at Workshop m/s Trans Cab

Tel: 62876666

of 70 2 Ave Strut 63

Policy No:

Claim No: C 10013319

Sum Insured:

Excess:

Make of Veh:

D.O.A. 21.6.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 25.6.19 11.51a.m

Person Contacted: Amanda

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SJX 884X : CC4/AG13021070/T1523W2 D.O.A : 07/11/2013

SHF 759T : CC3/AG18009002/K4223 D.O.A : 12/05/2018

26/6/19

Email preli revised to Ivy

ASS. REC. BY:

REF:

AG21

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

16

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHF 7597

Yr Regn:

06, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Perant Lotitok

c.c

1995

Colour

M. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

337283

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VIFI ABC 15AUC 28336P

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: M / S / R / Im / STD A / R / Im or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

R/Bal.

8

mm

Rear

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

21/6/19

D.O.I.

25/6/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt, O/S Rear, N/S Rear &amp; N/S Roof

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

File pass to

4/9/19

11 Rpm @ 14, 150k (Red 137, 065.47, 9190)

RECEIVED 04 SEP 2019

Date/Time, File Pass to?

☐

Prell. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 4/9- typist

Days Of Repair:

16

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS \$

Fees

Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format:

TP

Lump Sum / I.B.I. (\$

14, 150/2

450



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: C10003319

Our ref: CS/AGI19011150/Kvd3

Date: 26/6/2019

The Motor Claims Department  
M/s AUTO & GENERAL INSURANCE (S) PTE LTD  
(BUDGET DIRECT INSURANCE)

Dear Sir

**PRELIMINARY ADVICE OF VEHICLE NO. SHF 759T**

We thank you for your instruction on 25/6/2019


Please be informed that we had conducted the inspection of the above mentioned vehicle on 25/6/2019 at the premises of M/s TRANS-CAB SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$	151,215.47
Revised Estimate Amount	: S\$	17,681.36
"Check" Items Amount	: S\$	3,787.90
Market Value	: S\$	
LTA Reimbursement Value	: S\$	
Nett Value	: S\$	

**Description of Damage:**

The vehicle sustained damages at the o/s rear, o/s front, n/s rear and n/s front portion

**Comments/Present Status:**  
Damages Consistent



Yours faithfully,

Kenneth Kong  
Licensed Appraiser

**Veron Chen (LKKAUTO)**

---

**From:** Ng Wai Yin <waiyin.ng@transcab.com.sg>  
**Sent:** Wednesday, 10 July 2019 5:31 PM  
**To:** Veron Chen (LKKAUTO)  
**Subject:** <Book Value> TCS REF: AAD1906-202--Accident involving SJX884X & SHF0759T on 21.06.19

WITHOUT PREJUDICE

Dear Veron

Refer to our tele-conversation.

Book Value amount \$ 59,647.51.

Thank You  
Best Regards,  
**Ng Wai Yin**  
Finance Department  
TEL: 6603 1265 Ext.308

**\*\*\* Please be reminded that all claims correspondence to be send to [claims@transcab.com.sg](mailto:claims@transcab.com.sg)**



**TRANS-CAB SERVICES PTE LTD**

No. 2 Ang Mo Kio Street 63, Singapore 569111  
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764  
Website: [www.transcab.com.sg](http://www.transcab.com.sg)

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

## Veron Chen (LKKAuto)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Wednesday, 26 June 2019 1:56 PM  
**To:** 'Ivy Ratilla'  
**Cc:** SUR; 'Albert Hong'  
**Subject:** RE: TPPD Survey: Claim ref:C10003319/AH || OI- SJX884X (White) TP- SHF759T || Est: \$151215.47 || Transcab  
**Attachments:** SHF 759T PRELI ADVISED.pdf

Dear Ivy,

Enclosed preliminary revised of vehicle SHF 759T  
Date of survey: 25/6/2019  
Number of days : 16 days

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Tuesday, 25 June 2019 11:49 AM  
**To:** 'Ivy Ratilla' <ivy.r@budgetdirect.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** SUR <sur@lkkauto.com>; 'Albert Hong' <albert.hong@budgetdirect.com.sg>  
**Subject:** RE: TPPD Survey: Claim ref:C10003319/AH || OI- SJX884X (White) TP- SHF759T || Est: \$151215.47 || Transcab

Dear Sir / Mdm,

Thank you for the assignment.

Best Regards,

**Summer Lee** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Ivy Ratilla [<mailto:ivy.r@budgetdirect.com.sg>]  
**Sent:** Tuesday, 25 June, 2019 8:51 AM  
**To:** Admin-D (LKKAuto) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>; Albert Hong <[albert.hong@budgetdirect.com.sg](mailto:albert.hong@budgetdirect.com.sg)>  
**Subject:** TPPD Survey: Claim ref:C10003319/AH || OI- SJX884X (White) TP- SHF759T || Est: \$151215.47 || Transcab  
**Importance:** High

Hi Team,

Good morning.

We would like to arrange TP Survey for SHF759T. Please see below email for reference.

Kindly confirm.

Regards,

**Ivy**  
Admin Executive, Claims

T +65 6540 2185

F +65 6725 0853

E [ivy.r@budgetdirect.com.sg](mailto:ivy.r@budgetdirect.com.sg)



**Customer Care** +65 6221 2111

**Claims** +65 6221 2199

**Claims (Int.)** +65 6540 2199

190 Clemenceau Avenue, #03-01  
Singapore Shopping Centre  
Singapore  
239924  
[budgetdirect.com.sg](http://budgetdirect.com.sg)

auto  general

Auto & General Insurance (Singapore) Pte. Limited (Co. Reg. No. 201626103G) trading as **Budget Direct Insurance**.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

---

**From:** Julie Mangubat <[julie.m@budgetdirect.com.sg](mailto:julie.m@budgetdirect.com.sg)>

**Sent:** Monday, 24 June 2019 5:30 PM

**To:** Claims <[claims@budgetdirect.com.sg](mailto:claims@budgetdirect.com.sg)>; 'Amanda Tay' <[amanda.tay@transcab.com.sg](mailto:amanda.tay@transcab.com.sg)>

**Cc:** Albert Hong <[albert.hong@budgetdirect.com.sg](mailto:albert.hong@budgetdirect.com.sg)>

**Subject:** FW: Arrange for survey for SHF759T

**Importance:** High

Hi Amana

Moving forward please send ALL survey request to [claims@budgetdirect.com.sg](mailto:claims@budgetdirect.com.sg)

@Claims – hi Ivy, please help to arrange.

Thank you,  
-Julie

---

**From:** Amanda Tay <[amanda.tay@transcab.com.sg](mailto:amanda.tay@transcab.com.sg)>

**Sent:** Monday, 24 June, 2019 4:59 PM

**To:** Lincoln Yeo <[lincoln.yeo@budgetdirect.com.sg](mailto:lincoln.yeo@budgetdirect.com.sg)>; Albert Hong <[albert.hong@budgetdirect.com.sg](mailto:albert.hong@budgetdirect.com.sg)>; Julie Mangubat <[julie.m@budgetdirect.com.sg](mailto:julie.m@budgetdirect.com.sg)>

**Cc:** 'Candy Kong' <[candy.kong@transcab.com.sg](mailto:candy.kong@transcab.com.sg)>

**Subject:** Arrange for survey for SHF759T

Dear all

PLS ARRANGE LKK AUTO CONSULTANTS PTE LTD TO SURVEY.

Please arrange for survey as below :

SJX884X - 21.06.2019 at 1350Hrs – SHF759T

Lunch time : 12pm - 1pm.

Kindly pls dun arrange survey during lunch time. Vehicle in workshop.

"We Agree to let your In-house surveyor assess/ survey our vehicle with estimate."

*Thks & Rdgs*  
*Amanda Tay*  
*Claims Service Assistant*



**TRANS-CAB SERVICES PTE LTD**

No. 2 Ang Mo Kio Street 63, Singapore 569111

Main Line : (65) 6287 6666 Fax Line: (65) 6257 1330

Website: [www.transcab.com.sg](http://www.transcab.com.sg)

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

## Nivitha (LKK Auto)

---

**From:** Ivy Ratilla <ivy.r@budgetdirect.com.sg>  
**Sent:** Tuesday, 25 June 2019 8:51 AM  
**To:** Admin-D (LKKAuto)  
**Cc:** SUR; Albert Hong  
**Subject:** TPPD Survey: Claim ref:C10003319/AH || OI- SJX884X (White) TP- SHF759T || Est: \$151215.47 || Transcab  
**Attachments:** image001.wmz; img-624164201.pdf  
**Importance:** High

Hi Team,

Good morning.

We would like to arrange TP Survey for SHF759T. Please see below email for reference.

Kindly confirm.

Regards,

Ivy  
Admin Executive, Claims

T +65 6540 2185  
F +65 6725 0853  
E ivy.r@budgetdirect.com.sg



**Customer Care** +65 6221 2111  
**Claims** +65 6221 2199  
**Claims (Int.)** +65 6540 2199

190 Clemenceau Avenue, #03-01  
Singapore Shopping Centre  
Singapore  
239924  
[budgetdirect.com.sg](http://budgetdirect.com.sg)

auto  general

Auto & General Insurance (Singapore) Pte. Limited (Co. Reg. No. 201626103G) trading as **Budget Direct Insurance**.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.



This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

---

**From:** Julie Mangubat <julie.m@budgetdirect.com.sg>  
**Sent:** Monday, 24 June 2019 5:30 PM  
**To:** Claims <claims@budgetdirect.com.sg>; 'Amanda Tay' <amanda.tay@transcab.com.sg>  
**Cc:** Albert Hong <albert.hong@budgetdirect.com.sg>  
**Subject:** FW: Arrange for survey for SHF759T  
**Importance:** High

Hi Amana

Moving forward please send ALL survey request to [claims@budgetdirect.com.sg](mailto:claims@budgetdirect.com.sg)

@Claims – hi Ivy, please help to arrange.

Thank you,  
-Julie

---

**From:** Amanda Tay <[amanda.tay@transcab.com.sg](mailto:amanda.tay@transcab.com.sg)>  
**Sent:** Monday, 24 June, 2019 4:59 PM  
**To:** Lincoln Yeo <[lincoln.yeo@budgetdirect.com.sg](mailto:lincoln.yeo@budgetdirect.com.sg)>; Albert Hong <[albert.hong@budgetdirect.com.sg](mailto:albert.hong@budgetdirect.com.sg)>; Julie Mangubat <[julie.m@budgetdirect.com.sg](mailto:julie.m@budgetdirect.com.sg)>  
**Cc:** 'Candy Kong' <[candy.kong@transcab.com.sg](mailto:candy.kong@transcab.com.sg)>  
**Subject:** Arrange for survey for SHF759T

Dear all

PLS ARRANGE LKK AUTO CONSULTANTS PTE LTD TO SURVEY.

Please arrange for survey as below :

SJX884X - 21.06.2019 at 1350Hrs – SHF759T

Lunch time : 12pm - 1pm.

Kindly pls dun arrange survey during lunch time. Vehicle in workshop.

"We Agree to let your In-house surveyor assess/ survey our vehicle with estimate."

*Thks & Rds*  
*Amanda Tay*  
*Claims Service Assistant*



**TRANS-CAB SERVICES PTE LTD**

No. 2 Ang Mo Kio Street 63, Singapore 569111

Main Line : (65) 6287 6666 Fax Line: (65) 6257 1330

Website: [www.transcab.com.sg](http://www.transcab.com.sg)

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.



This email has been checked for viruses by AVG antivirus software.

[www.avg.com](http://www.avg.com)

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

**Veron Chen (LKKAuto)**

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Wednesday, 4 September 2019 9:41 AM  
**To:** Ng Wai Yin; calvin.er@transcab.com.sg  
**Cc:** jasminetan@transcab.com.sg; SUR  
**Subject:** SHF 759T-DOA: 21/6/2019  
**Attachments:** MARK EST.pdf

Dear Wai Yin/Calvin,

WITHOUT PREJUDICE

Lump Sum \$14,150 before GST @ 16 working days

Please provides us after paint photos.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

**Vehicle Details**

Vehicle No.:	SHF759T
Vehicle to be Exported:	Yes
Intended Deregistration Date:	21 Jun 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C003269
Chassis No.:	VF1ABL15AUC283369
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	30 Jun 2016
First Registration Date:	30 Jun 2016
Transfer Count:	0
Actual ARF Paid:	\$19,998.00

**Intended PARF Rebate Details**

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Jun 2024
PARF Rebate Amount:	\$14,998.00

**Intended COE Rebate Details**

COE Expiry Date:	29 Jun 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$37,164.00
COE Rebate Amount:	\$23,330.00
<b>Total Rebate Amount:</b>	<b>\$38,328.00</b>

**Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 21 Jun 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	21/06/2019 17:51
Date Of Accident	21/06/2019 13:50
Exact Location Of Accident	EAST COAST PARKWAY
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SHF759T
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666
<b>Vehicle Particulars</b>	
Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
<b>Insurance Company</b>	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	
<b>Driver</b>	
Name of Driver	LYE POH WAH
NRIC No	S1200743D
Date Of Birth	01/01/1956
Occupation	OUTDOOR
Date Of Driving Pass	17/05/1997
Driving Experience	22 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-98592433
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 257 YISHUN RING RD #05-1027
Postcode	760257
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	4
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 2	NAME: : UNKNOWN GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	ANG MO KIO NORTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 51 ANG MO KIO AVE 9 , POSTCODE: 569784 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4849999 - FAX NO: 62181399
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

Please see the attach Police Report T/20190621/2117.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJX884X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	

NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number PA7277C  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category GOODS VEHICLE  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SJQ9218Y  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### DETAILS OF INJURED PERSON 1

Name UNKNOWN  
Approximate Age  
Injuries Sustain  
Injured person in which vehicle? PA7277C  
Were seat belts worn?  
Was this injured conveyed to hospital by ambulance?  
Address  
Postcode

Sketch Plan Pg. 1

**SKETCH PLAN**


**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

  
\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NIC/FIN No.:



# Sketch Plan #2 Pg. 1

## SKETCH PLAN

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

PEAP See attach police report

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Amanda  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



**SINGAPORE  
POLICE FORCE**



T/20190621/2117

Police Station Of Origin:  
Ang Mo Kio North N.P.C  
51 Ang Mo Kio Avenue 9 SINGAPORE  
569784  
Tel No: 1800-4849999

3 of 3




Report No. T/20190621/2117

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F / Sgt 1 LEE CHING HAO NICHOLAS 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 21/06/2019 17:38
Officer In Charge Of Case: TP / GIT / Sr Staff Sgt NOR HIDAYU BINTE ABDUL SAMAD  Contact No.: 65476423	Classification Of Case:
Authentication Stamp NP158	

## Police Report Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20190621/2117

Police Station Of Origin:  
Ang Mo Kio North N.P.C  
51 Ang Mo Kio Avenue 9 SINGAPORE  
569784  
Tel No: 1800-4849999

1 of 3

Report No. T/20190621/2117

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 21/06/2019 17:38	Vide Report No.: G/20190621/0095	Station Diary No.: 65
--	-------------------------------------	--------------------------

## Informant's Particulars

Name of Informant: LYE POH WAH			Address: APT BLK 507A YISHUN AVENUE 4 #03-100 SINGAPORE 761507		
ID Type / ID No.: NRIC NO / S1200743D			Contact No.: Home/Office: Mobile: 98592433		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 63	Date of Birth: 01/01/1956	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 3 Date of Expiry:		

## General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 21/06/2019 13:50	Type of Location: Roundabout
Location: Along Road 1 EAST COAST PARKWAY  TOWARDS TOWN				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: Yes

## Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
PA7277C	Van	TOYOTA		Silver	Slightly Damaged	0
SHF759T	Car	RENAULT		Red	Slightly Damaged	2
SJQ9218Y	Car	KIA		Blue	Slightly Damaged	2
SJX884X	Car	MERCEDES BENZ		White	Slightly Damaged	0



**SINGAPORE  
POLICE FORCE**



T/20190621/2117

2 of 3

Report No. T/20190621/2117

Police Station Of Origin:  
Ang Mo Kio North N.P.C  
51 Ang Mo Kio Avenue 9 SINGAPORE  
569784  
Tel No: 1800-4849999

**CONTINUATION OF REPORT**

**Brief Details.**

On 21/06/2019 at about 1350hrs. I was driving taxi, plate: SHF 759T along east coast parkway towards town. I was driving along second lane, there a Mercedes, plate SJX884X driving along the extreme right lane. However, out of sudden I heard some noise from the right side as I thought I had hit on something. I steered my taxi towards the left side. Resulting my vehicle knocking onto a van, plate: PA7277C from my left side. A KIA, plate SJQ9218Y knocked onto the back of the van. Traffic Police was at scene and issued me a case card: G/20190621/0095. The driver of the van was conveyed by the ambulance to hospital.

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHF 759T****AAD1906-202***Not Not hash*  
*61 Pnp 814,150k*

25 JUL 2019

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

**SHF 759T**

VF1ABL15AUC283369

RENAULT

LATITUDE

21.6.19

**AUTO & GENERAL**

30/6/2016

		PART			LIST
1	1	BUMPER COVER REAR	\$	Bu	1,108.46 ✓
2	1	BUMPER LOWER REAR	\$	SL	768.84 X
3	1	BUMPER BRACKET CTR REAR	\$	SL	113.47 X
4	1	BUMPER BRACKET SIDE RH REAR	\$	SL	135.97 X
5	1	BUMPER RETAINER RH REAR	\$	DI	44.99 ✓
6	1	BUMPER REFLECTOR RH	\$	SL	43.61 X
7	1	BUMPER BRACKET SIDE LH REAR	\$	SL	135.97 X
8	1	BUMPER RETAINER LH REAR	\$	DI	44.99 ✓
9	1	BUMPER REFLECTOR LH	\$	SL	43.61
10	1	BUMPER BEAM REAR	\$	N	777.52
11	1	BUMPER BEAM BRACKET LH REAR	\$	N	225.95
12	1	BUMPER BEAM BRACKET RH REAR	\$	N	225.95
13	1	BOOT REAR	\$	N	2,872.68
14	1	BOOT REFLECTOR LAMP LH	\$	SL	493.35
15	1	BOOT REFLECTOR LAMP RH	\$	SL	493.35
16	1	FENDER PANEL INNER TRIM REAR LH	\$	SL	671.45
17	1	FENDER PANEL REAR LH	\$	B	3,299.13 ✓
18	1	WHEELARCH REAR LH	\$	SL	543.47 X
19	1	WHEEL HOUSING PANEL REAR LH	\$	N	4,682.09 X
20	1	CHASSIS PANEL REAR LH	\$	N	3,766.43 X
21	1	FENDER PANEL INNER TRIM REAR RH	\$	SL	671.45 X
22	1	FENDER PANEL REAR RH	\$	B	3,299.13 ✓
23	1	WHEELARCH REAR RH	\$	SL	543.47 X
24	1	WHEEL HOUSING PANEL REAR RH	\$	N	4,682.09
25	1	CHASSIS PANEL REAR RH	\$	N	3,766.43
26	1	TAILLAMP RH	\$	SL	552.55
27	1	TAILLAMP PANEL RH	\$	N	986.70
28	1	TAILLAMP LH	\$	SL	552.55
29	1	TAILLAMP PANEL LH	\$	N	986.70
30	1	OUTER PANEL REAR (End Panel)	\$	N	1,471.77

**Trans-cab Auto Services Pte Ltd****AAD1906-202**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHF 759T**

31	1	OUTER PANEL REAR (End Panel)TRIM	\$	PH	404.56	
32	1	EXHAUST REAR	\$	N	7,489.05	
33	1	EXHAUST CAP REAR	\$	N	230.49	
34	1	FUEL FLAP L70Y	\$	SL	343.57	
35	1	DOOR PANEL REAR RH	\$	N	2,844.66	
36	1	DOOR HANDLE OUTER REAR RH	\$	SL	126.49	
37	1	DOOR HANDLE CAP REAR RH	\$	SL	35.52	
38	1	DOOR HANDLE SEAL REAR RH	\$	SL	7.89	
39	1	DOOR HANDLE COVER REAR RH	\$	SL	13.22	
40	1	DOOR HANDLE MODULE REAR RH	\$	SL	133.60	
41	1	DOOR WHEATHESTRIP REAR RH	\$	SL	410.66	
42	1	DOOR PANEL REAR LH	\$	N	2,844.66	
43	1	DOOR HANDLE OUTER REAR LH	\$	SL	126.49	
44	1	DOOR HANDLE CAP REAR LH	\$	SL	35.52	
45	1	DOOR HANDLE SEAL REAR LH	\$	SL	7.89	
46	1	DOOR HANDLE COVER REAR LH	\$	SL	13.22	
47	1	DOOR HANDLE MODULE REAR LH	\$	SL	133.60	
48	1	DOOR WHEATHESTRIP REAR LH	\$	SL	410.66	
49	1	BUMPER COVER FRT	\$	Bu	1,259.42	✓
50	1	BUMPER SPOILER FRT	\$	SL	181.75	X
51	1	BUMPER ABSORBER FRT	\$	SL	394.68	X
52	1	BUMPER RETAINER FRT LH	\$	D/I SL	151.41	✓
53	1	BUMPER SUPPORT FRT	\$	SL	123.88	
54	1	BUMPER RETAINER FRT RH	\$	SL	150.77	
55	1	BUMPER SUPPORT FRT	\$	SL	123.88	
56	1	BUMPER UNDERTRAY FRT	\$	SL	472.83	
57	1	BUMPER GRILLE LOWER FRT	\$	SL	266.80	
58	1	BUMPER FOG LAMP GRILLE LH	\$	SL	207.21	
59	1	BUMPER FOG LAMP GRILLE RH	\$	SL	207.21	
60	1	BUMPER BEAM FRT	\$	N	914.08	
61	1	TOW COVER FRT	\$	SL	28.61	
62	1	RADIATOR GRILLE	\$	SL	1,707.78	
63	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	SL	225.36	
64	1	RADIATOR GRILLE FRAME	\$	SL	1,353.75	
65	1	FRAME FULL SUPPORT PANEL	\$	SL	615.90	
66	1	FRAME FULL SUPPORT BRACKET	\$	N	89.79	
67	1	FRONT BRACE PANEL	\$	N	177.22	
68	1	HEADLAMP LH	\$	SL	1,184.43	

**Trans-cab Auto Services Pte Ltd****AAD1906-202**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHF 759T**

69	1	HEADLAMP RH	\$	1,184.43 X
70	1	HEADLAMP PANEL FRT LH	\$	152.15 X
71	1	HEADLAMP PANEL FRT RH	\$	152.15 X
72	1	BONNET	\$	1,941.63 ✓
73	1	BONNET INSULATOR	\$	405.73
74	1	BONNET STRUT LH	\$	88.61
75	1	BONNET STRUT RH	\$	88.61
76	1	BONNET HINGE LH	\$	348.31
77	1	BONNET HINGE RH	\$	348.31
78	1	BONNET LOCK	\$	305.48
79	1	BONNET CABLE	\$	119.19
80	1	BONNET CABLE COVER	\$	161.03
81	1	BONNET SEAL OUTER	\$	92.36
82	1	BONNET SEAL INNER	\$	157.28
83	1	FENDER PANEL FRT LH	\$	783.83 ✓
84	1	WHEELARCH FRT LH	\$	278.84 X
85	1	FENDER BRACKET LOWER LH	\$	15.79 X
86	1	FENDER INSULATOR LH	\$	130.84 X
87	1	WHEEL HOUSING PANEL FRNT LH	\$	4,682.09 X
88	1	WHEEL HOUSING PANEL FRNT RH	\$	4,682.09 X
89	1	FENDER INSULATOR RH	\$	130.84 X
90	1	FENDER PANEL FRT RH	\$	783.83 ✓
91	1	WHEELARCH FRT RH	\$	278.84 X
92	1	FENDER BRACKET LOWER RH	\$	15.79 X
93	1	WIPER RESERVOIR	\$	348.25
94	1	WIPER RESERVOIR NECK	\$	136.11
95	1	WIPER RESERVOIR MOTOR	\$	270.06
96	1	AIR CLEANER LOWER	\$	271.26
97	1	AIR CLEANER HOSE	\$	76.14
98	1	BASE BATTERY TRAY	\$	363.40
99	1	AIR CLEANER BOX	\$	464.20
100	1	SUBFRAME OUTER FRT	\$	2,652.45
101	1	SUBFRAME BRACKET OUTER LH	\$	92.36
102	1	SUBFRAME BRACKET OUTER RH	\$	92.36
103	1	LOWER ARM LH L70Y	\$	685.76 X
104	1	KNUCKLE ARM LH L70Y	\$	846.98 X
105	1	ABSORBER FRT LH L70Y	\$	360.54 X
106	1	DRIVESHAFT LH	\$	1,747.45 X

**Trans-cab Auto Services Pte Ltd**

AAD1906-202

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHF 759T**

107	1	STABILIZER BAR FRT	\$	SL	604.65	
108	1	LOWER ARM RH L70Y	\$	SL	685.76	X
109	1	KNUCKLE ARM RH L70Y	\$	SL	846.98	X
110	1	ABSORBER FRT RH L70Y	\$	SL	360.54	X
111	1	DRIVESHAFT RH	\$	SL	1,747.45	X
112	2	STABILIZER LINK FRT	\$	SL	117.22	X
113	1	ROCKER PANEL INNER GARNISH RH	\$	SL	466.51	X
114	1	ROCKER PANEL INNER RH	\$	SL	1,024.79	X
115	1	ROCKER PANEL CENTER RH	\$	SL	990.25	✓
116	1	ROCKER PANEL OUTER RH	\$	SL	1,184.99	
117	1	AUTO COMPUTER	\$	SL	5,032.17	
118	1	INJECTION COMPUTER	\$	SL	4,706.30	
119	1	RHD HYDRAULIC POWER(ROCK&PINION)	\$	SL	5,154.52	
120	1	STEERING PUMP ELECTRIC L70Y	\$	SL	2,306.90	
121	1	STEERING PINION RACK L70Y	\$	SL	4,413.11	
122	1	DOOR PANEL FRT RH	\$	SL	2,844.66	
123	1	DOOR HANDLE OUTER FRT RH	\$	SL	477.76	
124	1	DOOR HANDLE COVER FRT RH	\$	SL	13.22	
125	1	DOOR HANDLE MODULE FRT RH	\$	SL	133.60	
127	1	DOOR WHEATHESTRIP FRONT RH	\$	SL	410.66	
128	1	DOOR SEAL FRONT RH	\$	SL	162.02	
129	1	DOOR MIRROR ASSY RH	\$	SL	1,483.40	
130	1	DOOR HARNESS WIRE RH	\$	SL	2,670.00	
131	1	DOOR PANEL FRT LH	\$	SL	2,844.66	
132	1	DOOR HANDLE OUTER FRT LH	\$	SL	477.76	
133	1	DOOR HANDLE COVER FRT LH	\$	SL	13.22	
134	1	DOOR HANDLE MODULE FRT LH	\$	SL	133.60	
135	1	DOOR WHEATHESTRIP FRONT LH	\$	SL	410.66	
136	1	DOOR MIRROR ASSY LH	\$	SL	1,483.40	
137	1	DOOR HARNESS WIRE LH	\$	SL	2,670.00	
138	1	DOOR HINGE UPPER LH	\$	SL	261.28	
139	1	DOOR HINGE LOWER LH	\$	SL	300.55	
140	1	DOOR CHECK FRT LH	\$	SL	194.77	
141	1	DOOR LOCK FRT LH	\$	SL	908.75	
142	1	DOOR CATCH FRT LH	\$	SL	131.23	

**TOTAL \$ 136,855.38****10% \$ 13,685.54****\$ 123,169.84**

80



**Trans-cab Auto Services Pte Ltd**

AAD1906-202

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 759T

**Special Nett**

1	1SET PARKING AID	\$	Sh	700.00	X
2	1SET REAR BUMPER CLIP	\$	na	66.00	✓
3	1SET BUMPER BRACKET CTR CLIP	\$	na	33.00	✓
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	} X
5	1SET BUMPER RETAINER RH CLIP RR	\$	na	20.00	
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	
7	1SET BUMPER RETAINER CLIP LH RR	\$	na	20.00	
8	1SET BUMPER LOWER REAR RIVET	\$	na	22.00	
9	1SET BUMPER LOWER REAR CLIP	\$	na	66.00	
10	1 EXHAUST MOUNTING REAR	\$	Sh	17.82	
11	1SET FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	
12	1SET FENDER WHEELARCH REAR LH CLIP	\$	na	35.00	
13	1 FENDER INNER TRIM CLIP LH	\$	na	28.00	
14	1 FENDER INNER TRIM CLIP RH	\$	na	28.00	
15	1 TAILLAMP CLIP RH	\$	na	5.00	}
16	1 TAILLAMP CLIP LH	\$	na	5.00	
17	2 REAR WINDSCREEN SEALANT	\$	na	80.00	40.00
18	1 WINDSCREEN MOULDING	\$	na	100.00	✓
19	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	30.00
20	1SET RADIATOR GRILLE FRAME CLIP	\$	na	52.00	X
21	1SET BUMPER CLIP FRT	\$	na	66.00	✓
22	1 BUMPER BRACKET CLIP FRT LH	\$	na	12.00	} X
23	1 BUMPER SUPPORT CLIP FRT LH	\$	na	10.50	
24	1 BUMPER BRACKET CLIP FRT RH	\$	na	12.00	
25	1 BUMPER SUPPORT CLIP FRT RH	\$	na	10.50	
26	1SET RADIATOR GRILLE SCREW	\$	Sh	16.00	
27	1SET BUMPER GRILLE LOWER CLIP	\$	na	69.00	
28	1SET FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00	
29	2 FRAME FULL SUPPORT PANEL NUT	\$	na	20.00	
30	1 FRONT LEFT TYRE	\$	Sh	330.00	
31	1 FRONT LEFT TYRE RIM	\$	Sh	380.00	
32	2 FRAME FULL SUPPORT PANEL STUD	\$	Sh	30.00	}
33	1 Windscreen moulding	\$	na	100.00	
34	1 FRONT WINDSCREEN SEALANT	\$	na	253.80	
35	1 FRONT WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
36	1SET Front licence plate with holder	\$	Sh	80.00	
37	1 WHEELARCH CLIP FRT LH	\$	na	30.50	

**Trans-cab Auto Services Pte Ltd**

AAD1906-202

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHF 759T**

38	1	WHEELARCH CLIP FRT RH	\$	nn	30.50	
39	2	BONNET STRUT L70Y	\$	nn	88.61	
40	6	BONNET INSULATOR CLIP L70Y	\$	nn	7.30	
41	2	BONNET CABLE COVER SCREW L70Y	\$	nn	10.85	
42	2	BONNET CABLE CLIP L70Y	\$	nn	6.31	
43	1	REAR LEFT TYRE	\$	sn	330.00	
44	1	REAR LEFT TYRE RIM	\$	sn	380.00	
45	1	FRONT RIGHT TYRE	\$	sn	330.00	
46	1	FRONT RIGHT TYRE RIM	\$	sn	380.00	
47	1	REAR RIGHT TYRE	\$	sn	330.00	
48	1	REAR RIGHT TYRE RIM	\$	sn	380.00	
49	1	REAR RH DOOR STICKER '6555-3333'	\$	nn	80.00	60sm
50	1	REAR LH DOOR STICKER '6555-3333'	\$	nn	80.00	60sm
51	1	FRONT LH DOOR STICKER 'Trans-Cab'	\$	nn	80.00	60sm
52	1	FRONT LH DOOR STICKER 'Classic'	\$	nn	80.00	15sm
53	1	FRONT RH DOOR STICKER 'Trans-Cab'	\$	nn	80.00	60sm
54	1	FRONT RH DOOR STICKER 'Classic'	\$	nn	80.00	15sm
55	1	DOOR CHECK BOLT	\$	sn	22.69	
56	1	DOOR GUIDE SCREW	\$	sn	10.85	
57	1	DOOR HINGE BOLT	\$	sn	10.85	
58	1	DOOR HINGE NUT LH	\$	sn	14.60	
59	1	DOOR CHECK NUT	\$	sn	3.75	
60	1	DOOR LOCK SCREW L70Y	\$	sn	6.12	
61	1	DOOR CATCH SCREW L70Y	\$	sn	10.06	

**TOTAL** \$ **5,855.63** <sup>61</sup>

**TOTAL PARTS** \$ **129,025.47**

**LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	7,500.00	242d
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	7,500.00	160d
To Rust-Proofing Of The Affected Areas.	\$	170.00	15d
To reinstall rear bumper parking sensor.	\$	170.00	6d

**Trans-cab Auto Services Pte Ltd****AAD1906-202**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHF 759T**

	To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	380.00	601
	To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	na 170.00	X
55				
56	To transfer of bootlid fittings, attachments and perform water seepage test.	\$	na 170.00	X
	To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	na 170.00	X
	To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00	1001
	To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	1201
	Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	na 380.00	X
	Towing Fees.	\$	150.00	501
	To repair and realign rear exhaust pipe.	\$	na 170.00	X
	To Check Electrical Lighting Concerned.	\$	170.00	401
	To check steering geometry and computer wheel alignment	\$	220.00	601
	To apply paint protection system (PPS) maintain and enhancement	\$	380.00	X
	To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na 380.00	X
	To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	na 340.00	X

**Trans-cab Auto Services Pte Ltd**

AAD1906-202

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 759T

To transfer of front bumper fittings, attachment and perform water seepage test.	\$	na 180.00	X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	na 380.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	2a
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	na 180.00	X
To remove and refit air bag system and reset vehicle warning indicators.	\$	na 480.00	X
To transfer of front windscreen fittings and conduct water seepage test.	\$	na 170.00	X
To transfer of front bonnet fittings, attachment and perform water seepage test.	\$	na 180.00	X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00	X
To transfer of Front Door fittings, attachment and perform water seepage test.	\$	360.00	6a
To check ABS and brake efficiency, final checking and testing.	\$	380.00	X
To transfer of Rear Door fittings, attachment and perform water seepage test.	\$	na 360.00	X

<b>TOTAL</b>	<b>\$</b>	<b>22,190.00</b>
--------------	-----------	------------------

<b>Over All Total</b>	<b>\$</b>	<b>151,215.47</b>
-----------------------	-----------	-------------------

**Repair Days (PART BY PART)****30 DAYS**

16 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL			Ref : CS/AGI19011150/Kvd3n2	
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Date : 12-09-2019	
			Code : AGI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SJX 884X	Veh. Inspected	SHF 759T	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10003319/AH	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	25/06/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	VF1ABL15AUC283369	Colour	METALLIC WHITE / RED	
Odometer	337283	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GITI	8 mm	
L/H Front Tyre	215/60 R16	GITI	8 mm	
R/H Rear Tyre	215/60 R16	GITI	8 mm	
L/H Rear Tyre	215/60 R16	GITI	8 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR ,O/S FRONT, N/S REAR AND N/S FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	21/06/2019	Inspection Date	25/06/2019	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		16 Working Days		



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 9

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 759T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	BUMPER COVER REAR	BUCKLED	1,108.46	1,108.46
1	BUMPER LOWER REAR	SERVICEABLE	768.84	-
1	BUMPER BRACKET CTR REAR	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR	DISTORTED	44.99	44.99
1	BUMPER REFLECTOR RH	SERVICEABLE	43.61	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR	DISTORTED	44.99	44.99
1	BUMPER REFLECTOR LH	SERVICEABLE	43.61	-
1	BUMPER BEAM REAR	TO REPAIR SEE LABOUR	777.52	-
1	BUMPER BEAM BRACKET LH REAR	TO REPAIR SEE LABOUR	225.95	-
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR	225.95	-
1	BOOT REAR	TO REPAIR SEE LABOUR	2,872.68	-
1	BOOT REFLECTOR LAMP LH	SERVICEABLE	493.35	-
1	BOOT REFLECTOR LAMP RH	SERVICEABLE	493.35	-
1	FENDER PANEL INNER TRIM REAR LH	SERVICEABLE	671.45	-
1	FENDER PANEL REAR LH	BENT	3,299.13	3,299.13
1	WHEELARCH REAR LH	SERVICEABLE	543.47	-
1	WHEEL HOUSING PANEL REAR LH	TO REPAIR SEE LABOUR	4,682.09	-
1	CHASSIS PANEL REAR LH	TO REPAIR SEE LABOUR	3,766.43	-
1	FENDER PANEL INNER TRIM REAR RH	SERVICEABLE	671.45	-
1	FENDER PANEL REAR RH	BENT	3,299.13	3,299.13
1	WHEELARCH REAR RH	SERVICEABLE	543.47	-
1	WHEEL HOUSING PANEL REAR RH	TO REPAIR SEE LABOUR	4,682.09	-
1	CHASSIS PANEL REAR RH	TO REPAIR SEE LABOUR	3,766.43	-
1	TAILLAMP RH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	986.70	-
1	TALLAMP LH	SERVICEABLE	552.55	-

Report Ref No. CS/AGI19011150/Kvd3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	986.70	-
1	OUTER PANEL REAR (END PANEL)	TO REPAIR SEE LABOUR	1,471.77	-
1	OUTER PANEL REAR (END PANEL) TRIM	SERVICEABLE	404.56	-
1	EXHAUST REAR	TO REPAIR SEE LABOUR	7,489.05	-
1	EXHAUST CAP REAR	TO REPAIR SEE LABOUR	230.49	-
1	FUEL FLAP L70Y	SERVICEABLE	343.57	-
1	DOOR PANEL REAR RH	TO REPAIR SEE LABOUR	2,844.66	-
1	DOOR HANDLE OUTER REAR RH	SERVICEABLE	126.49	-
1	DOOR HANDLE CAP REAR RH	SERVICEABLE	35.52	-
1	DOOR HANDLE SEAL REAR RH	SERVICEABLE	7.89	-
1	DOOR HANDLE COVER REAR RH	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE REAR RH	SERVICEABLE	133.60	-
1	DOOR WEATHERSTRIP REAR RH	SERVICEABLE	410.66	-
1	DOOR PANEL REAR LH	TO REPAIR SEE LABOUR	2,844.66	-
1	DOOR HANDLE OUTER REAR LH	SERVICEABLE	126.49	-
1	DOOR HANDLE CAP REAR LH	SERVICEABLE	35.52	-
1	DOOR HANDLE SEAL REAR LH	SERVICEABLE	7.89	-
1	DOOR HANDLE COVER REAR LH	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE REAR LH	SERVICEABLE	133.60	-
1	DOOR WEATHERSTRIP REAR LH	SERVICEABLE	410.66	-
1	BUMPER COVER FRT	BUCKLED	1,259.42	1,259.42
1	BUMPER SPOILER FRT	SERVICEABLE	181.75	-
1	BUMPER ABSORBER FRT	SERVICEABLE	394.68	-
1	BUMPER RETAINER FRT LH	DISTORTED	151.41	151.41
1	BUMPER SUPPORT FRT	SERVICEABLE	123.88	-
1	BUMPER RETAINER FRT RH	SERVICEABLE	150.77	-
1	BUMPER SUPPORT FRT	SERVICEABLE	123.88	-
1	BUMPER UNDERTRAY FRT	SERVICEABLE	472.83	-
1	BUMPER GRILLE LOWER FRT	SERVICEABLE	266.80	-
1	BUMPER FOG LAMP GRILLE LH	SERVICEABLE	207.21	-
1	BUMPER FOGLAMP GRILLE RH	SERVICEABLE	207.21	-

Report Ref No. CS/AGI19011150/Kvd3n2





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BUMPER BEAM FRT	TO REPAIR SEE LABOUR	914.08	-
1	TOW COVER FRT	SERVICEABLE	28.61	-
1	RADIATOR GRILLE	SERVICEABLE	1,707.78	-
1	RADIATOR GRILLE BADGE 'RENAULT'	SERVICEABLE	225.36	-
1	RADIATOR GRILLE FRAME	SERVICEABLE	1,353.75	-
1	FRAME FULL SUPPORT PANEL	SERVICEABLE	615.90	-
1	FRAME FULL SUPPORT BRACKET	TO REPAIR SEE LABOUR	89.79	-
1	FRONT BRACE PANEL	TO REPAIR SEE LABOUR	177.22	-
1	HEADLAMP LH	SERVICEABLE	1,184.43	-
1	HEADLAMP RH	SERVICEABLE	1,184.43	-
1	HEADLAMP PANEL FRT LH	TO REPAIR SEE LABOUR	152.15	-
1	HEADLAMP PANEL FRT RH	TO REPAIR SEE LABOUR	152.15	-
1	BONNET	BENT	1,941.63	1,941.63
1	BONNET INSULATOR	SERVICEABLE	405.73	-
1	BONNET STRUT LH	SERVICEABLE	88.61	-
1	BONNET STRUT RH	SERVICEABLE	88.61	-
1	BONNET HINGE LH	TO REPAIR SEE LABOUR	348.31	-
1	BONNET HINGE RH	TO REPAIR SEE LABOUR	348.31	-
1	BONNET LOCK	TO REPAIR SEE LABOUR	305.48	-
1	BONNET CABLE	SERVICEABLE	119.19	-
1	BONNET CABLE COVER	SERVICEABLE	161.03	-
1	BONNET SEAL OUTER	SERVICEABLE	92.36	-
1	BONNET SEAL INNER	SERVICEABLE	157.28	-
1	FENDER PANEL FRT LH	BENT	783.83	783.83
1	WHEELARCH FRT LH	SERVICEABLE	278.84	-
1	FENDER BRACKET LOWER LH	SERVICEABLE	15.79	-
1	FENDER INSULATOR LH	SERVICEABLE	130.84	-
1	WHEEL HOUSING PANEL FRT LH	TO REPAIR SEE LABOUR	4,682.09	-
1	WHEEL HOUSING PANEL FRT RH	TO REPAIR SEE LABOUR	4,682.09	-
1	FENDER INSULATOR RH	SERVICEABLE	130.84	-

Report Ref No. CS/AGI19011150/Kvd3n2





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FENDER PANEL FRT RH	BENT	783.83	783.83
1	WHEELARCH FRT RH	SERVICEABLE	278.84	-
1	FENDER BRACKET LOWER RH	SERVICEABLE	15.79	-
1	WIPER RESERVOIR	SERVICEABLE	348.25	-
1	WIPER RESERVOIR NECK	SERVICEABLE	136.11	-
1	WIPER RESERVOIR MOTOR	SERVICEABLE	270.06	-
1	AIR CLEANER LOWER	SERVICEABLE	271.26	-
1	AIR CLEANER HOSE	SERVICEABLE	76.14	-
1	BASE BATTERY TRAY	SERVICEABLE	363.40	-
1	AIR CLEANER BOX	SERVICEABLE	464.20	-
1	SUBFRAME OUTER FRT	SERVICEABLE	2,652.45	-
1	SUBFRAME BRACKET OUTER LH	TO REPAIR SEE LABOUR	92.36	-
1	SUBFRAME BRACKET OUTER RH	TO REPAIR SEE LABOUR	92.36	-
1	LOWER ARM LH L70Y	SERVICEABLE	685.76	-
1	KNUCKLE ARM LH L70Y	SERVICEABLE	846.98	-
1	ABSORBER FRT LH L70Y	SERVICEABLE	360.54	-
1	DRIVESHAFT LH	TO REPAIR SEE LABOUR	1,747.45	-
1	STABILIZER BAR FRT	SERVICEABLE	604.65	-
1	LOWER ARM RH L70Y	SERVICEABLE	685.76	-
1	KNUCKLE ARM RH L70Y	SERVICEABLE	846.98	-
1	ABSORBER FRT RH L70Y	SERVICEABLE	360.54	-
1	DRIVESHAFT RH	TO REPAIR SEE LABOUR	1,747.45	-
2	STABILIZER LINK FRT	SERVICEABLE	117.22	-
1	ROCKER PANEL INNER GARNISH RH	SERVICEABLE	466.51	-
1	ROCKER PANEL INNER RH	TO REPAIR SEE LABOUR	1,024.79	-
1	ROCKER PANEL CENTER RH	BENT	990.25	990.25
1	ROCKER PANEL OUTER RH	TO REPAIR SEE LABOUR	1,184.99	-
1	AUTO COMPUTER	SERVICEABLE	5,032.17	-
1	INJECTION COMPUTER	SERVICEABLE	4,706.30	-
1	RHD HYDRAULIC POWER (RACK & PINION)	SERVICEABLE	5,154.52	-
1	STEERING PUMP ELECTRIC L70Y	SERVICEABLE	2,306.90	-
1	STEERING PINION RACK L70Y	SERVICEABLE	4,413.11	-

Report Ref No. CS/AGI19011150/Kvd3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR PANEL FRT RH	TO REPAIR SEE LABOUR	2,844.66	-
1	DOOR HANDLE OUTER FRT RH	SERVICEABLE	477.76	-
1	DOOR HANDLE COVER FRT RH	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE FRT RH	SERVICEABLE	133.60	-
1	DOOR WEATHERSTRIP FRONT RH	SERVICEABLE	410.66	-
1	DOOR SEAL FRONT RH	SERVICEABLE	162.02	-
1	DOOR MIRROR ASSY RH	SERVICEABLE	1,483.40	-
1	DOOR HARNESS WIRE RH	SERVICEABLE	2,670.00	-
1	DOOR PANEL FRT LH	TO REPAIR SEE LABOUR	2,844.66	-
1	DOOR HANDLE OUTER FRT LH	SERVICEABLE	477.76	-
1	DOOR HANDLE MODULE FRT LH	SERVICEABLE	133.60	-
1	DOOR WEATHERSTRIP FRONT LH	SERVICEABLE	410.66	-
1	DOOR MIRROR ASSY LH	SERVICEABLE	1,483.40	-
1	DOOR HARNESS WIRE LH	SERVICEABLE	2,670.00	-
1	DOOR HINGE UPPER LH	TO REPAIR SEE LABOUR	261.28	-
1	DOOR HINGE LOWER LH	TO REPAIR SEE LABOUR	300.55	-
1	DOOR CHECK FRT LH	SERVICEABLE	194.77	-
1	DOOR LOCK FRT LH	TO REPAIR SEE LABOUR	908.75	-
1	DOOR CATCH FRT LH	TO REPAIR SEE LABOUR	131.23	-
1	DOOR HANDLE COVER FRT LH	SERVICEABLE	13.22	-
	LESS 10% DISCOUNT		-13,685.53	-1,370.71
			123,169.81	12,336.36
	<b>SPECIAL NETT ITEMS</b>			
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NOT NECESSARY	66.00	-

Report Ref No. CS/AGI19011150/Kvd3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:6 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	EXHAUST MOUNTING REAR (SN)	SERVICEABLE	17.82	-
1	SET FENDER WHEELARCH REAR RH CLIP (SN)	NOT NECESSARY	35.00	-
1	SET FENDER WHEELARCH REAR LH CLIP (SN)	NOT NECESSARY	35.00	-
1	FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	28.00	-
1	FENDER INNER TRIM CLIP RH (SN)	NOT NECESSARY	28.00	-
1	TAILLAMP CLIP RH (SN)	NOT NECESSARY	5.00	-
1	TAILLAMP CLIP LH (SN)	NOT NECESSARY	5.00	-
2	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	WINDSCREEN MOULDING (SN)	NECESSARY	100.00	100.00
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NECESSARY	100.00	30.00
1	SET RADIATOR GRILLE FRAME CLIP (SN)	NOT NECESSARY	52.00	-
1	SET BUMPER CLIP FRT (SN)	NECESSARY	66.00	66.00
1	BUMPER BRACKET CLIP FRT LH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT LH (SN)	NOT NECESSARY	10.50	-
1	BUMPER BRACKET CLIP FRT RH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT RH (SN)	NOT NECESSARY	10.50	-
1	SET RADIATOR GRILLE SCREW (SN)	SERVICEABLE	16.00	-
1	SET BUMPER GRILLE LOWER CLIP (SN)	NOT NECESSARY	69.00	-
1	SET FRAME FULL SUPPORT PANEL CLIP (SN)	NOT NECESSARY	70.00	-
2	FRAME FULL SUPPORT PANEL NUT (SN)	NOT NECESSARY	20.00	-
1	FRONT LEFT TYRE (SN)	SERVICEABLE	330.00	-
1	FRONT LEFT TYRE RIM (SN)	SERVICEABLE	380.00	-
2	FRAME FULL SUPPORT PANEL STUD (SN)	SERVICEABLE	30.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	FRONT WINDSCREEN SEALANT (SN)	NOT NECESSARY	253.80	-
1	FRONT WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	SET FRONT LICENCE PLATE WITH HOLDER (SN)	SERVICEABLE	80.00	-
1	WHEELARCH CLIP FRT LH (SN)	NOT NECESSARY	30.50	-
1	WHEELARCH CLIP FRT RH (SN)	NOT NECESSARY	30.50	-
2	BONNET STRUT L70Y (SN)	NOT NECESSARY	88.61	-
6	BONNET INSULATOR CLIP L70Y (SN)	NOT NECESSARY	7.30	-
2	BONNET CABLE COVER SCREW L70Y (SN)	NOT NECESSARY	10.85	-
2	BONNET CABLE CLIP L70Y (SN)	NOT NECESSARY	6.31	-
1	REAR LEFT TYRE (SN)	SERVICEABLE	330.00	-
1	REAR LEFT TYRE RIM (SN)	SERVICEABLE	380.00	-
1	FRONT RIGHT TYRE (SN)	SERVICEABLE	330.00	-

Report Ref No. CS/AGI19011150/Kvd3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 7 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT RIGHT TYRE RIM (SN)	SERVICEABLE	380.00	-
1	REAR RIGHT TYRE (SN)	SERVICEABLE	330.00	-
1	REAR RIGHT TYRE RIM (SN)	SERVICEABLE	380.00	-
1	REAR RH DOOR STICKER "6555-3333" (SN)	NECESSARY	80.00	60.00
1	REAR LH DOOR STICKER "6555-3333" (SN)	NECESSARY	80.00	60.00
1	FRONT LH DOOR STICKER "TRANS-CAB" (SN)	NECESSARY	80.00	60.00
1	FRONT LH DOOR STICKER "CLASSIC" (SN)	NECESSARY	80.00	15.00
1	FRONT RH DOOR STICKER "TRANS-CAB" (SN)	NECESSARY	80.00	60.00
1	FRONT RH DOOR STICKER "CLASSIC" (SN)	NECESSARY	80.00	15.00
1	DOOR CHECK BOLT (SN)	SERVICEABLE	22.69	-
1	DOOR GUIDE SCREW (SN)	SERVICEABLE	10.85	-
1	DOOR HINGE BOLT (SN)	SERVICEABLE	10.85	-
1	DOOR HINGE NUT LH (SN)	SERVICEABLE	14.60	-
1	DOOR CHECK NUT (SN)	SERVICEABLE	3.75	-
1	DOOR LOCK SCREW L70Y (SN)	SERVICEABLE	6.12	-
1	DOOR CATCH SCREW L70Y (SN)	SERVICEABLE	10.06	-
			5,855.61	605.00
	<b>LABOUR</b>			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		7,500.00	2,420.00
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BUMPER BEAM REAR, BUMPER BEAM BRACKET LH REAR, BUMPER BEAM BRACKET RH REAR, BOOT REAR, WHEEL HOUSING PANEL REAR LH, CHASSIS PANEL REAR LH, WHEEL HOUSING PANEL REAR RH, CHASSIS PANEL REAR RH, TAILLAMP PANEL RH, TAILLAMP PANEL LH, OUTER PANEL REAR (END PANEL), EXHAUST REAR, EXHAUST CAP REAR }.		7,500.00	1,600.00
	DOOR PANEL REAR RH, DOOR PANEL REAR LH, BUMPER BEAM FRT, FRAME FULL SUPPORT BRACKET, FRONT BRACE PANEL, HEADLAMP PANEL FRT LH, HEADLAMP PANEL FRT RH, BONNET HINGE LH, BONNET HINGE RH, BONNET LOCK, WHEEL HOUSING PANEL FRNT LH, WHEEL HOUSING PANEL FRNT RH, SUBFRAME BRACKET OUTER LH, SUBFRAME BRACKET OUTER RH, DRIVESHAFT LH, DRIVESHAFT RH, ROCKER PANEL INNER RH, ROCKER PANEL OUTER RH, DOOR PANEL FRT RH, DOOR PANEL FRT LH, DOOR HINGE UPPER LH, DOOR HINGE LOWER LH, DOOR LOCK FRT LH AND DOOR CATCH FRT LH. }		-	-



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 8 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	150.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO DROP DIESEL TANK,PIPES,HOSES TO FACILITATE BODYWORK REPAIR,FINAL CHECKING AND TESTING.		380.00	60.00
	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		380.00	100.00
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.		170.00	120.00
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	TOWING FEES.		150.00	50.00
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	40.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		220.00	60.00
	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	NOT NECESSARY	380.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO TRANSFER OF FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	340.00	-
	TO TRANSFER OF FRONT BUMPER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	180.00	-
	TO DISMANTLE AND REFIT FRONT END SUSPENSION,UNDERCARRIAGE PARTS,FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.		170.00	20.00
	TO TRANSFER OF REAR BUMPER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	180.00	-
	TO REMOVE AND REFIT AIR BAG SYSTEM AND RESET VEHICLE WARNING INDICATORS.	NOT NECESSARY	480.00	-

Report Ref No. CS/AGI19011150/Kvd3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:9 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER OF FRONT WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF FRONT BONNET FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	180.00	-
	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK.	NOT NECESSARY	380.00	-
	TO TRANSFER OF FRONT DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		360.00	60.00
	TO CHECK ABS AND BRAKE EFFICIENCY, FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	360.00	-
			22,190.00	4,740.00
<b>GRAND TOTAL</b>			<b>151,215.42</b>	<b>17,681.36</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>14,150.00</b>

Report Ref No. CS/AGI19011150/Kvd3n2

**KONG SENG CHEONG**

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.