



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBP 612B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
2	FRONT FORK ASSY LH/RH (CONSISTENT)	BENT	570.00	570.00
1	STEERING UNDER BRACKET (CONSISTENT)	BENT	225.00	180.00
	LESS 10% DISCOUNT		-79.50	-75.00
			715.50	675.00
SPECIAL NETT ITEMS				
1	STEERING CON -UPPER (SN) (CONSISTENT)	NECESSARY	65.00	50.00
1	STEERING CON- LOWER (SN) (CONSISTENT)	NECESSARY	85.00	60.00
			150.00	110.00
LABOUR				
	TOWING FEE.		70.00	50.00
	LABOUR CHARGES.		450.00	200.00
			520.00	250.00
GRAND TOTAL			1,385.50	1,035.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				800.00

Report Ref No. CC4/ASM19011165/Jga3q2

ONG HWEE JIE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.