

OPTION SERVICES

Address: Blk 189B Rivervale Drive, #04-1004, Singapore 542189
Tel: 6315 1239, Fax: 6315 3298, Mobile: 9061 0543

Muhammad Bin Khamis
Blk 134 Yishun St 11
#03-159
Singapore 760134


Invoice no:	POS0373/19
Date:	18 October 2019
Report no:	373M0619.SH
Vehicle :	FBP612B

INVOICE

No	Item Description	Qty	Unit Price	Total Amount (\$)
01	Being charges for the inspection of the accident vehicle, transport and photographs.			382.00
SGD(\$): Three Hundred and Eighty-two only			Grand Total:	382.00

"Cheque should be crossed and made payable to "Pro-Option Services"

PRO-OPTION SERVICES



.....
Authorised Signature

8 ASSESSMENT OF DAMAGE AND COSTS

Report no: 373M0619.SH
Vehicle no: FBP612B

A SPARE PARTS

Description	Qty	Assessed Condition	Repairer's Amount	Revised Amount	
Front fork assy LH/RH	2	bent	180 ✓ 570.00	570.00	✓
Steering under bracket	1	bent	225.00	225.00	
		Subtotal of the above	795.00	795.00	
		Discount 10%	79.50	79.50	
		Subtotal 1:	715.50	715.50	
(Special nett)	1	necessary	50 ✓ 65.00	65.00	
Steering con - upper	1	necessary	60 ✓ 85.00	85.00	
Steering con - lower		Subtotal 2:	150.00	150.00	
		Total cost of parts:	865.50	865.50	

B LABOUR

Towing fee (2x)

Labour charges.

	70.00	50 ✓	60.00
	450.00	200 ✓	300.00
	520.00		360.00
Total cost of labour:	1,385.50		1,225.50
Total cost of repair:			

9 CONCLUSION


The revised or adjusted cost of repairs to restore the vehicle is

(a) However, the recommended cost of repair based on lump sum basis would be

(b) The estimated number of days for the repairs are

The above recommendations in my view are fair and reasonable for the restoration of the vehicle to its pre-accident condition.

Yours faithfully


Liaw Leong San
Licensed Automotive Appraiser

Dated: 18 October 2019

\$1,225.50

\$1,110.00

Two (2) ✓

ATION SERVICES

Blk 189B Rivervale Drive, #04-1004, Singapore 542189

Mobile: 9061 0543

ACCIDENT VEHICLE INSPECTION REPORT

Report no : 373M0619.SH
Vehicle no : FBP612B

1 REFERENCE

Date of inspection : 21 June 2019
Requested by : Mislan Bin Khamis
Blk 134 Yishun St 11
#03-159
Singapore 760134
Type of survey : Independent
Repairer : Soon Hin Motors Pte Ltd
Blk 1018 Yishun Industrial Park A, #01-342, Singapore 768760
Date of accident : 15 June 2019

2 VEHICLE DATA

Make/model : YAMAHA GDR155A (AEROX)
Chassis no : MH3SG4640KJ049080
Engine no : G3J8E0088093
Date of registration : 28 Jan 2019
Engine capacity : 155 cc
Colour : Matt Grey

3 STATIC CONDITION CHECK

Steering : Affected
Foot brakes : Serviceable
Hand brakes : Serviceable
Paintwork : Good
General Condition : Good

4 TIRE CONDITION CHECK mm/Make

	<u>mm/Make</u>	<u>SIZE</u>
Front tread	: 6 mm/Maxxis	110/80-14
Rear tread	: 6 mm/Maxxis	140/70-14

5 BRIEF DESCRIPTION OF DAMAGE

Front forks bent, steering under bracket bent, etc. Please see para. 8 of this report for more details.

6 REMARKS

This inspection is carried out on a "WITHOUT PREJUDICE" basis and I have not authorized any repairs.

7 RECOMMENDATION

Cost of repairs : \$1,110.00 (lump sum)
Estimated no of days : Two (2)

SOON HIN MOTOR PTE LTD

Blk 1018 Yishun Industrial Park A, #01-342, Singapore 768760

Tel no: 67524893, 62573352

INVOICE

Mislan Bin Khamis
Blk 134 Yihsun St 11
#03-159
Singapore 760134

Invoice No: 011/19/SH/TP
Date: 23 October 2019

Item	Particular	Amount (\$)
1	To supply labour and materials to repair below mentioned vehicle to its pre-accident condition.	\$1,200.00
2	7% GST	\$84.00
	Vehicle No: <u>FBP612B</u> Make/Model: <u>Yamaha GDR155A</u> Accident Date: <u>15 June 2019</u>	
	(Sing Dollars: One Thousand Two Hundred and Eighty-Four only	
TOTAL:		\$1,284.00

.....
Authorized Signature