

OPTION SERVICES

Address: Blk 189B Rivervale Drive, #04-1004, Singapore 542189
Tel: 6315 2399, Fax: 6315 3298, Mobile: 9061 0543

Muhammad Bin Khamis
Blk 134 Yishun St 11
#03-159
Singapore 760134

Invoice no:	POS0373/19
Date:	18 October 2019
Report no:	373M0619.SH
Vehicle :	FBP612B

INVOICE

No	Item Description	Qty	Unit Price	Total Amount (\$)
01	Being charges for the inspection of the accident vehicle, transport and photographs.			382.00
SGD(\$): Three Hundred and Eighty-two only			Grand Total:	382.00

"Cheque should be crossed and made payable to "Pro-Option Services"

PRO-OPTION SERVICES



.....
Authorized Signature

8 ASSESSMENT OF DAMAGE AND COSTS

Report no: 373M0619.SH
 Vehicle no: FBP612B

A SPARE PARTS

Description	Qty	Assessed Condition	Repairer's Amount	Revised Amount
Front fork assy LH/RH	2	bent	570.00	570.00
Steering under bracket	1	bent	225.00	225.00
		Subtotal of the above	795.00	795.00
		Discount 10%	79.50	79.50
		Subtotal 1:	715.50	715.50
(Special nett)	1	necessary	65.00	65.00
Steering con - upper	1	necessary	85.00	85.00
Steering con - lower		Subtotal 2:	150.00	150.00
		Total cost of parts:	865.50	865.50

B LABOUR

Towing fee (2x)	70.00	60.00
Labour charges.	450.00	300.00
	520.00	360.00
Total cost of labour:	1,385.50	1,225.50
Total cost of repair:		

9 CONCLUSION

The revised or adjusted cost of repairs to restore the vehicle is

\$1,225.50

(a) However, the recommended cost of repair based on lump sum basis would be


\$1,110.00

(b) The estimated number of days for the repairs are

Two (2)

The above recommendations in my view are fair and reasonable for the restoration of the vehicle to its pre-accident condition.

Yours faithfully



 Liaw Leong San
 Licensed Automotive Appraiser

Dated: 18 October 2019

ATION SERVICES

Blk 189B Rivervale Drive, #04-1004, Singapore 542189

Mobile: 9061 0543

ACCIDENT VEHICLE INSPECTION REPORT

Report no : 373M0619.SH
Vehicle no : FBP612B

1 REFERENCE

Date of inspection : 21 June 2019
Requested by : Mislan Bin Khamis
Blk 134 Yishun St 11
#03-159
Singapore 760134
Type of survey : Independent
Repairer : Soon Hin Motors Pte Ltd
Blk 1018 Yishun Industrial Park A, #01-342, Singapore 768760
Date of accident : 15 June 2019

2 VEHICLE DATA

Make/model : YAMAHA GDR155A (AEROX)
Chassis no : MH3SG4640KJ049080
Engine no : G3J8E0088093
Date of registration : 28 Jan 2019
Engine capacity : 155 cc
Colour : Matt Grey

3 STATIC CONDITION CHECK

Steering : Affected
Foot brakes : Serviceable
Hand brakes : Serviceable
Paintwork : Good
General Condition : Good

4 TIRE CONDITION CHECK

	<u>mm/Make</u>	<u>SIZE</u>
Front tread	: 6 mm/Maxxis	110/80-14
Rear tread	: 6 mm/Maxxis	140/70-14

5 BRIEF DESCRIPTION OF DAMAGE

Front forks bent, steering under bracket bent, etc. Please see para. 8 of this report for more details.

6 REMARKS

This inspection is carried out on a "WITHOUT PREJUDICE" basis and I have not authorized any repairs.

7 RECOMMENDATION

Cost of repairs : \$1,110.00 (lump sum)
Estimated no of days : Two (2)

SOON HIN MOTOR PTE LTD

Blk 1018 Yishun Industrial Park A, #01-342, Singapore 768760

Tel no: 67524893, 62573352

INVOICE

Mislan Bin Khamis
Blk 134 Yihun St 11
#03-159
Singapore 760134

Invoice No: 011/19/SH/TP
Date: 23 October 2019

Item	Particular	Amount (\$)
1	To supply labour and materials to repair below mentioned vehicle to its pre-accident condition.	\$1,200.00
2	7% GST	\$84.00
	Vehicle No: <u>FBP612B</u>	
	Make/Model: <u>Yamaha GDR155A</u>	
	Accident Date: <u>15 June 2019</u>	
	(Sing Dollars: One Thousand Two Hundred and Eighty-Four only	
	TOTAL:	\$1,284.00

.....
Authorized Signature