

**TRANS-CAB AUTO SERVICES PTE LTD**  
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346  
 TEL NO.6287 6666 FAX NO.6366 8862  
 CO/GST REG NO.201019626G  
**SHD 9035A - AIG**

*Not Authored* RIZA  
*21 Aug 8*

Vehicle No.: SHD 9035A - RIZA  
 Chassis No.: JTDGJ20W805003310  
 Vehicle Make: TOYOTA  
 Vehicle Model: WISH 2.0 BI-FUEL  
 Date of Accident : 30.08.2015  
 Third Party Insurer : AIG

PART		LIST
1	1 Front Bumper	\$ 585.36 —
2	1 Front Bumper Lower Absorber	\$ 130.00 7
3	1 Front Bumper Reinforcement	\$ 318.11 7
4	1 Front Bumper Side Support LH	\$ 76.20 X
5	1 Front Bumper Side Support RH	\$ 76.20 X
6	1 Front Bumper Retainer RH	\$ 102.00 X
7	1 Front Bumper Fog Lamp RH	\$ 208.00 X
8	1 Front Bumper Fog Lamp Outer Chrome RH	\$ 190.00 X
9	1 Front Bumper Fog Lamp Grille RH	\$ 150.00 X
10	1 Front Bumper Retainer LH	\$ 102.00 X
11	1 Front Bumper Fog Lamp LH	\$ 208.00 7
12	1 Front Bumper Fog Lamp Outer Chrome LH	\$ 190.00 —
13	1 Front Bumper Fog Lamp Grille LH	\$ 150.00 —
14	1 Front Bumper Undertery	\$ 129.36 X
15	1 Front Headlamp RH	\$ 672.00 X
16	1 Front Headlamp LH	\$ 672.00 7
17	1 Front Support Panel Assy	\$ 1,222.32 X
18	1 Bonnet	\$ 1,019.16 X
19	1 Bonnet Hinge RH	\$ 81.60 X
20	1 Bonnet Hinge LH	\$ 81.60 X
21	1 Bonnet Lock	\$ 90.02 X
22	1 Bonnet Centre 'TOYOTA' Logo Badge	\$ 115.44 X
23	1 Front Fender RH	\$ 837.60 X
24	1 Front Fender Liner RH	\$ 369.14 X
25	1 Front Fender LH	\$ 369.14 X
26	1 Front Fender Liner LH	\$ 369.14 X
27	1 Radiator Assembly	\$ 2,268.24 X
28	1 Radiator Grille	\$ 462.48 X
29	1 Aircon Condenser	\$ 1,375.50 X

TOTAL	\$	12,620.61
25%	\$	3,155.15
	\$	9,465.46

**TRANS-CAB AUTO SERVICES PTE LTD**  
 NO.42 SUNGAI KADUT ST 1 SINGAPORE 729346  
 TEL NO.6287 6666 FAX NO.6366 8862  
 CO/GST REG NO.201019626G  
**SHD 9035A - AIG**

**RIZA**

**Special Nett**

1 Set Front Bumper Fastener Clip	\$	<i>nn</i> 40.00 ✓
1 CNG Sticker	\$	<i>nn</i> 15.00 ✓
1 Set Front Fender Liner Clip LH	\$	<i>nn</i> 30.00 ✓
1 Set Front Fender Liner Clip RH	\$	<i>nn</i> 30.00 X
1 Set Radiator Grille Clip	\$	<i>nn</i> 18.00 X
1 Front Licence Plate	\$	<i>M</i> 50.00 <i>25m</i>
<b>TOTAL</b>		<b>\$ 183.00</b>
<b>TOTAL PARTS</b>		<b>\$ 9,648.46</b>

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,800.00 <i>300l</i>
To Check Electrical Lighting Concerned.	\$	120.00 <i>20l</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>nn</i> 200.00 X
Putty And Spray Painting Of The Affected	\$	2,700.00 <i>400l</i>
To Vacuum, Replace, Refix And Recharge Air Condenser	\$	<i>nn</i> 350.00 X
To Replace, Refix And Top Up Coolant For Radiator	\$	<i>nn</i> 170.00 X
To Dismantle And Refit Aircon Assy And Attachment, Vacuum And Charge-In-Gas.	\$	<i>nn</i> 350.00 X
<b>TOTAL</b>		<b>\$ 6,690.00</b>
<b>Over All Total</b>		<b>\$ 16,338.46</b>

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature: \_\_\_\_\_

**Total Repair Days**

**10 DAYS**  
*2 days*