

AFF REC BY:

REF: CS/FCI 19011172/R19d304 Special Instruction:

Surveyor: RASU

ASSIGNMENT (Office)

From (Person): Karint

of FCI

Date/Time: 25.6.19 12.41p.m

Estimated Cost:

Bill to:

OD TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SJT 612K

Insured: SHC 8506 V

at Workshop m/s E thoz Group Focus Auto

Tel: 66547520

or 30 Bukit Batur Crescent

Policy No:

Claim No: D1900404/MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 18.6.2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 25.6.19 1.47p.m

Person Contacted: Chun Sin

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHC 8506V: NA/INC 18009030/r3 D.O.A: 01/05/2018
	SJT 612K: CCB/AG 15009183/Ana 3q2 D.O.A: 01/06/2015
28/6/19 @ 11.39am	visited to Kaven Tan by email.
*	The vehicle tow to Focus Auto for repair.
	Rasu finalised by \$3500, 7 days. CRed \$3691, 51%
*	MV: \$13.5K (est); CTA: \$9502; NV: \$3998.

(08/11/13)

ASS. REC. BY: P. S. M.

REF

FCI

4980H

(OE XPIRY: 2019/14P)

ASSIGNMENT

From: _____ Date: 26.6.2019

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJT 612Kat Workshop m/s Ethoz Groupof 30 Bukit Batok CrescentInsured: FCI

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 13.5K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ny

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJT 612K Yr Regn: 2009 / SLPType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MITSUBISHI LANCER 1.5A.c.c 1499Colour: RED A/C: Insured / Std / NI / NASp. Reading: 207195 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: Jmy5RCY2AAU000.248Gen. Cond: Good / Fair / Poor / BurntSteering: in order / Jammed / Leaked / Burnt orBrake: in order / Jammed / Leaked / Burnt orModi: Nil / SIRUM / STD A/Rim orTyre Size: F: 205/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 18/06/19

Survey held at

ETHOZ

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 26/06/19

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear n/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

ny G1A

RECEIVED 30 JUL 2019

Date/Time, File Pass to?

13/07/2019

Date/Time, File Return to?

2)

☐

Preli. Report

☐

Final Report

Days Of Repair: 7Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Report Format: TPLump Sum / I.B.I. (\$) 3500

150

50

50

72

322



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19004041MFSH

Date: 28 June 2019

Our Ref: CS/FCI19011172/R1qd3

The Motor Claims Department
MS First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJT 612K .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 26/06/2019 at the premises of M/s ETHOZ, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>9,559.80</u> .
Revised Estimate Amount	: S\$ <u>5,383.80</u> .
"Check" Items Amount	: S\$ <u>985.50</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages
at the rear n/s portion.



Yours faithfully

Rasul
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	20-06-2019	Our Ref No. D19004041MFSH
Accident Date	18-06-2019	Claim Type. Third Party
Insured Vehicle	SHC8506U	Third Party Vehicle. SJT612K
Survey Location	30 BUKIT BATOK CRESCENT	
Contact Person.	LEE CHEN SIN	
Contact No.	66547520/ 0	Fax No. 66547542
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ETHOZ GROUP LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 28 June 2019 11:39 AM
To: 'CWS Motor Claims'; assignments
Cc: 'Karen Tan'; SUR
Subject: RE: SURVEY ASSESSMENT - D19004041MFSH/1
Attachments: CSFCI19011172R1qd3.pdf

Dear Karen,

Enclosed herewith preliminary advice of SJT 612K.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 26 June 2019 7:54 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19004041MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 25 June 2019 12:41 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19004041MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4980H
Vehicle Details	
Vehicle No.:	SJT612K
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Jun 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER 1.5 MIVEC SPORTS AT ABS D/AB
Primary Colour:	Red
Manufacturing Year:	2009
Engine No.:	4A910124575
Chassis No.:	JMYSRCY2AAU000248
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$18,296.00
Original Registration Date:	23 Sep 2009
First Registration Date:	23 Sep 2009
Transfer Count:	0
Actual ARF Paid:	\$18,296.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Sep 2019
PARF Rebate Amount:	\$9,148.00
Intended COE Rebate Details	
COE Expiry Date:	22 Sep 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$15,019.00
COE Rebate Amount:	\$354.00
Total Rebate Amount:	\$9,502.00

The information contained herein is correct as at 28 Jun 2019

OK

13,500
9,502
13,998

~~13,500~~
3,500

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Lee Chen Sin
CLAIM DEPARTMENT
DID : 66547520
FAX :

Date : 24/06/2019

To : MS FIRST CAPITAL INSURANCE LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : LIM TECK MONG
: AXA INSURANCE PTE LTD

Certificate No : P2176988

Accident Date : 18/06/2019

Vehicle No : SJT- 612-K

Make & Model : MITSUBISHI LANCER 1.5 MIVEC SPORTS AT

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
Nett Item			
1	REAR BOOTLID <i>repair</i>	815.00	×
1	REAR BOOTLID EMBLEM CENTRE <i>re</i>	65.00	
1	REAR BOOTLID EMBLEM "LANCER" <i>re</i>	75.00	
1	REAR BOOTLID EMBLEM "EX" <i>re</i>	65.00	
1	REAR BOOTLID LAMP LH <i>X } sue</i>	255.00	×
1	REAR BOOTLID LAMP RH <i>X }</i>	255.00	×
1	REAR BOOTLID RUBBER <i>re</i>	274.00	
1	REAR BOOTLID LOCK <i>at</i>	141.00	
1	REAR LAMP LH <i>? X sue</i>	422.00	×

Date : 24/06/2019

To : MS FIRST CAPITAL INSURANCE LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : LIM TECK MONG
: AXA INSURANCE PTE LTD

Certificate No : P2176988

Accident Date : 18/06/2019

Vehicle No : SJT- 612-K

Make & Model : MITSUBISHI LANCER 1.5 MIVEC SPORTS AT

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	REAR LAMP RH <i>xou</i>	422.00	<i>✓</i>
1	REAR BUMPER <i>de</i>	968.00	
10	REAR BUMPER CLIP <i>n -</i>	50.00	
1	REAR BUMPER SIDE RETAINER LH <i>n -</i>	35.00	
1	REAR BUMPER SIDE RETAINER RH <i>x sou</i>	35.00	<i>✓</i>
1	REAR BUMPER TOWING COVER <i>mi</i>	55.00	
1	REAR BUMPER REFLECTOR LH <i>ca</i>	74.00	
1	REAR BUMPER REFLECTOR RH <i>x sou</i>	74.00	<i>✓</i>
1	REAR BUMPER REINFORCEMENT <i>? h</i>	385.00	
1	REAR END PANEL <i>h</i>	786.00	

Date : 24/06/2019

To : MS FIRST CAPITAL INSURANCE LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : LIM TECK MONG
: AXA INSURANCE PTE LTD

Certificate No : P2176988

Accident Date : 18/06/2019

Vehicle No : SJT- 612-K

Make & Model : MITSUBISHI LANCER 1.5 MIVEC SPORTS AT

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	REAR END PANEL TOP GARNISH ? de /	288.00	
1	SPARE TYRE BOARD cr /	294.00	
1	SPARE TYRE PANEL repair		
1	REAR EXHAUST BOX X Xsu	794.00	X
2	REAR EXHAUST BOX MOUNTING X Xsu	95.00	X
1	REAR FENDER LH repair		
1	REAR FENDER RH X svc		
	Sub Total	6722.00	
	Discount 10% On Parts	(672.20)	
	Special Nett Item		

RESTORE

RESTORE

RESTORE

3555
102
3199.55

Date : 24/06/2019

To : MS FIRST CAPITAL INSURANCE LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : LIM TECK MONG
: AXA INSURANCE PTE LTD

Certificate No : P2176988

Accident Date : 18/06/2019

Vehicle No : SJT- 612-K

Make & Model : MITSUBISHI LANCER 1.5 MIVEC SPORTS AT

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	REAR BOOTLID EMBLEM "MIVEC" <i>re</i>	55.00	
1	REAR BOOTLID EMBLEM "C & C" <i>re</i>	45.00	
1	REAR BUMPER SPOILER (CENTRE) <i>ca</i>	250.00	
1	REAR BUMPER SPOILER (LH) <i>de</i>	220.00	
1	REAR BUMPER SPOILER (RH) <i>Xsue</i>	220.00	
1	REAR NUMBER PLATE <i>bt</i>	35.00	
1	REVERSE SENSOR <i>re</i>	200.00	
1	END PANEL SEALANT <i>re</i>	50.00	

1075

Date : 24/06/2019

To : MS FIRST CAPITAL INSURANCE LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : LIM TECK MONG
: AXA INSURANCE PTE LTD

Certificate No : P2176988

Accident Date : 18/06/2019

Vehicle No : SJT- 612-K

Make & Model : MITSUBISHI LANCER 1.5 MIVEC SPORTS AT

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	1075.00	
	Labour & Misc		
	LABOUR TO CARRY OUT REAR REPAIR	900.00	700
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	35.00	
	TO SPRAY PAINTING ON REAR AFFECTED AREA	1,100.00	1000
	SPRAY RUST PROOF ON AFFECTED AREA	40.00	
	TO DETACH & RENEW REVERSE SENSOR	60.00	40
	TO REMOVE & INSTALL ALL REAR BOOT LID COMPONENT TO FACILITATE REPAIRS	100.00	60
	TO REMOVE & RENEW SPARE COMPARTEMENT TRIMS	100.00	60

1938

Date : 24/06/2019

To : MS FIRST CAPITAL INSURANCE LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : LIM TECK MONG
AXA INSURANCE PTE LTD

Certificate No : P2176988

Accident Date : 18/06/2019

Vehicle No : SJT- 612-K

Make & Model : MITSUBISHI LANCER 1.5 MIVEC SPORTS AT

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	TO REMOVE & RENEW REAR EXHAUST TO FACILIATE REPAIR	100.00	X11
	Sub Total	2435.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

9,559.80

Remarks:

7 days / Lumpsum
Repair after repair

SUB TOTAL

GST 7.0 %

TOTAL

669.19

10,228.99

Surveyor's name:

RASUL - Hp 90010068

Principal's name:

LIM TECK MONG

Survey Date & Time:

26/06/19 @ 1440

Repair limit \$3500
7 days

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883
TEL: 6886 9097 FAX: 6841 9095 Email: claims@focusauto.com.sg
GST: 201004495R RCB NO:201004495R

M/S : FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
TEL: 6507 3848 FAX: 6507 3849
ATTN: Motor Claim Department

Estimate No: EST0000971
Date: 26 Jul 2019
Policy No: P2176988
Veh Reg No: SJT612K
Make/Model: MITSUBISHI LANCER 1.5
MIVEC SPORT AT ABS
D/AB
Chassis No: JMYSRCY2AAU000248
Engine No: 4A910124575
Reg. Date: 23/09/2009

Your Ref No: SJT612K
Claim Type: Third Party
Accident Date: 18/06/2019
TP Veh Reg No: SHC8506U

Estimate Repair Cost to Vehicle No :SJT612K

PAGE:1/2

Description	U/Price	Quantity	List Price SS	Amount SS
MITSUBISHI LANCER 1.5 MIVEC SPORTS AT ABS D/AB				
Net Price				
1 Rear Boot <i>repair</i>	569.0000	1 PC	569.00 X	
2 Rear Boot Lock <i>cut</i>	60.0000	1 PC	60.00	
3 Rear Boot Lock Catch <i>X SU</i>	20.0000	1 PC	20.00 X	
4 Rear Boot Rubber <i>new</i>	155.0000	1 PC	155.00	
5 Rear Boot Hinge <i>X SU</i>	78.0000	2 PC	156.00 X	
6 Rear Boot Emblem (Lancer EX) <i>new</i>	43.0000	1 PC	43.00	
7 Rear Boot Emblem (MIVEC) <i>new</i>	32.0000	1 PC	32.00	
8 Rear Boot Centre Logo <i>new</i>	43.0000	1 PC	43.00	
9 Rear Boot Reflector LH <i>X SU</i>	102.0000	1 PC	102.00 X	
10 Rear Tail Lamp <i>X SU</i>	280.0000	1 PC	280.00 X	
11 Rear Fender Inner Side Garnish <i>cut @ 240</i>	240.0000	1 PC	480.00 X	
12 Rear Fender Inner Side Garnish Clipse <i>@ 5.50 new</i>	5.5000	3 PC	16.50	
13 Rear Spare Tyre Cover Board <i>new</i>	180.0000	1 PC	180.00	
14 Rear End Panel <i>bt</i>	423.0000	1 PC	423.00	
15 Rear End Panel Top Garnish <i>de</i>	144.0000	1 PC	144.00	
16 Rear Bumper <i>de</i>	747.0000	1 PC	747.00	
17 Rear Bumper Side Retainer <i>LH new / RH X SU</i>	15.0000	1 PC	30.00 X	
18 Rear Bumper Top Beam <i>bt</i>	90.0000	1 PC	90.00	
19 Rear Bumper Reinforcement <i>bt</i>	178.0000	1 PC	178.00	
20 Rear Bumper Towing Cover <i>new</i>	18.0000	1 PC	18.00	
21 Rear Bumper Reflector LH <i>new</i>	18.0000	1 PC	18.00	
22 Rear Bumper Clipse <i>new</i>	5.5000	4 PC	22.00	
23 Rear Number Plate Lamp <i>X SU</i>	38.0000	1 PC	38.00 X	
24 Rear Smart Sensor <i>new</i>	130.0000	1 PC	130.00	
			3,991.00	3,991.00
Special Net				
25 Rear Bumper Centre Lower Spoiler <i>cut</i>	420.0000	1 PC	420.00 250	
26 Rear Bumper Side Spoiler LH <i>de</i>	180.0000	1 PC	180.00	
27 Rear Bumper Sensor <i>new</i>	300.0000	1 SET	300.00 200	
28 Rear Number Plate <i>bt</i>	50.0000	1 PC	50.00 35	

2554.50
10%
2299.05

665

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883
 TEL: 6886 9097 FAX: 6841 9095 Email: claims@focusauto.com.sg
 GST: 201004495R RCB NO:201004495R

M/S : FIRST CAPITAL INSURANCE LIMITED
 36 ROBINSON ROAD
 #16-01 CITY HOUSE
 SINGAPORE 068877
 TEL: 6507 3848 FAX: 6507 3849
 ATTN: Motor Claim Department

Estimate No: EST0000971
 Date: 26 Jul 2019
 Policy No: P2176988
 Veh Reg No: SJT612K
 Make/Model: MITSUBISHI LANCER 1.5
 MIVEC SPORT AT ABS
 D/AB
 Chassis No: JMYSRCY2AAU000248
 Engine No: 4A910124575
 Reg. Date: 23/09/2009

Your Ref No: SJT612K
 Claim Type: Third Party
 Accident Date: 18/06/2019
 TP Veh Reg No: SHC8506U

Estimate Repair Cost to Vehicle No :SJT612K

PAGE:2/2

Description	U/Price	Quantity	List Price	Amount
			SS	SS
			950.00	950.00
Labour				
29 Panel Beating	1,200.0000	1 PC	1,200.00 700	
30 Check Wiring	60.0000	1 PC	60.00 30	
31 Rust Proofing	60.0000	1 PC	60.00 40	
32 To Remove & Replace Bumper Sensor	80.0000	1 PC	80.00 60	
33 To Spray Painting	850.0000	1 PC	850.00 800	
			2,250.00	2,250.00
			Total	SS 7,191.00

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND ONE HUNDRED NINETY ONE ONLY

For FOCUS AUTO PTE LTD

 
 AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2299.05

665.00

1630.00

4594.05

202

3625.28

41-3,500

Repair limit

\$3,500

7 days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19011172/R1qd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 01-08-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8506U	Veh. Inspected	SJT 612K	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19004041MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	25/06/2019	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI LANCER 1.5A	c.c	1499	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	JMYSRCY2AAU000248	Colour	RED	
Odometer	207795	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	YOKOHAMA	6 mm	
L/H Front Tyre	205/60 R16	YOKOHAMA	6 mm	
R/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm	
L/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/06/2019	Inspection Date	26/06/2019	
Survey held at	30 BUKIT BATOK CRESCENT SINGAPORE 658075			
Repairer	FOCUS AUTO PTE LTD			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJT 612K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT (N)	TO REPAIR SEE LABOUR	569.00	-
1	REAR BOOT LOCK (N)	CUT	60.00	60.00
1	REAR BOOT LOCK CATCH (N)	SERVICEABLE	20.00	-
1	REAR BOOT RUBBER (N)	NECESSARY	155.00	155.00
2	REAR BOOT HINGE @\$78.00 (N)	SERVICEABLE	156.00	-
1	REAR BOOT EMBLEM (LANCER EX)(N)	NECESSARY	43.00	43.00
1	REAR BOOT EMBLEM (MIVEC)(N)	NECESSARY	32.00	32.00
1	REAR BOOT CENTRE LOGO (N)	NECESSARY	43.00	43.00
1	REAR BOOT REFLECTOR LH (N)	SERVICEABLE	102.00	-
1	REAR TAIL LAMP (N)	SERVICEABLE	280.00	-
2	REAR FENDER INNER SIDE GARNISH @\$240.00 (N)	CUT (1 PC ONLY)	480.00	240.00
6	REAR FENDER INNER SIDE GARNISH CLIPSE @\$5.50 (N)	NECESSARY (3 PCS ONLY)	33.00	16.50
1	REAR SPARE TYRE COVER BOARD (N)	CRACKED	180.00	180.00
1	REAR END PANEL (N)	BENT	423.00	423.00
1	REAR END PANEL TOP GARNISH (N)	DEFORMED	144.00	144.00
1	REAR BUMPER (N)	DEFORMED	747.00	747.00
2	REAR BUMPER SIDE RETAINER @\$15.00 (N)	N/S NECESSARY / O/S SERVICEABLE	30.00	15.00
1	REAR BUMPER TOP BEAM (N)	BENT	90.00	90.00
1	REAR BUMPER REINFORCEMENT (N)	BENT	178.00	178.00
1	REAR BUMPER TOWING COVER (N)	MISSING	18.00	18.00
1	REAR BUMPER REFLECTOR LH (N)	CRACKED	18.00	18.00
4	REAR BUMPER CLIPSE @\$5.50 (N)	NECESSARY	22.00	22.00
1	REAR NUMBER PLATE LAMP (N)	SERVICEABLE	38.00	-
1	REAR SMART SENSOR (N)	CRACKED	130.00	130.00
	LESS 10% DISCOUNT		-	-255.45
			3,991.00	2,299.05
SPECIAL NETT ITEMS				
1	REAR BUMPER CENTRE LOWER SPOILER (SN)	CUT	420.00	250.00

Report Ref No. CS/FCI19011172/R1qd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER SIDE SPOILER LH (SN)	DEFORMED	180.00	180.00
1	SET REAR BUMPER SENSOR (SN)	NOT WORKING	300.00	200.00
1	REAR NUMBER PLATE (SN)	BENT	50.00	35.00
			950.00	665.00
	LABOUR			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BOOT.		1,200.00	700.00
	CHECK WIRING.		60.00	30.00
	RUST PROOFING.		60.00	40.00
	TO REMOVE & REPLACE BUMPER SENSOR.		80.00	60.00
	TO SPRAY PAINTING.		850.00	800.00
			2,250.00	1,630.00
GRAND TOTAL			7,191.00	4,594.05

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,500.00
---	--	--	-----------------

Report Ref No. CS/FCI19011172/R1qd3n2

MARKET VALUE: \$13,500.00 (EST)-LTA REIMBURSEMENT VALUE: \$9,502.00=NETT VALUE: \$3,998.00

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.