

PERFECT WERKZ

ANG JOO PENG Block 25 Kaki Bukit Road 4 #06-51 Synergy@KB Singapore 417800 JUNE 2019
 Bk 25 Kaki Bukit Rd 4 #06-51 Synergy@KB Singapore 417800
 # 06-51 SYNERGY@KB Tel: 62712214 Fax: (65) 69664526 ROC : 53364512C
 Singapore 417800

Accident date: 21st JUNE 2019

Estimated repair cost for vehicle no: U6606 HYUNDAI STAREX 2.5A 2017

S/n	Qty	Items	U/price	Amount
1	1	Rear fender -RH		\$1,550.00 <i>2x</i>
2	1	rear fender glass moulding		\$115.00 <i>x nn</i>
3	1	Rear fender glass-RH		\$1,050.00 <i>x nn</i>
4	1	Rear fender inner trim board		\$874.00 <i>x nn</i>
5	1	rear fender inner trim board clips		\$60.00 <i>x nn</i>
6	1	rear fender lower panel -RH		\$115.00 <i>2x</i>
7	1	rear door - RH		\$1,850.00 <i>bt -</i>
8	1	rear door glass -RH		\$1,050.00 <i>bro ✓</i>
9	2	rear R/H door top & lower hinge	\$80.00	\$160.00 <i>bt ✓</i>
10	1	rear R/H door top moulding		\$115.00 <i>de ✓</i>
11	1	rear R/H door outer handle		\$144.90 <i>x nn</i>
12	1	rear R/H door inner lock		\$226.70 <i>bt ✓</i>
13	1	rear R/H door inner trim board		\$855.00 <i>de ✓</i>
14	1	rear R/H door inner rubber		\$155.00 <i>de ✓</i>
15	1	rear L/H door glass		\$0.00 <i>x Repeated.</i>
16	1	rear RH door inner gear & motor		\$758.00 <i>bt ✓</i>
17	1	rear R/H door inner glass rubber		\$179.00 <i>de ✓</i>
18	1	Rear locker panel		\$352.00 <i>x nn</i>
19	1	Rear locker panel lower garnish		\$188.00 <i>de ✓</i>
			Subtotal :-	\$9,797.60

Labour charges

To Remove & install rear fender glass

5536.70
20% 4429.36

\$120.00 x

to remove & install RH front door glass

\$120.00 *80*

To Check Wiring System

\$80.00 *30*

Panel beating

\$800.00 *600*

Spray painting

\$800.00 *600*

Subtotal :-

\$1,920.00

Total :-

\$11,717.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4429.36
1310
5739.36
454600
5 days