ASS. REC. BY:	Kalvin			761 Kigd	Speci	d Instruction		
From (Person);		of	MS		D	ete/Time:	23/6	19@1.56pm
Estimated Cost	. P1			Bill to:				
To Inspect Veh			HC 680	χ				
at Workshop in				omotive		65	4466	89.
ofPolicy No	2 3 0.0	garny	ki Ave	2 # 01-0 Claim No:_	5	97682	/	
Sum Insured:				Excess:				1
Make of Veh; (Client's Record)					D	.O.A	23/06	2019
CA / REV / Date/Time: 3	REP. / REV 24 HRS 0-38pm/g 25/6/14	Person Co	ntaçtad:	Vincen	4ve	H.O.D. End	DUT	
Date/Time	Action/Instruction	aliandy.	1					
	SLK 47664:/							
	SHC 6802C:C	SFEZIC	900199	2/Klqd3n	1 D.	A : 28	101/20	19
26/6/1900	10.30m VEVI	sed to	Crysta	t lee' vr	n Me	naen	-	

Nivitha (LKK Auto)

From:

Crystal Lee <crystal_lee@sg.msig-asia.com>

Sent:

Tuesday, 25 June 2019 1:56 PM

To:

assignments@lkkauto.com; admin-d@lkkauto.com

Cc:

Ong Zi Hui

Subject:

Survey Request - Manual Assigned

Pre-inspection/Accident involving SHC6802C and SLK4766Y (MSIG) on 23.06.19

Manual Assigned

Dear LKK

Refer to the email below, please survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment.

Thank you & Best regards,

Crystal Lee

Admin Officer, Claims Services (In-House Survey)

D: +65 6594 2535 | F: +65 6643 1349 | crystal_lee@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg









A Member of MS&AD INSURANCE GROUP

From: Nabilah Rasol

Sent: Tuesday, 25 June, 2019 11:35 AM

To: Crystal Lee <crystal lee@sg.msig-asia.com>

Subject: FW: Pre-inspection/Accident involving SHC6802C and SLK4766Y (MSIG) on 23.06.19

From: Nabilah Rasol

Sent: Tuesday, 25 June, 2019 11:35 AM

To: 'Vincent Chua' <vincent.chua@premiertaxi.com>

Cc: Goh Wee Dek <weedek.goh@premiertaxi.com>; Liew Hai Leong <haileong.liew@premiertaxi.com>;

Pauline Tham <pauline tham@sg.msig-asia.com>

Subject: RE: Pre-inspection/Accident involving SHC6802C and SLK4766Y (MSIG) on 23.06.19

Hi Vincent,

Thank you for your selection.

We will proceed to assign LKK Auto Consultants Pte Ltd via Merimen at our end and update you upon confirmation.

Please do not contact them directly to prevent confusion.

Please be informed that our surveyor will also be conducting a post repair inspection within the stipulated timeline under the protocol.

Have a great week ahead!

Nabilah Rasol (Ms) Admin Officer, Claims Services (Motor) Direct line +65 6643 1335 | Direct fax +65 6225 7402 | nabilah_rasol@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg

A Member of MISSAD INSURANCE GROUP

From: Vincent Chua [mailto:vincent.chua@premiertaxi.com]

Sent: Tuesday, 25 June, 2019 9:29 AM

To: Nabilah Rasol <nabilah rasol@sg.msig-asia.com>

Cc: Goh Wee Dek <weedek.goh@premiertaxi.com>; Liew Hai Leong <haileong.liew@premiertaxi.com>;

Pauline Tham <pauline tham@sg.msig-asia.com>

Subject: RE: Pre-inspection/Accident involving SHC6802C and SLK4766Y (MSIG) on 23.06.19

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear Nabilah.

We would like to appoint "LKK Auto Consultants" as the SJE for this PRS.

Please kindly arrange for survey.

Thank you.

Regards

Vincent Chua Operations Assistant Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443 Tel: 6214 8880 Ext 066 | DID: 6544 6689 | Fax: 6214 1511

Visit us at: www.premiertaxi.com.sg

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

A Please Consider Your Environmental Responsibility Before Printing This E-mail, SAVE OUR TREES and REDUCE POLLUTION A

From: Nabilah Rasol [mailto:nabilah rasol@sg.msig-asia.com]

Sent: Tuesday, 25 June, 2019 8:40 AM

To: Vincent Chua < vincent.chua@premiertaxi.com> Cc: Pauline Tham <pauline tham@sg.msig-asia.com>

Subject: RE: Pre-inspection/Accident involving SHC6802C and SLK4766Y (MSIG) on 23.06.19

Hi Vincent.

We refer to your email dated 24/06/2019.

Please choose one surveyor from the list that you wish for us to appoint to conduct the pre-repair inspection:

- 1) LKK Auto Consultants Pte Ltd
- Formteam Consultancy Pte Ltd 2)
- 3) Automobile Inspection Services Pte Ltd
- 4) STA Inspection Pte Ltd
- 5) MSIG In-House Surveyors

This Fast-Lane settlement option is for clear-cut liability which MSIG will expedite offer @ 100% with express payment. Priority will be given to those opted for our in-house surveyor

To facilitate an expeditious claim settlement, we hope you are agreeable for the above surveyor to be the SJE (Single Joint Expert).

If not, you may wish to nominate any of the 10 surveyors listed below as the SJE, depending on their availability:

 Kalvin Ang 	6) Frankie Pang
2) Kenneth Kong	7) Ng You Han
3) Marcus Chua	8) Gary Soon
4) Henry Ng	9) Chow Bo Xiong
5) Lau Kwok Kwong	10) Axel Lee

NB:

(a) *Fast lane settlement is not applicable for cases that liability is in dispute*

(b) If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

We have created a dedicated motor survey mailbox for your motor survey request and pre-repair inspection. Please contact us (MSIG) by clicking this link: motorsurvey@sg.msig-asia.com

Have a great week ahead!

Nabilah Rasol (Ms)

Admin Officer, Claims Services (Motor)

Direct line +65 6643 1335 | Direct fax +65 6225 7402 | nabilah_rasol@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg









From: Vincent Chua [mailto:vincent.chua@premiertaxi.com]

Sent: Monday, 24 June, 2019 2:57 PM

To: Motor Survey < motorsurvey@sg.msig-asia.com>

Cc: Goh Wee Dek <weedek.goh@premiertaxi.com>; Liew Hai Leong <haileong.liew@premiertaxi.com>

Subject: Pre-inspection/Accident involving SHC6802C and SLK4766Y on 23.06.19

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear all,

We refer to the vehicles mentioned above.

Vehicle to be Surveyed: SHC6802C

Insured Vehicle: SLK4766Y Date of Accident: 23/06/2019

Name of Workshop: Premier Automotive Services Pte Ltd

Address of Survey Location: 23 Changi South Avenue 2, #01-02, S (486443)

Name of Contact Person: Mr Chua

Contact Number: 65446689

Email Address of Contact Person: vincent.chua@premiertaxi.com

Vehicle available for survey at any time

Kindly arrange for survey.

Kindly send us your panel surveyor list and arrange for survey.

Thank you.

Regards

Vincent Chua Operations Assistant Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443 Tel: 6214 8880 Ext 066 | DID: 6544 6689 | Fax: 6214 1511

Visit us at: www.premiertaxi.com.sg

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

A Please Consider Your Environmental Responsibility Before Printing This E-mail, SAVE OUR TREES and REDUCE POLLUTION

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Pauline Tham

Date: 26 Jun 2019

Preliminary Advice

Insured Vehicle No : SLK4766Y

TP Vehicle No

: SHC6802C

Accident Date

: 23/06/2019

Make

: KIA OPTIMA

Assignment Date

: 25/06/2019

Date of Inspection : 25/06/2019

Est. Duration of Repair

: 2.00

Inspection At

: PREMIER AUTOMOTIVE SERVICES PTE LTD (CHANGI)

23 CHANGI SOUTH AVE 2 #01-02

SINGAPORE 486443

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,006.87
Revised Amount	:S\$	412.12
Check Items (Estimated)	:S\$	0.00
Total	:S\$	412.12

:S\$ Lump Sum Repair

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

Text size + -

Enquire Transaction History

Transaction History Details

Log Date/Time:

14 Jul 2015 / 08:35:45

Receipt No.:

AACCK001-AX239-150714-000015

Asset Type:

Vehicle

Transaction Amount:

\$75,425.00

Asset ID:

SHC6802C

Channel:

AA Counterless - CYCLE & CARRIAGE KIA PTE LTD

Transaction Type:

01.02 Register New Vehicle (AA)

Business Transaction Reference No.:

20150714083545071899

Vehicle No.:

SHC6802C

Vehicle Type:

H10 - Public Transport Taxi (Motor Car)

Vehicle Attachment 1: Air-Con (Taxi)

Vehicle Attachment 2:

Vehicle Attachment 3:

Vehicle Scheme:

Taxi (Company)

First Registration Date: 14 Jul 2015

Original Registration

Date:

14 Jul 2015

Vehicle Make:

KIA

Vehicle Model:

OPTIMA 1.7(A) DIESEL

Chassis No.:

KNAGM414MF5593926

Engine No.:

D4FDEH313550

Motor No .:

Trailer Chassis No.: Propellant:

Diesel

Passenger Capacity:

Engine Capacity:

1685

Power Rating:

1584

Unladen Weight: Maximum Laden

2050

Weight:

Silver

Primary Color:

Secondary Color:

Manufacturing Year: 2014

Open Market Value:

\$21,629.00

Minimum PARF Benefit: \$13,368.00

PARF Eligibility: No. of Transfer:

Effective Ownership

14 Jul 2015 08:35:45

Date/Time: COE No.:

2015071401002893R

COE Expiry Date:

13 Jul 2023

COE Bid Category:

Actual QP/PQP Paid Amount:

\$53,004.00

Lifespan Expiry Date:

13 Jul 2023

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

aforesaid.	AND SECOND COMPANY OF THE PROPERTY OF THE PROP
	ACCIDENT STATEMENT
Date Of Report	24/06/2019 11:07
Date Of Accident	23/06/2019 15:30
Exact Location Of Accident	WOODLANDS CENTRE ROAD
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SHC6802C
Insured/Policyholder	
Name Of Registered Owner	PREMIER TAXIS PTE LTD
Co Reg No	200304975H
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62148880
Vehicle Particulars	
Manufacturer	KIA
Model	OPTIMA-1.7 D (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	5107202885
Cover Note Number	
Driver	
Name of Driver	KOH SZE HOW
NDIC No.	070010001

NRIC No S7931988J Date Of Birth 11/10/1979 Occupation OUTDOOR Date Of Driving Pass 20/12/2000 Driving Experience

18 YEARS AND 6 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-91789596

Fax Number Contact Number

EMail Address NOEMAIL Address

BLK 93A #05-159

TELOK BLANGAH STREET 31

Postcode

101093

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - HIRER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - CHANGE/CROSS LANE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

2

Number of Passengers (Including Driver)

Passenger 1

NAME:

: PAX IN THE REAR SEAT - CHINESE

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

VEH. A - 1 PAX VEH. B - 4 PAX

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLK4766Y

Vehicle Make/Model/Colour

SUBARU FORESTER

Details Of Properties

VEH B

Vehicle Category

PRIVATE CAR

Name of Driver

MALE CHINESE

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

DAMAGED ON THE LEFT FRONT PORTION

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of;
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

A Laxis


Policyholder's Signature Date & Time: × pr

Driver's Signature (If driver is not the policyholder) Date & Time:

C SHC6802C 4 S79319883 2 4 JUN 2019

Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

Sketch Plan Pg. 2



Date & Time:

Page 5 of 13

NRIC/FIN No.:

Sketch Plan Pg. 3

Describe Circumstance of the Accident.

ON 23/06/2019 @ 1530HRS, I WAS DRIVING MY TAXI (SHC 6802 C) – TRAVELING ALONG WOODLANDS CENTRE ROAD WITH A PASSENGER ONBOARD, IN THE LEFT LANE.


WHILE I WAS MOVING STRAIGHT AHEAD – WITHIN MY LANE, SUDDENLY VEHICLE B (SLK 4766 Y – SUBARU FORESTER) WHICH WAS FROM THE RIGHT - FAILED TO KEEP FOR PROPER LOOK OUT, HAD ENCROACHED ONTO MY PATH ON MY RIGHT ABRUPTLY.

AS SUCH, THE LEFT FRONT OF VEHICLE B COLLIDED ONTO THE RIGHT FRONT OF MY TAXI – WHILE HE WAS FILTERING LEFT INTO THE WOODLANDS TRAIN & CHECKPOINT TAXI STAND/DROP OFF.

DUE TO THE IMPACT, MY TAXI HAD DAMAGES ON THE RIGHT FRONT PORTION & VEHICLE B HAD DAMAGES ON THE LEFT FRONT PORTION.

NO INJURY INVOLVED.
VEHICLE B HAD 4 PASSENGERS ONBOARD.

*SCENE PHOTOS & VIDEO FOOTAGE CAPTURED.



Premier Automotive Services Pte Ltd

#01-02, 23 Changi Sth Ave 2

486443

Claim Reference:

Assessment number: 008886

Version: 1810

Date calculated: 25/06/2019 4:17 PM

Full Report

Registration: SHC6802C

Printed: 25/06/2019 4:17 PM

Summary Information

Claim

Location:

Singapore (SG)

Work Provider:

MSIG Insurance (Singapore) Pte Ltd

Printed by:

Claim Reference:

Estimated Repair Time: Actual Repair Days:

WEEDEK GOH

Currency:

Date of Incident:

Hire Car Start: Hire Car End:

SGD 23/06/19

Vehicle Details

Vehicle

Manufacturer:

Model:

Sub Model:

Model Sheet Number:

Registration:

VIN number:

Odometer:

KIA

OPTIMA (TF)

BASE MODEL

28 36 01

SHC6802C

Kahin 1004

1 25/6/19 1630L.

2 lys.

Us
After Ryzple

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey betspelatter spray painting To display damaged part(s) during resurvey
- Pads prices are subject to continuation.
- Third Early Survey is on a "Vistoria Prejudice" basis
- No illegal modification is allowed.
- Supplementary domesting ust the passurvoyed and is subject to final laptic validom insurance Company.

Acknowledged by Repairer

Signature:

Page 1 of 4

PRINT DATE 25/06/2019

Audatex System Using Manufacturer Times

Premier Automotive Services Pte

#01-02, 23 Changi Sth Ave 2 486443

Claim Reference:

Assessment number: 008886

Version: 1810

Date calculated: 25/06/2019 4:17 PM

Full Report

Registration: SHC6802C

Printed: 25/06/2019 4:17 PM


Vehicle Condition

Vehicle Status

Pre-Accident Damage: Date of Inspection:

Damage Areas

All Underbody



Labour

	Time Base 10 WU/h	Pri	ce = 50.	00 SGD/h
Code	Description		wu	Price SGD
66300R00)	RENEW R/FRT WING (BUMPER REMOVED) INCLUDE: WHEELHOUSE LINER AND REQUIRED		6.0	30.00
86451R00	ATTACHED PARTS IN REPAIR AREA R + R R + R LEFT FRONT WHEELHOUSE SHELL			
	1 HAN LEGATO WELLOW SELECTION OF THE SELECTION OF TH		3.0	15.00
86512R00)	RENEW FRONT BUMPER (BUMPER REMOVED) INCLUDES: R + R NECESSARY ATTACHED PARTS		7.0	35.00
87755R00	R + R R/SILL TRIM		3.0	15.00
NN	R/F WHEEL COVER R&R / NEW PARTS		10.0*	50.00
	Labour Cost	Hrs	wu	
	Panel / Mechanical Labour	2.90	29.0	145.00
	Total of Labour			145.00

Premier Automotive Services Pte Ltd

#01-02, 23 Changi Sth Ave 2 486443

Claim Reference:

Full Report

Assessment number: 008886

Registration: SHC6802C

Version: 1810

Printed: 25/06/2019 4:17 PM

Date calculated: 25/06/2019 4:17 PM

Material Cost - Paint

_				н
_	-	•	•	۰
_	~			U
	•			

Paint Work	SYSTEM AZT	Time Basis 10WU/h	
Code	Description	WU Price SGD	
	R/F WING NEW PART PAINTING	9.0	
	FRONT BUMPER NEW PART PAINT K1R	11.0	

Paint Material Per Part

Code	Description	Price SGD
0742	R/F WING NEW PART PAINTING	12.90
0283	FRONT BUMPER NEW PART PAINT K1R	47.12

Labour Cost - Paint		Hrs	WU	Price SGD
Factor	50.00 SGD/h			
Time Paint	65		20.0	
Preparation Main Work Metal		0.70	7.0	35.00
Preparation Comp. Work Plastic		0.30	3.0	15.00
Total	10 WU/h	3.00	30.0	150.00

Placerial Cost - Failit	Price SGD
New Part Painting	12.90
New Part Painting - Plastic K1R	47.12
Material-constant Metal	18.10
Material-constant Plastic	9.00
Total	87.12

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01 Price SGD
0283	FRONT BUMPER	865112T500	xm	531.00
0431	GRILLE BADGE	863183R500	* "	0.00
0742	R/F WING	663212T000	XM	384.00
7212	R/F WHEEL COVER	529602T100	x rypri	0.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			915.00
u: Used parts	Subtotal Discount	(+35.00%)		-320.25

Drice SCD

Premier Automotive Services Pte Ltd

#01-02, 23 Changi Sth Ave 2 486443

Claim Reference:

Assessment number: 008886

Version: 1810

Date calculated: 25/06/2019 4:17 PM

Full Report

Registration: SHC6802C

Printed: 25/06/2019 4:17 PM

_	6.115		
т	_	+-	
	u	La	

594.75

Ex	tr	as
----	----	----

Code	Description	Price SGD
1000	RH Wing sticker	₩ ¥ 30.00*
7212	[E]: R/F WHEEL COVER: Repair Back	0.00*
	Total Extras	30.00

Final Calculation

	SGD	SGD
Parts	915.00	
Total Discount(+35.00%)	-320.25	
Total Parts	323.23	594.75
Labour Time Base 10 WU/h		
Total 29.0 WU X 50.00 SGD/h	145.00	
Total of Labour	265	145.00
Total Of Extras		30.00
Paint Work Time Base 10 WU/h		
Labour Cost 30.0 WU X 50.00 SGD/h	150.00 246	>
Material Cost	87.12 74	30
Total Paint Including Material		237.12
Repair Cost Excludes GST		1,006.87
GST (+7.0%)		70.48
Repair Cost Included GST		1,077.35

1216.87

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

Claim Reference:

Assessment number: SHC6802C

Version: 1810

Date calculated: 28/06/2019 10:32 AM

Full Report

Registration: SHC6802C Printed: 28/06/2019 10:32 AM

Summary Information

Claim

Location:

Singapore (SG)

Work Provider:

MSIG Insurance (Singapore) Pte Ltd

Printed by:

WEEDEK GOH

Currency: Date of Incident: SGD 23/06/19

Claim Reference: Estimated Repair Time: Actual Repair Days:

Hire Car Start:

Hire Car End:

Vehicle Details

Vehicle

Manufacturer:

KIA

Model: Sub Model: OPTIMA (TF) BASE MODEL

Model Sheet Number:

28 36 01 SHC6802C

Registration: VIN number: Odometer:

Claim Reference:

Assessment number: SHC6802C

Version: 1810

Date calculated: 28/06/2019 10:32 AM

Full Report

Registration: SHC6802C Printed: 28/06/2019 10:32 AM

Vehicle Condition


Vehicle Status

Pre-Accident Damage: Date of Inspection:

Damage Areas

All Underbody





	Time Base 10 WU/h	Price	= 50.	00 SGD/h
Code	Description		wu	Price SGD
86451R00	R + R LEFT FRONT WHEELHOUSE SHELL		3.0	15.00
NN	R/F WHEEL COVER R&R / NEW PARTS	1	*0.0	50.00
0283	FRONT BUMPER REPAIR	2	0.0*	100.00
0741	L/F WING REPAIR	2	0.0*	100.00
	Labour Cost	Hrs	wu	
	Panel / Mechanical Labour	5.30	53.0	265.00
	Total of Labour			265.00

Paint		
Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description	WU Price SGD
	FRONT BUMPER REPAIR PAINT PLASTIC	15.0

Claim Reference:

Full Report

Assessment number: SHC6802C

Registration: SHC6802C Printed: 28/06/2019 10:32 AM

Version: 1810

Date calculated: 28/06/2019 10:32 AM

Paint Work

SYSTEM AZT

Time Basis 10WU/h

Code

Description

WU Price SGD

L/F WING REPAIR PAINTING <50%

10.0

Paint Material Per Part

Code	
0283	
0741	

Description

Price SGD

FRONT BUMPER REPAIR PAINT PLASTIC L/F WING REPAIR PAINTING <50%

40.50 8.00

Labour Cost - Paint		Hrs	wu	Price SGD
Factor	50.00 SGD/h	2075	50,6174	
Time Paint	•		25.0	
Preparation Main Work Metal		1.70	17.0	85.00
Preparation Comp. Work Plastic		0.60	6.0	30.00
Total	10 WU/h	4.80	48.0	240.00

Material Cost - Paint	Price SGD
Repair Painting	8.00
Repair Painting Plastic	40.50
Material-constant Metal	18.10
Material-constant Plastic	12.70
Total	79.30

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01 Price SGD
7212	R/F WHEEL COVER	529602T100		0.00
f: OEM Parts n: Non-OEM Parts u: Used parts	Savings Subtotal			0.00
a. osca parco	Total			0.00

Extras

Code	Description	Price SGD
7212	[E]: R/F WHEEL COVER : Repair Back	0.00*

Claim Reference:

Full Report

Assessment number: SHC6802C

Registration: SHC6802C

Version: 1810

Printed: 28/06/2019 10:32 AM

Date calculated: 28/06/2019 10:32 AM

Code

Description

Price SGD

Final Calculation		
	SGD	SGD
Labour Time Base 10 WU/h		
Total 53.0 WU X 50.00 SGD/h	265.00	
Total of Labour		265.00
Total Of Extras		0.00
Paint Work Time Base 10 WU/h		
Labour Cost 48.0 WU X 50.00 SGD/h	240.00	
Material Cost	79.30	
Total Paint Including Material		319.30
Repair Cost Excludes GST		584.30
GST (+7.0%)		40.90
Repair Cost Included GST		625.20

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS) - WU PARTIAL INCL IN OTHER POSITIONS

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case 1	Votified	Est Submitted	Adj Assigned	Adj Rpt		Adj Sub	mitted	Ins Auth'ed	Status		
Main 2	24 Jun 2019		25 Jun 2019 16:58 Edit Adj Rpt	S\$584.30 Edit Estima	-	S\$584. View R	100 mg		Repor	Pending for Survey Report Cancel Case	
М	ain	Re	ference		Claim D	etails		Docum	ents	1	Show All
CLAIM SUB	FOLDER DE	TAILS	ONE CLASS SANCERS	A PARTY STREET, ONLY	NASCHED COLD	NACE HIS THE	[Create	ed by insurer]	ADDIAMINATED SECTION	Service Labor	THE RESIDENCE
Insured:	YEO MEI	LIN, ID: S80258	70D				16				
Main Claimant:	PREMIER	TAXIS PTE LTD,	Co. Reg. No.:	200304975	н						
Vehicle Reg. No.:	SHC6802C			Date o	of Loss:	K 1 1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	/2019 15:00 - :59 Ionths and 9 Days From LTA Reg Date (Man Yr			Man Yr)]	
Claim Type:	pe: TP / 597682 Policy/Cover Note No.: A28879833QMY (Comprehensive) Coverage: 18/01/2019 - 17/01/20										
Vehicle Reg. No. SLK4766Y Policy I (Claims											
					Exces		S\$500.0				
Repairer:	Premier A	utomotive Servi	ces Pte Ltd (Ch	nangi) 23 Cl	hangi Soi	uth Ave	2 #01-02	2, 486443 Chang	i - Tel:		
Handling Insurer:	MSIG Ins	urance (Singapo	re) Pte. Ltd. (H	IQ) - Tel: +6	55 6827	7888	[Handled	by Pauline Tha	m - 6594 2	545]	
Adjuster:	25/07/20	Consultants Pte (19]	Ltd (HQ) - Tel:	6256-3561	[Hand	lled by k	(ALVIN	NG WEI KUN	[Final	Rpt due	2
Driver/Custo dian (Insured):		LEONG CHYN HWI	/ (41 / Male) ,	NRIC: S781	17326B E	mail:					
Adj Asg. Remarks:		anual assigned) Ve nail on 25/06/2019		ite. TP agree	on SJE -	- assign	LKK. Con	tact: Mr Chua @	65446689	Manually	assigned t
ASSOCIATE	D MAIL RE	CEIVED							View All	Compo	se Case Mai
There are no	mail for this	case.		- W - X-					-		
ALL ASSOC	IATED TAS	KS⊟					View A	II Search Task	S Create N	lew Task	Complet

Claim Documents

*SHC6802C (597682)

[SLK4766Y]

TP

PREMIER TAXIS PTE LTD

Jun 23 2019 3:00PM

[YEO MEI LIN]

Premier Automotive Services Pte Ltd

Up	load Documents Upload Photos Compose New Letter		View	View in Brow	rser ▼
Ass	sessment Reports		1 per	page 🔻	•
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Prin
1	26/06/19 10:30	Adjuster Immediate Advice	0	Load HTM	
Pho	otos/Images		3 per	page ▼	•
No.	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	26/06/19 09:29	General View	0	Load JPG	•
2	26/06/19 09:29	General View	0	Load JPG	•
3	26/06/19 09:29	General View	0	Load JPG	•
4	26/06/19 09:29	General View	0	Load JPG	•
5	26/06/19 09:29	General View	0	Load JPG	•
6	26/06/19 09:29	General View	0	Load JPG	•
7	26/06/19 09:29	General View	0	Load JPG	•
3	26/06/19 09:29	General View	0	Load JPG	•
9	26/06/19 09:29	General View	0	Load JPG	•
10	26/06/19 09:29	General View	0	Load JPG	•
11	26/06/19 09:29	General View	0	Load JPG	•
12	26/06/19 09:29	General View	0	Load JPG	•
13	26/06/19 09:29	General View	0	Load JPG	•
14	26/06/19 09:29	General View	0	Load JPG	•
15	01/07/19 08:56	Reinspection Photo	0	Load JPG	•
16	01/07/19 08:56	Reinspection Photo	0	Load JPG	•
17	01/07/19 08:56	Reinspection Photo	0	Load JPG	•
18	01/07/19 08:56	Reinspection Photo	0	Load JPG	•
Doc	cumentation		1 per	page v	•
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	
1	25/06/19 15:43	PRI	0	Load PDF	
2	25/06/19 15:43	OI Accident Report	0	Load PDF	
3	25/06/19 15:43	TP SHC6802C E-REPORT	0	Load PDF	
1	25/06/19 15:54	Agree on SJE	0	Load PDF	
Vo.	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)		Thumbnail	Print
1	25/06/19 16:56	Survey Request - Manual Assigned	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save	Print
There are no document checklists configured.		2025/11/27 (2/12)

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)		
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.		

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Pava Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/MSG19011176/K1QD3S2

D4FDEH313550

458773 km

KNAGM414MF5593926

Date:

05/07/2019

REFERENCE

Handling Insurer: Claimant Vehicle

MSIG Insurance (Singapore) Pte. Ltd.

SHC6802C

No: Date of Loss: 23/06/2019 Policy No:

A28879833QMY

Insured Vehicle No:

SLK4766Y

Nature of Claim:

TP

Engine No:

Chassis No:

Odometer:

Claim No: 597682

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SHC6802C

Make & Model:

KIA OPTIMA, 1.7 D (A)

14/07/2015 (Man. Year: 2014)

Reg. Date: Colour:

Silver

Engine Capacity:

1685 cc

Market Value/New Car Price:

Sum Insured (S\$):

N/A

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes No

Footbrake (Serviceable): Pre-accident Condition:

Yes

Handbrake (Serviceable):

CONDITION OF TYRES

Yes

Engine Modification:

Rear Tyre Size:

205/65 R16

Front Tyre Size: Front Left Side: Front Right Side: 205/65 R16 Achilles 7 mm

Rear Left Side: Rear Right Side:

Achilles 7 mm Achilles 7 mm

Achilles 7 mm The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	624.75	0.00	624.75	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	592.12	584.30	7.82	1.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,216.87	584.30	632.57	51.98
+ GST 7.00/7.00% (S\$)	85.18	40.90	44.28	51.98
Nett Amount (S\$)	1,302.05	625.20	676.85	51.98

INSPECTION

Date of Assignment:

25/06/2019

Date Inspected:

25/06/2019 Inspected At:

Premier Automotive Services Pte Ltd (Changi)

23 Changi South Ave 2 #01-02

Singapore 486443

Estimated Period of Repair:

2.0 days

Adjuster:

KALVIN ANG WEI KUN

Manager:

SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Jul 2019)

Parts: 143 KIA OPTIMA 1.7 D (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHC6802C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

Qty	Part No.	Particulars	Condition	Repairer's	Amount
1		*FRONT BUMPER	Repair	531.00 FL	*-FL
1		*GRILLE BADGE (NPA)	Not Necessary	0.00 FL	*-FL
1		*R/F WING	Repair	384.00 FL	*-FL
1		*R/F WHEEL COVER (NPA)	Repair	0.00 FL	*-FL
1 inchise	nart S=SncNett	*RH WING STICKER	Not Necessary	30.00 FS	*-FS
11011100	part o operior	. California de la calacteria de la cala	Sub Total (S\$)	945.00	0.00
		- List Item Discou	int on L Items 35.00/35.00% (S\$)	320.25	0.00
			Total Parts (S\$)	624.75	0.00
	1 1 1 1 1 1	1 1 1 1	1 *FRONT BUMPER 1 *GRILLE BADGE (NPA) 1 *R/F WING 1 *R/F WHEEL COVER (NPA) 1 *RH WING STICKER anchise part. S=SpcNett. L=ListItemDisc.	1 *FRONT BUMPER Repair 1 *GRILLE BADGE (NPA) Not Necessary 1 *R/F WING Repair 1 *R/F WHEEL COVER (NPA) Repair 1 *RH WING STICKER Not Necessary anchise part. S=SpcNett. L=ListItemDisc. —	1 *FRONT BUMPER Repair 531.00 FL 1 *GRILLE BADGE (NPA) Not Necessary 0.00 FL 1 *R/F WING Repair 384.00 FL 1 *RH WING STICKER Not Necessary 0.00 FL 1 *RH WING STICKER Not Necessary 30.00 FS anchise part. S=SpcNett. L=ListItemDisc. Sub Total (S\$) 945.00 - List Item Discount on L Items 35.00/35.00% (S\$) 320.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TOTAL LABOUR.	New	265.00	265.00
2	PAINT WORK: LABOUR COST.	New	240.00	240.00
3	PAINT WORK: MATERIAL COST.	New	87.12	79.30
		Gross Labour Cost (S\$)	592.12	584.30
	Penortu	vas unsubmitted during this print-out		

< END OF ESTIMATES >