

**COMFORTDELGRO ENGINEERING PTE LTD**

**REPAIR ESTIMATE\***

ACG

VEHICLE NO : SH 8208Z

DATE 24/6/2019 14:23

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>Rebuilt</i>			\$ 553.00
	Rear Bumper Reinforcement <i>Xsu</i>			\$ 428.40
	Rear Bumper Reinforcement Bracket (LH/RH) <i>Xsu</i>		\$ 80.30	\$ 160.60
	Rear Bumper Clip 10 pcs <i>nd</i>			\$ 22.00
	Rear Bumper Bracket <i>Xsu</i>		\$ 35.60	\$ 71.20
	Rear Bumper Sponge <i>Xsu</i>			\$ 103.50
	Rear Bumper Under Cover <i>nd</i>			\$ 228.00
	<b>SUB TOTAL</b>			<b>\$ 1,566.70</b>
	<b>LESS 20%</b>			<b>\$ 313.34</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 1,253.36</b>
	Rear Bumper Rubber Mat <i>nd</i>			\$ 50.00 <b>Nett</b>
	Rear Bumper Advertisement Logo <i>Xsu</i>			\$ 50.00 <b>Nett</b>
	Rear Bumper Reverse Sensor <i>Xsu</i>			\$ 135.70 <b>Nett</b>
	Rear Fender Advertisement Logo (LH/RH) <i>Xsu</i>		\$ 100.00	\$ 200.00 <b>Nett</b>
				<b>\$ 435.70</b>
	<b>Labour Charge</b>			
	Panel Beating			\$ <del>400.00</del> <b>200</b>
	Spray Painting Charge			\$ <del>300.00</del> <b>200</b>
	Wiring Charge			\$ 30.00 <b>X<sub>2</sub></b>
	Remove/Refix Reverse Sensor			\$ <del>80.00</del> <b>30</b>
	<b>TOTAL LABOUR</b>			<b>\$ 810.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 2,499.06</b>

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before spray painting
- To display during a repair/during resurvey
- Parts prices are subject to fluctuation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

Larry Ng

*Calvin LKK*  
*24/6/19 1535h*  
*2 by,*  
*PIP*  
*Before Paint photo*

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.