

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

21-Jun-19

ESTIMATE REPAIR BILL FOR HYUNDAI I30 (A) REGN NO: SHD 1404 X

1 pc	O/s mirror Assy	mis	\$	742.49
	<i>o/s front door x rep</i>		Less 20%	\$ 148.50
			\$	593.99

S/NETT

1 set	o/s door stickers	nec	\$	100.00
-------	-------------------	-----	----	--------

Sundry NEC

\$ ~~50.00~~
20

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same

\$ ~~300.00~~
200

To putty and spray painting on front o/s door

\$ ~~200.00~~
180

To apply rustproofing on the repaired and replaced panels.

\$ ~~80.00~~
\$ 1,323.99

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kehi 10/10/19
24/6/19 10:10hr
2 Reps
PIP
After Repair photo

LPK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To spray paint and partial during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplemental claim must be insured and is subject to final approval from insurance company

Acknowledged by Repairer
Signature:
Date: