

ENDORSE

ASS. REC. BY:

REF: CS/INC 1901184/Dg/302

Special Instruction:

Surveyor: Gry/17

ASSIGNMENT (Office)

From (Person): Cynthia Ang

of INC

Date/Time: 25/6/19 @ 9.49am

Estimated Cost:

Bill to:

OD PP WS TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 2352K

Insured: SJM 156 Y

at Workshop m/s

Soon Truck

Tel: 65425119

of

10 Amk Ind. Park 2A #01-05/06

Policy No:

Claim No:

MT 1050341-002

Sum Insured:

Excess:

Make of Veh:

D.O.A

21/6/19

(Client's Record)

26/6/19

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

Date/Time:

3:18pm @ 25/6/19

Person Contacted:

Lynn

Vehicle

IN / OUT

Date/Time

Action/Instruction

Estimate ✓

SHC 2352K : CC3 / AIG / 4019179 / M1pm 352

D.O.A : 04/10/2014

SJM 156Y : ✓

REF:

AGENCY:

ASSIGNMENT

COE Jan 2027

Team: _____ Date: _____

Estimated Cost: _____

OD / IP / WS / IP RES / OP RES / LVA / HIV / MV

To Inspect Vehicle No: _____

at Work shop no: _____

of _____

Insured: _____

Policy No: _____

Claim No: _____

Claim Insured: _____ Excess: _____

(Check Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Est. or Market Value: _____

IDAC Accident Report Consistent? Yes or No


GA / DR Source Consistent? Yes or No

Est. repairs: 12 days Yes: Yes or No

Est. Sum: 20 % 3 Val: Yes or No

GA / REV / REP: / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT



Veh No: SHC 2352K or Page: 2019 Jan

Type: M/Gar / B/Cycle / Bus / Van / Lorry / Truck / Prime Mover /

Truck / Trailer or _____

Make: Toyota Prius or 1798

Colour: Blue AGE: Insured / STD / NI / NA

Sp. Reading: 76487 TRadio: Insured / STD / NI / NA

Eng/No: 2ZR2B84998

C/No: JTDKB3FU903077835

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Good / Jammed / Leaked / Burnt or _____

Brake: Good / Jammed / Leaked / Burnt or _____

Mod: Nil / S/Rim / STD / R/Rim or _____

Tyre Size: F: 195/65 R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Goodyear

Front: S/S mm Rear: S/S mm

R/Ral: S/S mm L/Ral: S/S mm

D.O.A: 21/06/19 D.O.I: 26/06/19 Chunni AMK

Survey held at: Chunni AMK

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Front & Rear O/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time: _____ Action / Instruction: NTUC SJM 156Y

24/07/19 Invoice 2/S 20000/- with 12 days of rep
Chkd \$13753.34, 40%

RECEIVED 24 JUL 2019

Date/Time, File Pass to? Prel. Report

24/7/19 Final Report

Date/Time, File Return to? _____

Days Of Repair: 12

Resurvey No. of Trip: 2

Add Fee: Site Insp (\$)

Interview (\$)

Tech. Inv. (\$)

Weekend (\$)

Survey Fee:	<u>250</u>
Transportation	
Site Insp. fee	
Photos	
Others	
TOTAL	<u>250</u>

Report Format: 71

Lump Sum / LVA: 20000

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE

VEHICLE NO: SHC 2352K

DATE : 21.06.2019

MAKE :

TEL NO : 6542 5119

MODEL : TOYOTA PRIUS

FAX NO : 6542 6039

Nil

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
BONNET <i>Dented</i>			\$ 950.50 ✓
INSULATOR, HOOD <i>NH</i>			\$ 398.10 X
INSULATOR CLIPS <i>NH</i>			\$ 3.60 X
BONNET LOCK <i>BT</i>			\$ 132.60 ✓
RADIATOR GRILLE <i>broken/damaged</i>			\$ 438.00 ✓
RADIATOR GRILLE EMBLEM <i>dislodged</i>			\$ 88.00 ✓
LAMP ASSY, FOG, RH <i>mostly broken</i>			\$ 920.00 ✓
LAMP ASSY, FOG, LH <i>mostly broken</i>			\$ 920.00 ✓
FRONT BUMPER COVER <i>distorted</i>			\$ 499.90 ✓
FRONT BUMPER REINFORCEMENT <i>BT</i>			\$ 696.40 ✓
FRONT BUMPER REINFORCEMENT ABSORBER <i>BT</i>			\$ 115.70 ✓
FRONT BUMPER SPONGE <i>from</i>			\$ 78.80 ✓
FRONT BUMPER CENTRE GRILLE <i>broken/damaged</i>			\$ 301.90 ✓
FRONT BUMPER CLIPS <i>nic</i>			\$ 22.00 ✓
ENGINE UNDER COVER (RRF) <i>broken</i>			\$ 457.40 ✓
COVER, FRONT BUMPER HOLE, RH <i>dislodged</i>			\$ 28.38 ✓
COVER, FRONT BUMPER HOLE, LH <i>cut</i>			\$ 28.38 ✓
FRONT BUMPER LOWER REINFORCEMENT BRACKET (LH/RH) <i>BT/crack</i>		\$ 165.00	\$ 330.00 ✓
FRONT BUMPER CENTRE FRAME <i>BT NH</i>			\$ 236.90 BT X
ABSORBER, FRONT BUMPER, LOWER (SPONGE LOWER) <i>BT broken</i>			\$ 127.70 BT X
UNIT ASSY, HEADLAMP, RH (LED) <i>broken/mostly</i>			\$ 3,455.00 ✓
UNIT ASSY, HEADLAMP, LH (LED) <i>broken mostly</i>			\$ 3,455.00 ✓
HEAD LAMP PANEL (RH) <i>BT</i>			\$ 240.10 BT ✓
HEAD LAMP PANEL (LH) <i>BT</i>			\$ 240.10 BT ✓
TOP PANEL CENTRE <i>BT</i>			\$ 364.90 ✓
TOP PANEL (RH) <i>BT</i>			\$ 145.90 ✓
TOP PANEL (LH) <i>BT</i>			\$ 145.90 ✓
BRACE PANEL <i>BT</i>			\$ 75.20 ✓
RADIATOR ASSY <i>BT</i>			\$ 1,881.30 BT ✓
RADIATOR FAN COWLING ASSY <i>NH</i>			\$ 661.30 X
RADIATOR TOP HOSE, LH <i>NH</i>			\$ 43.03 X
RADIATOR TOP HOSE, RH <i>NH</i>			\$ 42.60 X
RADIATOR BOTTOM MOUNTING <i>NH</i>			\$ 27.50 X
STAY, RADIATOR SUPPORT, RH <i>NH</i>			\$ 65.70 X
STAY, RADIATOR SUPPORT, LH <i>NH</i>			\$ 65.70 X
RADIATOR FAN BLADE (RH) <i>NH</i>			\$ 233.10 X
RADIATOR FAN BLADE (LH) <i>NH</i>			\$ 233.10 X
RADIATOR FAN MOTOR (RH) <i>NH</i>			\$ 543.70 X
RADIATOR FAN MOTOR (LH) <i>NH</i>			\$ 543.70 X
DEFLECTOR, RADIATOR SIDE, RH <i>SVC</i>			\$ 83.50 X
DEFLECTOR, RADIATOR SIDE, LH <i>SVC</i>			\$ 77.00 X
HORN (HIGH) <i>NH</i>			\$ 114.20 X
HORN (LOW) <i>NH</i>			\$ 114.20 X
AIR DUCT CENTRE <i>NH</i>			\$ 129.40 X
INLET ASSY, AIR CLEANER <i>Crack</i>			\$ 132.00 ✓
AIR DUCT CENTRE <i>NH</i>			\$ 94.03 X
CONDENSER ASSY. W/RECEIVER <i>BT</i>			\$ 1,336.60 BT ✓

SHC 2352K

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
FENDER SUB-ASSY, FRONT RH <i>Dental</i>			\$ 945.30	✓
FRONT FENDER SHIELD,RH <i>NN</i>			\$ 196.60	X
FRONT FENDER SHIELD CLIP <i>NH</i>			\$ 3.80	X
FRONT FENDER HYBRID EMBLEM, RH <i>Nic</i>			\$ 53.50	✓
WIRING FRONT <i>with term mainly check connector</i>		<i>24744.46</i>	\$ 6,138.00 <i>6138.00</i>	X ✓
SUB TOTAL		<i>18558.34</i>	\$ 28,655.22	
LESS 20% <i>25%</i>			\$ 5,731.04	
DISCOUNTED TOTAL			\$ 22,924.18	
FRONT NO. PLATE <i>cut</i>			\$ <i>45/ea</i> 25.00	NETT ✓
FRONT NO PLATE TRIM COVER <i>cut</i>			\$ 30.00	NETT ✓
FRONT NO.PLATE GARNISH <i>cut</i>			\$ 99.00	NETT ✓
FRONT DOOR COMFORT LOGO, RH <i>Nec</i>			\$ 75.00	NETT ✓
		<i>219.00</i>	\$ 229.00	
LABOUR CHARGE				
Panel Beating			\$ 1,000.00	800/-
Spray Painting Charge			\$ 1,000.00	800/-
Wiring Charge			\$ 50.00	30/-
Tuff Kote			\$ 100.00	40/-
Towing Charge			\$ 50.00	72
Remove/Refix Aircon & Refill Gas			\$ 150.00	80/-
Remove/Refix Dashboard		<i>2100.00</i>	\$ 400.00	150/-
Remove/Refix Fuse Box			\$ 120.00	50/-
Diagnosis & Resetting To Erase Fault Code			\$ 480.00	150/-
TOTAL LABOUR			\$ 3,350.00	

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE

VEHICLE NO: SHC 2352K (Supplementary)

DATE : 26.06.2019

MAKE :

TEL NO : 6542 5119

MODEL : TOYOTA PRIUS

FAX NO : 6542 6039

	PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	REAR EXHAUST PIPE <i>RT</i>			\$ 1,163.40 ✓
	SUB TOTAL			\$ 1,163.40
	LESS 20% <i>25%</i>			\$ 232.68
	DISCOUNTED TOTAL			\$ 930.72
	<p><i>26/06/2019</i></p> <p><i>Tym</i></p> <p><i>2kk Ando</i></p> <p><i>8</i></p>			872.55

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Yi Ahm

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE

VEHICLE NO: SHC 2352K (Supplementary)

DATE : 26.06.2019

MAKE :

TEL NO : 6542 5119

MODEL : TOYOTA PRIUS

FAX NO : 6542 6039

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
BONNET HINGE (RH) <i>1st</i>			\$ 57.70
BONNET HINGE (LH) <i>1st</i>			\$ 57.70
FRONT BUMPER LOWER REINFORCEMENT <i>1st</i>			\$ 241.40
SUB TOTAL		<i>356.80</i>	\$ 356.80
LESS 20% <i>25%</i>			\$ 71.36
DISCOUNTED TOTAL		<i>267.60</i>	\$ 285.44
 LABOUR CHARGE			
Remove/Refix Engine <i>Chassis repair 1st (Nuc)</i>		<i>250.00</i>	\$ <i>250.00</i>
TOTAL LABOUR			\$ 450.00
ESTIMATE TOTAL			\$ 735.44
 <i>1 year</i>		<i>517.60</i>	
<i>2 KE And</i>			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Nivitha (LKK Auto)

From: Cynthia Ang <Cynthia.Ang@income.com.sg>
Sent: Tuesday, 25 June 2019 3:45 PM
To: 'assignments@lkkauto.com'; Admin-D (LKKAuto)
Subject: RE: TP CASES FARMED OUT TO LKK ON 25/06/2019

Hi LKK,

Resend with the following details.

Thank you.

With Regards

Cynthia Ang
Admin Assistant
Motor Insurance
T +65 6430 7900
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.

Find out more at income.com.sg/careers

IN with you

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

From: Cynthia Ang
Sent: Tuesday, 25 June 2019 9:49 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>
Cc: Teng Ken Leong <kenleong.teng@income.com.sg>; Thio Tse Kiat <tsekiat.thio@income.com.sg>; Cynthia Ang <Cynthia.Ang@income.com.sg>
Subject: TP CASES FARMED OUT TO LKK ON 25/06/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	Eric Tang	MT/1050061-002	FZ6005P	HKL LIM TEAM MOTORSPT	BLK 1008 #01-24 BUKIT MERAH LANE 3 SINGAPORE 159722	James Lim / 9242 3895		XE1528C	21/06/2019	
2	Eric Tang	MT/1050364-002	S1L9897P	PEGASUS ENGINEERING & TRADING PTE LTD	74 KIAN TECK ROAD SINGAPORE 628800	Yoyo / 65137748		SGK2839T	23/06/2019	
3	Jared Liu	MT/1034112-003	S1P4297H	PEGASUS ENGINEERING & TRADING PTE LTD	74 KIAN TECK ROAD SINGAPORE 628800	Yoyo / 65137748	14:00-16:00	YL8550S	01/11/2018	Owner waiting
4	Azhari	MT/1050072-002	SME8157Z	PERFORMANCE MOTORS LTD	303 ALEXANDRA ROAD SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941	Caroline / 6319 0174		SJT7859U	20/06/2019	
5	Serene Lim	MT/1048606-002	SBX2U	PREMIUM AUTOMOBILES PTE LTD	281 ALEXANDRA ROAD SINGAPORE 159938	Tony Foong / 6366 2323	10:00-12:00	GZ7468T	11/06/2019	
6	Jared Liu	MT/1044498-002	JNY2143	A S PHOON PTE LTD	36 TOH GUAN ROAD EAST #01-35 ENTERPRISE HUB SINGAPORE 608580	Kee Ger Ong / 6515 0770		YN4530R	11/05/2019	
7	Helena Tan	MT/1050289-002	SDY193Y	GOLDBELL ENGINEERING PTE LTD	BLK K PANDAN LOOP IND ESTATE #01-12	Soo Leong Keat / 9739 7127	10:00-12:00	GBF918Y	22/06/2019	
8	Cyndiie Yong	MT/1050341-002	SHC2352K	SOON HOCK MOTOR PTE LTD	10 ANG MO KIO IND PK 2-A #01-05/06 AMK AUTOPOINT SINGAPORE 568047	Ms Lynn / 65425119		SJM156Y	21/06/2019	

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

With Regards

Cynthia Ang
Admin Assistant
Motor Insurance
T +65 6430 7900
www.income.com.sg

income
made different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers

in with you

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

MCD819081177 / ComfortDelGro Engineering Pte Ltd - Loyang
 ENTRY DATE & TIME: 22/06/2019 09:39
 SUBMITTED BY: Catherine Por May Juan

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/06/2019 09:39
Date Of Accident	21/06/2019 02:00
Exact Location Of Accident	SLE TO BKE AFT EXIT 11
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC2352K
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	
Manufacturer	TOYOTA
Model	PRIUS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	
Driver	
Name of Driver	NG CHOON LAN
NRIC No	S1621825A
Date Of Birth	15/06/1963
Occupation	OUTDOOR
Date Of Driving Pass	16/08/1983
Driving Experience	35 YEARS AND 10 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-93820601
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	636A 05-309 SENJA RD
Postcode	671636
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJM156Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRT
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	
Vehicle Make/Model/Colour	
Details Of Properties	RAILING
Vehicle Category	NA/UNKNOWN
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damago	NOT SURE
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	NG CHOON LAN
Approximate Age	56
Injuries Sustain	NECK,BACK,LEGS
Injured person in which vehicle?	SHC2352K
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this {form} and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

Refer Attachment.

A) SHC-2352K

B) SJM-1564

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 20/6/19 at 0200hrs while I Veh A was driving along the Slip Road towards SLE, Veh B collided on the right rear portion of my moving vehicle. The impact caused my vehicle to lose control and collided onto the railing on the right and spin 360° and stopped again on the left lane of the slip road facing towards BLE. My Veh A sustained overall body damage (front, back, RH front). Veh B sustained serious damage on its front portion. I felt severe pain on my neck, back, both legs and with be consulting the doctor subsequently.

DECLARATION

I/We declare the foregoing particulars are true in every respect.
 COMFORT TRANSPORTATION PTE LTD
 CO. REG. NO. 199303821R





 \$ E. Moolthy
 CSO
 2/7/19

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



+

[Handwritten signature]

NG CHAN LAM

21-06-2019

[Handwritten signature]
 S R Moorthy
 CSO
 21/6/19.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT			
NTUC INCOME INSURANCE CO-OPERATIVE LTD		Ref: CS/INC19011184/Dqd3e2	
73 BRAS BASAH ROAD		Date: 29-07-2019	
#05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			
ATTN: CYNDIIE YONG		Code: INC	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJM 156Y	Veh. Inspected	SHC 2352K
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1050341-002	Excess (\$)	0.00
Assign From	CYNTHIA ANG	Assign Date	25/06/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	JTDKB3FU903077835	Colour	BLUE
Odometer	76487 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	GOODYEAR	5 mm
L/H Front Tyre	195/65 R15	GOODYEAR	5 mm
R/H Rear Tyre	195/65 R15	GOODYEAR	5 mm
L/H Rear Tyre	195/65 R15	GOODYEAR	5 mm
4. Description of Damages			
<p>THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR O/S PORTION.</p> <p>DAMAGES SEE DETAILS.</p>			
5. General Information			
Accident Date	21/06/2019	Inspect Date / Time	26/06/2019 (09:54 AM)
Survey held at	SOON HOCK CAR CARE BLK 10 AMK IND PK 2A #01-05/06 AMK AUTOPOINT . SINGAPORE 568047		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 2352K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BONNET	DENTED	950.50	950.50
1	INSULATOR, HOOD	NOT NECESSARY	398.10	-
1	INSULATOR CLIPS	NOT NECESSARY	3.60	-
1	BONNET LOCK	BENT	132.60	132.60
1	RADIATOR GRILLE	BROKEN / DEFORMED	438.00	438.00
1	RADIATOR GRILLE EMBLEM	DISLodge	88.00	88.00
1	LAMP ASSY, FOG, RH	MOUNTING BROKEN	920.00	920.00
1	LAMP ASSY, FOG, LH	MOUNTING BROKEN	920.00	920.00
1	FRONT BUMPER COVER	DISTORTED	499.90	499.90
1	FRONT BUMPER REINFORCEMENT	BENT	696.40	696.40
1	FRONT BUMPER REINFORCEMENT ABSORBER	BENT	115.70	115.70
1	FRONT BUMPER SPONGE	TORN	78.80	78.80
1	FRONT BUMPER CENTRE GRILLE	BROKEN / DEFORMED	301.90	301.90
1	FRONT BUMPER CLIPS	NECESSARY	22.00	22.00
1	ENGINE UNDER COVER	BROKEN	457.40	457.40
1	COVER, FRONT BUMPER HOLE, RH	DISLodge	28.38	28.38
1	COVER, FRONT BUMPER HOLE, LH	CUT	28.38	28.38
2	FRONT BUMPER LOWER REINFORCEMENT BRACKET (LH/RH) @\$165.00	BENT / CRACKED	330.00	330.00
1	FRONT BUMPER CENTRE FRAME	NOT NECESSARY	236.90	-
1	ABSORBER, FRONT BUMPER, LOWER (SPONGE LOWER)	BROKEN	127.70	127.70
1	UNIT ASSY, HEADLAMP, RH (LED)	MOUNTING BROKEN	3,455.00	3,455.00
1	UNIT ASSY, HEADLAMP, LH (LED)	MOUNTING BROKEN	3,455.00	3,455.00
1	HEAD LAMP PANEL (RH)	BENT	240.10	240.10
1	HEAD LAMP PANEL (LH)	BENT	240.10	240.10
1	TOP PANEL CENTRE	BENT	364.90	364.90
1	TOP PANEL (RH)	BENT	145.90	145.90

Report Ref No. CS/INC19011184/Dqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TOP PANEL (LH)	BENT	145.90	145.90
1	BRACE PANEL	BENT	75.20	75.20
1	RADIATOR ASSY	BENT	1,881.30	1,881.30
1	RADIATOR FAN COWLING ASSY	NOT NECESSARY	661.30	-
1	RADIATOR TOP HOSE, LH	NOT NECESSARY	43.03	-
1	RADIATOR TOP HOSE, RH	NOT NECESSARY	42.60	-
1	RADIATOR BOTTOM MOUNTING	NOT NECESSARY	27.50	-
1	STAY, RADIATOR SUPPORT, RH	NOT NECESSARY	65.70	-
1	STAY, RADIATOR SUPPORT, LH	NOT NECESSARY	65.70	-
1	RADIATOR FAN BLADE (RH)	NOT NECESSARY	233.10	-
1	RADIATOR FAN BLADE (LH)	NOT NECESSARY	233.10	-
1	RADIATOR FAN MOTOR (RH)	NOT NECESSARY	543.70	-
1	RADIATOR FAN MOTOR (LH)	NOT NECESSARY	543.70	-
1	DEFLECTOR, RADIATOR SIDE, RH	SERVICEABLE	83.50	-
1	DEFLECTOR, RADIATOR SIDE, LH	SERVICEABLE	77.00	-
1	HORN (HIGH)	NOT NECESSARY	114.20	-
1	HORN (LOW)	NOT NECESSARY	114.20	-
1	AIR DUCT CENTRE	NOT NECESSARY	129.40	-
1	INLET ASSY, AIR CLEANER	CRACKED	132.00	132.00
1	AIR DUCT CENTRE	NOT NECESSARY	94.03	-
1	CONDENSER ASSY, W/RECEIVER	BENT	1,336.60	1,336.60
1	FENDER SUB-ASSY, FRONT RH	DENTED	945.30	945.30
1	FRONT FENDER SHIELD, RH	NOT NECESSARY	196.60	-
1	FRONT FENDER SHIELD CLIP	NOT NECESSARY	3.80	-
1	FRONT FENDER HYBRID EMBLEM, RH	NECESSARY	53.50	53.50
1	WIRING FRONT	TORN / CONNECTOR CRACKED	6,138.00	6,138.00
1	REAR BUMPER	DISTORTED / MOUNTING BROKEN	458.60	458.60
1	REAR BUMPER RE-INFORCEMENT	BENT	318.80	318.80
1	REAR BUMPER COVER	LOWER DISTORTED	552.60	552.60
1	REAR BUMPER SIDE RETAINER	NOT NECESSARY	112.70	-

Report Ref No. CS/INC19011184/Dqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER UNDER SIDE COVER (RH)	NOT NECESSARY	232.00	-
1	REAR BUMPER TOWING COVER	DISTORTED / MOUNTING BROKEN	82.70	82.70
1	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	SEAL, REAR BUMPER SIDE, RH	CUT / MOUNTING BROKEN	148.40	148.40
1	TAIL LAMP ASSY (UPPER) (RH)	CRACKED	557.90	557.90
1	TAIL LAMP ASSY (LOWER) (RH)	CRACKED	548.40	548.40
1	REAR FENDER, RH	DENTED	836.70	836.70
1	REAR FENDER SHIELD (RH)	NOT NECESSARY	134.20	-
1	REAR EXHAUST PIPE (ADDITIONAL)	BENT	1,163.40	1,163.40
1	BONNET HINGE (RH) (ADDITIONAL)	BENT	57.70	57.70
1	BONNET HINGE (LH) (ADDITIONAL)	BENT	57.70	57.70
1	FRONT BUMPER LOWER REINFORCEMENT (ADDITIONAL)	BENT	241.40	241.40
	LESS 20% DISCOUNT		-6,836.08	-
	LESS 25% DISCOUNT		-	-7,447.69
			27,344.34	22,343.07
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NO. PLATE (SN) }	CUT	25.00	45.00
1	FRONT NO. PLATE TRIM COVER (SN) }		30.00	-
1	FRONT NO. PLATE GARNISH (SN)	CUT	99.00	99.00
1	FRONT DOOR COMFORT LOGO, RH (SN)	NECESSARY	75.00	75.00
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
			279.00	269.00
	<u>LABOUR</u>			
	PANEL BEATING.		2,000.00	1,300.00
	SPRAY PAINTING CHARGE.		1,500.00	1,200.00
	WIRING CHARGE.		100.00	60.00
	TUFF KOTE.		150.00	60.00
	TOWING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE / REFIX AIRCON & REFILL GAS.		150.00	80.00
	REMOVE / REFIX DASHBOARD.		400.00	150.00

Report Ref No. CS/INC19011184/Dqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE / REFIX FUSE BOX.		120.00	50.00
	DIAGNOSIS & RESETTING TO ERASE FAULT CODE.		480.00	150.00
	REMOVE / REFIX CUSHION & UPHOLSTERY REAR.		150.00	80.00
	REMOVE / REFIX REVERSE SENSOR.		80.00	40.00
	REMOVE / REFIX ENGINE. (ADDITIONAL)		450.00	250.00
			5,630.00	3,420.00
	GRAND TOTAL		33,253.34	26,032.07
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			20,000.00

Report Ref No. CS/INC19011184/Dqd3e2

ANG BRYAN TANI

Automotive Assessor / Investigator

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.