

Worksheet

ASS. REC. BY:

REF: 53/MSG/19008624/GKL3⁰²

Serial Instruction:

Summary

GA

ASSIGNMENT (Office)

From (Person): Christina Wong

of MSIG

Date/Time: 24.6.2019

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No: SIB 66854

Insured: FBL 1357A

at Workshop info: Sau Hock Motor

Tel: 91098638

of 10 Amk Industrial Park 2A #02-14

Policy No: MSP/VINT/18-389672

Claim No: MSG/Y/19-000561

Sum Insured:

Excess:

Make of Vch.
(Client's Record)

D.O.A. 11.6.19

CA / REV / REP. / REV 24 HRS

Date/Time: 15.5.19 4:26 PM

Person Contacted: Robert

I.O.D. Endorsement

Vehicle IN/OUT

Date/Time	Action/Instruction (X) (Check)
	SIB 66854 - X
	FBL 1357A - X
	Dismantle: 17/5/2019
	After repair: 21/5/2019
	\$3000, 5 Days.
	(\$ 3,800/- Red - 56%)

Do Not Finalise

[Signature]
9/7/2019

RECEIVED 9 JUL 2019

REF: MSIG

87480

ASSIGNMENT

From: 16.5.2019

Veh No: SUB6685G 18 Apr 2016

Estimated Cost:

Type: M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover

OD: TP / WS / TP RES / OD RES / EVA / INV / MY

Truck / Trailer or

To inspect Vehicle No: SUB 6685G

Make: Honda Vezel 1.5X cc 1496

at Workshop no: Sau Hock Motor

Colour: silver Insured / Std / NI / NA

at 10 Amk Industrial Park 2A # 02-14

Sp Reading: 43640 Life Insured / Std / NI / NA

Insured:

Engine:

Policy No:

Chassis:

Claims No:

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: The / Jammed / Locked / Burnt or

(Client's Receipt)

Brake: In / Jammed / Leaked / Burnt or

Make of Veh:

Mod: Nil / S/Rim / STD / Rim or

(Policy Condition)

Tyre Size:

F:

R:

Remark: The veh had commenced its repair at the time of inspection.



BS / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value:

Front:

Rear:

IDAC Accident Report:

Consistent? Yes or No

R/Bal:

R/Bal:

GIA / PR. Item:

Consistent? Yes or No

L/Bal:

L/Bal:

Est. Repair:

S

days

Res:

Yes or No

D.O.A.

D.O.A.

Lump Sum:

%

Val:

Yes or No

Survey held at:

w/s

CA / REV / REP. / 24 HRS

"up"

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time:

Action / Instruction:

\$4000 - \$5000

17/5/2019

Date/Time: File Pass to:

☐

Prel. Report

Days Of Repair: 5

11

☐

Final Report

Resurvey No. of Trip: 2

Date/Time: File Return to:

25

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Insp (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

1 - 100 km

1 - 100 km

1 - 100 km

1 - 100 km

1 - 100 km

Report Format:

PRC

Lump Sum / L.B.L: (\$)

120

11

131

Nivitha (LKK Auto)

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Monday, 24 June 2019 5:41 PM
To: Christina Wong; assignments
Subject: RE: Our ref:MSC/v/19000561 Your ref:SLB6685G -Paper Survey needed Urgently

Dear Christina,

Thank you for the email.

Dear Assignment Team,

FYNA

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Christina Wong <Christina_Wong@sg.msig-asia.com>
Sent: Monday, 24 June 2019 5:39 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: Our ref:MSC/v/19000561 Your ref:SLB6685G -Paper Survey needed Urgently

Der Veron





Please expedite paper survey, TP lawyer kept chasing.

I have sendback report in Merimen.

Best Regards

Christina Wong
Senior Executive, Claims Services (Motor)
Direct line +65 6643 1311 | Direct fax +65 6225 7402 | christina_wong@sg.msig-asia.com



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | <http://www.msig.com.sg/> | Follow us on    

A member of  INSURANCE GROUP

PAR Automotive Consultancy

Regn. No. S2986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0279-19-SHM

24 May 2019

Lim Eng Hiong Joseph
Blk 553 Ang Mo Kio Ave 10 #06-1992
Singapore 560553

INVOICE No. 0279-19-SHM

Vehicle No. SLB6685G

<u>S/NO.</u>	<u>SERVICES RENDERED</u>	<u>Amount due</u>
1	Being accident vehicle appraisal services, transport, photographs and re-inspection (work in progress and post repair inspection).	\$697.00
Total amount payable		<u>\$697.00</u>

Kindly cross your cheque in favour of "PAR Automotive Consultancy"

We thank you in anticipation for your prompt payment.

• PAR Automotive Consultancy



Report No: 0279-19-SHM

24 May 2019

ACCIDENT VEHICLE SURVEY REPORT

Lim Eng Hiong Joseph
Blk 553 Ang Mo Kio Ave 10 #06-1992
Singapore 560553

VEHICLE INFORMATION:

Vehicle Reg No.:	SLB6685G	Odometer:	043640km
Make & Model:	Honda Vezel 1.5X A	Colour:	Silver
Chassis number:	RU11113153	Date of accident:	11/05/2019
Year of Regn.:	18/04/2016	Date inspected:	13/05/2019
Repairer at:	Sau Hock Motor Services	Date inspected (After Repair):	21/05/2019
	Blk 10 Ang Mo Kio Ind Park 2A #02-14		
	AMK AutoPoint		
	Singapore 568047		

STATIC CHECKS, where applicable:

Steering :	serviceable
Footbrake :	serviceable
Handbrake :	serviceable
Paintwork :	Good
General condition :	Good

TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
Front:	6mm/Dunlop	6mm/Dunlop	215/60R16
Rear:	6mm/Dunlop	6mm/Dunlop	215/60R16

POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the rear portion.
Please see details as described in the Annex for parts and labour.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

Parts and Labour Assessment

Report No: 0279-19-SHM

Vehicle No: SLB6685G

Description of part	Qty	Condition as inspected	Repairer's estimate	Our adjustment
Rear bumper	1	squashed	762.70	/ 762.70
Rear bumper RH/LH <i>NN</i>	2	deformed	390.00	X 390.00
Rear bumper reflector RH/LH <i>LH - CPA</i> <i>RH X NN</i>	1 / 2	fractured	282.20	141.1 / 282.20
Rear bumper side retainer RH/LH <i>NN</i>	2	necessary	44.00	X 44.00
Rear end panel <i>Repair</i>	1	buckled	415.60	X 415.60
Rear end panel inner tailgate antenna sensor	1	reuse	85.00	0.00
Rear end panel lower under cover	1	reuse	190.00	0.00
Rear end panel outer buzzer	1	reuse	80.00	0.00
Tailgate	1	buckled	953.30	/ 953.30
Tailgate logo "Honda" <i>NN</i>	1	necessary	25.00	X 25.00
Tailgate emblem "Vezel"	1	necessary	56.20	/ 56.20
Tailgate mechanism lock	1	bent	157.50	/ 157.50
Rear number plate lamp RH/LH	2	fractured	77.00	X 77.00
Tailgate outer garnish	1	fractured	220.00	X 220.00
Tailgate outer garnish clip - set	11	necessary	71.50	X 71.50
Tailgate outer lock handle switch	1	shorted	175.50	X 175.50
Tailgate reflector lamp back rubber gasket RH/LH	2	necessary	37.00	X 37.00
Tailgate reflector lamp clip RH/LH	6	necessary	39.00	26 39.00
Tailgate reflector lamp RH/LH <i>LH - CPA</i> <i>RH X NN</i>	1 / 2	fractured	826.40	326.2 826.40
Tailgate rubber guide stopper RH/LH <i>NN</i>	2	deformed	25.00	X 25.00
Tailgate weatherstrip	1	deformed	96.80	/ 96.80
Tailgate windscreen moulding	1	necessary	120.00	67.9 120.00
Rear tail lamp back rubber gasket RH/LH <i>NN</i>	2	necessary	130.60	X 130.60
Rear tail lamp clip RH/LH	8	necessary	52.00	X 52.00
Rear tail lamp inner panel RH/LH	2	repair	270.00	0.00
Rear tail lamp RH/LH <i>NN</i>	2	fractured	949.20	X 949.20
Subtotal before discount			6,531.50	3,906.50
Percentage discount 0% and 20%			0.00	1,181.30
Sub-total 1			6,531.50	4,725.20

2587.7

20%: 2070.16

PAR Automotive Consultancy

Rear bumper clip - set	1	necessary	30.00	✓	30.00
Rear bumper reverse sensor	1	shorted	350.00	200	300.00
Tailgate reverse camera	1	shorted	550.00	N/A	550.00
Tailgate inner trim board clip - set	1	necessary	30.00	✓	30.00
Rear number plate c/w holder	1	reuse	50.00	NN	0.00
Tailgate windscreen sealant	1	necessary	100.00	60	100.00
Subtotal before discount			1,110.00		1,010.00
Percentage discount 0% and 0%			0.00		0.00
Sub-total 2			1,110.00		1,010.00
Parts-total			7,641.50		5,735.20

LABOUR

1. To straighten and panel beating rear fender RH/LH, rear boot floor panel and rear frame members. To cut and weld rear end panel. To remove and refit above parts.	1,600.00	1,250.00	600
2. To putty, re-spray painting and polish affected areas.	1,500.00	1,320.00	600
3. To check and rectify wiring system.	80.00	50.00	30
4. To remove and refit rear windscreen.	150.00	120.00	100
5. To rust proof affected areas.	120.00	60.00	1390
Labour total	3,450.00	2,800.00	
Parts & Labour total	11,091.50	8,535.20	

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on LUMP SUM repairs is :
and the recommended number of working days for the repairs is :


\$6,800.00

8

B J Loi (I Eng. MIML, AIRTE)
Automotive Appraiser

3780.16
20% : 3000

Pre-inspection SHC6463Y & SLN4629U on 25.06.19

From: Chin, Lee-Ying
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY
Sent: 6/25/2019 3:01:39 PM
Attachments:  25062019143420-0001.pdf

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

From: Liew Hai Leong [<mailto:haileong.liew@premiertaxi.com>]
Sent: Tuesday, June 25, 2019 2:37 PM
To: AIG SGP, Claims-Survey
Cc: Goh Wee Dek; Vincent Chua
Subject: [EXTERNAL] Pre-inspection SHC6463Y & SLN4629U on 25.06.19

This message is from an external sender; be cautious with links and attachments.

Dear All

We refer to the above mentioned.

Kindly arrange for survey.

Vehicle in workshop for survey

Regards

Liew Hai Leong

Operation Assistant

Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443
Tel: 6214 8880 Ext 068 | DID: 6544 6689 | Fax: 6214 1511
Visit us at: www.premiertaxi.com.sg

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

 Please Consider Your Environmental Responsibility Before Printing This E-mail. SAVE OUR TREES and REDUCE POLLUTION 

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/05/2019 10:59
Date Of Accident	11/05/2019 19:55
Exact Location Of Accident	ROCHOR CANAL ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLB6685G
Insured/Policyholder	
Name Of Registered Owner	LIM ENG HIONG JOSEPH
NRIC No	S0188748C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90254773
Alternative Phone No	OTHERS-96744320

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL 1.5X A
Exact Purpose for which vehicle was being used at time of accident	LEISURE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5108534644
Cover Note Number	

Driver

Name of Driver	LIM ENG HIONG JOSEPH
NRIC No	S0188748C
Date Of Birth	26/08/1950
Occupation	INDOOR
Date Of Driving Pass	23/01/1981
Driving Experience	38 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90254773
Fax Number	
Contact Number	OTHERS-96744320
EMail Address	NOEMAIL

Address	BLK 553 ANG MO KIO AVENUE 10 #06-1992
Postcode	560553
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : CHUA LEE BUEH GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO ACCIDENT STATEMENT AS ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBC1357A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	TAMILARASAN SUBURAYAN
NRIC/Passport Number	03551581
Contact Number	98530618
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 13/05/19

Driver's Signature

(if driver is not the policyholder)

Date & Time:


Reporting Centre Personnel's Signature

Name: Joelle Tan

NRIC/FIN No.: AMK AUTOPOINT PTE LTD

13.05.2019

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

While turning into ~~the~~ Minor Road Rochor Canal just before Zebra Crossing I stop my vehicle to allow an elderly man to cross. M/c suddenly hit from behind with heavy force. No injury on both sides.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Jeethin

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Joelle Tan

Reporting Centre Personnel's Signature
Name: **Joelle Tan**
NRIC/FIN No.: **AMK AUTOPOINT PTB LTD**
13.05.2019

Accident Photo



Accident Photo



Accident Photo





Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/05/2019 13:39
Date Of Accident	11/05/2019 19:30
Exact Location Of Accident	ROCHOR CANAL ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBC1357A
Insured/Policyholder	
Name Of Registered Owner	BEE TECK INTERNATIONAL PTE LTD
Co Reg No	0
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-83422630
Alternative Phone No	OFFICE-83422630

Vehicle Particulars

Manufacturer	PIAGGIO
Model	X8 200-198CC (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken REPORTING ONLY

Vehicle Category MOTORCYCLE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	MSD/VMT/18-389692-CA
Cover Note Number	

Driver

Name of Driver	TAMILARASAN SUBURAYAN
NRIC No	G5245138N
Date Of Birth	17/01/1987
Occupation	OUTDOOR
Date Of Driving Pass	08/11/2017
Driving Experience	1 YEAR AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83422630
Fax Number	
Contact Number	OFFICE-83422630
Email Address	NOEMAIL

Address	6D MANDAI ESTATE #08-10 M-SPACE
Postcode	S729938
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE SEE ATTACHED SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLB6685G
Vehicle Make/Model/Colour	HONDA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

13 MAR 2019

IDAC BUKIT BATON (PAC)
511 Bukit Batok Street 23
Singapore 659545
Tel: 6560 3312 Fax: 6560 0722
Email: vacbb@singnet.com.sg




Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on Saturday 11th May night time 7.50pm I am traveling in ophir rd in front of me a car also traveling he also take left in Rocher canal rd i am also been left zebra crossing suddenly people run way that time in front of me car to put brake i also put brake to stop but can't control so i hit the car back side door. no injuries happened i am alright. The other party car num [SLB 6685G] my vehicle num [FBI 1357A]

DECLARATION

I/We declare the foregoing particulars are true in every respect.

13 MAY 2019

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC BUKIT BATOK (VAC)
511 Bukit Batok Street 23
Singapore 659545
Tel: 6560 3312 Fax: 6569 0722
Email: vacbb@singnet.com.sg

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Photo



Accident Photo



03/14/2018 20:28

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



...CLAIM SUBFOLDER...(Pending for Survey Report)



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 May 2019 11:10		15 May 2019 16:16 Edit Adj Rpt	S\$3,000.00 Edit Estimates	S\$3,000.00 View Rpt		Pending for Survey Report Cancel Case


















































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	BEE TECK INTERNATIONAL PTE LTD , Co. Reg. No.: 200310572K								
Main Claimant:	LIM ENG HIONG JOSEPH , ID: S0188748C								
Vehicle Reg. No.:	SLB6685G	Date of Loss:	11/05/2019 19:00 - :59 [36 Months and 23 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MSC/V/19-000561	Policy/Cover Note No.:	MSD/VMT/18-389692-CA (TP, Fire & Theft) Coverage: 29/09/2018 - 28/09/2019						
Vehicle Reg. No. (Insured):	FBC1357A	Policy No. (Claimant):							
		Excess:							
Repairer:	Sau Hock Motor Services (HQ) 10 Ang Mo Kio Industrial Park 2A, #02-14 AMK Autopoint, 568047 Ang Mo Kio - Tel: 91098638								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 26/06/2019]								
Driver/Custodian (Insured):	TAMILARASAN SUBURAYAN () , NRIC: G5245138N Email:								
Adj Asg. Remarks:	SURVEY DISAGREE ON SJE - ASSIGN LKK. LIABILITY: 100% CONTACT: ROBERT 9109 8638								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (24/06/2019): Report Send Back Alerts - SLB6685G (TP) 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLB6685G (MSC/V/19-000561)
[FBC1357A]
TP
LIM ENG HIONG JOSEPH
May 11 2019 7:00PM
[BEE TECK INTERNATIONAL PTE LTD]
Sau Hock Motor Services

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Photos/Images									3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	06/06/19 13:59	General View								Load JPG	<input checked="" type="checkbox"/>	
2	06/06/19 13:59	General View								Load JPG	<input checked="" type="checkbox"/>	
3	06/06/19 13:59	General View								Load JPG	<input checked="" type="checkbox"/>	
4	06/06/19 13:59	General View								Load JPG	<input checked="" type="checkbox"/>	
5	06/06/19 13:59	General View								Load JPG	<input checked="" type="checkbox"/>	
6	06/06/19 13:59	General View								Load JPG	<input checked="" type="checkbox"/>	
7	06/06/19 13:59	General View								Load JPG	<input checked="" type="checkbox"/>	
8	06/06/19 13:59	General View								Load JPG	<input checked="" type="checkbox"/>	
9	06/06/19 13:59	General View								Load JPG	<input checked="" type="checkbox"/>	
10	06/06/19 13:59	General View								Load JPG	<input checked="" type="checkbox"/>	
11	06/06/19 13:59	General View								Load JPG	<input checked="" type="checkbox"/>	
12	06/06/19 13:59	General View								Load JPG	<input checked="" type="checkbox"/>	
13	06/06/19 13:59	General View								Load JPG	<input checked="" type="checkbox"/>	
14	06/06/19 13:59	General View								Load JPG	<input checked="" type="checkbox"/>	
15	06/06/19 13:59	General View								Load JPG	<input checked="" type="checkbox"/>	
16	06/06/19 13:59	General View								Load JPG	<input checked="" type="checkbox"/>	
17	06/06/19 13:59	General View								Load JPG	<input checked="" type="checkbox"/>	
18	06/06/19 13:59	General View								Load JPG	<input checked="" type="checkbox"/>	
19	06/06/19 13:59	General View								Load JPG	<input checked="" type="checkbox"/>	
20	06/06/19 13:59	General View								Load JPG	<input checked="" type="checkbox"/>	
21	06/06/19 13:59	General View								Load JPG	<input checked="" type="checkbox"/>	
22	06/06/19 13:59	General View								Load JPG	<input checked="" type="checkbox"/>	
23	06/06/19 13:59	General View								Load JPG	<input checked="" type="checkbox"/>	
24	06/06/19 13:59	General View								Load JPG	<input checked="" type="checkbox"/>	
25	06/06/19 13:59	General View								Load JPG	<input checked="" type="checkbox"/>	
26	06/06/19 13:59	General View								Load JPG	<input checked="" type="checkbox"/>	
27	06/06/19 13:59	General View								Load JPG	<input checked="" type="checkbox"/>	
28	06/06/19 13:59	General View								Load JPG	<input checked="" type="checkbox"/>	
29	06/06/19 13:59	General View								Load JPG	<input checked="" type="checkbox"/>	
30	06/06/19 13:59	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>	
31	06/06/19 13:59	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>	
32	06/06/19 13:59	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>	
33	06/06/19 13:59	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>	
34	06/06/19 13:59	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>	
35	06/06/19 13:59	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>	
36	06/06/19 13:59	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>	
37	06/06/19 13:59	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
99	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
100	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
101	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
102	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
103	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
104	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
105	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
106	06/06/19 13:59	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
107	06/06/19 14:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
108	06/06/19 14:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
109	06/06/19 14:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
110	06/06/19 14:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
111	06/06/19 14:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
112	06/06/19 14:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
113	06/06/19 14:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
114	06/06/19 14:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
115	06/06/19 14:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
116	06/06/19 14:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
117	06/06/19 14:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
118	06/06/19 14:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
119	06/06/19 14:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
120	06/06/19 14:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
121	06/06/19 14:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
122	06/06/19 14:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
123	06/06/19 14:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
124	06/06/19 14:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	14/05/19 11:11	Notice of PRI	 Load PDF	
2	15/05/19 09:41	SURVEY DISAGREE ON SJE - ASSIGN LKK	 Load PDF	
3	24/06/19 17:24	TP survey report and bill	 Load PDF	
4	24/06/19 17:30	survey photos-1	 Load PDF	
5	24/06/19 17:30	survey photos-2	 Load PDF	
6	24/06/19 17:31	survey photos-3	 Load PDF	
7	24/06/19 17:31	survey photos-4	 Load PDF	
8	24/06/19 17:32	survey photos -5	 Load PDF	
9	24/06/19 17:32	survey photos -6	 Load PDF	
10	24/06/19 17:36	OI Reports- FBC1357A	 Load PDF	
11	24/06/19 17:37	TP report-SLB6685G	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/07/19 17:47	PRS Invoice	 Load PDF	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
2	09/07/19 17:47	Colour Photo	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
<div></div>	
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>	

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19008628/GSD3E2-1

Date: 10/07/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMT/18-389692-CA
Claimant Vehicle No :	SLB6685G	Insured Vehicle No :	FBC1357A
Date of Loss:	11/05/2019	Nature of Claim:	TP
		Claim No:	MSC/V/19-000561

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB6685G	Engine No:	L15B4033159
Make & Model:	HONDA VEZEL, 1.5 X (A)	Chassis No:	RU11113153
Reg. Date:	18/04/2016 (Man. Year: 2016)	Odometer:	43640 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,641.50	2,390.16	5,251.34	68.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,450.00	1,390.00	2,060.00	59.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,091.50	3,780.16	7,311.34	65.92
Approved Total (Overridden) (S\$)		3,000.00		
Nett Amount (S\$)	11,091.50	3,000.00	8,091.50	72.95

INSPECTION

Date of Assignment:	15/05/2019	
Date Inspected:	16/05/2019 Inspected At:	Sau Hock Motor Services (HQ) 10 Ang Mo Kio Industrial Park 2A, #02-14 AMK Autopoint Singapore 568047
Estimated Period of Repair:	5.0 days	

Adjuster: XING GUO QIANG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Jul 2019)
Parts:	M1-SUV	HONDA VEZEL 1.5 X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLB6685G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Squashed	762.70 F	*762.70 FL
2	2		*REAR BUMPER RH / LH	Not Necessary	390.00 F	*-FL
3	1		*REAR BUMPER REFLECTOR RH / LH	N/S Cracked / O/S Not Necessary	282.20 F	*141.10 FL
4	2		*REAR BUMPER SIDE RETAINER RH / LH	Not Necessary	44.00 F	*-FL
5	1		*REAR END PANEL	Repair	415.60 F	*-FL
6	1		*REAR END PANEL INNER TAILGATE ANTENNA SENSOR	Not Necessary	85.00 F	*-FL
7	1		*REAR END PANEL LOWER UNDER COVER	Not Necessary	190.00 F	*-FL
8	1		*REAR END PANEL OUTER BUZZER	Not Necessary	80.00 F	*-FL
9	1		*TAILGATE	Buckled	953.30 F	*953.30 FL
10	1		*TAILGATE LOGO HONDA	Not Necessary	25.00 F	*-FL
11	1		*TAILGATE EMBLEM VEZEL	Necessary	56.20 F	*56.20 FL
12	1		*TAILGATE MECHANISM LOCK	Bent	157.50 F	*157.50 FL
13	2		*REAR NUMBER PLATE LAMP RH / LH	Not Necessary	77.00 F	*-FL
14	1		*TAILGATE OUTER GARNISH	Not Necessary	220.00 F	*-FL
15	11		*SET TAILGATE OUTER GARNISH CLIP	Not Necessary	71.50 F	*-FL
16	1		*TAILGATE OUTER LOCK HANDLE SWITCH	Not Necessary	175.50 F	*-FL
17	2		*TAILGATE REFLECTOR LAMP BACK RUBBER GASKET RH / LH	Not Necessary	37.00 F	*-FL
18	1		*TAILGATE REFLECTOR LAMP CLIP RH / LH (6PCS)	Necessary	39.00 F	*26.00 FL
19	1		*TAILGATE REFLECTOR LAMP RH / LH	N/S Cracked / O/S Not Necessary	826.40 F	*326.20 FL
20	2		*TAILGATE RUBBER GUIDE STOPPER RH / LH	Not Necessary	25.00 F	*-FL
21	1		*TAILGATE WEATHERSTRIP	Deformed	96.80 F	*96.80 FL
22	1		*TAILGATE WINDSCREEN MOULDING	Necessary	120.00 F	*67.90 FL
23	2		*REAR TAIL LAMP BACK RUBBER GASKET RH / LH	Not Necessary	130.60 F	*-FL
24	8		*REAR TAIL LAMP CLIP RH / LH	Not Necessary	52.00 F	*-FL
25	2		*REAR TAIL LAMP INNER PANEL RH / LH	Repair	270.00 F	*-FL
26	2		*REAR TAIL LAMP RH / LH	Not Necessary	949.20 F	*-FL
27	1		*SET REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
28	1		*REAR BUMPER REVERSE SENSOR	Shorted	350.00 FS	*200.00 FS
29	1		*TAILGATE REVERSE CAMERA	Not Necessary	550.00 FS	*-FS
30	1		*SET TAILGATE INNER TRIM BOARD CLIP	Necessary	30.00 FS	*30.00 FS
31	1		*REAR NUMBER PLATE C/W HOLDER	Not Necessary	50.00 FS	*-FS
32	1		*TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 7,641.50 2,907.70

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 0.00/20.00% (S\$)					0.00	517.54
Total Parts (S\$)					7,641.50	2,390.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO STRAIGHTEN AND PANEL BEATING REAR FENDER RH / LH, REAR BOOT FLOOR PANEL AND REAR FRAME MEMBERS. TO CUT AND WELD REAR END PANEL. TO REMOVE AND REFIT ABOVE PARTS	New	1,600.00	600.00
2	TO PUTTY, RE-SPRAY PAINTING AND POLISH AFFECTED AREAS	New	1,500.00	600.00
3	TO CHECK AND RECTIFY WIRING SYSTEM	New	80.00	30.00
4	TO REMOVE AND REFIT REAR WINDSCREEN	New	150.00	100.00
5	TO RUST PROOF AFFECTED AREAS	New	120.00	60.00
Gross Labour Cost (S\$)			3,450.00	1,390.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >