

INS. CASE OWNER:

CC4, AG 190 11189, D 0039

LKK:
IDAC

Surveyor:

Bryson

DOI:

ASSIGNMENT

Date / Time:

21/6/2014

Registered in Merimen:

25/6/2014

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLU1199B

Name of Insured:

Fan Chue Keong, Albert.

Insured Tel No.:

HP:

Claim No.:

Policy No.:

Make / Model:

Excess Sec II :SS

D.O.A.:

20/6/2014

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO: TP GIA REPORT: YES / NO

Insured Liability: %

Final? Yes / No

SPH 188 D



INSRS:

WSP:

Tel:

Liability:

RMKS:

Tuned for



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

PRELIMINARY ADVICE

Date/Time:

Sent By:

Post-Repair Photos:

Others:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No. : 27

If NO or B 28, Ass. Lia :

Repair Cost:

S\$ 4500.00

Loss of Rental (LOR):

S\$ 720.00

(

6 days) x \$120

Loss of Use (LOU):

S\$ -

(\$

x

days)

Loss of Income (LOI):

S\$ -

(\$

x

days)

LOR only ☒ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$ 7.45

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

Total:

S\$ 5227.45

Global Sum S\$: 5200.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$ 5200.00

Name 1:

Tuned Performance Pte Ltd

Payee 2 (Surfer 1/2/3):

S\$ -

Name 2:

Payee 3 (Surfer 1/2/3):

S\$ -

Name 3:

ASS. REC. BY:

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

5

days

Res.: _____

Yes or No

Lum Sum: _____

20

%

3 Val.: _____

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: _____

SFH 188 D

Yr Regn: _____

2016 Sep

Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: _____

Nissan X-Trail

C.C.

1997

Colour: _____

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading: _____

112326

T/Radio:

Insured / Std / NI / NA

Eng/No: _____

MR20884576B

C/No: _____

JN1JANT32Z0002445

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: Nil / ☒ S/Rim / ☐ STD A/Rim or

Tyre Size: _____

F:

225/60 R18

R:

- 11 -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bridgestone

Front

Rear

R/Bal. _____

S

mm

R/Bal. _____

S

mm

L/Bal. _____

S

mm

L/Bal. _____

S

mm

D.O.A. _____

20/06/2019

D.O.I. _____

24/06/2019

Survey held at _____

Tune Performance

Des. of Damages: Frt / ☒ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

Rw

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

AIG 8LU 1199 B

4/1 - \$4500 (Red \$7503.25 / 631)

Date/Time, File Pass to?



: Prel. Report

1)



: Final Report

Date/Time, File Return to?

2)

Report Form(s): _____

Lump Sum P.P.F. is: _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: _____



: Site Insp (\$



: Interview (\$



: Tech. Insp (\$



: Weekend (\$

Survey Fee: _____

Transportation

\$ + RS. \$

Photos

Others

TOTAL

TUNED PERFORMANCE PTE LTD

C/O REG: 201905120W

AIG INSURANCE	D.O.A: 20-JUNE-2019
78 SHENTON WAY #07-16	VEHICLE NUMBER: 5FH188D
SINGAPORE 079120	MAKE/MODEL: NISSAN X-TRAIL
	CHASSIS NUMBER: JN1JANT32Z0002445

QTY	PARTICULARS	UNIT PRICE-SGD
<u>PARTS REPLACEMENT- LIST ITEMS</u>		
1	REAR BUMPER <i>distorted</i>	958.00 ✓
1	REAR BUMPER REINFORCEMENT <i>bt</i>	785.00 ✓
1	TAILGATE <i>pen</i>	5006.40 X
1	END PANEL <i>pen</i>	1102.50 X
		7851.90
	LESS 30%	5496.26
<u>PARTS REPLACEMENT - NETT ITEMS</u>		
	BALANCE B/F	5496.26
1	TAILGATE LOGO <i>Nec</i>	68.50 ✓
1	TAILGATE EMBLEM -X-TRAIL <i>Nec</i>	90.00 ✓
1	TAILGATE INNER TRIM <i>NH</i>	490.00 X
2	TAILGATE HINGE <i>NH</i>	291.00 X
2	TAILGATE ABSORBER <i>NH</i>	310.50 X
1	TAILGATE RUBBER <i>defunct</i>	176.50 ✓
1	TAILGATE LOCK <i>pen</i>	670.00 ✓
1	TAILGATE LOCK STRIKER <i>NH</i>	90.00 X
2	TAILGATE STOPPER <i>SVC</i>	85.00 X
2	REAR BUMPER BRACKET <i>SVC</i>	290.00 X
2	REAR BUMPER REFLECTOR <i>SVC</i>	179.00 X
2	REAR BUMPER REFLECTOR CHROME <i>NF</i>	160.50 X
1	REAR BUMPER CHROME <i>distorted</i>	115.00 ✓
1	REAR X-TRAIL CHROME PLATE <i>bt</i>	180.00 ✓
1	REAR LOCK SENSOR <i>NH</i>	168.00 X
1	REAR BUMPER UNDER GARNISH <i>NF distorted</i>	815.00 ✓
1	END PANEL TOP GARNISH <i>NH</i>	320.00 X
1	SPARE TYRE TOP BOARD <i>NH</i>	385.00 X
2	REAR TAILGATE LAMP -INNER <i>NH</i>	535.00 X
		5419.00
	LESS 25%	1083.80
	SUBTOTAL	4335.20
	BALANCE C/F	9831.46

PARTS REPLACEMENT - SPECIAL NETT ITEMS		
	BALANCE B/F	9831.46
1SET REAR BUMPER CLIP <i>NH</i>		80 30/-
1SET REAR REVERSE SENSOR <i>Done</i>		400 350/-
1 JOINT SEALANT <i>NH</i>	<i>880.00</i>	150 X
1 WINDSCREEN SEALANT <i>NH</i>		150 X
1 AFTMKT REAR BUMPER PROTECTOR <i>distorted</i>		980 500/-
	SUBTOTAL	1740
	BALANCE C/F	11571.46
S/NO	LABOUR AND MISCELLANEOUS CHARGES	
	BALANCE B/F	8043.25
1 CHECK REAR WIRING AND LIGHTING SYSTEM		60 NH
2 REMOVE, REFIT REAR LINING, TRIM AND GARNISH		200 120/-
3 REMOVE AND RENEW REAR REVERSE SENSOR		150 60/-
4 REMOVE AND STRAIGHTEN REAR EXHAUST	<i>1720.00</i>	150 NH
5 REMOVE AND REFIT REAR WINDSCREEN		150 NH
6 TRANSFER PARTS, ATTACHMENT FROM OLD TO NEW TAILGATE		200 NH
7 PANEL BEATING ON AFFECTED AREAS		1500 800/-
8 SPRAY PAINTING ON AFFECTED AREAS		1400 700/-
9 APPLY ANTI RUST ON AFFECTED AREAS		150 40/-
	SUBTOTAL	3960
	GRAND TOTAL	12003.25

24/06/2019 @ 1408hrs

Net Amount

2/5mm 5 days.

2
ryan

LKK Auto

5723.60

L/S 4500/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PRE-REPAIR INSPECTION REQUEST – SFH188D vs SLU1199B (OI) on D.O.A.: 20/06/2019

From: Hor, Yinnul
To: "assignments@lkkauto.com", Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY, Chin, Lee-Ying, Kaur, Baljit, Abu Kassim, Noor Marissa, Azlan, Syazairinda, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Subramaniam, Divyashni, Tor
Sent: 6/21/2019 5:00:27 PM
Attachments:  SKM_C300190621145800.pdf  SKM_C300190621145800.pdf

Hi,

Please refer to the enclosed request from **Tuned Performance**.

Claim no : 2657885318SG003
Case Owner : Chan Kian Meng

If you have any queries/concerns, please let us know.

Thanks & Regards,

Hor Yin Rut (Viviane)
AIG
Claim Adjuster II, Singapore FNOL Claims Operations – Auto
Yinnul.Hor@aig.com | www.aig.as

From: tuned performance [mailto:tunedperformance15@gmail.com]
Sent: Friday, June 21, 2019 4:48 PM
To: Hor, Yinnul
Subject: [EXTERNAL] Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLU1199B AND SFH188D ON 20/06/2019

This message is from an external sender; be cautious with links and attachments.

Dear Sir,

We have agreed and selected the surveyor / surveyor company proposed by you to conduct the pre-repair inspection as a single joint expert whereby the cost of the pre-repair survey carried out by single joint expert will be bear by you.

We have selected :

LKK AUTO CONSULTANTS PTE LTD - MY BRYAN

as the motor surveyor / surveyor company named in your attached list.

Kindly forward your assignment to them asap so that we can arrange for the survey with them.

*Do get the surveyor / surveyor office to check with us on the availability of the car at the workshop before sending their surveyor down for PRI survey. We'll not be held responsible for wasted trips made to the workshop

On Fri, Jun 21, 2019 at 3:38 PM Hor, Yinnul <Yinnul.Hor@aig.com> wrote:

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยของข้อมูลที่เข้ารหัสลับ เพื่ออ่านมัน
ให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려
면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya,
membuka attachment.

[Click here](#) by 2019-06-28 15:38 +08 to read your message.
After that, open the attachment.

[More info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the individual named. If you have received this email in error or simply do not

believe this is for you, please notify the sender immediately by email and delete this message. If you are not the named individual, you should not disseminate, distribute or copy this e-mail. Please notify the sender immediately by e-mail if you have received this e-mail by error. Copyright © 2004-2017 Protonmail, Inc. All rights reserved.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or

other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Yinrul.Hor@aig.com
To: tunedperformance15@gmail.com
Cc: Andy-SY.Fong@aig.com, Lee-Ying.Chin@aig.com, Baljit.Kaur@aig.com, NoorMariasa.AbuKassim@aig.com, Syazairdina.Azlan@aig.com, yokeshi.chan@aig.com, ShengYang.Lim@aig.com, Aashweenjeetkaur.Mithoosingh@aig.com, Divyashri.Subramaniam@aig.com, Wahxin.Tong@aig.com
Subject: aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLU1199B AND SFH188D ON 20/06/2019
Date: Fri, 21 Jun 2019 07:38:15 +0000
Without Prejudice

Your Reference : TP-002
Our Reference : SLU1199B

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yin Rul (Viviane)
AIG
Claim Adjuster II, Singapore FNOL Claims Operations - Auto
Yinrul.Hor@aig.com | www.aig.sg

From: tuned performance [mailto:tunedperformance15@gmail.com]
Sent: Friday, June 21, 2019 3:18 PM
To: Hor, Yinrul; Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariasa; Azlan, Syazairdina; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Chan, Yoke Shi
Subject: [EXTERNAL] OUR REF: TP-002 // YOUR REF: SLU1199B ACCIDENT INVOLVING SLU1199B AND SFH188D

This message is from an external sender; be cautious with links and attachments.

WITHOUT PREJUDICE

OUR REF : TP-002
YOUR REF : SLU1199B

Dear Sir / Madam,
PRE-REPAIR INSPECTION FOR SFH188D
ACCIDENT INVOLVING SLU1199B AND SFH188D ON 20.06.2019.

We refer to the above matter and enclosed herewith our client's GIA report and notification of Pre-repair inspection for your attention.

We also enclosed herewith the State Court of the Republic of Singapore Practice Direction-Amendment No. 1 of 2016 of 2016 of Pre-repair Inspection for your attention.

Thank you and have a nice day.

Best Regards,

Kenneth

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Jun 2019 Edit Reg		24 Jun 2019 00:00 Edit Adj Rpt	S\$4,500.00 Edit Estimates	S\$4,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	FAN CHEE KEONG ALBERT, ID: S1424942G								
Main Claimant:	WILLIAM CHUA GIM TECK, ID: S7726867G								
Vehicle Reg. No.:	SFH188D	Date of Loss:	20/06/2019 18:00 - :59 [33 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 2657885318SG	Policy/Cover Note No.:	(Comprehensive) Coverage: 11/12/2018 - 10/12/2019						
Vehicle Reg. No. (Insured):	SLU11998	Policy No. (Claimant):	5105329178						
		Excess:							
Repairer:	Tuned Performance Pte Ltd - Ubi (HQ) 53 UBI AVENUE 1 #01-23 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934, 408934 Ubi - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 04/07/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SFH188D (2657885318SG)
[SLU1199B]

TP

WILLIAM CHUA GIM TECK

Jun 20 2019 6:00PM

[FAN CHEE KEONG ALBERT]

Tuned Performance Pte Ltd - Ubi

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser	
Letters/Correspondences										1 per page 1	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	(Draft)	Third Party Express Settlement - Payment Breakdown							Edit		
Photos/Images										3 per page 1	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	11/10/19 15:27	Rear View Right							Load JPG ☒		
2	11/10/19 15:27	Rear View Left							Load JPG ☒		
3	11/10/19 15:28	General View							Load JPG ☒		
4	11/10/19 15:28	General View							Load JPG ☒		
5	11/10/19 15:28	General View							Load JPG ☒		
6	11/10/19 15:28	General View							Load JPG ☒		
7	11/10/19 15:28	General View							Load JPG ☒		
8	11/10/19 15:28	General View							Load JPG ☒		
9	11/10/19 15:28	General View							Load JPG ☒		
10	11/10/19 15:28	General View							Load JPG ☒		
11	11/10/19 15:28	General View							Load JPG ☒		
12	11/10/19 15:28	General View							Load JPG ☒		
13	11/10/19 15:28	General View							Load JPG ☒		
14	11/10/19 15:28	General View							Load JPG ☒		
15	11/10/19 15:28	General View							Load JPG ☒		
16	11/10/19 15:28	General View							Load JPG ☒		
17	11/10/19 15:28	General View							Load JPG ☒		
18	11/10/19 15:28	General View							Load JPG ☒		
19	11/10/19 15:28	General View							Load JPG ☒		
20	11/10/19 15:28	General View							Load JPG ☒		
21	11/10/19 15:28	General View							Load JPG ☒		
22	11/10/19 15:28	General View							Load JPG ☒		
23	11/10/19 15:28	General View							Load JPG ☒		
24	11/10/19 15:28	General View							Load JPG ☒		
25	11/10/19 15:28	General View							Load JPG ☒		
26	11/10/19 15:28	General View							Load JPG ☒		
27	11/10/19 15:28	General View							Load JPG ☒		
28	11/10/19 15:28	General View							Load JPG ☒		
29	11/10/19 15:28	General View							Load JPG ☒		
30	11/10/19 15:28	General View							Load JPG ☒		
31	11/10/19 15:28	General View							Load JPG ☒		
32	11/10/19 15:28	General View							Load JPG ☒		
33	11/10/19 15:29	Odometer Reading							Load JPG ☒		
34	11/10/19 15:29	Chassis Number							Load JPG ☒		
35	11/10/19 15:30	Reinspection Photo							Load JPG ☒		
36	11/10/19 15:30	Reinspection Photo							Load JPG ☒		
37	11/10/19 15:30	Reinspection Photo							Load JPG ☒		
38	11/10/19 15:30	Reinspection Photo							Load JPG ☒		
39	11/10/19 15:30	Reinspection Photo							Load JPG ☒		
40	11/10/19 15:30	Reinspection Photo							Load JPG ☒		

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
41	11/10/19 15:30	Reinspection Photo	 Load JPG	☒
42	11/10/19 15:30	Reinspection Photo	 Load JPG	☒
43	11/10/19 15:30	Reinspection Photo	 Load JPG	☒
44	11/10/19 15:30	Reinspection Photo	 Load JPG	☒
45	11/10/19 15:30	Reinspection Photo	 Load JPG	☒
46	11/10/19 15:30	Reinspection Photo	 Load JPG	☒
47	11/10/19 15:30	Reinspection Photo	 Load JPG	☒
48	11/10/19 15:30	Reinspection Photo	 Load JPG	☒
49	11/10/19 15:30	Reinspection Photo	 Load JPG	☒
50	11/10/19 15:30	Reinspection Photo	 Load JPG	☒
51	11/10/19 15:30	Reinspection Photo	 Load JPG	☒
52	11/10/19 15:30	Reinspection Photo	 Load JPG	☒
53	11/10/19 15:30	Reinspection Photo	 Load JPG	☒
54	11/10/19 15:30	Reinspection Photo	 Load JPG	☒
55	11/10/19 15:30	Reinspection Photo	 Load JPG	☒
56	11/10/19 15:30	Reinspection Photo	 Load JPG	☒
57	11/10/19 15:30	Reinspection Photo	 Load JPG	☒
58	11/10/19 15:30	Reinspection Photo	 Load JPG	☒
59	11/10/19 15:30	Reinspection Photo	 Load JPG	☒
60	11/10/19 15:30	Reinspection Photo	 Load JPG	☒
61	11/10/19 15:30	Reinspection Photo	 Load JPG	☒
62	11/10/19 15:30	Reinspection Photo	 Load JPG	☒
63	11/10/19 15:30	Reinspection Photo	 Load JPG	☒
64	11/10/19 15:30	Reinspection Photo	 Load JPG	☒
65	11/10/19 15:30	Reinspection Photo	 Load JPG	☒
66	11/10/19 15:30	Reinspection Photo	 Load JPG	☒
67	11/10/19 15:30	Reinspection Photo	 Load JPG	☒
68	11/10/19 15:30	Reinspection Photo	 Load JPG	☒
69	11/10/19 15:30	Reinspection Photo	 Load JPG	☒
70	11/10/19 15:30	Reinspection Photo	 Load JPG	☒
71	11/10/19 15:30	Reinspection Photo	 Load JPG	☒
72	11/10/19 15:30	Reinspection Photo	 Load JPG	☒
73	11/10/19 15:30	Reinspection Photo	 Load JPG	☒
74	11/10/19 15:30	Reinspection Photo	 Load JPG	☒
75	11/10/19 15:30	Reinspection Photo	 Load JPG	☒
76	11/10/19 15:30	Reinspection Photo	 Load JPG	☒
77	11/10/19 15:30	Finishing Photo	 Load JPG	☒
78	11/10/19 15:30	Finishing Photo	 Load JPG	☒
79	11/10/19 15:30	Finishing Photo	 Load JPG	☒
80	11/10/19 15:30	Finishing Photo	 Load JPG	☒
81	11/10/19 15:30	Finishing Photo	 Load JPG	☒
82	11/10/19 15:30	Finishing Photo	 Load JPG	☒
83	11/10/19 15:30	Finishing Photo	 Load JPG	☒
84	11/10/19 15:30	Finishing Photo	 Load JPG	☒
85	11/10/19 15:30	Finishing Photo	 Load JPG	☒
86	11/10/19 15:30	Finishing Photo	 Load JPG	☒
87	11/10/19 15:30	Finishing Photo	 Load JPG	☒
88	11/10/19 15:30	Finishing Photo	 Load JPG	☒
89	11/10/19 15:30	Finishing Photo	 Load JPG	☒
90	11/10/19 15:30	Finishing Photo	 Load JPG	☒
91	11/10/19 15:30	Finishing Photo	 Load JPG	☒
92	11/10/19 15:30	Finishing Photo	 Load JPG	☒
93	11/10/19 15:30	Finishing Photo	 Load JPG	☒
94	11/10/19 15:30	Finishing Photo	 Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/06/19 16:00	EMAIL FROM AIG DD 21.06.2019	Load PDF	
2	25/06/19 16:00	TP GIA REPORT	Load PDF	
3	19/12/19 15:28	WORKSHOP INVOICE	Load PDF	
4	19/12/19 15:28	AUTHORISATION TO ACT FORM	Load PDF	
5	19/12/19 15:28	Release Voucher	Load PDF	
6	19/12/19 15:28	RENTAL RECEIPT	Load PDF	
7	19/12/19 15:28	LTA SEARCH	Load PDF	
8	19/12/19 15:28	LOD	Load PDF	
9	19/12/19 15:28	LETTER TO OI	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	26/06/19 09:42	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) ^ v			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SLU1199B (Insd veh)	Model:	NISSAN X-TRAIL 2.0 CVT
	SFH188D (TP veh)		(A)
Date of Accident:	20/06/2019		

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	:	\$	16,073.43
Final Repair Cost	:	\$	5,200.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	6 days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	5,200.00
Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Tuned Performance Pte Ltd	:	\$ 5,200.00
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

19 Dec
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19011189/DDA3Q2

Date: 19/12/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant

Vehicle No : SFH188D

Insured Vehicle No : SLU1199B

Date of Loss: 20/06/2019

Nature of Claim: TP

Claim No: 2657885318SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SFH188D

Make & Model: NISSAN X-TRAIL, 2.0 CVT (A)

Engine No: MR20889576B

Reg. Date: 17/09/2016 (Man. Year: 2016)

Chassis No: JN1JANT32Z0002445

Colour: Blue

Odometer: 112326 km

Engine Capacity: 1997 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/60 R18

Rear Tyre Size: 225/60 R18

Front Left Side: Bridgestone 5 mm

Rear Left Side: Bridgestone 5 mm

Front Right Side: Bridgestone 5 mm

Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,113.43	4,003.60	8,109.83	66.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,960.00	1,720.00	2,240.00	56.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,073.43	5,723.60	10,349.83	64.39
Approved Total (Overridden) (S\$)		4,500.00		
Nett Amount (S\$)	16,073.43	4,500.00	11,573.43	72.00
+ Car Rental (6.0 x S\$120.00/day) (S\$)		720.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,227.45		
Global Sum Settlement (S\$)		5,200.00		

INSPECTION

Date of Assignment: 24/06/2019

Date Inspected: 24/06/2019 Inspected At:

Tuned Performance Pte Ltd - Ubi (HQ)
 53 UBI AVENUE 1 #01-23 PAYA UBI
 INDUSTRIAL PARK SINGAPORE
 408934
 Singapore 408934

Estimated Period of Repair: 5.0 days

Adjuster: BRYAN TANI**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	958.00 FL	*958.00 FL
2	1		*REAR BUMPER REINFORCEMENT	Bent	785.00 FL	*785.00 FL
3	1		*TAILGATE	Repair	5,006.40 FL	*- FL
4	1		*END PANEL	Repair	1,102.50 FL	*- FL
5	1		*TAILGATE LOGO	Necessary	68.50 FN	*68.50 FN
6	1		*TAILGATE EMBLEM -X-TRAIL	Necessary	90.00 FN	*90.00 FN
7	1		*TAILGATE INNER TRIM	Not Necessary	490.00 FN	*- FN
8	2		*TAILGATE HINGE	Not Necessary	291.00 FN	*- FN
9	2		*TAILGATE ABSORBER	Not Necessary	310.50 FN	*- FN
10	1		*TAILGATE RUBBER	Deformed	176.50 FN	*176.50 FN
11	1		*TAILGATE LOCK	Damaged	670.00 FN	*670.00 FN
12	1		*TAILGATE LOCK STRIKER	Not Necessary	90.00 FN	*- FN
13	2		*TAILGATE STOPPER	Serviceable	85.00 FN	*- FN
14	2		*REAR BUMPER BRACKET	Serviceable	290.00 FN	*- FN
15	2		*REAR BUMPER REFLECTOR	Serviceable	179.00 FN	*- FN
16	2		*REAR BUMPER REFLECTOR CHROME	Not fitted	160.50 FN	*- FN
17	1		*REAR BUMPER CHROME	Distorted	115.00 FN	*115.00 FN
18	1		*REAR X-TRAIL CHROME PLATE	Bent	180.00 FN	*180.00 FN
19	1		*REAR LOCK SENSOR	Not Necessary	168.00 FN	*- FN
20	1		*REAR BUMPER UNDER GARNISH	Distorted	815.00 FN	*815.00 FN
21	1		*END PANEL TOP GARNISH	Not Necessary	320.00 FN	*- FN
22	1		*SPARE TYRE TOP BOARD	Not Necessary	385.00 FN	*- FN
23	2		*REAR TAILGATE LAMP -INNER	Not Necessary	535.00 FN	*- FN
24	1		*SET REAR BUMPER CLIP	Necessary	60.00 FS	*30.00 FS
25	1		*SET REAR REVERSE SENSOR	Damaged	400.00 FS	*350.00 FS
26	1		*JOINT SEALANT	Not Necessary	150.00 FS	*- FS
27	1		*WINDSCREEN SEALANT	Not Necessary	150.00 FS	*- FS
28	1		*AFTMKT REAR BUMPER PROTECTOR	Distorted	980.00 FS	*500.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	15,010.90	4,738.00
- List Item Discount on L Items 30.00/30.00% (\$\$)	2,355.57	522.90
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	541.90	211.50
Total Parts (\$\$)	12,113.43	4,003.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK REAR WIRING AND LIGHTING SYSTEM	New	60.00	0.00
2	REMOVE,REFIT REAR LINING ,TRIM AND GARNISH	New	200.00	120.00
3	REMOVE AND RENEW REAR REVERSE SENSOR	New	150.00	60.00
4	REMOVE AND STRAIGHTEN REAR EXHAUST	New	150.00	0.00
5	REMOVE AND REFIT REAR WINDSCREEN	New	150.00	0.00
6	TRANSFER PARTS ,ATTACHMENT FROM OLD TO NEW TAILGATE	New	200.00	0.00
7	PANEL BEATING ON AFFECTED AREAS	New	1,500.00	800.00
8	SPRAY PAINTING ON AFFECTED AREAS	New	1,400.00	700.00
9	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	40.00
Gross Labour Cost (S\$)			3,960.00	1,720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >