

ASS. REC. BY:

REF: CS/INC1901191/Rtd321

Special Instruction:

Surveyor: Rasul

ASSIGNMENT (Office)

From (Person): Cynthia Ang

of

INC

Date/Time:

25/6/19 @ 9:49am

Estimated Cost:

Bill to:

OD / PP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SME 8157Z

Insured: SJT 7859 U

at Workshop m/s

Performance Motor

Tel: 63190174

of

303 Alexandra Road

Policy No:

Claim No:

MT/1050072-002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:09am @ 25/6/19

Person Contacted:

Caroline

Vehicle IN/OUT

Date/Time	Action/Instruction
	Estimate / <input checked="" type="checkbox"/>
	SME 8157Z ✓
	SJT 7859 U: CC4 / ASM18006599 / TI pD3q2 D.O.A.: 06/04/2018
	Part by Part \$13,053.25 (Red: 3147.15; 19%), 7 days

Gimzyar

Pernu

REF:


14692

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SME 81572
 at Workshop m/s PERFORMANCE
 of 303, ALEXANDRA RD
 Insured: INC
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Vch: _____

(Policy Condition)

Remark: **The veh had commenced its
 repair at the time of inspection.**



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMG81572 Yr Regn: 2014 / NOV
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: B.M.W X5 C.C. 2979
 Colour: GRY A/C: Insured / Std / NI / NA
 Sp.Reading: 91862 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WBAK R020900 C46475
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 255/50R19
 R: 255/50R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front		Rear	
R/Bal. <u>6</u> mm		R/Bal. <u>6</u> mm	
L/Bal. <u>6</u> mm		L/Bal. <u>6</u> mm	
D.O.A. <u>20/06/19</u>		D.O.I. <u>25/06/19</u>	<u>1150Am</u>

Survey held at PERFORMANCE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

REAR O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 15 AUG 2019

14/8/2019

Date/Time, File Pass to?

1) 13/8 Typst ☐ : Preli. Report
☒ : Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B. (\$) TP 13,053.25Days Of Repair: 7Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

250

250

Nivitha (LKK Auto)

From: Cynthia Ang <Cynthia.Ang@income.com.sg>
Sent: Tuesday, 25 June 2019 3:45 PM
To: 'assignments@lkkauto.com'; Admin-D (LKKAuto)
Subject: RE: TP CASES FARMED OUT TO LKK ON 25/06/2019

Hi LKK,

Resend with the following details.

Thank you.

With Regards

Cynthia Ang
Admin Assistant
Motor Insurance
T +65 6430 7900
www.income.com.sg

income
made different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.

Find out more at income.com.sg/careers

in with you

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

From: Cynthia Ang
Sent: Tuesday, 25 June 2019 9:49 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>
Cc: Teng Ken Leong <kenleong.teng@income.com.sg>; Thio Tse Kiat <tsekiat.thio@income.com.sg>; Cynthia Ang <Cynthia.Ang@income.com.sg>
Subject: TP CASES FARMED OUT TO LKK ON 25/06/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	Eric Tang	MT/1050061-002	FZ6005P	HKL LIM TEAM MOTORSPORT	BLK 1008 #01-24 BUKIT MERAH LANE 3 SINGAPORE 159722	James Lim / 9242 3895		XE1528C	21/06/2019	
2	Eric Tang	MT/1050364-002	SL19897P	PEGASUS ENGINEERING & TRADING PTE LTD	74 KIAN TECK ROAD SINGAPORE 628800	Yoyo / 65137748		SGK2839T	23/06/2019	
3	Jared Liu	MT/1034112-003	SLP4297H	PEGASUS ENGINEERING & TRADING PTE LTD	74 KIAN TECK ROAD SINGAPORE 628800	Yoyo / 65137748	14:00-16:00	YL8550S	01/11/2018	Owner waiting
4	Azhari	MT/1050072-002	SME8157Z	PERFORMANCE MOTORS LTD	303 ALEXANDRA ROAD SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941	Caroline / 6319 0174		SJT7859U	20/06/2019	
5	Serene Lim	MT/1048606-002	SBX2U	PREMIUM AUTOMOBILES PTE LTD	281 ALEXANDRA ROAD SINGAPORE 159938	Tony Foong / 6366 2323	10:00-12:00	GZ7468T	11/06/2019	
6	Jared Liu	MT/1044498-002	JNY2143	A S PHOON PTE LTD	36 TOH GUAN ROAD EAST #01-35 ENTERPRISE HUB SINGAPORE 608580	Kee Ger Ong / 6515 0770		YN4530R	11/05/2019	
7	Helena Tan	MT/1050289-002	SDY193Y	GOLDBELL ENGINEERING PTE LTD	BLK K PANDAN LOOP IND ESTATE #01-12 SINGAPORE 10 ANG MO KIO IND PK 2-A #01-05/06 AMK	Soo Leong Keat / 9739 7127	10:00-12:00	GBF918Y	22/06/2019	
8	Cyndie Yong	MT/1050341-002	SHC2352K	SOON HOCK MOTOR PTE LTD	AUTOPOINT SINGAPORE 568047	Ms Lynn / 65425119		SJM156Y	21/06/2019	

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

With Regards

Cynthia Ang
Admin Assistant
Motor Insurance
T +65 6430 7900
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers



PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/06/2019 14:02
Date Of Accident	20/06/2019 18:15
Exact Location Of Accident	WOODLANDS AVENUE 3
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SME8157Z
Insured/Policyholder	
Name Of Registered Owner	YEOH BENG TECK
NRIC No	S2581469Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98518512
Alternative Phone No	OFFICE-98518512

Vehicle Particulars

Manufacturer	BMW
Model	X5 XDRIVE35I 7SEATER SR LED NAV HUD
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5107294838
Cover Note Number	

Driver

Name of Driver	YEOH BENG TECK
NRIC No	S2581469Z
Date Of Birth	05/05/1967
Occupation	INDOOR
Date Of Driving Pass	20/12/1988
Driving Experience	30 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98518512
Fax Number	
Contact Number	OFFICE-98518512
EEmail Address	NOEMAIL

Address	17 JALAN TANI
Postcode	548554
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	DRIZZLING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Refer Annex 1

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJT7859U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHONG XUN DUN
NRIC/Passport Number	S9320079I
Contact Number	97453693
Address	
Postcode	
Insurance Company Name	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Nature Of Damage	
No. Of Passenger (Including Driver)	1


SKETCH PLAN

IMPORTANT NOTICE



1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 21/06/19
1411 hrs

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: 
NRIC/FIN No.: 620790400

Annex 1

On 20 June 2019 at around 1815 hours, I was driving my car (SME8157Z) along Woodlands Avenue 3 and filtering into the left side adjoining lane merging into BKE towards PIE direction. As I slowed down and stepped on the brake to stop at the road stop line to let a motorbike on the straight road to pass, a silver coloured Nissan Latio (SJT7859U), who was driving behind my car and failed to slow down, banged hard into the back of my car, causing substantial damage to the rear right part (driver side) of my car.

The Nissan Latio car also suffered substantial damage to the left frontal (passenger side) of his car. The driver when asked if he had seen me slowing down to stop at the stop line to give way to a bike coming from the adjoining road, he claimed that he thought I will continue to drive out onto the merging road. I suspect he may not have seen the incoming motorbike, hence his thinking that I will continue to drive straight out and because of that he had not slowed down his car's speed, resulting in the accident. Looking at the condition and location of the damage which are on the rear driver side on my car and at the frontal passenger side of the other car, I would assume that he had not slowed down when reaching the merging lane and when he realised that my car had slowed and then stopped, he quickly swerved to his right in trying to avoid hitting my car. Unfortunately, he could have been driving at a higher speed at that time or he may already been driving too close to the back of my car to be able to swerve away totally, hence the damage on his car at the passenger side. My assumption on his speed are based on the serious extent of the damage caused to both the cars.

Both car can still be driven after the accident. There are no injury to people. The driver, Mr. Chong confirmed that he did not sustain any injury. Note that the road surface was wet from rain earlier and it was still drizzling at the time of accident.

Attached are 6 photographs showing the extent of damage to both cars and the location of the accident for your reference.

The particular of the other driver are :-

Car No. : SJT7859U
Car model : Nissan Latio
Driver's name : Mr. Chong Xun Dun
NRIC No. : S9320079I
Mobile No. : 9745 3693
Car Insurer : NTUC Income

This report is lodged as I wish to claim third party damages from the other vehicle driver due to his negligent in causing the accident.

Written by 
Yeoh Beng Teck
S2581469Z
Driver / Owner of SME8157Z
Mobile No. 9851 8512
NTUC Income Policy No. 5107294838

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

24 JUN 2019

Estimate No. : b1 51652 Page No. : 1 of 5
Date Estimated : 21/06/2019
Prepared By : Inthiran A/L Thurasamy

- ESTIMATE REPAIR FOR -

Yeoh Beng Teck
17 Jalan Tani

Singapore 548554

- ACCOUNT - 100

NTUC Income Ins Co-operative Ltd
73 Bras Basah Road #05-01
NTUC Trade Union House
Singapore 189556
Motor Department

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SME8157Z	0C46475	27/11/2014	X5 xDrive35i	0

DESCRIPTION

VALUE

To replace rear bumper, tailgate bottom, attachments
and repair tail panel.

2550 3,825.00

Painting rear bumper, tailgate bottom and tail panel.

2474 2,749.00

To check electrical wiring systems and lightings at the
rear section for proper function.

150 177.00

To remove old PDC assembly, replace damaged parts and
reconnect to new bumper including conduct checks for
proper function.

150 177.00

To replace rear exhaust silencer including alignment
system and conduct checks for leak.

451 531.00

To remove and install boot compartment carpet and garnish
to facilitate repairs.

230 271.00

To carry out body cavity preservation.
(Per panel).

nn X 118.00

Sundries.

? 150.00

Total Labour 1: 7,998.00

DESCRIPTION

QTY PRIC

VALUE

TAILPIPE TRIM ALU LOOK H-

1 133.80

133.80

Fixing bow ? x sm

1 12.30

12.30

Heat resista ? x sm

1 30.55

30.55

ACTUATOR DRIVE EXHAUST FLAP x m

1 170.35

170.35

REAR SILENCER WITH EXHAUST FLAP H-

1 2,371.55

2,371.55

BOOTLID BOTTOM H-

1 1,018.85

1,018.85

MOUNTING BUMPER CORNER RR RH x

1 108.75

108.75

MOUNT BUMPER REAR CENTRE ? x suc

1 192.15

192.15

RR BUMPER CARRIER ? x suc

1 849.25

849.25

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 51652
Date Estimated : 21/06/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SME8157Z	0C46475	27/11/2014	X5 xDrive35i	0

DESCRIPTION	QTY	PRIC	VALUE
MOUNT BUMPER RR RH ? <i>cut from</i>	1	192.15	192.15
UNDERRIDE PROTECTION(PURE EXPERIEN <i>1 pc X nn</i>)	1	526.60	526.60
TRIM STRIP BUMPER REAR (PURE EXPERI <i>cut</i>)	1	160.15	160.15
RR LH FLAP TOWING EYE PRIMED <i>cut</i>	1	47.60	47.60
REAR BUMPER BOTTOM TRIM PANEL (V6) ? <i>cut</i>	1	375.15	375.15
REAR BUMPER PANEL PRIMED (PDC) <i>de</i>	1	1,575.55	1,575.55
RH REFLECTOR <i>mis</i>	1	36.80	36.80
DECOUPING RING PDC TORQUE CONVERTER <i>1 pc X nn</i>	1	5.05	20.20
PDC SENSOR SOPHISTO GRAU II WA90 <i>A X Svc</i>	1	380.65	380.65

Total Parts : 8,202.40

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 25/06/19 @ 1155 Excess S\$ _____

Surveyor's Name Rafael Sign _____

Surveyor's Tel 92010068 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend 7 days

17125.90

Labour 1	:	7,998.00
Parts	:	8,202.40
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,134.03
Grand Total	:	17,334.43

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

16200.40

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 51652
Date Estimated : 21/06/2019
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Yeoh Beng Teck
17 Jalan Tani

- ACCOUNT - 100
NTUC Income Ins Co-operative Ltd
73 Bras Basah Road #05-01
NTUC Trade Union House
Singapore 189556
Motor Department

Singapore 548554

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SME8157Z	0C46475	27/11/2014	X5 xDrive35i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments, bottom boot lid include making good the tail end panel and knocking out dents caused by the accident	2550.00		2,550.00 ✓
To spray paint rear bumper, boot lid and tail end panel	2474.00		2,474.00 ✓
To check electrical wiring systems and lightings at the rear section for proper function	150.00		150.00 ✓
To remove old PDC assembly and reconnet to new bumper include conducting checks for proper function	150.00		150.00 ✓
To replace rear exhaust silencer including alignment of system and conducting checks for leak	451.00		451.00 ✓
To remove and install boot compartment carpet and garnish to facilitate repairs	230.00		230.00 ✓
* To carry out body cavity preservation for bottom boot lid (Per panel)	100.00		100.00 (3) ✓
# To transfer lock mechanism from old to new boot lid include conducting checks on new boot lid central locking system for proper function	451.00		451.00 (3) ✓
Sundries	150.00		150.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# CLAMPING BUSH *	66.80	1.00		66.80 NW ✓
TAILPIPE TRIM ALU LOOK	133.80	1.00		133.80 ✓
REAR SILENCER WITH EXHAUST FLAP	2,371.55	1.00		2,371.55 ✓
BOOTLID BOTTOM	1,018.85	1.00		1,018.85 ✓
MOUNTING BUMPER CORNER RR RH	108.75	1.00		108.75 ✓
MOUNT BUMPER RR RH	192.15	1.00		192.15 ✓
TRIM STRIP BUMPER REAR (PURE EXPERI	160.15	1.00		160.15 ✓
REAR BUMPER BOTTOM TRIM PANEL (V6)	377.25	1.00		377.25 ✓

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

REAR BUMPER PANEL PRIMED (PDC)	1,584.35	1.00	1,584.35 ✓
REAR SILENCER HEAT INSULATOR * <i>bt</i> ✓	269.80	1.00	269.80
# EXPANDING RIVET BLACK * <i>nu</i> ✓	1.35	20.00	27.00
RH REFLECTOR	36.80	1.00	36.80

SUPPLEMENTARY ITEMS

Total Labour :	6,706.00
Total Parts :	6,347.25
Total Labour & Parts :	13,053.25
Deduction for Excess :	0.00
Total Repair Costs less Excess:	13,053.25
GST @7%:	913.73
Grand Total :	13,966.98

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 51652
Date Estimated : 21/06/2019
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Yeoh Beng Teck
17 Jalan Tani

- ACCOUNT - 100
NTUC Income Ins Co-operative Ltd
73 Bras Basah Road #05-01
NTUC Trade Union House
Singapore 189556
Motor Department

Singapore 548554

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SME8157Z	0C46475	27/11/2014	X5 xDrive35i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
# To transfer lock mechanism from old to new boot lid include conducting checks on new boot lid central locking system for proper function	451.00		451.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# CLAMPING BUSH * <i>new</i>	66.80	1.00		66.80
# EXPANDING RIVET BLACK * <i>new</i>	1.35	20.00		27.00

Total Labour :	451.00
Total Parts :	93.80
Total Labour & Parts :	544.80

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19011191/R1td3e2

73 BRAS BASAH ROAD

Date: 27-08-2019

#05-01 NTUC TRADE UNION HOUSESINGAPORE

189556



ATTN : AZHARI

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJT 7859U	Veh. Inspected	SME 8157Z
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1050072-002	Excess (\$)	0.00
Assign From	CYNTHIA ANG	Assign Date	25/06/2019

2. Vehicle Particulars & Condition

Make & Model	B.M.W. X5	c.c	2979
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	WBAKR020900C46475	Colour	GREY
Odometer	91862 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	255/50 R19	MICHELIN	6 mm
L/H Front Tyre	255/50 R19	MICHELIN	6 mm
R/H Rear Tyre	255/50 R19	MICHELIN	6 mm
L/H Rear Tyre	255/50 R19	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	20/06/2019	Inspect Date / Time	25/06/2019 (11:50 AM)
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SME 8157Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	SUNDRIES (SN)	NECESSARY	150.00	150.00
1	TAILPIPE TRIM ALU LOOK (SN)	BENT	133.80	133.80
1	FIXING BOW (SN)	SERVICEABLE	12.30	-
1	HEAT RESISTA (SN)	SERVICEABLE	30.55	-
1	ACTUATOR DRIVE EXHAUST FLAP (SN)	NOT NECESSARY	170.35	-
1	REAR SILENCER WITH EXHAUST FLAP (SN)	BENT	2,371.55	2,371.55
1	BOOTLID BOTTOM (SN)	BENT	1,018.85	1,018.85
1	MOUNTING BUMPER CORNER RR RH (SN)	SCRATCHED	108.75	108.75
1	MOUNT BUMPER REAR CENTRE (SN)	SERVICEABLE	192.15	-
1	RR BUMPER CARRIER (SN)	SERVICEABLE	849.25	-
1	MOUNT BUMPER RR RH (SN)	CRACKED	192.15	192.15
1	UNDERRIDE PROTECTION (PURE EXPERIEN (SN)	NOT NECESSARY	526.60	-
1	TRIM STRIP BUMPER REAR (PURE EXPERI (SN)	SCRATCHED	160.15	160.15
1	RR LH FLAP TOWING EYE PRIMED (SN)	NOT NECESSARY	47.60	-
1	REAR BUMPER BOTTOM TRIM PANEL (V6) (SN)	CUT	377.25	377.25
1	REAR BUMPER PANEL PRIMED (PDC) (SN)	DEFORMED	1,584.35	1,584.35
1	RH REFLECTOR (SN)	MISSING	36.80	36.80
4	DECOUPING RING PDC TORQUE CONVERTER (SN)	NOT NECESSARY	20.20	-
1	PDC SENSOR SOPHISTOGRAU II WA90 (SN)	SERVICEABLE	380.65	-
1	CLAMPING BUSH (SN) (ADDITIONAL)	NECESSARY	66.80	66.80
1	REAR SILENCER HEAT INSULATOR (SN) (ADDITIONAL)	BENT	269.80	269.80
20	EXPANDING RIVET BLACK (SN) (ADDITIONAL)	NECESSARY	27.00	27.00
			8,726.90	6,497.25
<u>LABOUR</u>				
TO REPLACE REAR BUMPER, TAILGATE BOTTOM. ATTACHMENTS AND REPAIR TAIL PANEL.			3,825.00	2,550.00
PAINTING REAR BUMPER, TAILGATE BOTTOM AND TAIL PANEL.			2,749.00	2,474.00
TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION.			177.00	150.00

Report Ref No. CS/INC19011191/R1td3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION.	NOT NECESSARY	177.00	150.00
	TO REPLACE REAR EXHAUST SILENCER INCLUDING ALIGNMENT SYSTEM AND CONDUCT CHECKS FOR LEAK.		531.00	451.00
	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS		271.00	230.00
	TO CARRY OUT BODY CAVITY PRESERVATION.(PER PANEL)		118.00	-
	TO CARRY OUT BODY CAVITY PRESERVATION FOR BOTTOM BOOT LID (PER PANEL). (ADDITIONAL)		100.00	100.00
	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOT LID INCLUDE CONDUCTING CHECKS ON NEW BOOT LID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION. (ADDITIONAL)		451.00	451.00
			8,399.00	6,556.00
GRAND TOTAL			17,125.90	13,053.25
RECOMMENDED COST OF REPAIRS (CONFIRMED)				13,053.25

Report Ref No. CS/INC19011191/R1td3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.