

ASS. REC. BY:

REF:

CS/INC19011195/RISd302 Special Instruction:

Surveyor: RasulASSIGNMENT (Office)

From (Person):

Cynthia Ang

of

INC

Date/Time:

25/6/11

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDY 193Y

Insured:

GBF 918Y

at Workshop m/s

Gardbell Engineering

Tel:

9739 7127

of

Blk K pandan loop Ind. Est #01-12

Policy No:

Claim No:

MT/1050285 -002

Sum Insured:

Excess:

Make of Veh:

D.O.A.

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10.23am @ 25/6/11

Person Contacted:

S00

Vehicle:

IN/OUT

Date/Time

Action/Instruction

1-3/11/11 ✓SDY 193Y - CB / AIG 09008924/n D.O.A. 15/09/2005GBF 918Y - ✓26/07/11Confirmed HS \$ 4,800/- @ 5 days with Rasul.(\$ 2,879.30 Real - 38%)

Rasul

REF:


99344

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SDY 1934
 at Workshop m/s GOLD HILL
 of BLK K Amazon Loop Ind #01-12
 Insured: INC
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SDY 1934 Yr Regn: 2013 / DKL
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: MERCEDES Benz C180 Comp c.c. 1898
 Colour: GREY A/C: Insured / Std / NI / NA
 Sp. Reading: 55711 T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: WDD 204 331 291 311 84

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 285 / 35 ZR 18
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 22/06/19Survey held at GOLD HILLDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 26 JUL 2019

26/7/2019

Date/Time, File Pass to?

26/07/19

1) Typ-4

Date/Time, File Return to?

2)

☐ : Preli. Report☒ : Final ReportDays Of Repair: 5Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) 4,800/- 15

290

290

Nivitha (LKK Auto)

From: Cynthia Ang <Cynthia.Ang@income.com.sg>
Sent: Tuesday, 25 June 2019 3:45 PM
To: 'assignments@lkkauto.com'; Admin-D (LKKAuto)
Subject: RE: TP CASES FARMED OUT TO LKK ON 25/06/2019

Hi LKK,

Resend with the following details.

Thank you.

With Regards

Cynthia Ang
Admin Assistant
Motor Insurance
T +65 6430 7900
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.

Find out more at Income.com.sg/careers

in with you

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

From: Cynthia Ang
Sent: Tuesday, 25 June 2019 9:49 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>
Cc: Teng Ken Leong <kenleong.teng@income.com.sg>; Thio Tse Kiat <tsekiat.thio@income.com.sg>; Cynthia Ang <Cynthia.Ang@income.com.sg>
Subject: TP CASES FARMED OUT TO LKK ON 25/06/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	Eric Tang	MT/1050061-002	FZ6005P	HKL LIM TEAM MOTORSPORT	BLK 1008 #01-24 BUKIT MERAH LANE 3 SINGAPORE 159722	James Lim / 9242 3895		XE1528C	21/06/2019	
2	Eric Tang	MT/1050364-002	SL19897P	PEGASUS ENGINEERING & TRADING PTE LTD	74 KIAN TECK ROAD SINGAPORE 628800	Yoyo / 65137748		SGK2839T	23/06/2019	
3	Jared Liu	MT/1034112-003	SLP4297H	PEGASUS ENGINEERING & TRADING PTE LTD	74 KIAN TECK ROAD SINGAPORE 628800	Yoyo / 65137748	14:00-16:00	YL8550S	01/11/2018	Owner waiting
4	Azhari	MT/1050072-002	SME8157Z	PERFORMANCE MOTORS LTD	303 ALEXANDRA ROAD SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941	Caroline / 6319 0174		SJT7859U	20/06/2019	
5	Serene Lim	MT/1048606-002	SBX2U	PREMIUM AUTOMOBILES PTE LTD	281 ALEXANDRA ROAD SINGAPORE 159938	Tony Foong / 6366 2323	10:00-12:00	GZ7468T	11/06/2019	
6	Jared Liu	MT/1044498-002	JNY2143	A S PHOON PTE LTD	36 TOH GUAN ROAD EAST #01-35 ENTERPRISE HUB SINGAPORE 608580	Kee Ger Ong / 6515 0770		YN4530R	11/05/2019	
7	Helena Tan	MT/1050289-002	SDY193Y	GOLDBELL ENGINEERING PTE LTD	BLK K PANDAN LOOP IND ESTATE #01-12	Soo Leong Keat / 9739 7127	10:00-12:00	GBF918Y	22/06/2019	
8	Cyndie Yong	MT/1050341-002	SHC2352K	SOON HOCK MOTOR PTE LTD	10 ANG MO KIO IND PK 2-A #01-05/06 AMK AUTOPOINT SINGAPORE 568047	Ms Lynn / 65425119		SJM156Y	21/06/2019	

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

With Regards

Cynthia Ang

Admin Assistant

Motor Insurance

T +65 6430 7900

www.income.com.sg

income
made different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.

Find out more at income.com.sg/careers

in with you

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

Shirley Hiew (LKK Auto)

From: Soo Leong Keat <SooLeongKeat@goldbell.com.sg>
Sent: Thursday, 25 July 2019 4:40 PM
To: Rasul (LKKAuto)
Cc: Ramesh; Mohamad Bin Omar
Subject: RE: SDY 193Y DOA : 22/06/19

Dear Rasul

We agreed with the finalized amount \$4800 before GST and 5days of repair.

Thank you.

Regards,
Junior Soo

From: Rasul (LKKAuto) <Rasul@lkkauto.com>
Sent: Thursday, July 25, 2019 4:25 PM
To: Soo Leong Keat <SooLeongKeat@goldbell.com.sg>
Subject: RE: SDY 193Y DOA : 22/06/19

Hi Soo,

Finalised amount round up is 4800
kindly confirmed


Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Soo Leong Keat [<mailto:SooLeongKeat@goldbell.com.sg>]
Sent: Thursday, 25 July, 2019 4:14 PM
To: Rasul (LKKAuto)
Cc: Ramesh; Mohamad Bin Omar
Subject: RE: SDY 193Y DOA : 22/06/19
Importance: High

Dear Rasul

As spoken, after revised adjusted estimate report total lump sum 15% is \$ 4780 / 5 days lump sum.
Please confirm.

Thank you.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	24/06/2019 16:12
Date Of Accident	22/06/2019 12:20
Exact Location Of Accident	ALONG BOUNDARY ROAD TOWARDS LOR CHUAN
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SDY193Y
Insured/Policyholder	
Name Of Registered Owner	VINCENT TAN HAI YORK
NRIC No	S6919934H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96820697
Alternative Phone No	OFFICE-96820697
Vehicle Particulars	
Manufacturer	MERCEDES-BENZ
Model	C180 COUPE (R18)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2018-00015023
Cover Note Number	
Driver	
Name of Driver	MARC TAN BOON HAO
NRIC No	S9925628A
Date Of Birth	12/08/1999
Occupation	INDOOR
Date Of Driving Pass	12/05/2018
Driving Experience	1 YEAR AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-90901193
Fax Number	
Contact Number	
EEmail Address	MARCTANBH63@GMAIL.COM

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PARENT
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I was driving along Boundary Road towards Lor Chuan before the turn off into Serangoon Avenue 3 at 1233hrs on 22 June 2019. I was driving along the middle lane when a car in front of me tried to change from the left lane to the middle lane. His entry into my lane blocked my path and thus i slowed down and brake. As a result, a van (GBF918Y) behind drove too close to my car and unable to stop and collided onto the rear of my car. The driver of the van admitted he was at fault and hence we proceeded with insurance claims. Damages to my car were on the rear portion. No injuries were involved.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBF918Y
Vehicle Make/Model/Colour	NISSAN / NV350 PANEL VAN 2.5 5MT 5DR EURO V
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	CHEW YERN CHEONG
NRIC/Passport Number	S8377678A
Contact Number	96424466
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	3

Passenger 1

NAME: : P1
GENDER: : MALE

Passenger 2

NAME: : P2
GENDER: : MALE

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
 4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- Consent under the Personal Data Protection Act (PDPA)**
- I understand, acknowledge, agree and consent that:
- (a) my insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/are be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

VERIFIED BY AJAX MARS
REPORTING OFFICER

Muhammad Faizal


Bin Pabla

Witnessed by Reporting Centre
Personnel

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Sketch Plan



ACCIDENT STATEMENT (2000 characters)

I was driving along Boundary Road towards Lor Chuan before the turn off into Serangoon Avenue 3 at 1233hrs on 22 June 2019. I was driving along the middle lane when a car in front of me tried to change from the left lane to the middle lane. His entry into my lane blocked my path and thus i slowed down and brake. As a result, a van (GBF918Y) behind drove too close to my car and unable to stop and collided onto the rear of my car. The driver of the van admitted he was at fault and hence we proceeded with insurance claims. Damages to my car were on the rear portion. No injuries were involved.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MUHAMMAD FAIZAL BIN PABILA

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

24 June 2019 at 3:05 PM

Date/Time:

24 June 2019 at 3:05 PM



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue, 18 Singapore 638894

Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)

Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)

Website: www.goldbell.com.sg

Co. Reg. No.: 198003963G

DATE : 25/06/2019
TO : NTUC MOTOR CLAIMS DEPT
ATTN :
OFFICE / MOBILE :
EMAIL ADDRESS :

VEHICLE NO. : SDY193Y
MODEL NO. : MERCEDES C180 COUPE
CHASSIS NO. : WDD2043312G131184
ENGINE NO. : 2.7491E+13
REG. DATE : 13/12/2013

FROM : GOLDBELL ENGINEERING PTE LTD
ATTN : JUNIOR SOO
OFFICE / MOBILE : 97397127
FAX NO. :

REF. NO. :
D.O.A. : 22/06/2019
POLICY NO. : PNPV2018-00015023
CLAIM TYPE : 3rd Party Claim

WORKSHOP : Blk K, Pandan Loop Ind. Estate #01-12 Singapore 128219

S/N	PART NO.	DESCRIPTION	QUANTITY	LIST PRICE
1		REAR BUMPER <i>de</i>	1	\$ 1,500.00
2		REAR BUMPER CLIP <i>re</i>	10	\$ <i>70</i> 700
3		RR BUMPER HOLDER LH <i>? Com</i>	1	\$ 40.00
4		RR BUMPER HOLDER RH <i>? ca</i>	1	\$ 40.00

SUB-TOTAL : \$ 1,587.00
LESS 10% : \$ 158.70
PARTS TOTAL : *1428.30* \$ 1,428.30

NETT

1		RR BUMPER LOWER <i>de</i>	1	\$ 180.00
2		RR BUMPER TOW COVER <i>sc</i>	1	\$ 50.00
3		RR BUMPER REINFORCEMENT <i>bt</i>	1	\$ 666.00
4		BOOTLID <i>bt</i>	1	\$ 1,720.00
5		BOOTLID MOULDING <i>? X 2 n</i>	1	\$ 20.00 X
6		BOOTLID END GARNISH <i>X 3 n</i>	1	\$ 115.00 X
7		C 180 WORDING <i>re</i>	1	\$ 78.00
8		MERCEDES BENZ "LOGO" <i>re</i>	1	\$ 52.00
9		7G - TRONIC" WORDING <i>re</i>	1	\$ 60.00
10		RR LIGHT LH <i>X</i>	1	\$ 700.00 X
11		RR LIGHT RH <i>X</i>	1	\$ 700.00 X
12		REVERSE CAMERA <i>? X 3 n</i>	1	\$ 480.00 X

NETT TOTAL : \$ 2,941.00

SPECIAL NETT

1		RR NUMBER PLATE <i>X</i>	1	\$ 60.00
2		RR NUMBER PLATE HOLDER <i>X 3 n</i>	1	\$ 120.00
3		REVERSE SENSOR <i>? X</i>	2	\$ <i>220</i> 560.00

SPECIAL NETT TOTAL : \$ 740.00

bizSAFE
S T A R



Certificate No.: AJA(S)01/Q1243

Certificate No.: AJA01/3054



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638894

Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)

Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)

Website: www.goldbell.com.sg

Co. Reg. No.: 198003963G

LABOUR CHARGES

- 1 LABOUR TO REMOVE & REFIT NECESSARY PARTS
TO REPAIR & KNOCK OUT WHERE NECESSARY.
STRAIGHTEN & RESHAPE, REPOSITION
& REALIGN REPLACEMENT PARTS
TO ORIGINAL POSITION.
- 2 SPRAY PAINT ON THE AFFECTED AREAS
- 3 TO REMOVE & REFIT REVERSE SENSOR
- 4 WIRING

\$ 1,200.00

600

\$ 1,000.00

\$ 80 250.00

\$ 60 120.00

LABOUR TOTAL :

\$ 2,570.00

TOTAL :

\$ 7,679.30

7% GST

\$ 537.55

GRAND TOTAL :

\$ 8,216.85

PREPARED BY : JUNIOR SOO

DATE / TIME : 25/06/19 @ 1455

SURVEYOR : Rasul

MOBILE NO. : 9006068

OFFICE FAX NO. :

EMAIL ADDRESS : rasul@lkkauto.com

REPAIR TYPE : PART-BY-PART / LUMP SUM

RE-SURVEY : BEFORE PAINT / AFTER PAINT

NO. OF DAYS : 5 days

REMARKS :

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Certificate No: AJA(S)01/Q1243

Certificate No: AJA01/3054



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19011195/R1sd3e2

73 BRAS BASAH ROAD

Date: 01-08-2019



#05-01 NTUC TRADE UNION HOUSESINGAPORE

189556

ATTN : HELENA TAN

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBF 918Y	Veh. Inspected	SDY 193Y
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1050289-002	Excess (\$)	0.00
Assign From		Assign Date	25/06/2019

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ C180 COUPE	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	WDD2043312G131184	Colour	GREY
Odometer	55711 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	255/35Z R18	MICHELIN	6 mm
L/H Front Tyre	255/35Z R18	MICHELIN	6 mm
R/H Rear Tyre	255/35Z R18	MICHELIN	6 mm
L/H Rear Tyre	255/35Z R18	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	22/06/2019	Inspect Date / Time	25/06/2019 (02:52 PM)
Survey held at	BLK K PANDAN LOOP IND EST #01-12		
Repairer	GOLDBELL ENGINEERING PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDY 193Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	1,500.00	1,500.00
10	REAR BUMPER CLIP	NECESSARY	70.00	70.00
1	RR BUMPER HOLDER LH	CRACKED	40.00	40.00
1	RR BUMPER HOLDER RH	CRACKED	40.00	40.00
	LESS 10% DISCOUNT		-165.00	-165.00
			1,485.00	1,485.00
<u>SPECIAL NETT ITEMS</u>				
1	RR BUMPER LOWER (SN)	DEFORMED	180.00	180.00
1	RR BUMPER TOW COVER (SN)	SCRATCHED	50.00	50.00
1	RR BUMPER REINFORCEMENT (SN)	BENT	666.00	666.00
1	BOOTLID (SN)	BENT	1,720.00	1,720.00
1	BOOTLID MOULDING (SN)	NOT NECESSARY	20.00	-
1	BOOTLID END GARNISH (SN)	NOT NECESSARY	115.00	-
1	C 180 WORDING (SN)	NECESSARY	78.00	78.00
1	MERCEDES BENZ "LOGO" (SN)	NECESSARY	52.00	52.00
1	7G-TRONIC" WORDING (SN)	NECESSARY	60.00	60.00
1	RR LIGHT LH (SN)	NOT NECESSARY	700.00	-
1	RR LIGHT RH (SN)	NOT NECESSARY	700.00	-
1	REVERSE CAMERA (SN)	NOT NECESSARY	480.00	-
1	RR NUMBER PLATE (SN)	NOT NECESSARY	60.00	-
1	RR NUMBER PLATE HOLDER (SN)	NOT NECESSARY	120.00	-
2	REVERSE SENSOR (SN)	NOT NECESSARY	560.00	-
			5,561.00	2,806.00
<u>LABOUR</u>				
	LABOUR TO REMOVE & REFIT NECESSARY PARTS TO REPAIR & KNOCK OUT WHERE NECESSARY. STRAIGHTEN & RESHAPE, REPOSITION & REALIGN REPLACEMENT PARTS. TO ORIGINAL POSITION.		1,200.00	600.00
	SPRAY PAINT ON THE AFFECTED AREAS.		1,000.00	600.00
	TO REMOVE & REFIT REVERSE SENSOR.		250.00	80.00

Report Ref No. CS/INC19011195/R1sd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	WIRING.		120.00	60.00
			2,570.00	1,340.00
GRAND TOTAL			9,616.00	5,631.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				4,800.00

Report Ref No. CS/INC19011195/R1sd3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.