

## CHUNNI MOTOR WORK PTE LTD

Go Swire my LKK

## REPAIR ESTIMATE\*

VEHICLE NO : SHC 2545X

DATE : 24.06.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

AIG

| Qty | Parts Description/ Labour                           | Type | Unit Price | Amount      |
|-----|-----------------------------------------------------|------|------------|-------------|
|     | Bonnet <i>Dented</i>                                |      |            | \$ 2,265.90 |
|     | Bonnet Hinge (LH/RH) <i>bt</i>                      |      | \$ 41.00   | \$ 82.00    |
|     | Bonnet Insulator <i>NN</i>                          |      |            | \$ 196.50   |
|     | Bonnet Insulator Clips <i>NN</i>                    |      |            | \$ 8.40     |
|     | Radiator Grille <i>NN</i>                           |      |            | \$ 251.00   |
|     | Radiator Grille H Emblem <i>NN</i>                  |      |            | \$ 27.50    |
|     | Front Bumper Cover <i>broken</i>                    |      |            | \$ 544.50   |
|     | Front Bumper Sponge <i>NN</i>                       |      |            | \$ 99.20    |
|     | Front Bumper Reinforcement <i>NN</i>                |      |            | \$ 402.10   |
|     | Front Bumper Grille (RH) <i>dislodged</i>           |      |            | \$ 41.60    |
|     | Front Bumper Bracket Top (RH) <i>NN</i>             |      |            | \$ 22.40    |
|     | Front Bumper Bracket (RH) <i>broken</i>             |      |            | \$ 24.60    |
|     | Headlamp Support Top Cover <i>NN</i>                |      |            | \$ 222.60   |
|     | Headlamp Support Panel Assy <i>broken</i>           |      |            | \$ 907.40   |
|     | Headlamp (RH) <i>broken</i>                         |      |            | \$ 1,388.00 |
|     | Headlamp Halogen Bulb (RH) <i>NN</i>                |      |            | \$ 14.40    |
|     | Radiator Expansion Tank <i>NN</i>                   |      |            | \$ 28.30    |
|     | Front Fender (RH) <i>Buc</i>                        |      |            | \$ 663.00   |
|     | Front Fender Apron Panel (RH) <i>Dented</i>         |      |            | \$ 637.00   |
|     | Front Fender Shield (RH) <i>turn</i>                |      |            | \$ 174.90   |
|     | Front Door Mirror Assy (RH) <i>broken</i>           |      |            | \$ 670.00   |
|     | Rocker Panel Outer Garnish <i>NN</i>                |      |            | \$ 341.40   |
|     | Front Pillar Upper Cover/Garnish <i>cut / 121</i>   |      |            | \$ 83.50    |
|     | Front Windscreen Glass <i>broken</i>                |      |            | \$ 1,017.80 |
|     | Front Windscreen Moulding <i>kcc</i>                |      |            | \$ 113.30   |
|     | Front Windscreen Pillar Outer (RH) <i>Dented</i>    |      |            | \$ 1,745.50 |
|     | Wiper Container <i>damaged</i>                      |      |            | \$ 61.90    |
|     | Wiper Container Motor <i>Dem</i>                    |      |            | \$ 75.00    |
|     | Front Wheel Rim (RH) <i>1st</i>                     |      |            | \$ 325.30   |
|     | Front Wheel Hub Cap (RH) <i>dislodged</i>           |      |            | \$ 107.10   |
|     | Front Wheel Bearing <i>2 Dem</i>                    |      |            | \$ 540.50   |
|     | Front Shock Absorber (Assy) (RH) <i>2 dislodged</i> |      |            | \$ 342.20   |
|     | Front Shock Absorber Mounting (RH) <i>NN</i>        |      |            | \$ 108.80   |
|     | Front Drive Shaft (RH) <i>2 Dem</i>                 |      |            | \$ 1,030.80 |
|     | Rack & Pinion Assy <i>2 Dem</i>                     |      |            | \$ 1,191.30 |
|     | STG Tie End <i>2 dislodged</i>                      |      |            | \$ 62.60    |
|     | Stabilizer Bar <i>2 dislodged</i>                   |      |            | \$ 252.30   |
|     | Stabilizer Bar Bush (RH) <i>NN</i>                  |      |            | \$ 16.40    |
|     | Stabilizer Bar Link <i>2 dislodged</i>              |      |            | \$ 61.10    |
|     | Stabilizer Bracket <i>NN</i>                        |      |            | \$ 24.00    |
|     | Front Suspension Lower Arm (RH) <i>2 1st</i>        |      |            | \$ 529.30   |
|     | Knuckle Arm (RH) <i>2 dislodged</i>                 |      |            | \$ 552.00   |
|     | Engine Under Cover <i>NN</i>                        |      |            | \$ 334.60   |
|     | Engine Crossmember <i>2 Dented</i>                  |      |            | \$ 2,094.40 |
|     | ABS Sensor (RH) <i>NN</i>                           |      |            | \$ 234.00   |

SHC 2545X

| Qty                                                                                                                                                                                                            | Parts Description/ Labour                                                                                                | Type | Unit Price | Amount                      |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------|------|------------|-----------------------------|
|                                                                                                                                                                                                                | SUB TOTAL                                                                                                                |      |            | \$ 19,916.40                |
|                                                                                                                                                                                                                | LESS 20%                                                                                                                 |      |            | \$ 3,983.28                 |
|                                                                                                                                                                                                                | DISCOUNTED TOTAL                                                                                                         |      |            | \$ 15,933.12                |
|                                                                                                                                                                                                                | Front Fender Advertisement Logo (RH) <i>N/C</i>                                                                          |      |            | \$ 100.00                   |
|                                                                                                                                                                                                                | Front Door Comfort Logo (RH) <i>N/C</i>                                                                                  |      |            | \$ 75.00                    |
|                                                                                                                                                                                                                | Front Door Advertisement Logo (RH) <i>N/C</i>                                                                            |      |            | \$ 100.00                   |
|                                                                                                                                                                                                                | Front Windscreen Sealant <i>N/C</i>                                                                                      |      |            | \$ 46.00                    |
|                                                                                                                                                                                                                | Front ERP Sticker <i>N/C</i>                                                                                             |      |            | \$ 26.00                    |
|                                                                                                                                                                                                                | Front Tyre (RH) <i>provided 50% depreciation</i>                                                                         |      |            | \$ <sup>108.00</sup> 216.00 |
|                                                                                                                                                                                                                | Gearbox Assy <i>NN</i>                                                                                                   |      |            | \$ 8,000.00                 |
|                                                                                                                                                                                                                |                                                                                                                          |      |            | \$ 8,563.00                 |
|                                                                                                                                                                                                                | Labour Charge                                                                                                            |      |            |                             |
|                                                                                                                                                                                                                | Panel Beating                                                                                                            |      |            | \$ 2,000.00                 |
|                                                                                                                                                                                                                | Spray Painting Charge                                                                                                    |      |            | \$ 1,750.00                 |
|                                                                                                                                                                                                                | Wiring Charge                                                                                                            |      |            | \$ 50.00                    |
|                                                                                                                                                                                                                | Tuff Kote                                                                                                                |      |            | \$ 100.00                   |
|                                                                                                                                                                                                                | Towing Charge                                                                                                            |      |            | \$ 50.00                    |
|                                                                                                                                                                                                                | Remove/Refix Undercarriage (FRONT)                                                                                       |      |            | \$ 200.00                   |
|                                                                                                                                                                                                                | FRT Wheel Alignment                                                                                                      |      |            | \$ 120.00                   |
|                                                                                                                                                                                                                | Remove/Refix Aircon & Refill Gas                                                                                         |      |            | \$ 150.00                   |
|                                                                                                                                                                                                                | Remove/Refix Gearbox                                                                                                     |      |            | \$ 450.00                   |
|                                                                                                                                                                                                                | Remove/Refix Dashboard                                                                                                   |      |            | \$ 450.00                   |
|                                                                                                                                                                                                                | Remove/Refix Front Windscreen Glass                                                                                      |      |            | \$ 120.00                   |
|                                                                                                                                                                                                                | Remove/Refix Cushion & Upholstery Front                                                                                  |      |            | \$ 90.00                    |
|                                                                                                                                                                                                                | Re-set Frt ABS System                                                                                                    |      |            | \$ 200.00                   |
|                                                                                                                                                                                                                | Re-set Frt Power Window System                                                                                           |      |            | \$ 200.00                   |
|                                                                                                                                                                                                                | Diagnostic & Resetting To Erase Fault Code                                                                               |      |            | \$ 480.00                   |
|                                                                                                                                                                                                                | TOTAL LABOUR                                                                                                             |      |            | \$ 6,410.00                 |
|                                                                                                                                                                                                                | ESTIMATE TOTAL                                                                                                           |      |            | \$ 30,906.12                |
|                                                                                                                                                                                                                | <p>26/06/2019 @ 1100m</p> <p><i>N/A Antimal</i></p> <p><i>L/Smm 9 days.</i></p> <p><i>yan</i></p> <p><i>LKK Auto</i></p> |      |            |                             |
| This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. |                                                                                                                          |      |            |                             |