

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 8981E

MAKE :

MODEL : HYUNDAI i40

DATE 24/6/2019 15:58

(F2)

Alt / Rear

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper			\$ 553.00	
	Rear Bumper Clip 10 pcs			\$ 22.00	
	Rear Bumper Under Cover			\$ 228.00	
	SUB TOTAL			\$ 803.00	
	LESS 20%			\$ 160.60	
	DISCOUNTED TOTAL			\$ 642.40	
	Rear Bumper Rubber Mat			\$ 50.00	Nett
	Rear Bumper Advertisement Logo			\$ 50.00	Nett
	Rear Fender Advertisement Logo (LH/RH)		\$ 100.00	\$ 200.00	Nett
				\$ 300.00	
	Labour Charge				
	Panel Beating			\$ 400.00 ²⁰⁰	
	Spray Painting Charge			\$ 300.00 ²⁰⁰	
	Wiring Charge			\$ 30.00 ^X	
	Remove/Refix Reverse Sensor			\$ 80.00 ³⁰	
	TOTAL LABOUR			\$ 810.00	
	ESTIMATE TOTAL			\$ 1,752.40	

Kahin 16/16

25/6/19 1045h

200

P/P

Before Part phl

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.