

HS180 700K

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

25 JUN 2019

Estimate No. : b1 51677	Page No. : 1 of 4
Date Estimated : 24/06/2019	
Prepared By : Joseph Yaguel	

- ESTIMATE REPAIR FOR - Teo Su Lin, Delia 65 Tampines Central 7 #13-28 Singapore 528597	- ACCOUNT - 219 India Int'L Insurance Pte Ltd 64 Cecil Street #04-05 IOB Building Singapore 049711
--	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMK7927T	ED05835	25/04/2019	216i GT	0

DESCRIPTION	VALUE
Replacing rear bumper panel and rework left rear side panel	1700 2550.00
Spray rear bumper and left rear side panel	1730 1923.00
To check electrical wiring systems and lightings at the rear section for proper function.	180 177.00
Sundries	? 80.00
Total Labour 1:	4,730.00

DESCRIPTION	QTY	PRIC	VALUE
RR BUMPER LH SIDE GUIDE ? for	1	61.50	61.50
REAR BUMPER CARRIER ? for	1	458.10	458.10
SUPPORT ? for	1	45.30	45.30
RR BUMPER LH INNER SIDE GUIDE ? for	1	67.55	67.55
REAR BUMPER PANEL PRIMED (LINES PDC) for	1	1,029.50	1045.45 1,029.50
Rear light left for	1	270.50	270.50
DECOUPLING RING PDC TORQUE CONVERTER ? for	4	5.05	20.20
Total Parts :			1,952.65

Claims OD / 3rd Party / Uninsured losses / Direct Settlement	
Regn No. 22/01/19 01455	Claim No.
Date & Time	Excess S\$

	Surveyor's Name <u>RAME</u> Sign	Labour 1 : 4,730.00
	Surveyor's Tel <u>9600068</u> Authorised Yes / No	Parts : 1,952.65
	Authorised Date _____ Time _____	Labour 2 : 0.00
	BY SURVEYOR Yes / No PML Yes / No	Excess : 0.00
	Surveyor's Email _____	Total GST @ 7% : 467.79
	No. of Working Days Recommend <u>4 days</u>	Grand Total : 7,150.44

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 51677**
Date Estimated : **24/06/2019**
Prepared By : **Joseph Yaguel**

- ESTIMATE REPAIR FOR -

Teo Su Lin, Delia
65 Tampines Central 7
#13-28

Singapore 528597

- ACCOUNT - 219

India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMK7927T	ED05835	25/04/2019	216i GT	0

DESCRIPTION	ACCOUNT:		
	ORIGINAL PRICE	DISC. %	NETT
To replace left tail lamp, rear bumper and attachments etc including to make good the rear left fender and knock out dented area caused by the accident. To remove and install body parts in order to carry out painting job.	1,700.00	0	1,700.00 ✓
To respray rear bumper and rear left fender	1,730.00	0	1,730.00 ✓
To check electrical wiring systems and lightings at the rear section for proper function.	150.00	0	150.00 ✓
Sundries	80.00	0	80.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# RR BUMPER LH INNER SIDE GUIDE	67.55	1	0	67.55 ✓
REAR BUMPER PANEL PRIMED (LINES PDC	1,045.45	1	0	1,045.45 ? ✓
# REAR LH REFLECTOR	37.90	1	0	37.90 (\$) ✓
REAR LH LIGHT IN THE SIDE PANEL	365.20	1	0	365.20 ✓
#				
#				

SUPPLEMENTARY ITEMS

DATE	WORKING DAYS
Rasul LKK 7/8/19	3
CONFIRMED DATE	
PLEASE FINALISE	

Total Labour :	3,660.00
Total Parts :	1,516.10
Total Repair Costs less Excess:	5,176.10
GST @7%:	362.33
Grand Total :	5,538.43

CAR RENTAL - \$224.70
LTA SEARCH FEE - \$7.45

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : **b1 51677**
Date Estimated : **24/06/2019**
Prepared By : **Joseph Yaguel**

- ESTIMATE REPAIR FOR -

Teo Su Lin, Delia
65 Tampines Central 7
#13-28

Singapore 528597

- ACCOUNT - 219

India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMK7927T	ED05835	25/04/2019	216i GT	0

DESCRIPTION	ACCOUNT: ORIGINAL PRICE	DISC. %	NETT
-------------	----------------------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# REAR LH REFLECTOR <i>sc</i>	37.90	1	0	37.90
#				
#				

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	37.90
Total Repair Costs less Excess:	37.90