

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

25 JUN 2019

Estimate No. : b1 51677
Date Estimated : 24/06/2019
Prepared By : Joseph Yaguel

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -

Teo Su Lin, Delia
65 Tampines Central 7
#13-28

Singapore 528597

- ACCOUNT - 219

India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMK7927T	ED05835	25/04/2019	216i GT	0

DESCRIPTION	VALUE
Replacing rear bumper panel and rework left rear side panel	2,550.00
Spray rear bumper and left rear side panel	1,923.00
To check electrical wiring systems and lightings at the rear section for proper function.	177.00
Sundries	80.00

Total Labour 1: 4,730.00

DESCRIPTION	QTY	PRIC	VALUE
RR BUMPER LH SIDE GUIDE	1	61.50	61.50
REAR BUMPER CARRIER	1	458.10	458.10
SUPPORT	1	45.30	45.30
RR BUMPER LH INNER SIDE GUIDE	1	67.55	67.55
REAR BUMPER PANEL PRIMED (LINES PDC	1	1,029.50	1,029.50
Rear light left	1	270.50	270.50
DECOUPING RING PDC TORQUE CONVERTER	4	5.05	20.20

Total Parts : 1,952.65



Labour 1	:	4,730.00
Parts	:	1,952.65
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	467.79
Grand Total	:	7,150.44

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **