



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLF 7531 P

Parts	(a) Cost / List Price Items	\$	7,073.40
	Plus/Less 25%	\$	1,768.35
	Total of Cost / List	\$	5,305.05
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items		
Total Parts Cost			
Labour		\$	2,840.00
Total		\$	8,145.05

The above total will be subjected to 7% G.S.T.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Name of Surveyor	:	Kenneth
Company	:	LKK
Survey conducted on	:	_____ at _____
<u>Remarks By Surveyor</u>		
(a)	The repair of this vehicle is authorized / is not authorized until further notice.	
(b)	Recommended Days of Repair	: 04 day(s)
(c)	Resurvey	: Required / Not Required
(d)	Excess	: \$ _____
(e)	Signature of surveyor	: Le Date: 25/6/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SLF 7531 P**
Make & Model : **TOYOTA PRIUS**
Chassis No : **JTDKB3FU703532052**

Submit By : **Carmen Lim**
Year Manufacture : **2016**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	RH front door <i>R₁</i>	1	\$1,226.70		✓
2	RH front door hinge top <i>R</i>	1	\$78.34		X
3	RH front door hinge bottom <i>R</i>	1	\$78.34		X
4	RH front door lock <i>R</i>	1	\$428.40		X
5	RH front door checker <i>S₂</i>	1	\$156.79		X
6	RH front door weatherstip	1	\$198.49		?
7	RHF door glass outer moulding	1	\$122.95		?
8	RHF power window motor <i>S₂</i>	1	\$543.25		✓
9	RHF power window regulator <i>D, 1</i>	1	\$211.78		✓
10	RHF door outer handle <i>S₂</i>	1	\$375.60		X
11	RH rear door <i>R₁</i>	1	\$1,181.75		✓
12	RH rear door hinge top <i>R</i>	1	\$78.34		X
13	RH rear door hinge bottom <i>R</i>	1	\$78.34		X
14	RH rear door lock <i>R</i>	1	\$411.70		X
15	RH rear door checker <i>S₂</i>	1	\$156.79		X
16	RH rear door weatherstip <i>S₂</i>	1	\$178.40		X
17	RHR door glass outer moulding <i>R₂</i>	1	\$111.61		X
18	RHR power window motor <i>S₂</i>	1	\$511.69		X
19	RHR power window regulator <i>R</i>	1	\$177.64		X
20	LH side skirt <i>CMS</i>	1	\$721.50		✓
21	LH side skirt clip <i>M</i>	10	\$45.00		✓
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

