

SJE :

Date of Survey :

Date of ReSurvey:

Contacts :

After-Paint:

 Vehicle Nos : **SLR 423B**

Model : Honda Vezel

Year :

Chassis No :

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount:

Working Day:

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$	
1	Tailgate	1	\$ 1,620.00	\$ 1,283.50 1,620.00	DDV
2	Tailgate outer Garnish	1	\$ 385.00	\$ 385.00	NNX
3	Tailgate logo	1	\$ 58.00	\$ 58.00	✓
4	Tailgate emblem 'Vezel'	1	\$ 56.20	\$ 56.20	✓
5	Tailgate emblem 'Hybrid'	1	\$ 48.30	\$ 48.30	✓
6	Tailgate reflector	2	\$ 395.00	\$ 790.00	BRV
7	Tailgate weather strip	1	\$ 185.00	\$ 155.00 185.00	CutV
8	Tailgate inner trim board	1	\$ 325.00	\$ 325.00	NNX
9	Tailgate inner lock	1	\$ 245.00	\$ 245.00	NNX
10	Taillamp lower garnish Rh	1	\$ 165.00	\$ 165.00	✓
11	Taillamp lower garnish Lh	1	\$ 165.00	\$ 165.00	✓
12	Tailgate lock sensor	1	\$ 185.30	\$ 185.30	✓
13	Tailgate antenna	1	\$ 300.00	\$ 100.00 300.00	✓
14	Rear windscreen moulding top	1	\$ 104.00	\$ 104.00	✓
15	Rear windscreen moulding bottom	1	\$ 104.00	\$ 104.00	✓
16	Rear windscreen moulding side	1	\$ 82.00	\$ 82.00	✓
17	Rear bumper	1	\$ 1,185.00	\$ 1,020.00 1,185.00	DDV
18	Rear bumper side retainer	2	\$ 78.00 88.00	\$ 156.00 176.00	NECV
19	Rear bumper bracket	2	\$ 136.00	\$ 272.00	BTV
20	Rear bumper reflector	2	\$ 132.80 187.00	\$ 265.60 374.00	BRV
21	Rear bumper lower splash guard	1	\$ 150.30	\$ 150.30	BTV
22	Smart buzzer	1	\$ 195.00	\$ 195.00	✓
23	Rear end panel	1	\$ 725.00	\$ 659.00 725.00	DDV
24	Rear end panel top garnish	1	\$ 204.00	\$ 138.50 204.00	DLV
25	Spare tyre panel	1	\$ 1,230.00	\$ 962.30 1,230.00	DDV
26	Spare tyre panel top board	1	\$ 420.00	\$ 420.00	NNX
27	Spare tyre panel insulator	1	\$ 240.00	\$ 240.00	NECV
28	Spare tyre panel tools tray	1	\$ 264.00	\$ 264.00	NNX
29	Exhaust pipe	1	\$ 895.00	\$ 895.00	✓
30	Exhaust mounting	2	\$ 42.50	\$ 85.00	✓
31	Exhaust heat shield	1	\$ 185.00	\$ 185.00	✓
32	Front bumper	1	\$ 1,027.50	\$ 1,027.50	DDV
33	Front bumper reinforcement	1	\$ 653.00	\$ 445.00 653.00	BTV
34	Front bumper centre grille base	1	\$ 223.00	\$ 223.00	BRV
35	Front bumper lower grille	1	\$ 165.00	\$ 165.00	BRV
36	Front grille logo	1	\$ 82.00	\$ 50.00 82.00	NECV
37	Front grille chrome garnish	1	\$ 224.00	\$ 224.00	BRV
38	Headlamp Lh	1	\$ 1,784.50	\$ 1,580.00 1,784.50	BRV
Parts Sub Total :				\$ 9721.80 15,577.10	
Discount 20%				\$ 1944.36 3,115.42	
PARTS TOTAL :				\$ 7777.44 12,461.68	

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$	
Prepared by Eric	(8269-9999) Page 1 of 2	1	\$ 60.00	\$ 60.00	NNX

2	Windscreen primer and cleaner	1	\$ 60.00	\$ 60.00	NNX
3	Tailgate outer garnish clips	1	\$ 50.00	\$ 50.00	NNX
4	Tailgate reflector clips	1	\$ 50.00	\$ 30.00	50.00 VNEC
5	Rear windscreen clips	1	\$ 50.00	\$ 30.00	50.00 NEC
6	Rear bumper clips	1	\$ 50.00	\$ 30.00	50.00 NEC
7	Rear end panel top garnish clips	1	\$ 50.00	\$ 30.00	50.00 NEC
8	Front bumper lower grille clips	1	\$ 50.00	\$ 30.00	50.00 NEC
9	Tailgate windscreen inner seal	1	\$ 80.00	\$ 40.00	80.00 NEC
10	Tailgate sealant	1	\$ 100.00	\$ 60.00	100.00 NEC
11	Rear end panel sealant	1	\$ 100.00	\$ 60.00	100.00 NEC
12	Spare tyre panel sealant	1	\$ 100.00	\$ 60.00	100.00 NEC
13	Front no plate with casing	1	\$ 80.00	\$ 50.00	80.00 NEC
14	Reverse sensor	2	\$ 200.00	\$ 200.00	400.00 SC
SPECIAL NETT TOTAL :				\$ 620.00	1,280.00

Nos.	LABOUR	S\$
1	R&R tailgate component	\$ 50.00 100.00
2	R&R reverse sensor	\$ 60.00 100.00
3	R&R rear windscreen	\$ 140.00 250.00
4	Disconnect wire harness to facilitate repair, reconnect and test function	\$ 50.00 80.00
5	R&R rear hybrid battery to facilitate repair	\$ 50.00 100.00
6	R&R upholstery	\$ 90.00 200.00
7	R&R exhaust pipe	\$ 80.00 200.00
8	Reset fault code	\$ 150.00 300.00
9	Panel beat	\$ 1200.00 1,600.00
10	Rust proofing	\$ 80.00 150.00
11	Spray painting front	\$ 200.00 800.00
12	Spray painting rear	\$ 1000.00 1,400.00
LABOUR TOTAL :		\$ 3140 5,280.00

PARTS TOTAL : \$ 12,461.68
SPECIAL NETT TOTAL : \$ 1,280.00
LABOUR TOTAL : \$ 5,280.00
GRAND TOTAL : \$ 19,021.68

Resurvey on
1/7/19

1515 hrs

Lump sum repairs
Repair days 9

TG Lim

Parts 7777.44
S/N 620.00
Labour 3140.00
11,537.44

L/S 11,500/2

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: