

ASS. REC. BY:

Surveyor: KalvinREF: CS/FCI 19011223/K1td3n2 Special Instruction:

CWS

ASSIGNMENT (Office)

From (Person):

Sithara

of

FCI

Date/Time:

3:58pm @ 25/6/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKV 367 X

Insured:

SHA 8803Y

at Workshop n/s

premier Automotive

Tel:

6544 6689

of

23 chengji South Ave 2 # 01-02

Policy No:

Claim No:

D19004112 MPSTH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

24/6/2019

CA / REV / REP. / REV 24 HRS

wop

H.O.D. Endorsement:

Date/Time: 4:11pm @ 25/6/19

Person Contacted:

VincentVehicle IN / OUT

Date/Time

Action/Instruction

1-should ✓SKV 367 X: ✓SHA 8803Y: CS/MSG16009005/Tigh3d1 D.O.A 14/05/201626/6 @ 10:46am - Rensed via preli advise email

Surveyor: Kalvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKV367X Yr Regn: 27 Aug 2015

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mitsubishi Atrage c.c. 1193Colour: M. Grey A/C: Ins / Std / NI / NASp. Reading: 33900 T/Radio: Ins / Std / NI / NA

Eng/No: _____

C/No: MMBSTA13AFH010637

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F: 185/55R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 28/6/19 D.O.I. 25/6/19Survey held at Premise

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
1/7/19	Call 4/5 \$1600 / 3 hrs. Cred: 1891201 54% FCZ

RECEIVED 2 JUL 2019

Date/Time, File Pass to?

1) 217 Typist

Date/Time, File Return to?

2) _____

Report Format:

Lump Sum / B.I. \$ 16000☐ : Prel. Report☒ : Final ReportDays Of Repair: 3Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

130
50
50
26
256



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: D19004108MFSH

Date: 26/06/2019

Our Ref: CS/FCI19011223/K1td3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SKV 367X

Please be informed that we had conducted the inspection of the abovementioned vehicle
24/06/2019 at the premises of M/s Premier Automotive have the following to report: -

Workshop Estimate Amount	: S\$	3,491.36
Revised Estimate Amount	: S\$	2,296.00
"Check" Items Amount	: S\$	0.00
Market Value	: S\$	
LTA Reimbursement Value	: S\$	
Nett Value	: S\$	

Description of Damage:

The vehicle sustained damages at the
Rear portion.



Comments/ Present Status:
Damages Consistent.

Yours faithfully
Kalvin
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	24-06-2019	Our Ref No. D19004112MFSH
Accident Date	24-06-2019	Claim Type. Third Party
Insured Vehicle	SHA8803Y	Third Party Vehicle. SKV367X
Survey Location	23 CHANGI SOUTH AVENUE 2 #03-02	
Contact Person.	GOH WEE DEK	
Contact No.	62148880/ 65446682	Fax No. 62141511
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIER AUTOMOTIVE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 26 June 2019 10:46 AM
To: Admin-D (LKKAuto); 'CWS Motor Claims'; assignments
Cc: 'Sithara'; SUR
Subject: RE: SURVEY ASSESSMENT - D19004108MFSH/1
Attachments: PRELI ADVISED SKV 367X.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SKV 367X**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 26 June 2019 7:50 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19004108MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 25 June 2019 3:00 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19004108MFSH/1

Dear Sir/Mdm,

Text size + -

Enquire Vehicle Registration Details**Owner Particulars**

NRIC/Passport/Company Cert No.: 200612929E
Owner ID Type: Company
Owner Name: PREMIER RENT A CAR PTE. LTD.
Registered Address: 23 CHANGI SOUTH AVENUE 2 #04-03 SINGAPORE 486443
Mailing Address: -
Birth Date: -

Vehicle Particulars

Vehicle No.: SKV367X
Previous Vehicle No.: -
Effective Date of Ownership: 27 Aug 2015
Original Regn Date: 27 Aug 2015
Registration Date: 27 Aug 2015
Year of Manufacture: 2015
Vehicle Type: Private Hire (Self-Drive) Motor Car
Vehicle Scheme: -
Vehicle Attachment 1: No Attachment
Vehicle Attachment 2: -
Vehicle Attachment 3: -
Vehicle Make: MITSUBISHI
Vehicle Model: ATTRAGE 1.2 CVT
Primary Colour: Grey
Secondary Colour: -
Passenger Capacity: 4
Chassis No.: MMBSTA13AFH010637
Engine No.: 3A92UCK4851

Engine Capacity/Power Rating: 1193 cc /

Maximum Power Output: 57.0 kW (76 bhp)
Propellant: Petrol
Max Unladen Weight: 940 kg
Maximum Laden Weight: 1335 kg
Open Market Value: \$12,180.00
PARF Eligibility: Yes
PARF Eligibility Expiry Date: 26 Aug 2025
Minimum PARF Benefit: \$2,500.00
No. of Transfers: 0
IU Label No.: 1125920818
COE No.: 2015030101001521E
COE Expiry Date: 26 Aug 2025
COE Category: A - Car (up to 1600cc & 97kW (130bhp))
COE Registration Category: A - Car (up to 1600cc & 97kW (130bhp))

Quota Premium (QP) /
Prevailing Quota Premium: \$57,199.00 / -
Actual QP Paid: \$57,199.00
QP (Regn Cat): \$57,199.00
OPC Cash Rebate Eligibility: No
QP during COE Bidding
Exercise: \$57,199.00
Additional Registration Fee
Rate: First \$12,180.00 (100%)
Actual ARF Paid: \$5,000.00
Vehicle Lifespan Expiry Date: No Lifespan
CO2 Emission: 113.00 (g/km)
CEVS Rebate Utilised Amount: \$7,180.00

Message: To renew the COE, the Prevailing Quota Premium payable is that of Category A. This is a public service vehicle.



Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.
Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.
Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution
Copyright © 2015 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

24-Jun-19

ESTIMATE REPAIR BILL FOR MITSUBISHI ATTRAGE REGN NO: SKV 367 X

1 pc	Bootlid emblem "Attrage" <i>new</i>	\$	20.00
1 pc	Bootlid emblem "Logo" <i>new</i>	\$	41.00
1 pc	Rear bumper <i>UL</i>	\$	659.00
1 pc	Rear bumper reinforcement <i>X m</i>	\$	315.00
2 pcs	Rear bumper side bracket o/s & n/s @\$22.00 <i>X m</i>	\$	44.00
	<i>Ren n/s Fender x repair</i>	\$	1,079.00
	<i>Ren Bootlid x repair</i>		
	Less 20%	\$	215.64
		\$	863.36

S/NETT

1 set	Rear bumper clips <i>new</i>	\$	48.00
1 set	Reverse sensor <i>skilled</i>	\$	280.00 20
	Sundry <i>new</i>	\$	50.00 20
	To dismantle / replace reverse sensor to new bumper and reset to the same	\$	120.00 50
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00 50
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, rear n/s fender, bootlid etc	\$	900.00 400
	To putty and spray painting on end panel, rear bumper, bootlid, rear n/s fender	\$	900.00 720
	To apply rustproofing on the repaired and replaced panels.	\$	180.00 20
		\$	3,491.36

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kahin 16/11/19 3491.20
25/6/19 1645L
3 Pay
4/5
After Repair



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19011223/K1td3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 03-07-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 8803Y	Veh. Inspected	SKV 367X	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19004112MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	25/06/2019	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI ATTRAGE	c.c	1193	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	MMBSTA13AFH010637	Colour	METALLIC GREY	
Odometer	33900	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/55 R15	YOKOHAMA	7 mm	
L/H Front Tyre	185/55 R15	YOKOHAMA	7 mm	
R/H Rear Tyre	185/55 R15	YOKOHAMA	7 mm	
L/H Rear Tyre	185/55 R15	YOKOHAMA	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/06/2019	Inspection Date	25/06/2019	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKV 367X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOTLID EMBLEM "ATTRAGE"	NECESSARY	20.00	20.00
1	BOOTLID EMBLEM "LOGO"	NECESSARY	41.00	41.00
1	REAR BUMPER	DEFORMED	659.00	659.00
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	315.00	-
2	REAR BUMPER SIDE BRACKET O/S & N/S @\$22.00	SERVICEABLE	44.00	-
1	REAR N/S FENDER (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR BOOTLID (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 20% DISCOUNT		-215.80	-144.00
			863.20	576.00
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	SET REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			378.00	268.00
LABOUR				
	TO DISMANTLE/REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME.		120.00	30.00
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.		180.00	50.00
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE END PANEL, REAR N/S FENDER, BOOTLID ETC.		900.00	400.00
	TO PUTTY AND SPRAY PAINTING ON END PANEL, REAR BUMPER, BOOTLID, REAR N/S FENDER.		900.00	720.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	150.00	-
			2,250.00	1,200.00
GRAND TOTAL			3,491.20	2,044.00



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,600.00
---	--	--	----------

Report Ref No. CS/FCI19011223/K1td3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.