

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 995T

DATE 24/6/2019 11:49

MAKE :

MODEL : MERCEDES BENZ VIANO (REAR)

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper X			\$ 1,372.00
	Bumper L/H Side, RR X			\$ 473.60
	Bumper R/H Side, RR X			\$ 473.60
	Tail Gate "2.2" Logo X			\$ 78.00
	Tail Gate "CDI" Logo X			\$ 78.00
	Tail Gate Via No Logo X			\$ 78.00
	Tail Lamp Assy, RH X			\$ 622.44
	Rear Fender (RH) X			\$ 3,188.00
	Rear Fender Protector (RH) X			\$ 56.48
	Rear Windscreen Glass X			\$ 1,273.98
	SUB TOTAL			\$ 7,694.10
	LESS 20%			\$ 1,538.82
	DISCOUNTED TOTAL			\$ 6,155.28
	Rear Bumper Rubber Mat X			\$ 50.00
	Tail Gate "MAXICAB" Logo X			\$ 30.00
	Rear Windscreen Sealant X			\$ 46.00
				\$ 126.00
	Labour Charge			
	Panel Beating			\$ 560.00 200
	Spray Painting Charge			\$ 600.00 200
	Wiring Charge			\$ 50.00 20
	Tuff Kote			\$ 50.00 X
	Remove/Refix Reverse Sensor			\$ 120.00 X
	TOTAL LABOUR			\$ 1,380.00
	ESTIMATE TOTAL			\$ 7,661.28
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Carmy

Cheng

Kahin 1009
 24/6/19 134-L
 2 H.
 US
 After Repair pls

to Consultants hence notify
 the Repairer of the following:
 • To survey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification is allowed
 • Supplemental charges must be resurveyed and
 is subject to final approval from insurance company
 Acknowledged by Repairer
 Signature:
 Date: