	ASS. REC. BY: REF. CS SM019011238 Agd3n2 Special Instruction:	
Munnyan	Surveyor Adnay ASSIGNMENT (Office)	
	From (Person): Ruth (hua Get Trang of SMO Date/Time:	
	OD (TD) WS/TP RES! OD ALE/TVA: ETV! MV / CO	
	Tel: 6+4+9241	
	of I Kaki Bukit Ave C. Blk (#01-43	
	Toney No.	
	Sum Insured: Excess: D.O.A. 25.6. 2019	
	Make of Veh:	
	Date/Time: 26.6.19 2540 Person Contacted Sulty Vehicle IN JOUT	
	Date/Time Action/Instruction () Estimate	
	YN 5333L:	
	53E 3232 H. CL6 [A]G14022274 [AZO3q2 Do. A 27/11/2014 03/7/19@ 9-40~ Informed Buth Chua, we are pending estimate from a 16/7/90248pm nevised to Routh Chua via Merianen.	epaver
	16/11/20 2.48 M nevised to Ruth Chus via Mersnich. 15 \$4900, 4 days (Red \$4012.80, 45%)	
	15 64900, 4 days cheen a (011100)	

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place

#05-01/06, Singapore Land Tower

Singapore 048623

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Ruth Chua Gek Tiang

Date:

16 Jul 2019

Preliminary Advice

Insured Vehicle No : YN5333L

TP Vehicle No

: SJE3232H

Accident Date

: 25/06/2019

Assignment Date

: 25/06/2019

Date of Inspection : 26/06/2019

Est. Duration of Repair

Inspection At

: 4.00

: NEW HOCK TECK MOTOR PTE LTD (HQ)

1 KAKI BUKIT AVE 6, BLK C #01-43 AUTOBAY@KAKI BUKIT

SINGAPORE 417883

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,912.80
Revised Amount	:S\$	6,126.20
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,126.20
Lump Sum Repair	:S\$	4,900.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
---	---	---

) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments : KINDLY ASSIST TO ADD-IN THE MAKE & MODEL OF SJE 3232H: TOYOTA HARRIER ELEGANCE 2.0 CVT.

...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status		
Main	25 Jun 2019	E.A. Gybride	25 Jun 2019 16:30 Assign				New Assignm Cancel Case	nent	
	Main	R	eference	Cla	aim Details	Docum	ents	Show All	
CLAIM S	UBFOLDER DE	TAILS			200 00 PH 100 2 TH 100 PH 100	[Cr	eated by insur	er]	
Insured: Main Clair	mant		YONG ANN PTE	LTD, Co. Reg	. No.: 199609027N				
Vehicle R			232H	D	ate of Loss:	10.74	06/2019 10:00 -	:59	
Claim Typ		TP /	CMTD1903020	Р	Policy/Cover Note No.:		D19MTPCVE001506 (Comprehensive)		
Vehicle R	eg. No. (Insured)	YN53	33L	P	olicy No. (Claimant):				
Repairer:		Bukit Somp	- Tel: 6747 9241 to Insurance Sing	Pte Ltd (HQ)	xcess: 1 Kaki Bukit Ave 6, td. (HQ) - Tel: 6461				
Adjuster:		IKK	6329 5153] LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 [Final Rpt due 04/07/2019]						
	Remarks:	WS: 6	7479241 REENA/S DENT -NO TP SAS S	UKYI -PLEASE	BE INFORMED THAT	OUR INSURED HA	S NOT REPORTE	D THE	
ASSOCI	ATED MAIL RE	CEIVED				View /	All Compos	se Case Mail	
There are	e no mail for this	case.							
E ALL AS	SOCIATED TAS	KS			View All Se	arch Tasks C	reate New Task	Complete	
Due D	P	Type Task	Group Subje	ct Handle	r Assigned Βγ	Completed O	n Created	On Done	

Shiau Chan (LKKAuto)

From:

Do-Not-Reply <do-not-reply@merimen.com>

Sent:

Wednesday, 3 July 2019 9:40 AM do-not-reply@merimen.com

To:

SUR

Cc: Subject:

TP VEHICLE SJE 3232H (YOUR REF: CMTD1903020)

This mail is associated with:
*SJE3232H (CMTD1903020)
[YN5333L]

TP
YEO SOK BUAY
Jun 25 2019 10:00AM
[YANG YONG ANN PTE LTD]
New Hock Teck Motor Pte Ltd

Dear Ruth,

Please be informed that we have inspected the vehicle SJE 3232H on 26/06/2019.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms) LKK Auto Consultants Pte Ltd Tel: 6256 3561

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)



This email has been checked for viruses by AVG antivirus software. www.avg.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	Cinconoro NDIC
Owner ID Type:	Singapore NRIC
Owner ID:	7858E
Vehicle Details	C1E3333H
Vehicle No.:	SJE3232H
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Jul 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HARRIER ELEGANCE 2.0 CVT
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	3ZRB580138
Chassis No.:	ZSU600048295
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$26,556.00
Original Registration Date:	06 Aug 2015
First Registration Date:	06 Aug 2015
Transfer Count:	0
Actual ARF Paid:	\$24,179.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Aug 2025
PARF Rebate Amount:	\$18,134.00
Intended COE Rebate Details	
COE Expiry Date:	05 Aug 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$60,789.00
COE Rebate Amount:	\$36,800.00
Total Rebate Amount:	\$54,934.00

The information contained herein is correct as at 16 Jul 2019

MSME19062931 / SME Motor Pte Ltd - Kwiv Solot ENTRY DATE & TIME 26/06/2019 09:36 SUBMITTED BY Chia Per Ving

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible; Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

40	,	DEN	22.0	TEN	ae N	т
AC	201	DJE 0	 3 I A	4	11-1	ш

26/06/2019 09:36 Date Of Report 25/06/2019 10:45 Date Of Accident

BEDOK NORTH RD TWDS BEDOK NORTH Exact Location Of Accident

SINGAPORE Country/State of Loss

DETAILS OF OWN VEHICLE

SJE3232H Vehicle Registration Number

Insured/Policyholder

YEO SOK BUAY Name Of Registered Owner

S1637858E NRIC No.

NOEMAIL Email Address

(LOCAL) +65-92472952 Mobile Phone No OFFICE-92472952 Alternative Phone No.

Vehicle Particulars

TOYOTA Manufacturer HARRIER Model

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

THIRD PARTY If No. Please state action to be taken

PRIVATE CAR Vehicle Category

Insurance Company

NTUC INCOME INSURANCE CO-OPERATIVE LTD Name of Insurance Company

COMPREHENSIVE Type Of Coverage

NO Fleet Policy

5101999834 Policy Number

Cover Note Number

Driver

YEO SOK BUAY Name of Driver S1637858E NRIC No

05/02/1964 Date Of Birth INDOOR Occupation

07/05/1994 Date Of Driving Pass

25 YEARS AND 1 MONTH Driving Experience

FEMALE Gender

(LOCAL) +65-92472952 Mobile Number

Fax Number

OFFICE-92472952 Contact Number

NOEMAIL EMail Address

Address

63 CHEMPAKA AVE

Postcode

349672

Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - CHANGE/CROSS LANE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles (including own vehicle)

2

involved in the accident

NO

Was any body injured in the Accident? Was any injured conveyed to hospital by

ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

I WAS TRAVELLING STRAIGHT ALONG BEDOK NORTH ROAD TOWARDS BEDOK RESERVOIR. SUDDENLY, VEHICLE B ENCROACHED INTO MY LANE AND HIT ON THE RIGHT PORTION OF MY VEHICLE.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

YN5333L

Vehicle Make/Model/Colour

VEHICLE B

Details Of Properties

COMMERCIAL VEHICLE

Vehicle Category Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Flease report correctly the details of the actident to speed up the dains process
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any writin misred esentation or withholding of material. facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy lebility on the part of the insurance companies.
- 5 Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Mahagement Centre established by the General Misurance Association of Singapore (6(A) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the ladgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to ropies of the report being made available aforesaid.
- Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore (*GIA*) may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (reflectively the "Personal Information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers" i, the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (IV) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes"]
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law tirms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- ic) my Personal information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents/including their lawyers/law firms), which may be sited outside of singapore, for one or more of the above Purposes,
- (d) my Personal information will also be collected and used to complie claims history for the purpose of fraud detection, investigation and management in present and all future claims
- (a) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud. regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Oriver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

NRIC/FIN No.

NEW HOOK TECK

Sketch Plan #2 Pg. 1

SKETCH PLAN

SMOK HONIN KA

TOWANGU BEROK

PA CJE3232H

B - VN53331

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

1 1	vou tra	reality str	ayput	MONO!	g bado	k word	n 1d	toward	ds bods	k
2626A	VON :									
Syde	lenily.	ranicke w of mi	3	entrol	icheu	into mi	1 ane	ovd	MH ON	the
rujirj	10110	w 01 111	1 10	riich .						
					200750					
				TO PIECE						
-			-11111							
	200038									

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Edicyholder's Signature Date & Time: Oriver's Signature (if driver is not the policyholder) Date & Tune:

Reporting Centre Personnel's Signature Banter MRIC/FIN Mo.



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883 Website: www.nhtmotor.com Email: admin@nhtmotor.com Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

YEO SOK BUAY Blk 1 Kaki Bukit Ave 6 # 01-43 Singapore 417883

TP Soupo

26/06/2019

ZSU600048255

Accident date: 25/06/2019

Estimated repair cost for vehicle no: SJE3232H TOYOTA HARRIER 2.0 A '15

S/N	QTY	CHASSIS: ZSU600048295	U/PRICE	AMOUNT
1	1	Front R/H Head Lamp Let		\$2,821.70
2	1	Front R/H Head Lamp Lower Bracket ***		\$174.40
3	1	Front R/H Fender		\$781.90
4	1	Front R/H Fender Cowling 2 xxx		\$374.80
5	8	Front R/H Fender Cowling Clip	\$6.50	\$52.00
6	1	Front R/H Side Mirror Assy Distanted		\$1,303.00
7	ţ	Front Bumper Chiss Nr. 30 Front RIH Buyer Retainer 75	Subtotal:-	\$5,507.80
8	1	Front Bunger St. New 75	6461.60	
) Labo	ur ch	arges	4846:20	
To ch	eck w	riring		\$100.00
Tuff	ote	LKK Auto Consultants hence notify the Repairer of the following:	200	\$150.00
Pane	l beat	To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation	1280	\$800.00
Spra	y pain	Third party survey is on a "Without Prejudice" basis No allowed modification(s) is allowed.		\$800.00
		Acknowledged by Repairer Signature;	Subtotal:-	\$1,850.00
		Date:	Total:-	\$7,357.80
			tolal.	6126-202
		(4-91C)	45	4SK.
			(Dours.

8912 10

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

D19MTPCVE001506

CS/SMO19011238/AQD3N2

Date:

18/07/2019

REFERENCE

Handling Insurer:

Claimant

Vehicle No:

Date of Loss:

Sompo Insurance Singapore Pte.

SJE3232H

25/06/2019

Policy No:

Insured Vehicle

YN5333L

No:

Nature of Claim:

TP

Claim No:

CMTD1903020

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SJE3232H

Make & Model:

TOYOTA HARRIER, 2.0 ELEGANCE CVT (A) 06/08/2015 (Man. Year: 2015)

Engine No: Chassis No:

Odometer:

3ZRB580138 ZSU600048295

47625 km

Reg. Date: Colour:

Black

1986 cc

N/A

Engine Capacity: Market Value/New Car

Price:

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

Yes Footbrake (Serviceable): No Pre-accident Condition:

Yes

Handbrake (Serviceable): **CONDITION OF TYRES**

General Condition:

Yes Engine Modification:

Steering (Serviceable):

225/65 R17

Front Tyre Size: Front Left Side:

Yokohama 6 mm

225/65 R17

Rear Tyre Size: Rear Left Side:

Yokohama 6 mm

Front Right Side:

Yokohama 6 mm

Rear Right Side:

Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,062.80	4,846.20	2,216.60	31.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,850.00	1,280.00	570.00	30.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,912.80	6,126.20	2,786.60	31.27
Approved Total (Overridden) (S\$)		4,900.00	310010000000000000000000000000000000000	
(S\$)	8,912.80	4,900.00	4,012.80	45.02
+ GST 7.00/7.00% (S\$)	623.90	343.00	280.90	45.02
Nett Amount (S\$)	9,536.70	5,243.00	4,293.70	45.02

INSPECTION

Date of Assignment:

25/06/2019

Date Inspected:

26/06/2019 Inspected At:

New Hock Teck Motor Pte Ltd (HQ)

1 Kaki Bukit Ave 6, Blk C #01-43

Autobay@Kaki Bukit Singapore 417883

Estimated Period of Repair:

4.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Jul 2019)

Parts: M1-SUV TOYOTA HARRIER 2.0 ELEGANCE CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJE3232H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
4	4		*FRONT R/H HEAD LAMP	Cut	2,821.70 F	*2,821.70 FL
2	4		*FRONT R/H HEAD LAMP LOWER BRACKET	Not Necessary	174.40 F	*-FL
3	1		*FRONT R/H FENDER *FRONT R/H FENDER COWLING	Dented Not Necessary	781.90 F 374.80 F	*781.90 FL *- FL
5	8		*FRONT R/H FENDER COWLING CLIP *FRONT R/H SIDE MIRROR ASSY	Not Necessary Distorted	52.00 F 1,303.00 F	*- FL *1,303.00 FL
7	1		*FRONT BUMPER *FRONT BUMPER CLIPS	Torn Necessary	1,450.00 F 30.00 F	*1,450.00 FL *30.00 FL
9	1		*FRONT R/H BUMPER RETAINER	Necessary	75.00 F	*75.00 FL
- T	anchise	part. L=ListIt		Sub Total (S\$) ns 0.00/25.00% (S\$)	7,062.80 0.00	6,461.60 1,615.40
				Total Parts (S\$)	7,062.80	4,846.20

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended	Labour
-------------	--------

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			30.00
1	TO CHECK WIRING	New	100.00	
2	TUFF KOTE	New	150.00	0.00
-		New	800.00	600.00
4	PANEL BEATING SPRAY PAINTING	New	800.00	650.00
		Gross Labour Cost (S\$)	1,850.00	1,280.00
	Repo	rt was unsubmitted during this print-out.		

< END OF ESTIMATES >