

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19011238/AQD3N2
Date: 25/09/2019

REFERENCE

Handling Insurer: Sompo Insurance Singapore Pte. Ltd. Policy No: D19MTPCVE001506
Claimant Vehicle No : SJE3232H **Insured Vehicle No :** YN5333L
 Date of Loss: 25/06/2019 Nature of Claim: TP Claim No: CMTD1903020

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJE3232H**
 Make & Model: TOYOTA HARRIER, 2.0 ELEGANCE CVT (A) Engine No: 3ZRB580138
 Reg. Date: 06/08/2015 (Man. Year: 2015) Chassis No: ZSU600048295
 Colour: Black Odometer: 47625 km
 Engine Capacity: 1986 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/65 R17 Rear Tyre Size: 225/65 R17
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,062.80	1,563.67	5,499.13	77.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,850.00	1,030.00	820.00	44.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,912.80	2,593.67	6,319.13	70.90
Approved Total (Overridden) (S\$)		2,000.00		
(S\$)	8,912.80	2,000.00	6,912.80	77.56
+ GST 7.00/7.00% (S\$)	623.90	140.00	483.90	77.56
Nett Amount (S\$)	9,536.70	2,140.00	7,396.70	77.56

INSPECTION

Date of Assignment: 25/06/2019
 Date Inspected: 26/06/2019 Inspected At: New Hock Teck Motor Pte Ltd (HQ)
 1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit
 Singapore 417883
 Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Sep 2019)
Parts:	M1-SUV	TOYOTA HARRIER 2.0 ELEGANCE CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	LKK Auto Consultants Pte Ltd/SJE3232H/25/09/2019 14:40	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT R/H HEAD LAMP	Not Necessary	2,821.70 F	*- FL
2	1		*FRONT R/H HEAD LAMP LOWER BRACKET	Not Necessary	174.40 F	*- FL
3	1		*FRONT R/H FENDER	Dented	781.90 F	*781.90 FL
4	1		*FRONT R/H FENDER COWLING	Not Necessary	374.80 F	*- FL
5	8		*FRONT R/H FENDER COWLING CLIP	Not Necessary	52.00 F	*- FL
6	1		*FRONT R/H SIDE MIRROR ASSY	Distorted	1,303.00 F	*1,303.00 FL
7	1		*FRONT BUMPER	Not Necessary	1,450.00 F	*- FL
8	1		*FRONT BUMPER CLIPS	Not Necessary	30.00 F	*- FL
9	1		*FRONT R/H BUMPER RETAINER	Not Necessary	75.00 F	*- FL
					Sub Total (S\$)	7,062.80
					- List Item Discount on L Items 0.00/25.00% (S\$)	0.00
					Total Parts (S\$)	1,563.67

F=Franchise part. L=ListItemDisc.

LKK Auto Consultants Pte Ltd/SJE3232H/25/09/2019 14:40. Not valid without Reference section.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	100.00	30.00
2	TUFF KOTE	New	150.00	0.00
3	PANEL BEATING	New	800.00	500.00
4	SPRAY PAINTING	New	800.00	500.00
Gross Labour Cost (\$\$)			1,850.00	1,030.00

LKK Auto Consultants Pte Ltd/SJE3232H/25/09/2019 14:40. Not valid without Reference section.

< END OF ESTIMATES >