

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0775/2019/TG
Date : 20-Jun-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Ng Zi Hao
Address : Blk 775 Bedok Reservoir View
#04-105
Singapore 470774
Telephone : HP +65 91559340
Type of Claim : Own Damage Claims
Policy No. : 1700079236-01
Vehicle No : **SLU 5949 C**
Model Code : Audi A4 Sedan 1.4 TFSI S
Model / Year : Dec-17
Engine No : CVN 047470
Chassis No : WAUZZZF45JA036156
Mileage : -
Date In : -
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 19-Jun-19
Place of Accident : 83 Farleigh Avenue

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLU 5949 C

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	✓
2	To dismantle and renew front bumper, rhs front fender and rhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 2,450.00	1250.
3	To respray front bumper and rhs front fender.	\$ 2,000.00	1100
4	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 5,002.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLU 5594 C

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER COVER	\$ 1,946.00	de
2	FRONT BUMPER FIXING PARTS	\$ 258.00	?
3	FRONT BUMPER SUCURING STRIP	2 \$ 64.00	na
4	FRONT CENTER LOWER GRILLE	\$ 178.00	?
5	FRONT CLOSING ELEMENT- LOWER CENTER	\$ 191.00	?
6	FRONT BUMPER AIR GUIDE - RH	\$ 56.00	?
7	RADIATOR GRILLE	\$ 1,053.00	?
8	FRONT BUMPER AIR GUIDE GRILLE - RH	\$ 123.00	mis
9	FRONT BUMPER GUIDE SECTION - RH	\$ 34.00	?
10	FOAM FILLER PIECE	\$ 113.00	?
11	FRONT BUMPER CARRIER	\$ 733.00	?
12	FRONT BUMPER TOP COVER	\$ 116.00	?
13	CAUTION STICKER	NEC \$ 13.00	?
14	A/C STICKER	NEC \$ 7.00	?
15	LOCK CARRIER BRACKET	\$ 125.00	?
16	FRONT BUMPER SUPPORT - LH/RH	\$ 51.00	X
17	HORN FOR LOW TONE - RH	\$ 262.00	X
18	SPRING SHACKLE - RH	\$ 26.00	?
19	FRONT FENDER - RH	\$ 700.00	bl
20	FRONT FENDER ATTACHMENT PARTS - RH	\$ 183.00	?
SUB TOTAL SPARE PARTS		\$ 6,232.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLU 5949 C

		<u>Damage Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/NETT</u>	<u>REMARKS</u>
21	CLOSING ELEMENT FOR FRONT FENDER - RH	\$ 45.00	?
22	BRACKET FOR FRONT FENDER - RH	\$ 32.00	?
23	POP RIVET	6 \$ 18.00	ne ✓
24	FRONT FENDER SUPPORT - RH	\$ 107.00	X
25	WHEEL HOUSING LINER - RH	\$ 220.00	?
26	WHEEL HOUSING LINER ATATCHMENT PARTS	\$ 82.00	?
27	WHEEL SPOILER	-	?
28	FRONT FENDER TRIM PLATE - RH	\$ 33.00	?
29	STONE CHIP GUARD - RH	\$ 46.00	ne ✓
30	FRONT FENDER TOP COVER - RH	\$ 28.00	ne ✓
31	FRONT FENDER TOP COVER - RH	\$ 21.00	ne ✓
32	LED HEADLIGHT - RH	\$ 7,087.00	One ✓
33	POWER MODULE FOR HEADLIGHT	\$ 716.00	?
34	CONTROL UNIT FOR HEADLIGHT	\$ 685.00	?
35	HEADLIGHT FOR HOSE	\$ 32.00	?
36	LIFT CYLINDER FOR HEADLIGHT - RH	\$ 192.00	?
37	CORRUGATED PIPE FOR HEADLIGHT	\$ 83.00	?
38	HEADLIGHT BRACKET	\$ 4.00	?
39	LIFT CYLINDER BRACKET FOR HEADLIGHT	\$ 6.00	?
40	CORRUGATED PIPE FOR HEADLIGHT CLEANER	\$ 35.00	?
SUB TOTAL SPARE PARTS		\$ 9,472.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLU 5949 C

		<u>Damage Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/NETT</u>	<u>REMARKS</u>
61	RADIATOR SUPPORT AIR GUIDE - RH	\$ 25.00	?
62	INNER RADIATOR AIR GUIDE - RH	\$ 11.00	?
63	LOWER RADIATOR DEFLECTOR	\$ 19.00	?
64	UPPER RADIATOR DEFLECTOR	\$ 15.00	?
65	FRONT NUMBER PLATE	\$ 40.00	mx
66	SUNDRIES	\$ 300.00	?
TOTAL SPARE PARTS		\$ 16,114.00	
TOTAL LABOUR CHARGES		\$ 5,002.00	
GRAND TOTAL		\$ 21,116.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

:

Tanpin 97495719

Surveyed Date

:

25/6/17 @ 1115.

Authorised Date

:

Excess Cost

:

Not Authorise

Liability

:

Ex: to be advise

Remarks

:

Resumy before paint

surelkhanto.com

04 days

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant