

#28 (Rev. 11/11)

Premium

Taylor

REF:

ALG 113/ALG 190112431 TISC03/L

ASSIGNMENT

From:

Date:

25/6/19

Estimated Cost:

☒ (P) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLT 5763B

at Workshop m/s

Premium

of

SS ubi Road

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

\$300/-

(Client's Record)

Make of Veh:

11am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$92K

IDAC Accident Rpt:

Consistent? Yes or No

GIA / PR Seen:

Consistent? Yes or No

Est. Repairs:

days

Res:

Yes or No

Lum Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle IN / OUT

Veh No:

SLT 5763B

Yr Regn:

2017, Nov

Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

Audi 193 SB

cc

499

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp Reading:

40999

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

W442778V 9 J4640832

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Mod: ☒ Nil / ☐ SRim / ☐ STD A/Rim or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / ☒ GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

6

mm

R/Bal:

6

mm

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A.

D.O.I.

25/6/19 12pm

Survey held at

Premium Ubi

Des. of Damages: ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SLT 5763B -X
03/12/19	Adrian Confirmed R/P \$5,497.84 @ 4 days with Boss (\$2,618.16 Red - 32%)

RECEIVED 13 JAN 2020

6/12/2019

Date/Time, File Path for

13/01/20

1) Type SL

Date/Time, File Path for

2)

Report Format:

Lump Sum

\$5,497.84 R/P

Days Of Repair:

4

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp \$5

☐

Interview \$5

☐

Tech Ins \$5

☐

Witness \$5

Survey Fee:

200 + 11

Transportation:

3 + RS 31

Phone:

Other:

Other:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	92418
Vehicle Details	
Vehicle No.:	SLT5763B
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Jun 2019
Vehicle Make:	AUDI
Vehicle Model:	A3 SPORTBACK 1.0 TFSI S TRONIC (LED)
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	CHZ571013
Chassis No.:	WAUZZZ8V9JA040832
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$24,162.00
Original Registration Date:	01 Nov 2017
First Registration Date:	01 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$15,827.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	31 Oct 2027
PARF Rebate Amount:	\$11,870.00
Intended COE Rebate Details	
COE Expiry Date:	31 Oct 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$41,761.00
COE Rebate Amount:	\$34,856.00
Total Rebate Amount:	\$46,726.00

The information contained herein is correct as at 26 Jun 2019

OK



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : YEO AIK TUAN KELVIN
Period of Insurance : 01 Nov 2018 To 31 Oct 2019
Engine No. : CHZ571013
Chassis No. : WAUZZZ8V9JA040832

Vehicle No. : SLT5763B
Policy No. : 1700055096-01
Endorsement No. :
Issued Date : 09 Oct 2018

ABOUT THE COVER

Make/Model : AUDI A3 Sportback 1.0 TFSI S tronic
Engine Capacity/Tonnage : 999.00 CC Sum Insured : Market Value First Year of Registration : 2017
Driver Restriction : NA Off Peak Car : No Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive* :

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 20 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2050cc Optional

* Limitations rendered inoperative by Section 6 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

YEO AIK TUAN KELVIN - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408698 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia)

0504125208

PREMIUM LEASING - SLOH

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

ASP/EMC

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0784/2019/DY/GW
Date : 24-Jun-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Yeo Aik Tuan Kelvin
Address : 10 Siglap Rise
Singapore 455967
Telephone : HP +65 92345031
Type of Claim : Own Damage Claims
Policy No. : 1700055096-01
Vehicle No : **SLT 5763 B**
Model Code : Audi A3 SportsBack 1.0
Model / Year : 1/11/2017
Engine No : CHZ 571013
Chassis No : WAUZZZ8V9JA040832
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 20-Jun-19
Place of Accident : Junction at Chai Chee Street >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLT 5763 B

S/n	Nature of Jobs	Estimated Charges	Surveyor's Reccomendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	✓
2	To dismantle and renew front bumper assy. Re-organise front crash management components. Reinstall all parts removed.	\$ 1,050.00	500
3	To respray front bumper and bonnet.	\$ 1,600.00	1100
4	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 3,202.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SLT 5763 B**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER	\$ 1,698.00	de- 1358.40
2	FRONT BUMPER GRILLE-CENTER	\$ 146.00	cu- 116.40
3	FRONT BUMPER CLOSING ELEMENT-LH	\$ 270.00	? X nn
4	RADIATOR GRILLE	\$ 1,301.00	de- 1040.80
5	RADIATOR GRILLE CLOSING ELEMENT	\$ 174.00	? ✓ 138.80 cu
6	FRONT BUMPER COVER	\$ 111.00	? ✓ 88.80 dis
7	FRONT BUMPER FOAM FILLER PIECE	\$ 172.00	? X nn
8	FRONT BUMPER REINFORCEMENT BAR	\$ 660.00	? ✓ 527.60 ht
9	AIR CONDITIONER STICKER	\$ 7.00	? X nn
10	SIGN ' CAUTION '	\$ 13.00	? X nn
11	FRONT CAR PLATE NO.	S/N \$ 40.00	ht- ✓
12	SUNDRIES	\$ 300.00	? ✓ 17.92
TOTAL SPARE PARTS		\$ 4,892.00	
TOTAL LABOUR CHARGES		\$ 3,202.00	
GRAND TOTAL		\$ 8,094.00	8116

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax


27/6/19

Name : Tanjika 97495749
Surveyed Date :
Authorised Date : Not Authorised
Excess Cost : 25/6/19 @ 12pm
Liability :
Remarks : Repair before part
04 days
Surv / Mando.com.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0784/2019/DY/GW 23-Jul-19 Glory Tan 1 of 1 SLT 5763 B Audi A3 SportsBack 1.0
Quantity	Description	Unit Price	Amount
<u>Parts</u> 1	Radiator air guide LHS	\$ 22.00	de✓ 17-12
		<u>\$ 22.00</u>	
<u>LABORS</u>			
	TOTAL	\$ 22.00	

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0784/2019/DY/GW
Date	:	24-Jun-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Taufikh,

4 days - ok - Jy - 27 Sep 2019

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Yeo Aik Tuan Kelvin
Address	:	10 Siglap Rise Singapore 455967
Telephone	:	HP +65 92345031
Type of Claim	:	Own Damage Claims
Policy No.	:	1700055096-01
Vehicle No	:	SLT 5763 B
Model Code	:	Audi A3 SportsBack 1.0
Model / Year	:	1/11/2017
Engine No	:	CHZ 571013
Chassis No	:	WAUZZZ8V9JA040832
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	20-Jun-19
Place of Accident	:	Junction at Chai Chee Street >

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLT 5763 B

S/n	Nature of Jobs		Estimated Charges	Surveyor's Reccomendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$	360.00	\$ 360.00
2	To dismantle and renew front bumper assy. Re-organise front crash management components. Reinstall all parts removed.	\$	1,050.00	\$ 500.00
3	To respray front bumper and bonnet.	\$	1,600.00	\$ 1,100.00
4	To carry out diagnostic check.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 3,202.00	\$ 2,152.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SLT 5763 B**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER	\$ 1,698.00	\$ 1,358.40
2	FRONT BUMPER GRILLE-CENTER	\$ 146.00	\$ 116.40
3	FRONT BUMPER CLOSING ELEMENT-LH	\$ 270.00	
4	RADIATOR GRILLE	\$ 1,301.00	\$ 1,040.80
5	RADIATOR GRILLE CLOSING ELEMENT	\$ 174.00	\$ 138.80
6	FRONT BUMPER COVER	\$ 111.00	\$ 88.80
7	FRONT BUMPER FOAM FILLER PIECE	\$ 172.00	
8	FRONT BUMPER REINFORCEMENT BAR	\$ 660.00	\$ 527.60
9	AIR CONDITIONER STICKER	\$ 7.00	
10	SIGN ' CAUTION '	\$ 13.00	
11	FRONT CAR PLATE NO.	S/N \$ 40.00	\$ 40.00
	SUPPLEMENTARY	\$ 22.00	\$ 17.12
12	SUNDRIES	\$ 300.00	\$ 17.92
	TOTAL SPARE PARTS	\$ 4,914.00	\$ 3,345.84
	TOTAL LABOUR CHARGES	\$ 3,202.00	\$ 2,152.00
	GRAND TOTAL	\$ 8,116.00	\$ 5,497.84

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0784/2019/DY/GW 23-Jul-19 Glory Tan 1 of 1 SLT 5763 B Audi A3 SportsBack 1.0	
Quantity	Description	Unit Price	Amount	
<u>Parts</u> 1	Radiator air guide LHS	\$ 22.00	\$ 17.12	dev
		\$ 22.00	\$ 17.12	

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLT 5763 B

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0784/2019/NH

10TH JAN 2020

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

total pages

RE: INSURANCE CLAIM FOR SLT 5763 B, Audi A3 SB 1.0 TFSI.

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

With reference to the above-mentioned vehicle, no. **SLT 5763 B**, claimant, **Mr. Yeo Aik Tuan, Kelvin**, please find the related document per attached.

1. A copy of the Original invoice no. 85014711 – S\$ 5,561.69.
2. A copy of the Discharge Voucher duly signed by client.

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encl
AIG – SLT 5763 B

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6366 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 18:11

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014711 Date: 09/01/2020 Order: SLT5763B Term: 30	Account: A0006 IT 01 AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No: SLT5763B (V 35674)	Regn Date: 01/11/2017	Mileage: 44977	WIP No.: 57663
Model: A3 SPORTSBACK 1.0 TFSI 8V FANG	Chassis: WAUZZZ8V9JA040832	Engine: CHZ 571013	Dept: U
You have been assisted by :- UB-Tony Foong (33)			

		Details	Qty	Unit Price	Amount
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE.	40.00	1.00	40.00
Q	EXC	M: 8888 Insurance Excess/Liability	-300.00	1.00	-300.00
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	360.00	1.00	360.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER ASSY. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	500.00	1.00	500.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER AND BONNET	1100.00	1.00	1,100.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A8V0807065R GRD	COVER(LAST)	Less 020%	1.00	1698.00
X	A8V3807647B 989	GRILLE	Less 020%	1.00	145.50
X	A8V3853651AA3FZ	(A) (SK) GRILLE 24/6/1	Less 020%	1.00	1301.00
X	A8V3853949	PLATE	Less 020%	1.00	173.50
X	A8V0807217A	COVER	Less 020%	1.00	111.00
X	A8V4807109E	BEAM	Less 020%	1.00	659.50
X	A8V0010515A	STICKER	Less 020%	1.00	6.40
X	A8K0010520A	PLATE	Less 020%	1.00	12.20
X	AM 91178401	007347/(V) (SK) BOLT	Less 020%	1.00	3.80
X	A8V0121283K	AIR DUCT	Less 020%	1.00	21.40
Parts 3,305.84					Sub-Total 5,197.84
Labour 0.00					7% GST 363.85
Sublet 2,192.00					Grand Total 5,561.69
Menus 0.00					
Lubricant 0.00					



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLT 5763 B

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0784/2019/TG
26 July 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages

RE: CLAIM - OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A3 SportsBack 1.0
Vehicle Chassis No. : WAUZZZ8V9JA040832
Vehicle Regn No. : SLT 5763 B
Vehicle Mileage : 42613 KM
Vehicle Owner : Mr. Yeo Aik Tuan, Kelvin
Certificate No : 1700055096-01
Own Damage Excess : \$321.00 (Incl. 7% GST)
Accident Date : 20 June 2019
Place : Junction At Chai Chee Street
Repair Cost : \$ 5561.69
WIP No. : 57663
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408609
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :

Time :

Date :


1510h
31/7/2019

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Jun 2019		26 Jun 2019 09:36 Edit Adj Rpt	S\$5,497.84 Edit Estimates	S\$5,497.84 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured: YEO AIK TUAN KELVIN , ID: S16592418, Tel: +6592345031, Email: ANGIEAERIA@GMAIL.COM									
Vehicle Reg. No.: SLT5763B		Date of Loss: 20/06/2019 08:00 - :59 19 Months and 19 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 3206688844SG		Policy/Cover Note No.: 1700055096 (Comprehensive)							
		Excess: S\$300.00							
Repairer: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Yap, Weijoe] Weijoe.Yap@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 05/07/2019]									
Driver/Custodian: AERIA ANGELA MARIANNE (56 / Female) , NRIC: S15604358, Tel: +6592345031 Email: ANGIEAERIA@GMAIL.COM									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLT5763B (3206688844SG)
OD
Jun 20 2019 8:00AM
[YEO AIK TUAN KELVIN]
Premium Automobiles Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser v	
Video			1 per page v ☒	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	21/06/19 09:06	Video - Accident [Linked Accident Report Documents]	 Load MP4	☐
Photos/Images			3 per page v ☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/06/19 11:07	General View	 Load JPG	☒
2	26/06/19 11:07	General View	 Load JPG	☒
3	26/06/19 11:07	General View	 Load JPG	☒
4	26/06/19 11:07	General View	 Load JPG	☒
5	26/06/19 11:07	General View	 Load JPG	☒
6	26/06/19 11:07	General View	 Load JPG	☒
7	26/06/19 11:07	General View	 Load JPG	☒
8	26/06/19 11:07	General View	 Load JPG	☒
9	26/06/19 11:07	General View	 Load JPG	☒
10	26/06/19 11:07	General View	 Load JPG	☒
11	26/06/19 11:07	General View	 Load JPG	☒
12	26/06/19 11:07	General View	 Load JPG	☒
13	26/06/19 11:07	General View	 Load JPG	☒
14	26/06/19 11:07	General View	 Load JPG	☒
15	26/06/19 11:07	General View	 Load JPG	☒
16	26/06/19 11:07	General View	 Load JPG	☒
17	26/06/19 11:07	General View	 Load JPG	☒
18	26/06/19 11:07	General View	 Load JPG	☒
19	26/06/19 11:07	General View	 Load JPG	☒
20	26/06/19 11:07	General View	 Load JPG	☒
21	26/06/19 11:07	General View	 Load JPG	☒
22	26/06/19 11:07	General View	 Load JPG	☒
23	26/06/19 11:07	General View	 Load JPG	☒
24	26/06/19 11:07	General View	 Load JPG	☒
25	26/06/19 11:07	General View	 Load JPG	☒
26	26/06/19 11:07	General View	 Load JPG	☒
27	03/12/19 11:52	Reinspection Photo	 Load JPG	☒
28	03/12/19 11:52	Reinspection Photo	 Load JPG	☒
29	03/12/19 11:52	Reinspection Photo	 Load JPG	☒
30	03/12/19 11:52	Reinspection Photo	 Load JPG	☒
31	03/12/19 11:52	Reinspection Photo	 Load JPG	☒
32	03/12/19 11:52	Reinspection Photo	 Load JPG	☒
33	03/12/19 11:52	Reinspection Photo	 Load JPG	☒
34	03/12/19 11:52	Reinspection Photo	 Load JPG	☒
35	03/12/19 11:52	Reinspection Photo	 Load JPG	☒
36	03/12/19 11:52	Reinspection Photo	 Load JPG	☒
37	03/12/19 11:52	Reinspection Photo	 Load JPG	☒
Documentation			1 per page v ☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/06/19 10:58	ESTIMATE .pdf	 Load PDF	☐

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
2	26/06/19 10:58	CI & DRIVING.pdf		Load PDF
3	26/06/19 10:58	SLT 5763B GIA.pdf		Load PDF
4	03/12/19 11:50	ESTIMATE & SUPP MARKED.pdf		Load PDF
5	14/01/20 09:54	WORKSHOP INVOICE		Load PDF
6	14/01/20 09:54	DISCHARGE VOUCHER		Load PDF

Linked Accident Report Documents

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	21/06/19 09:06	Video - Accident		Load MP4

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	21/06/19 11:25	Addendum Sheet		Load JPG ☒
2	04/09/19 01:21	Accident Statement		Load HTM
3	04/09/19 01:21	Accident Statement		Load HTM

Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	21/06/19 09:02	Accident Photo		Load JPG ☒
2	21/06/19 09:02	Accident Photo		Load JPG ☒
3	21/06/19 09:02	Accident Photo		Load JPG ☒
4	21/06/19 09:02	Accident Photo		Load JPG ☒
5	21/06/19 09:02	Accident Photo		Load JPG ☒
6	21/06/19 09:02	Accident Photo		Load JPG ☒
7	21/06/19 09:02	Accident Photo		Load JPG ☒
8	21/06/19 09:02	Accident Photo		Load JPG ☒

Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	21/06/19 08:59	Sketch Plan		Load JPG ☒
2	21/06/19 08:59	Sketch Plan #2		Load JPG ☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19011243/T1SD3Q2

Date: 14/01/2020

REFERENCE

Insured/Claimant: YEO AIK TUAN KELVIN Policy No: 1700055096
Date of Loss: 20/06/2019 Nature of Claim: OD Claim No: 3206688844SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLT5763B**
Make & Model: AUDI A3 SPORTBACK, 999cc TFSI S TRONIC (LED) (A) Engine No: CHZ571013
Reg. Date: 01/11/2017 (Man. Year: 2017) Chassis No: WAUZZZ8V9JA040832
Colour: Silver Odometer: 40999 km
Engine Capacity: 999 cc
Market Value/New Car Price: S\$92,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,909.12	3,345.84	1,563.28	31.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,202.00	2,152.00	1,050.00	32.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,111.12	5,497.84	2,613.28	32.22
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	7,811.12	5,197.84	2,613.28	33.46
+ GST 7.00/7.00% (S\$)	546.78	363.85	182.93	33.46
Nett Amount (S\$)	8,357.90	5,561.69	2,796.21	33.46

INSPECTION

Date of Assignment: 26/06/2019

Date Inspected: 25/06/2019 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,698.00 FS	*1,358.40 FS
2	1		*FRONT BUMPER GRILLE -CENTER	Cracked	146.00 FS	*116.40 FS
3	1		*FRONT BUMPER CLOSING ELEMENT -LH	Not Necessary	270.00 FS	*- FS
4	1		*RADIATOR GRILLE	Deformed	1,301.00 FS	*1,040.80 FS
5	1		*RADIATOR GRILLE CLOSING ELEMENT	Cracked	174.00 FS	*138.80 FS
6	1		*FRONT BUMPER COVER	Distorted	111.00 FS	*88.80 FS
7	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	172.00 FS	*- FS
8	1		*FRONT BUMPER REINFORCEMENT BAR	Bent	660.00 FS	*527.60 FS
9	1		*AIR CONDITIONED STICKER	Not Necessary	7.00 FS	*- FS
10	1		*SIGN CAUTION	Not Necessary	13.00 FS	*- FS
11	1		*FRONT CAR PLATE NO	Bent	40.00 FS	*40.00 FS
12	1		*SUNDRIES	Necessary	300.00 FS	*17.92 FS
13	1		*RADIATOR AIR GUIDE LHS	Deformed	17.12 FS	*17.12 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					4,909.12	3,345.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,FOG LAMPS ,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER ASSY .RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
3	TO RESPRAY FRONT BUMPER AND BONNET	New	1,600.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			3,202.00	2,152.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >