

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0787/2019/TG
Date : 24-Jun-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Aspen Resources Pte Ltd
Address : 190 Macpherson Road
#07-01
Singapore 348548
Telephone : HP +65 8188/458 (Driver) Mr. Daniel
Type of Claim : Own Damage Claims
Policy No. : 1900010832
Vehicle No : **SMH 5568 A**
Model Code : Audi Q7 2.0 TFSI QU
Model / Year : 25/1/2019
Engine No : CYR 074064
Chassis No : WAUZZZ4M6KD001788
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 22-Jun-19
Place of Accident : Along Buyong Road Turning To

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMH 5568 A

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	
2	To dismantle and renew front bumper, lhs front fender and headlight. Re-organise front crasg management components. Reinstall all parts removed.	\$ 3,150.00 2250-	
3	To dismantle lhs front door panel trims, remove and reinstall lhs wing mirror assy.	S/N \$ 450.00 ? photo	
4	To respray front bumper, lhs front fender and lhs front door.	\$ 3,000.00 2700	
5	To renew lhs front rim and carry out wheel alignment.	S/N \$ 280.00 ✓	
6	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 7,080.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SMH 5568 A**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER	\$ 2,242.00	de ✓
2	FRONT BUMPER FIXING PARTS	\$ 403.00	?
3	FRONT BUMPER CLOSING ELEMENT	\$ 191.00	?
4	FRONT BUMPER SPOILER - LH/RH	\$? 252.00	ign - de ✓
5	FRONT BUMPER AIR GUIDE GRILLE - LH	\$ 271.00	?
6	END CAP - LH	\$ 30.00	?
7	SPRING CLIP - LH	4 \$ 3.00	re ✓
8	FRONT BUMPER GUIDE SECTION - LH	\$ 40.00	?
9	FRONT WHEEL COVER - LH	NEC \$? 302.00	de ✓
10	FRONT WHEEL COVER - RH	NEC \$? 302.00	
11	FRONT WHEEL COVER CLIP	6 \$ 5.00	non ✓
12	FRONT FENDER - LH	\$ 1,481.00	bt ✓
13	FRONT FENDER ATTACHMENT PARTS	\$ 69.00	?
14	FRONT FENDER BRACKET - LH	\$ 59.00	?
15	BRACE - LH	\$ 93.00	?
16	HEX BOLTS	4 \$ 7.00	?
17	DOUBLE STUD WITH HEXAGON DRIVE	2 \$ 13.00	?
18	FRONT FENDER CLOSING ELEMENT - LH	\$ 30.00	?
19	SPREADER RIVET	4 \$ 6.00	re ✓
20	FRONT WHEEL HOUSING LINER - LH	\$ 223.00	de ✓
SUB-TOTAL SPARE PARTS		\$ 6,022.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SMH 5568 A**

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		<u>S/Nett</u>	<u>Remark</u>
21	WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 50.00	?
22	OUTER WHEEL SPOILER - LH	\$ 40.00	?
23	INNER WHEEL SPOILER - LH	\$ 40.00	?
24	LED HEADLIGHT	\$ 9,074.00	?
25	HEADLIGHT HOSE - LH	\$ 35.00	X
26	ALUMINIUM RIM	\$ 1,116.00	cut
27	RUBBER VALVE	2 \$ 7.00	new
28	SUNDRIES	\$ 200.00	?
TOTAL SPARE PARTS		\$ 16,584.00	
TOTAL LABOUR CHARGES		\$ 7,080.00	
GRAND TOTAL		\$ 23,664.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

:

Tan Jiah 97495749

Surveyed Date

:

Not Advised

Authorised Date

:

Ex: to be advise

Excess Cost

:

Liability

:

Reserving before point

Remarks

:

6 days

Survellikanto.com

25/6/19 @ 1210

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant