

ASS. REC. BY:

REF: CS/CTI190112561 kvd3n2 Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Elaine Chong

of CTI

Date/Time: 26.6.19 10.21a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SML 8899D

Insured: GBD 14647

at Workshop m/s Motor Image

Tel: 670 38101

of 19 lorong 8 Toa Payoh

Policy No: DM CVS N 1424941804

Claim No: SVM 1910202942C02

Sum Insured:

Excess:

Make of Veh:

D.O.A. 22.6.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 26.6.19 10.47a.m

Person Contacted:

Daniel

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

GBD 14647 ✓

SML 8899D ✓

23/9/19

Final fig \$ 1385.92 confirmed by email (Ref 3947.88, 749)

ASS. REC. BY:

REF:

C121

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.: Yes or No

Lum Sum:

1.31

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SM 2 88990

Yr Regn:

06, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Subaru

(A)

Wagon

c.c

1995

Colour:

M. Gray

A/C:

Insured / Std / NI / NA

Sp. Reading

2307

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JFISK 7KL 5K G 006848

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/55R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

22/6/19

D.O.A.

30/7/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 / File pass to

RECEIVED 23 SEP 2019

Date/Time, File Pass to?



: Prel. Report

1)



: Final Report

Date/Time, File Return to?

Days Of Repair:

2

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

220

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Report Format:

Merimen

Lump Sum / I.B.I. (\$

1385.92

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Jun 2019		26 Jun 2019 10:21 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All	
CLAIM SUBFOLDER DETAILS		[Created by insurer]			
Insured:					
Main Claimant:	LEE CHIN SHUN , ID: S7829951G				
Vehicle Reg. No.:	SML8899D	Date of Loss:	22/06/2019 12:00 - :59		
Claim Type:	TP / SNM19D202942C02	Policy/Cover Note No.:	DMCVSN1424941804		
Vehicle Reg. No. (Insured):	GBD1464T	Policy No. (Claimant):			
		Excess:	S\$500.00		
Repairer:	Motor Image Enterprises Pte Ltd (Toa Payoh) 19 Lorong 8 Toa Payoh, 319255 Toa Payoh - Tel: 67038101				
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]				
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000				
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 05/07/2019]				
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail			
There are no mail for this case.					
ALL ASSOCIATED TASKS					
		View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler
		Assigned By	Completed On	Created On	Done?
No results.					

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 23 September 2019 12:42 PM
To: Ooi Siow Hooi
Cc: TPY Insurance Team; Kenneth Kong (LKKAUTO); SUR
Subject: RE: SML8899D - 3RD PARTY CLAIM - (TP) - (GBD1464T) - CHINA TAIPING - FINALIZED

Dear Siow Hooi,

WITHOUT PREJUDICE

Confirmed amount \$1385.92 before GST @ 2 working days

Kindly send Final invoice and all supporting documents directly to CHINA TAIPING

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ooi Siow Hooi <hooi@motorimage.net>
Sent: Monday, 23 September 2019 10:42 AM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: TPY Insurance Team <tpyinsteam@tanchong.org>
Subject: FW: SML8899D - 3RD PARTY CLAIM - (TP) - (GBD1464T) - CHINA TAIPING - FINALIZED

Hi Veron,

Please refer to the attachment.

Thank You

Best Regards,
Siowhooi
Admin Assistant
Motor Image Enterprises Pte Ltd
19 Toa Payoh Lorong 8, Singapore 319255
Tel: +65-6703 8333 DID: +65-6703 8115
Fax: +65-6253 5535
Email: hooi@motorimage.net
Website: www.tanchong.com : www.motorimage.net

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/06/2019 15:25
Date Of Accident	22/06/2019 12:55
Exact Location Of Accident	CARPARK LOT 53 BEHIND BLK 125 BUKIT MERAH LANE 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SML8899D
Insured/Policyholder	
Name Of Registered Owner	LEE CHIN SHUN
NRIC No	S7829951G
Email Address	SHUNOLEE@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-92392952
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	SUBARU
Model	FORESTER-2.0 I-L EYESIGHT AWD CVT (A)
Exact Purpose for which vehicle was being used at time of accident	PERSONAL/LEISURE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	LEE CHIN SHUN
NRIC No	S7829951G
Date Of Birth	15/10/1978
Occupation	INDOOR
Date Of Driving Pass	16/06/1998
Driving Experience	21 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92392952
Fax Number	
Contact Number	OFFICE-NOPHONE
EEmail Address	SHUNOLEE@YAHOO.COM.SG

Address	509 SERANGOON NORTH AVENUE 4 #03-366
Postcode	550509
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD1464T
Vehicle Make/Model/Colour	NISSAN
Details Of Properties	REAR SIDE
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	KOK OON
NRIC/Passport Number	S0117154B
Contact Number	96777800
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

DATE: 22/6/19



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 22nd June 2019, at approximately 12:58pm, Kok Oon, NRIC S0117154B had reversed his vehicle ~~at~~ GBD 1464T into my vehicle, SML 8899D. My vehicle was stationary and parked in a parking lot number 53 located behind B1K 125, Bukit Merah Lane 1. The bumper of GBD 1464T had collided into the bumper of SML 8899D.

I have a witness, Calvin Lee, Hp 96777800 who was with me outside of the vehicle when the incident happened. I also have a letter signed off by both Kok Oon and myself in agreement that he caused the accident.

A : SML 8899D

B : GBD 1464T

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Bradley

Policyholder's Signature

Date & Time: 22/6/19

SIAMC SketchPlanForm_V8

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Iman

Reporting Centre Personnel's Sign

Name: ISMAN

NRIC/FIN No: S810-S31P

Common Statement

SI-BTCC-PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident so as to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service provider/agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud; regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time: 02/01/19

2:15 pm

Driver's Signature

(If driver is not the policyholder)

Date & Time:



Reporting Centre Personnel's Signature

Name: ISHAN

NRIC/TIN No.: S8101831F

GIA/ACC-PlanForm-V3

Driving License

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

EFFECTIVE DATE 15 Jun 1998

Class 3 Motor Cars <= 3000kg with <= 7 passengers exclusive of the driver, and other motor vehicles <= 2500kg

NF 4754



REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number **S7829951G**

Name
LEE CHIN SHUN
(LI JINGSHUN)

Date of Birth: 15 Oct 1978
Valid Until: 30 Jul 2012

0020906052



Identification Card



Identification Card



Smile
on my mac

S0117154B

KOK OON 96721450

12:58pm 22/6/19

JIA SENG TRADING P/L
23, KALIDASA AVENUE

I, Kok Oon, NRIC S0117154B, had reversed my vehicle that I was operating, GBD 1464T, into vehicle, SML 8899 L, belonging to Lee Chin Shun, S78299574, at the carpark lot 53 located behind Blk #5125, Bukit Merah Lane 1. ^{causing damage and dent} at 1258 pm 22nd June 2019. I hereby ^{into the bumper,} acknowledge that the above is true.


Kok Oon


Lee Chin Shun

ESTIMATE / QUOTATION COST OF ACCIDENT REPAIR

REG NO: SML8899D	MODEL : FORESTER 2.0I-S EYESIGHT AWD CVT
REF NO:INS/IC/CHI/0278/2019	YEAR: 15-JUN-2019
ENGINE NO: FB20YF43506	CHASSIS NO: JF1SK7KL5KG006848
DOA: 22/06/2019	TOA: 1258HRS
TYPE OF CLAIM: 3RD PARTY	INS COMPANY: CHINA TAIPING

S/N	NATURE OF JOB	AMOUNT
1.	REPAIR/REPLACE REAR BUMPER & BUMPER BEAM	\$2240.00 <i>5601</i>
2.	RESPRAY REAR BUMPER & BUMPER BEAM	\$1680.00 <i>4201</i>
3.	TO SUPPLY & INSTALL REVERSE SENSOR – 2 EYES <i>sm</i>	\$300.00 <i>X</i>
4.	SUNDRIES <i>new</i>	\$100.00 <i>201</i>
5.		
6.		
7.		
8.		
9.		
10.		
	Total Labour	\$4320.00

DATE APPROVAL:	
TIME APPROVAL:	
SURVEY BY:	<i>Kenneth</i>
HP / EMAIL:	<i>96910631</i>
BEFORE PAINT:	<i>Yes</i>
DAYS GIVEN:	<i>02</i>

*Not Withheld
Before Paint*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature: _____
Date: _____

Estimate

Date 06 / 24 / 2019

001 / 001

Name	QUOTATION FOR SML8899D	Tel(Home)	
Address		Tel(Office)	
E-Mail		Tel(Portable)	
		Fax	
		Model Name	S14
		Body Model	SK7AKFL
		Vin-Code	JF1SK7KL5KGD06B48

Part Number	Part Code Name	Part Code	Q'ty	Price
57704SJ310	BUMPER-FACE,REAR	FIG-591 57704A	1	<i>Bu</i> 482.40
57711SJ0309P	BACK BEAM COMPLETE-REAR	FIG-591 57711D	1	<i>n</i> 252.00
57707SJ320	BRACKET-REAR BUMPER SIDE,RIGHT	FIG-591 57707H	1	<i>n</i> 14.40
57707SJ330	BRACKET-REAR BUMPER SIDE,LEFT	FIG-591 57707I	1	<i>n</i> 14.40
57707SJ300	BRACKET-REAR BUMPER CORNER,RIG HT	FIG-591 57707AC	1	<i>Ln</i> 17.30
57707SJ310	BRACKET-REAR BUMPER CORNER,LEF T	FIG-591 57707AD	1	<i>Ln</i> 17.30
57734SJ310	BUMPER GUARD-REAR	FIG-591 57734A	1	<i>Ln</i> 216.00
		Page-Total		1,013.80
		Sub-Total		1,013.80
		Total		1,013.80
		Tax		0.00
		Grand Total		1,013.80

Memo

Grand Total
1,013.80

5333.80

--

Tel

Estimate

Date 06 / 24 / 2019

001 / 001

Name	QUOTATION FOR SML888D	Tel(Home)	
Address		Tel(Office)	
E-Mail		Tel(Portable)	
		Fax	
		Model Name	S14
		Body Model	SK7AKFL
		Vin-Code	JF15K7HL5KG006848

Part Number	Part Code Name	Part Code	Q'ty	Price
57704SJ310	BUMPER-FACE,REAR	FIG-591 57704A	1	<i>Bu</i> 482.40
57711SJ0309P	BACK BEAM COMPLETE-REAR	FIG-591 57711D	1	<i>n</i> 252.00
57707SJ320	BRACKET-REAR BUMPER SIDE,RIGHT	FIG-591 57707H	1	<i>n</i> 14.40
57707SJ330	BRACKET-REAR BUMPER SIDE,LEFT	FIG-591 57707I	1	<i>n</i> 14.40
57707SJ300	BRACKET-REAR BUMPER CORNER,RIG HT	FIG-591 57707AC	1	<i>Ln</i> 17.30
57707SJ310	BRACKET-REAR BUMPER CORNER,LEF T	FIG-591 57707AD	1	<i>Ln</i> 17.30
57734SJ310	BUMPER GUARD-REAR	FIG-591 57734A	1	<i>Ln</i> 216.00
		Page-Total		1,013.80
		Sub-Total		1,013.80
		Total		1,013.80
		Tax		0.00
		Grand Total		1,013.80

Memo

Grand Total
1,013.80

--

Tel

MotorImage

19 Lorong 8 Toa Payoh
Singapore 319255



ESTIMATE / QUOTATION COST OF ACCIDENT REPAIR

REG NO: SML8899D	MODEL : FORESTER 2.0I-S EYESIGHT AWD CVT
REF NO:INS/IC/CHI/0278/2019	YEAR: 15-JUN-2019
ENGINE NO: FB20YF43506	CHASSIS NO: JF1SK7KL5KG006848
DOA: 22/06/2019	TOA: 1258HRS
TYPE OF CLAIM: 3 RD PARTY	INS COMPANY: CHINA TAIPING

S/N	NATURE OF JOB	AMOUNT
1.	REPAIR/REPLACE REAR BUMPER & BUMPER BEAM	\$2240.00 3601
2.	RESPRAY REAR BUMPER & BUMPER BEAM	\$1680.00 4201
3.	TO SUPPLY & INSTALL REVERSE SENSOR - 2 EYES sm	\$300.00 X
4.	SUNDRIES	\$100.00 201
5.		
6.		
7.		
8.		
9.		
10.		
Total Labour		\$4320.00

DATE APPROVAL:	
TIME APPROVAL:	
SURVEY BY:	Kenneth
HP / EMAIL:	98910631
BEFORE PAINT:	Yes
DAYS GIVEN:	02

Not Notion
Respray B4 paint

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0278/2019
DATE : 30-JUL-2019

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SEVENTON WAY
#07-16 AIG BUILDING
S(079120)
TEL : 91007211
FAX :
MOTOR CLAIM DEPT

OWNER'S NAME : LEE CHIN SHUN (LI JINGSHUN)
ADDRESS : BLK 509 SERANGOON NORTH AVENUE 4
#03-366
S(550509)
TELEPHONE NO : 9239 2952

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1900109370
VEHICLE NO : SML8899D
MODEL CODE : SK7AKFL
MODEL/YEAR : FORESTER 2.0I-S EYESIGHT AWD CVT
ENGINE NO : FB20YF43506
CHASSIS NO : JF1SK7KL5KG006848
MILEAGE : 2308 KM
DATE IN : 30/07/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : DANIEL A JUDE**
ACCIDENT DATE : 22/06/2019

Print Date : 21/09/2019
Print Time : 16:56:54

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SML8899D

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM) AGAINST GSD1464T - CHINA TAIPING INSURED		
2	ZZ/001	CONDUCT TP CLAIM CN TAIPING DATE:22/06/2019 TIME: 1258HRS LOCATION:CARPARK LOT 53 BUKIT MERAB LANE		
3	ZZ/002	REPAIR/REPLACE REAR BUMPER & BUMPER BEAM	560.00	560.00
4	ZZ/003	RESPRAY REAR BUMPER & BUMPER BEAM	420.00	420.00
5	ZZ/004	SUNDRIES	20.00	20.00
TOTAL LABOUR CHARGES			1000.00	1000.00

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SML8899D

		DAMAGED PARTS & PRICES			
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
1 BUMPER FACE R HC	57704SJ310	482.40			OK
SUB TOTAL		482.40	0.00	0.00	0.00
LESS DISCOUNT		96.48	0.00	0.00	0.00
GRAND TOTAL		385.92	0.00	0.00	0.00
OVERALL TOTAL		385.92			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SML8899D

NETT ITEM	482.40
LESS 20 %	-96.48
NETT AMOUNT	385.92

LIST ITEM	0.00
LESS 50 %	0.00
LIST AMOUNT	0.00

SPECIAL NETT AMOUNT	0.00
---------------------	------

S/LIST ITEM	0.00
LESS %	0.00
S/LIST AMOUNT	0.00

TOTAL LABOUR CHARGES	1000.00
TOTAL SPARE PARTS CHARGES	385.92

TOTAL CHARGES	1385.92
ADD 7 % GST	97.01

GRAND TOTAL	1482.93
-------------	---------

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119011256/KVD3N2

Date: 27/09/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN1424941804
Claimant Vehicle No :	SML8899D	Insured Vehicle No :	GBD1464T
Date of Loss:	22/06/2019	Nature of Claim:	TP
		Claim No:	SNM19D202942C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SML8899D	Engine No:	FB20YF43506
Make & Model:	SUBARU FORESTER, 2.0 I-L EYESIGHT AWD CVT (A)	Chassis No:	JF1SK7KL5KG006848
Reg. Date:	15/06/2019 (Man. Year: 2018)	Odometer:	2307 km
Colour:	Metallic Grey		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55R18	Rear Tyre Size:	225/55R18
Front Left Side:	Bridgestone 9 mm	Rear Left Side:	Bridgestone 9 mm
Front Right Side:	Bridgestone 9 mm	Rear Right Side:	Bridgestone 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,413.80	405.92	1,007.88	71.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,920.00	980.00	2,940.00	75.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	5,333.80	1,385.92	3,947.88	74.02
+ GST 7.00/7.00% (\$\$)	373.37	97.01	276.36	74.02
Nett Amount (\$\$)	5,707.17	1,482.93	4,224.24	74.02

INSPECTION

Date of Assignment:	26/06/2019	
Date Inspected:	30/07/2019	Inspected At: Motor Image Enterprises Pte Ltd (Toa Payoh) 19 Lorong 8 Toa Payoh Singapore 319255
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Sep 2019)
Parts:	M1-SUV	SUBARU FORESTER 2.0 I-L EYESIGHT AWD CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SML8899D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER FACE-REAR	Buckled	482.40 F	*482.40 FN
2	1		*BACK BEAM COMPLETE-REAR	Repair	252.00 F	*- FN
3	1		*BRACKET-REAR BUMPER SIDE,RIGHT	Repair	14.40 F	*- FN
4	1		*BRACKET-REAR BUMPER SIDE,LEFT	Repair	14.40 F	*- FN
5	1		*BRACKET-REAR BUMPER CORNER,RIGHT	Serviceable	17.30 F	*- FN
6	1		*BRACKET-REAR BUMPER CORNER,LEFT	Serviceable	17.30 F	*- FN
7	1		*BUMPER GUARD-REAR	Serviceable	216.00 F	*- FN
8	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS
9	1		*REVERSE SENSOR-2 EYES	Serviceable	300.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	1,413.80	502.40
- Nett Item Discount on N Items 0.00/20.00% (\$\$)	0.00	96.48
Total Parts (\$\$)	1,413.80	405.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPAIR/REPLACE REAR BUMPER & BUMPER BEAM	New	2,240.00	560.00
2	RESPRAY REAR BUMPER & BUMPER BEAM	New	1,680.00	420.00
Gross Labour Cost (S\$)			3,920.00	980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >