

IMPERIUM AUTOMOTIVE

25 Kaki Bukit Road 4 #01-49 Synergy@KB, Singapore 417800

HP : 9748 9940 Shawn Tan Fax : 6346 7213

Email: shawn7530@hotmail.com

25 June 2019

Vehicle No.: SJZ 8261 E

Model: Mercedes Benz B180

QTY	DESCRIPTION	AMT S\$
	<u>List Items</u>	
1	Front bonnet	1980.00
2	Front bonnet hinges	Bent/Buc \$ 2,883.00 ✓
1	Front bonnet lock	11 \$ 150.00 X
1	Front bonnet lock catch	11 \$ 185.00 ✓
1	Front bonnet logo	11 \$ 65.00 X
2	Front headlamps	11 \$ 68.00 ✓
2	Front headlamp panels	1250 x 2 = 2500 \$ 2,570.00 ✓
2	Front headlamp top garnishes	11 \$ 470.00 X
1	Front grille	11 \$ 570.00 X
1	Front grille chrome moulding	Bent/Cro \$ 680.00 ✓
1	Front grille logo	Bent \$ 295.00 ✓
1	Front bumper	11 \$ 68.00 ✓
1	Front bumper clip (1 set)	125.00 \$ 1,535.00 ✓
1	Front bumper fog lamp	11 \$ 60.00 ✓
1	Front bumper fog lamp cover	11 \$ 280.00 X
1	Front bumper fog lamp chrome moulding	11 \$ 85.00 X
1	Front bumper inner sponge	11 \$ 125.00 ✓
1	Front bumper lower grille	To 11 \$ 165.00 ✓
1	Front bumper reinforcement	11 \$ 145.00 ✓
2	Front bumper reinforcement stays	11 \$ 685.00 ✓
2	Front bumper side retainers	11 \$ 290.00 X
1	Front bumper tow hook cover	11 \$ 136.00 X
1	Front bumper side undercover	11 \$ 48.00 X
1	Front bumper centre undercover	11 \$ 135.00 X
2	Front fenders	11 \$ 155.00 X
2	Front fender inner shields	11 \$ 1,990.00 1/2 ✓
2	Front fender inner shield clips (2 set)	11 \$ 350.00 X
1	Front support panel	11 \$ 120.00 X
1	Front support panel top cover garnish	Bent/Cro \$ 655.00 ✓
1	Air con condenser	Be/To 11 \$ 235.00 ✓
1	Radiator	11 \$ 1,055.00 X
1	Radiator fan assy	11 \$ 2,439.00 X
2	Radiator side garnishes	11 \$ 1,335.00 X
1	Air intake duct	Be/To 11 \$ 220.00 ✓
1	Wiper panel garnish	11 \$ 95.00 X
1	Rear windscreen inner seal	11 \$ 525.00 X
1	Rear tailgate	11 \$ 85.00 ✓
2	Rear tailgate dampers	11 \$ 2,080.00 ✓
		11 \$ 270.00 X
		\$ 23,302.00

c/f:

\$ 23,302.00

List Items

1	Rear tailgate inner board	425.00	cm	\$	550.00 ✓
2	Rear tailgate lamps		11	\$	690.00 X
1	Rear tailgate lock		su	\$	185.00 X
1	Rear tailgate rubber		twl	\$	175.00 ✓
1	Rear tailgate "C&C" emblem		nu	\$	38.00 ✓
1	Rear tailgate "B180" emblem		nlc	\$	70.00 ✓
2	Rear taillamps		o/s no/dye	\$	1,050.00 pc
1	Rear end panel		no/serf	\$	656.00 ✓
1	Rear end panel inner garnish		twl	\$	135.00 ✓
1	Rear end panel air vent		11	\$	128.00 X
1	Rear bumper		dis	\$	1,185.00 ✓
2	Rear bumper brackets		ns	\$	191.20 X
1	Rear bumper clip (1 set)		nu	\$	60.00 ✓
1	Rear bumper lower diffuser		11	\$	320.00 X
2	Rear bumper reflectors		11	\$	210.00 X
1	Rear bumper reinforcement		serf	\$	485.00 ✓
2	Rear bumper side retainers		su	\$	150.00 X
1	Rear bumper top chrome plate		serf	\$	145.00 ✓
2	Rear bumper side chrome mouldings		nu	\$	360.00 ✓
1	Rear bumper undercover		11	\$	128.00 X
1	Rear spare tyre board		11	\$	425.00 X
1	Rear spare tyre panel		11	\$	1,065.00 X
1	Rear exhaust silencer		11	\$	1,760.00 X
2	Rear exhaust mountings		11	\$	96.00 X
1	Rear exhaust chrome tail pipe		11	\$	255.00 X
2	Rear fender inner trims		11	\$	970.00 X
				\$	34,784.20
Discount 10%				\$	3,478.42
				\$	31,305.78

Special Nett Items

1	Front number plate with holder	serf	\$	50.00	40
1	Rear windscreen sealant	nu	\$	80.00	40
1	Rear number plate with holder	serf	\$	50.00	40
1	Rear reverse sensor (1 set)	stued	\$	480.00	200
			\$	660.00	

Spare Parts Total c/f:

\$ 31,965.78

<u>S/N.</u>	<u>Labour Charges</u>		
1	To check wiring and reset headlamps focusing.	\$	80.00 30
2	To remove, replaced damaged lamps and check up rear wiring.	\$	80.00 7
3	To remove and refit inner garnishes.	\$	150.00 80
4	To remove and refit rear reverse sensor.	\$	150.00 50
5	To transfer rear tailgate mechanism and wiring assembly.	\$	120.00 60
6	To remove, replace air-con condenser and conduct leakage test.	\$	180.00 100
7	To remove and refit rear windscreen glass.	\$	180.00 120
8	To remove, refit and replace exhaust silencer and mountings.	\$ 11	150.00 x
9	To apply undercoating.	\$	200.00 100
10	Panel beating.	\$	2,500.00 1200
11	To respray painting on the affected areas.	\$	2,400.00 1800
		\$	6,190.00

Grand Total : \$ 38,155.78

3800

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: