

ASS. REC. BY:

REF: CS/CT19011277/Jtd3

n2

Special Instruction:

Surveyor: the fe

ASSIGNMENT (Office)

Menimen

From (Person): Irene Tay

of

CT1

Date/Time: 26/6/19 @ 12:38pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLK 5100L

Insured:

at Workshop m/s

Kah Motor

Tel:

8288 6309

of

255 Alexander Road

Policy No:

DMPCSN1801501901

Claim No:

SNM10D2018801

Sum Insured:

Excess:

Make of Veh:

D.O.A. 13/3/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

28/6/19

Person Contacted:

Anileka

Vehicle IN/OUT

Date/Time

Action/Instruction

Inspected ✓

Insp: GA Mandai Estate

SLK 5100L-

26/6-

revert via menimen

27/6/10:25-

mandate approval by Irene Tay

27/June 11:02am- email authorise repair to Anileka

REF:

CTI

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

93k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SLK 5100L

Yr Regn: 18 Jan 2017

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Accord

C.C. 1997

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading:

47101

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MRHCR1630GP000086

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 225/50R17

R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

13/3/19

D.O.I.

25/6/19

Survey held at

Kah motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Will email (ia)

Confirmed P/P \$3780.44 - 4 days of repair. (Red: 2025.14; 34%)

RECEIVED 05 JUL 2019

Date/Time, File Pass to?

1) 57 Typist

Date/Time, File Return to?

2)

Report Format :

0h

Lump Sum / I.B.I. (\$

3780.44

Days Of Repair:

4

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

220

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 26 Jun 2019

Preliminary Advice

Vehicle No	: SLK5100L	Accident Date	: 13/03/2019
Make	: HONDA ACCORD	Policy No.	: DMPCSN1801501901
Assignment Date	: 26/06/2019	Excess	: S\$0.00
Date of Inspection	: 25/06/2019	Est. Duration of Repair	: 4.00
Inspection At	: KAH MOTOR CO SDN BHD (MANDAI) 8 MANDAI ESTATE, CBODY REPAIR AND PAINT CENTRE SINGAPORE 729905		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear and n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,805.58
Revised Amount	:S\$	3,780.44
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,780.44

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	93,000.00
COE / PARF Rebate	:S\$	63,815.00
Salvage Value	:S\$	
Margin for Repair	:S\$	29,185.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Mar 2019		26 Jun 2019 12:35 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured: SHENG AIHUI	
Vehicle Reg. No.: SLK5100L	Date of Loss: 13/03/2019 19:00 - :59
Claim Type: OD / SNM19D201188C01	Policy/Cover Note No.: DMPCSN1801501901 (Comprehensive)
	Excess: S\$0.00
Repairer: Kah Motor Co Sdn Bhd (ALEXANDRA) 255 ALEXANDRA ROAD, - Alexandra - Tel:	
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]	
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 05/07/2019]	
Adj Asg. Remarks: PLEASE SURVEY AND REVERT	

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Thursday, 27 June 2019 11:02 AM
To: Anikka Lai; Admin-D (LKKAUTO)
Subject: RE: SLK 5100L

Dear Sir,

As instructed by our client China Tai ping, please proceed to repair the insured vehicle **SLK 5100L (Excess \$0/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Please get the addendum sheet from insured TP covert to OD claim

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Anikka Lai <anikkalai@honda.com.sg>
Sent: Wednesday, 26 June 2019 1:04 PM
To: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Subject: RE: SLK 5100L

Dear Nivitha,

The report I have is TP claims report. Attached for your kind perusal.

Thank you

Warmest Regards

Anikka Lai
Kah Motor Co. Sdn Bhd
6A Mandai Estate
Singapore 729903
DID : 6514 5248 HP : 8288 6302
Email: anikkalai@honda.com.sg

Claim Audit

AUDIT TRAIL					By
No.	On	Audit	Remarks		
1	26 Jun 2019 09:08	Clim Veh Model Changed	(204944) HONDA ACCORD 2.0 VTIS 5AT (A).		[I] Irene Tay Hui Ping
2	26 Jun 2019 09:08	Clim Created	Reg No: SLK5100L, Policy No: DMPCSN1801501901, Acct Date: 2019/03/13, Claim Type: OD, Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ), Workshop: Kah Motor Co Sdn Bhd (ALEXANDRA), Ins.Status => Incoming Claim		[I] Irene Tay Hui Ping
3	26 Jun 2019 12:35	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):PLEASE SURVEY AND REVERT		[I] Irene Tay Hui Ping
4	26 Jun 2019 12:35	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/07/05		[I] Irene Tay Hui Ping
5	26 Jun 2019 12:35	Adj Mandate Set	Approved:0.00.		[I] Irene Tay Hui Ping
6	26 Jun 2019 12:56	Assignment 1st Accessed			[A] Nivitha Govindasamy
7	26 Jun 2019 14:03	Clim Registration Modified	Rep:202030->200153.		[I] Irene Tay Hui Ping
8	26 Jun 2019 14:26	Adj Adjuster Assigned	[None] -> ONG HWEE JIE		[A] LEE SU THING
9	26 Jun 2019 16:50	Adj Rpt Initiated			[A] DENISE TAY KWEE CHENG
10	26 Jun 2019 16:50	Clim Dtl Modified	Insured ID: -> S7275777G, Circumstances of Loss: -> 55.		[A] DENISE TAY KWEE CHENG
11	26 Jun 2019 16:50	Clim Dtl Modified	JPJ Reg. Date: -> 2017/01/18.		[A] DENISE TAY KWEE CHENG
12	26 Jun 2019 16:50	Clim Details Notified			[A] DENISE TAY KWEE CHENG
13	26 Jun 2019 16:55	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/07/05		[A] DENISE TAY KWEE CHENG
14	26 Jun 2019 17:01	Adj Mandate Request	Cur.Req:3780.44:DAMAGE CONSISTENT REPAIR COST ECONOMICAL		[A] DENISE TAY KWEE CHENG
15	27 Jun 2019 10:25	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/07/05		[I] Irene Tay Hui Ping
16	27 Jun 2019 10:25	Adj Mandate Set	Approved:3780.44.		[I] Irene Tay Hui Ping

Date From



Date To



Audit Type

None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2191287	26/06/2019 16:50	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLK5100L		11.77

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	5777G

Vehicle Details

Vehicle No.:	SLK5100L
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Jun 2019
Vehicle Make:	HONDA
Vehicle Model:	ACCORD 2.0 VTIS 5AT
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	R20Z21600128
Chassis No.:	MRHCR1630GP000086
Maximum Power Output:	114.0 kW (152 bhp)
Open Market Value:	\$29,696.00
Original Registration Date:	18 Jan 2017
First Registration Date:	18 Jan 2017
Transfer Count:	0
Actual ARF Paid:	\$33,575.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Jan 2027
PARF Rebate Amount:	\$25,181.00

Intended COE Rebate Details

COE Expiry Date:	17 Jan 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,109.00
COE Rebate Amount:	\$38,634.00
Total Rebate Amount:	\$63,815.00

The information contained herein is correct as at 26 Jun 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GlA Records Management Centre established by the General Insurance Association of Singapore (GlA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 14/03/2019 17:00
Date Of Accident 13/03/2019 19:00
Exact Location Of Accident PIE (TUAS) B4 EXIT 24
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLK5100L
Insured/Policyholder
Name Of Registered Owner SHENG AIHUI
NRIC No S7275777G
Email Address DAVIDSHENG@HOTMAIL.COM
Mobile Phone No (LOCAL) +65-91550167
Alternative Phone No OFFICE-67666707

Vehicle Particulars

Manufacturer HONDA
Model ACCORD-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number DMPCSN1801501901
Cover Note Number

Driver

Name of Driver SHENG AIHUI
NRIC No S7275777G
Date Of Birth 01/01/1972
Occupation INDOOR
Date Of Driving Pass 26/09/1998
Driving Experience 20 YEARS AND 5 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-91550167
Fax Number
Contact Number OFFICE-67666707
Email Address DAVIDSHENG@HOTMAIL.COM

Address

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident CHAIN COLLISION
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 3
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance?
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

AS ANNEX D&E

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SGG9735J
Vehicle Make/Model/Colour NISSAN / BROWN
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver QUEK WEI KEE
NRIC/Passport Number S7625429Z
Contact Number 97878040
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SGT7052R

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

LIJU JOY

NRIC/Passport Number

Contact Number

92392600

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

Vehicle Number: SLK5700L

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)** I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

14 Mar 2019
11:30 AM

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature


Name:

NRIC/FIN No.:

Sketch Plan Pg. 2

Vehicle Number: SLK 5100L

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving at the 2nd lane at quite slow speed during the rush hour, the B car hit me at the back (left) of the car.

I was alone, no injury involved.

*Statement recorded in _____ language by driver.

*Own Damage (OD) Claim submission must be proceeded within 14 Days from Date of Accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 14 Mar 2014
11:30 AM

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
 3 ANSON ROAD #16-00
 SPRINGLEAF TOWER
 SINGAPORE 079909

Registration No : SLK5100L
 Chassis No : MRHCR1630GP000086
 Model : ACCORD 2.0 AT 2016
 Owner's Name : SHENG AIHUI
 Ins Policy No. :
 Date of Accident : 13/3/2019

Document No. : SQT19001223
 Date : 15. Mar 2019
 Customer No. : WC008
 Svc Advisor : ANIKKA LAI SWEE KAM
 Engine No : R20Z21600128
 Date | Time : 15. Mar 2019 6:59:44 PM
 Surveyor Name :
 Survey Date :
 Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	OWN DAMAGE CLAIMS-J/NO: POLICY/CLAIMS NO: DMPCSN180150901 OWNER: SHENG AIHUI ACC DATE: 13/03/2019 SURVEYED BY: DATE: AUTHORIZED ON : REF NO :						
33550-T2A-G21	TAILLIGHT ASSYL. <i>CRA</i>	1	623.10	5	591.94	41.44	633.38
34155-T2A-E01	LIGHT ASSYL.LID <i>nnx</i>	1	410.70	5	390.16	27.31	417.47
71500-T2M-T80ZZ	FACE ASSYRR.BUMPER <i>DEF</i>	1	630.50	5	598.97	41.93	640.90
71593-T2A-A01	SPACERR.RR.BUMPER SIDE <i>nel</i>	1	12.20	5	11.59	0.81	12.40
71598-T2A-A01	SPACERL.RR.BUMPER SIDE <i>nel</i>	1	12.20	5	11.59	0.81	12.40
91505-TM8-003	CLIP,BUMPER <i>nel</i>	4	2.30	5	8.74	0.61	9.35
71555-S5A-J00	BRACKETL.RR.BUMPER <i>nel</i>	1	5.80	5	5.51	0.39	5.90
71503-T2M-T50	MOULDINGRR.BUMPER <i>SCR</i>	1	210.90	5	200.35	14.02	214.37
33555-T2A-A11	REFLECTOR ASSYL.RR. <i>nnx</i>	1	26.30	5	24.98	1.75	26.73
75830-T2M-T11ZB	MUDGUARDL.RR. <i>DEF</i>	1	65.00	5	61.75	4.32	66.07
Sum Item					1905.58	133.39	2,038.97
BOSUN	SUNDRIES	1	100.00 <i>30</i>		100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	150.00 <i>120</i>		150.00	10.50	160.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER (N)	1	150.00 <i>120</i>		150.00	10.50	160.50
BKBU02R	REMOVE & RENEW RR BUMPER & DAMAGE PARTS	1	2000.00 <i>1120</i>		2000.00	140.00	2140.00
BP02R	SPRAY PAINTING ON RR BUMPER & LHR DOOR.	1	1500.00 <i>900</i>		1500.00	105.00	1605.00
Sum Labor					3900.00	273.00	4,173.00

Survey By

Hue Jie - CLK

Printed on 21/6/2019 1:44:51 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

Registration No : SLK5100L

Chassis No : MRHCR1630GP000086

Model : ACCORD 2.0 AT 2016

Owner's Name : SHENG AIHUI

Ins Policy No. :

Date of Accident : 13/3/2019

Document No. : SQT19001223

Date : 15. Mar 2019

Customer No. : WC008

Svc Advisor : ANIKKA LAI SWEE KAM

Engine No : R20Z21600128

Date | Time : 15. Mar 2019 6:59:44 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Date & Time	25/6/19						
Excess	TBA						
Status	P/P 4 days.						
Signature							
Total Amount					5,805.58	406.39	6,211.97
Total (Inclusive of GST)							6,211.97

Not Authorise.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 21/6/2019 1:44:51 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd. it will be refunded.

Motor Claims Department

MS First Capital Insurance Ltd

cwsmotorclaims@msfirstcapital.com.sg



This email has been checked for viruses by AVG antivirus software.
www.avg.com

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WC008 / CHINA TAIPING
Chassis No: MRHCR1630GP000086
License No: SLK5100L
Mileage: 47101
Engine No: R20Z21600128

Document No: SVO19040274
Printed By: ANIKKALAI
Order Date: 25. June 2019
Order Time: 11:56:03 AM
Service Advisor: ANIKKA LAI SWEE KAM

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount incld Amount	GST
	OWN DAMAGE CLAIMS-J/NO: POLICY/CLAIMS NO: DMPCSN180150901 OWNER: SHENG AIHUI ACC DATE: 13/03/2019 SURVEYED BY: DATE: AUTHORIZED ON : REF NO :						
33550-T2A-G21	TAILLIGHT ASSYL.	1	623.10	5	591.94	41.44	633.38
71500-T2M-T80ZZ	FACE ASSYRR.BUMPER	1	630.50	5	598.97	41.93	640.90
71593-T2A-A01	SPACERR.RR.BUMPER SIDE	1	12.20	5	11.59	0.81	12.40
71598-T2A-A01	SPACERL.RR.BUMPER SIDE	1	12.20	5	11.59	0.81	12.40
91505-TM8-003	CLIP.BUMPER	4	2.30	5	8.74	0.61	9.35
71555-S5A-000	BRACKETL.RR.BUMPER	1	5.80	5	5.51	0.39	5.90
71503-T2M-T50	MOULDINGRR.BUMPER	1	210.90	5	200.35	14.02	214.37
75830-T2M-T11ZB	MUDGUARDL.RR.	1	65.00	5	61.75	4.32	66.07
	SUM PARTS:				1,490.44	104.33	1,594.77
BOSUN		1	30.00		30.00	2.10	32.10
	SUNDRIES						
BA02R	0671	1	120.00		120.00	8.40	128.40
	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)						
BML02I	1757	1	120.00		120.00	8.40	128.40
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER (N) TEST.(N)						
BKBU02R	0671	1	1,120.00		1,120.00	78.40	1,198.40
	REMOVE & RENEW RR BUMPER & DAMAGE PARTS						
	ATTACHMENT ITEMS						
BP02R	1610	1	900.00		900.00	63.00	963.00
	SPRAY PAINTING ON RR BUMPER & LHR DOOR.						
	SUM LABOUR:				2,290.00	160.30	2,450.30
	TOTAL SGD				3,780.44	264.63	4,045.07

Total Payable (SGD)**4,045.07**

GST Amount is calculated from individual line(s)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI19011277/JTD3N2

Date: 11/07/2019

REFERENCE

Insured/Claimant: SHENG AIHUI Policy No: DMPCSN1801501901
Date of Loss: 13/03/2019 Nature of Claim: OD Claim No: SNM19D201188C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLK5100L
Make & Model: HONDA ACCORD, 2.0 VTIS 5AT (A)
Reg. Date: 18/01/2017 (Man. Year: 2016)
Colour: Grey
Engine Capacity: 1997 cc
Market Value/New Car Price: S\$93,000.00
Sum Insured (S\$): Market Value/New Car Price

Engine No: R20Z21600128
Chassis No: MRHCR1630GP000086
Odometer: 47101 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Footbrake (Serviceable): Yes
Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/50R17
Front Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm
Rear Tyre Size: 225/50R17
Rear Left Side: Michelin 6 mm
Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,005.58	1,520.44	485.14	24.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,800.00	2,260.00	1,540.00	40.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,805.58	3,780.44	2,025.14	34.88
+ GST 7.00/7.00% (S\$)	406.39	264.63	141.76	34.88
Nett Amount (S\$)	6,211.97	4,045.07	2,166.90	34.88

INSPECTION

Date of Assignment: 26/06/2019
Date Inspected: 25/06/2019 Inspected At: KAH MOTOR CO SDN BERHAD
NO. 255 ALEXANDRA ROAD
SINGAPORE 159937

Estimated Period of Repair: 4.0 days

Adjuster: ONG HWEE JIE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 10 Jul 2019)
Parts: 143	HONDA ACCORD 2.0 VTIS 5AT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK5100L)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILLIGHT ASSYL	Cracked	591.94 FS	*591.94 FS
2	1		*LIGHT ASSYL LID	Not Necessary	390.16 FS	*- FS
3	1		*FACE ASSYRR BUMPER	Deformed	598.97 FS	*598.97 FS
4	1		*SPACERR RR BUMPER SIDE	Necessary	11.59 FS	*11.59 FS
5	1		*SPACERL RR BUMPER SIDE	Necessary	11.59 FS	*11.59 FS
6	1		*CLIP BUMPER (4 Pcs)	Necessary	8.74 FS	*8.74 FS
7	1		*BRACKETL RR BUMPER	Necessary	5.51 FS	*5.51 FS
8	1		*MOULDINGRR BUMPER	Scratched	200.35 FS	*200.35 FS
9	1		*REFLECTOR ASSYL RR	Not Necessary	24.98 FS	*- FS
10	1		*MUDGUARDL RR	Deformed	61.75 FS	*61.75 FS
11	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					2,005.58	1,520.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & RENEW REVERSE SENSORS-4 PCS	New	150.00	120.00
2	INSPECT RR LIGHTING MECHANISMS.PERFORM WATER	New	150.00	120.00
3	REMOVE & RENEW RR BUMPER & DAMAGE PARTS	New	2,000.00	1,120.00
4	SPRAY PAINTING ON RR BUMPER & LHR DOOR	New	1,500.00	900.00
Gross Labour Cost (S\$)			3,800.00	2,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >