

REVISED

ASS. REC. BY:

REF:

CT/TPD19011283/P

Special Instructions:

SUBJECT:

ASSIGNMENT (Office)

From (Person):

Kawaliah Kamle

of

SPF

Date/Time:

20/6/2019

Estimated Cost:

Bill to:

OD+TP+WS+TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

STZ 1789X

Insured:

at Workshop no/s

Tel:

of

Policy No:

MHASPP0600002012F

Claim No:

TP/IP/86381/2019

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

9/6/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time

Person Contacted:

Vehicle IN/OUT

Date/Time

Action/Instruction ()

Estimate

STZ 1789X - X

[Handwritten signature and date 20/6/19]

Vehicles to be inspected: FBG3955P - Rider (Deceased)

IO In-Charge: SIO Clarence Lim

q) Case IAFP-IB-20190614 - Mechanical Inspection of Motorcycle, FBP6436D (TP/IP/33063/2019)

On 26 May 2019 (Sunday) at about 12.41 a.m., the Accused and the Deceased were on their motorcycle, was travelling straight along Tampines Expressway towards the direction of Pan Island Expressway, 8.4 km on lane 1 of the 5-lanes road when the motorcycle swayed to their right side and collided into the centre guard railings. Due to the impact, the Accused and the Deceased were flung forward and landed on lane 1 of the 5-lanes road. The centre guard railings were not damaged. As a result of the accident, the Deceased sustained multiple injuries and he was pronounced dead by Paramedic Munirah at 12.56 a.m. at scene. Meanwhile, the Accused who smelt strongly of alcohol and admitted of drinking beer before the accident. The Accused sustained multiple abrasions and complained pain at his ribs region. Subsequently, the Accused was placed under arrest and was conveyed to Changi General Hospital by an ambulance with escort by Traffic Police Officers. Breathalyser test was not conducted to the Accused at scene due to the facial injuries sustained by him.

Vehicles to be inspected: FBP6436D - Rider (Deceased)

IO In-Charge: SIO Clarence Lim

r) Case IAFP-IB-20190614 - Mechanical Inspection of Motorcycle, FV8060L (TP/IP/33565/2019)

s) Case IAFP-IB-20190614 - Mechanical Inspection of Motor Bus, SMB65Z (TP/IP/33565/2019)

On 27 May 2019 (Monday) at about 10.03 p.m., the Involved Party was driving his motor bus, SMB65Z along Choa Chu Kang Way towards Sungei Kadut Avenue and upon approaching the signalized junction of Choa Chu Kang Avenue 4, the driver then made a right turn on green light only. Halfway making the right turn, the victim (rider of motorcycle) appeared travelling straight from the opposite direction and collided onto the motor bus.

Vehicles to be inspected: FV8060L - Rider (Victim)
SMB65Z - Defendant

IO In-Charge: IO Hidayu

t) Case IAFP-IB-20190614 - Mechanical Inspection of Motor Car, SGQ1003M (TP/IP/36381/2019)

u) Case IAFP-IB-20190614 - Mechanical Inspection of Motor Car, SJZ1789X (TP/IP/36381/2019)

v) Case IAFP-IB-20190614 - Mechanical Inspection of Motorcycle, JSN1887 (TP/IP/36381/2019)

w) Case IAFP-IB-20190614 - Mechanical Inspection of Motorcycle, JRW8414 (TP/IP/36381/2019)

On 09 June 2019 at about 12.02pm, the driver of SGQ1003M was driving his motor car on the right lane of 3 lanes, along BKE(PIE) slip road into PIE(AP). Whilst negotiating a downslope left bend, the driver lost controlled of his vehicle and skidded towards the right before the car plunges into a group of pedestrians (including TPO and Paramedic) and other vehicles which were involved in an accident earlier. As a result of the accident, multiple victims were conveyed with slight to serious injuries.

Vehicles to be inspected: SGQ1003M - Defendant
SJZ1789X - Involved Party
JSN1887 - Involved Party
JRW8414 - Involved Party