

REF: C/TPD19011287/P2
ASSIGNMENT (Office)
Date/Time: 20/6/2019

ASS. REC. BY: _____
Surveyor: _____
From (Person): Kamaliah Kamie. of SPF Bill to: _____
Estimated Cost: _____
OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS Insured: _____
To Inspect Vehicle No: SGK 69715 Tel: _____
at Workshop m/s _____
of _____
Policy No: MHASPP06000020127 Claim No: TP/IP/35671/2019
Sum Insured: _____ Excess: _____
Make of Veh: _____ D.O.A. 4/6/2019
(Client's Record)
CA / REV / REP. / REV 24 HRS
Date/Time: _____ Person Contacted: _____
Vehicle IN/OUT

Date/Time	Action/Instruction () Estimate
	SGK 69715 - X

On 04 June 2019 at about 6.08pm, the driver was driving his motor car on the right lane of 5 lanes, along Central Boulevard towards Cross Street when the driver lost control of his vehicle and skidded towards the right before the car plunges into a group of pedestrians standing along the pavement. As a result of the accident, multiple victims were conveyed with slight to serious injuries.

Vehicles to be inspected: SJD3446M - Defendant

IO In-Charge: IO Dylan Ma

y) Case IAFP-IB-20190614 - Mechanical Inspection of Motor Car, SGK69715 (TP/IP/35671/2019)

On 04 June 2019 at about 6.57pm, the driver was driving his motor car along car park service road of Blk 809 Hougang Central. Whilst approaching the exit car park gantry, driver claimed he was stepping on his brake. However, his vehicle suddenly surged forward before bashing through the gantry and collided onto another motor car and a pedestrian. As a result of the accident, the pedestrian sustained fracture and was conveyed to Sengkang Hospital.

Vehicles to be inspected: SGK69715 - Defendant

IO In-Charge: IO Dylan Ma

z) Case IAFP-IB-20190614 - Mechanical Inspection of Motor Car, SME5202X (TP/IP/17453/2019)

aa) Case IAFP-IB-20190614 - Mechanical Inspection of Motor Car, SME5695G (TP/IP/17453/2019)

On 20 March 2019 at about 2.40 am. The Deceased was riding his motorcycle along Tampines South Flyover lost control of his motorcycle veered to the left hit onto the left guard railing and fell off from the guard railing and landed onto the centre of 3-lanes along PIE towards ECP. Thereafter, the deceased was ran over by two motor cars, SME5202X and SME5695G. Both vehicles were inspected by Mr Lim Chwee Hai. However, DPP Deborah Lee directed to send both motor cars for full mechanical inspection by LKK Consultant.