

Date: 22 JUNE 2019
Vehicle No: SME8537K
Model: HONDA FREED 1.5G
Chassis: GB71075531
Reg.Year: 2018

Third Party Insurer: AIG
Third Party Veh No: EU730G
Date of Accident: 20 JUNE 2019

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1		REAPIR
2	REAR BUMPER	1		REPAIR
			SUB TOTAL	\$0.00
			LESS 20%	\$0.00
			PARTS TOTAL	\$0.00

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER CLIPS	8	\$5.50	nn \$44.00
			S/N TOTAL	\$44.00

ESTIMATE

LABOUR CHARGES:

LABOUR CHARGES TO REPAIR, READJUST REAR BUMPER, REAR TAILGATE & ETC
BACK TO ORIGINAL CONDITIONS \$250.00 *200*

LABOUR CHARGES FOR PAINTING TO SUPPLY PAINT AND FURNISHING MATERIAL
AT REAR ACCIDENT AREA & ETC \$600.00 *400*

TO REMOVE & REFIX REAR BUMPER REVERSE SENSOR & ETC \$50.00 *✓*

LABOUR TOTAL \$900.00

ONG TOTAL \$944.00

*Not wither
Presony After Paier
2days*

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223

