

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG

Claim Type: Third Party

Accident Date: 24/06/2019

TP Veh Reg No: SLG8298B

Estimate No: ES1991683/YISHUN

Date: 26 Jun 2019

Policy No: 5099732112-02

Veh Reg No: SLX8319K

Make/Model: TOYOTA HARRIER
 PREMIUM 2.0 CVT SR

Chassis No: ZSU600086024

Engine No: 3ZRBB52473

Reg. Date: 12/04/2018

Not Authored

Primary B4 paid

8-3

2453.97

Estimate Repair Cost to Vehicle No :SLX8319K

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 REAR BUMPER	1,395.30	1 PC	<i>Bur</i> 1,395.30	<i>✓</i>
2 REAR BUMPER LOWER SKIRT	496.10	1 PC	<i>Ad/LG</i> 496.10	<i>✓</i>
3 REAR BUMPER SPONGE	133.90	1 PC	<i>CM</i> 133.90	<i>✓</i>
4 REAR BUMPER CLIPS	3.50	6 PCS	<i>Ne</i> 21.00	<i>✓</i>
5 REAR BUMPER LH SIDE RETAINER	92.33	1 PC	<i>CM</i> 92.33	<i>✓</i>
			2,138.63	
	Less 25%		534.66	1,603.97
Special Net				
6 REAR WINDSCREEN GLASS GUM	40.00	1 ROLL	<i>nn</i> 40.00	<i>X</i>
7 REVERSE SENSOR	200.00	1 SET	<i>Shor</i> 200.00	<i>✓</i>
			240.00	240.00
Labour				
8 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	<i>nn</i> 120.00	<i>X</i>
9 REMOVE & REFIX REAR BUMPER ASSY, REFLECTORS, LOWER SKIRT, KNOCK & REPAIR REAR PANEL AND REALIGN THE SAME	450.00	1 LA	450.00	<i>350.00</i>
10 PUTTY & RESPRAY ON REAR BUMPER, REAR PANEL	400.00	1 LA	400.00	<i>300.00</i>
			970.00	970.00
			Total	S\$ 2,813.97
			Add GST @ 7%	196.98
			Total Amount Payable	<u>S\$ 3,010.95</u>

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Corr -
Low 3 x \$100 = 300
LTA - 8