

AIG



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLK 7409 J

Parts	(a) Cost / List Price Items	\$	2,075.50
	Plus/Less 25%	\$	518.88
	Total of Cost / List	\$	1,556.63
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	200.00
Total Parts Cost		\$	1,756.63
Labour		\$	1,940.00
Total		\$	3,696.63

The above total will be subjected to 7% G.S.T.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Name of Surveyor

:

Kenneth

Company

:

LKK

Survey conducted on

:

26/8/19

at

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 01 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$

(e) Signature of surveyor

:

Le

Date:

26/8/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.

Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : SLK 7409 J
Make & Model : TOYOTA PRIUS
Chassis No : JTDKB3FU003540154

Submit By : SERENGE
Year Manufacture : 2016
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor <i>SL</i>	1	\$200.00	S.N	<i>X</i>
2	Rear bumper	1	\$497.50		<i>7</i>
3	Rear bumper clip	10	\$40.00		<i>7</i>
4	Rear bumper side retainer LH <i>SL</i>	1	\$112.70		<i>X</i>
5	Rear bumper side retainer RH <i>SL</i>	1	\$112.70		<i>X</i>
6	Rear bumper reinforcement	1	\$398.90		<i>7</i>
7	Rear bumper lower garnish centre	1	\$582.60		<i>7</i>
8	Rear bumper lower garnish LH <i>SL</i>	1	\$149.70		<i>X</i>
9	Rear bumper lower garnish RH <i>SL</i>	1	\$149.70		<i>X</i>
10	Rear bumper tow cover <i>SL</i>	1	\$31.70		<i>X</i>
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



Vehicle No. : SLK 7409 J Submit By : Carmen Lim
Make & Model : TOYOTA PRIUS Year of Manufacture : 2016

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.