

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 400M**AAD1906-212**

Not Withheld
Assurance 25 JUN 2019
U/Sy & ?

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 400M

VF1ABL15AUC283283

RENAULT

LATITUDE

22.6.19

AIG

17/10/2016

		PART		LIST	
1	1	BUMPER COVER REAR	\$	<i>B</i> 1,108.46	✓
2	1	BUMPER LOWER REAR	\$	<i>B</i> 768.84	✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>DIT</i> 113.47	✓
4	1	BUMPER BRACKET SIDE RH REAR	\$	<i>S</i> 135.97	X
5	1	BUMPER RETAINER RH REAR	\$	<i>S</i> 44.99	X
6	1	BUMPER REFLECTOR RH	\$	<i>CM</i> 43.61	✓
7	1	BUMPER BRACKET SIDE LH REAR	\$	<i>S</i> 135.97	X
8	1	BUMPER RETAINER LH REAR	\$	<i>S</i> 44.99	X
9	1	BUMPER REFLECTOR LH	\$	<i>CM</i> 43.61	✓
10	1	BUMPER BEAM REAR	\$	<i>B</i> 777.52	✓
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>B</i> 225.95	✓
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>B</i> 225.95	✓
13	1	BOOT REAR	\$	<i>B</i> 2,872.68	✓
14	1	BOOT FINISHER	\$	<i>S</i> 470.06	X
15	1	BOOT WHEATERSTRIP	\$	<i>DIT/G</i> 323.05	✓
16	1	BOOT REFLECTOR LAMP LH	\$	<i>CM</i> 493.35	✓
17	1	BOOT REFLECTOR LAMP RH	\$	<i>CM</i> 493.35	✓
18	1	BOOT BADGE 'RENAULT'	\$	<i>N</i> 225.36	✓
19	1	BOOT BADGE	\$	<i>N</i> 225.36	✓
20	1	BOOT STRUT LH	\$	<i>S</i> 276.08	} X
21	1	BOOT STRUT RH	\$	<i>S</i> 276.08	
22	1	BOOT HINGE LH	\$	<i>N</i> 367.84	
23	1	BOOT HINGE RH	\$	<i>N</i> 367.84	
24	1	BOOT INNER TRIM	\$	<i>S</i> 586.45	
25	1	BOOT SWITCH	\$	<i>S</i> 168.13	
26	1	BOOT LOCK	\$	<i>N</i> 202.67	
27	1	BOOT LOCK CATCH	\$	<i>N</i> 74.40	
28	2	LICENCE PLATE LAMP	\$	<i>S</i> 50.52	
29	2	BOOT RUBBER PLUG	\$	<i>S</i> 221.81	
30	1	FENDER PANEL INNER TRIM REAR LH	\$	<i>S</i> 671.45	

Trans-cab Auto Services Pte Ltd**AAD1906-212**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 400M

31	1	FENDER PANEL REAR LH	\$	R	3,299.13	X
32	1	WHEELARCH REAR LH	\$	SL	543.47	X
33	1	FENDER PANEL INNER TRIM REAR RH	\$	SL	671.45	X
34	1	FENDER PANEL REAR RH	\$	R	3,299.13	X
35	1	WHEELARCH REAR RH	\$	SL	543.47	X
36	1	TAILLAMP RH	\$	mg cm	552.55	✓
37	1	TAILLAMP PANEL RH	\$	R	986.70	X
38	1	TAILLAMP LH	\$	mg cm	552.55	✓
39	1	TAILLAMP PANEL LH	\$	R	986.70	X
40	1	OUTER PANEL REAR (End Panel)	\$	R	1,471.77	✓
41	1	OUTER PANEL REAR (End Panel)TRIM	\$	CM	404.56	✓
42	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	B11 Bu	2,189.88	✓
43	1	SPARE WHEEL PANEL TRIM	\$	SL	612.21	X
44	1	EXHAUST REAR	\$	R	7,489.05	X
45	1	EXHAUST CAP REAR	\$	nd	230.49	✓
46	1	BUMPER COVER FRT	\$	CM	1,259.42	✓
47	1	BUMPER SPOILER FRT	\$	D.Y	181.75	✓
48	1	BUMPER ABSORBER FRT	\$	CM	394.68	✓
49	1	BUMPER RETAINER FRT LH	\$	D.Y	151.41	✓
50	1	BUMPER SUPPORT FRT	\$	SL	123.88	X
51	1	BUMPER RETAINER FRT RH	\$	D.Y	150.77	✓
52	1	BUMPER SUPPORT FRT	\$	SL	123.88	X
53	1	BUMPER UNDERTRAY FRT	\$	SL	472.83	X
54	1	BUMPER GRILLE LOWER FRT	\$	CM	266.80	✓
55	1	BUMPER FOG LAMP GRILLE LH	\$	SL	207.21	X
56	1	BUMPER FOG LAMP GRILLE RH	\$	SL	207.21	X
57	1	BUMPER BEAM FRT	\$	R	914.08	✓
58	1	TOW COVER FRT	\$	SL	28.61	X
59	1	RADIATOR GRILLE	\$	CM	1,707.78	✓
60	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	m	225.36	✓
61	1	RADIATOR GRILLE FRAME	\$	CM	1,353.75	✓
62	1	FRAME FULL SUPPORT PANEL	\$	CM	615.90	✓
63	1	FRAME FULL SUPPORT BRACKET	\$	R	89.79	X
64	1	FRONT BRACE PANEL	\$	R	177.22	X
65	1	HORN	\$	SL	314.17	X
66	1	HORN BRACKET	\$	R	40.45	X
67	1	HEADLAMP LH	\$	mg cm	1,184.43	✓
68	1	HEADLAMP RH	\$	mg cm	1,184.43	✓

Trans-cab Auto Services Pte Ltd

AAD1906-212

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 400M

69	1	HEADLAMP PANEL FRT LH	\$	N	152.15
70	1	HEADLAMP PANEL FRT RH	\$	N	152.15
71	1	BONNET	\$	N	1,941.63
72	1	BONNET INSULATOR	\$	SL	405.73
73	1	BONNET STRUT LH	\$	SL	88.61
74	1	BONNET STRUT RH	\$	SL	88.61
75	1	BONNET HINGE LH	\$	N	348.31
76	1	BONNET HINGE RH	\$	N	348.31
77	1	BONNET LOCK	\$	N	305.48
78	1	BONNET CABLE	\$	SL	119.19
79	1	BONNET CABLE COVER	\$	SL	161.03
80	1	BONNET SEAL OUTER	\$	SL	92.36
81	1	BONNET SEAL INNER	\$	SL	157.28
82	1	FENDER PANEL FRT LH	\$	N	783.83
83	1	WHEELARCH FRT LH	\$	SL	278.84
84	1	FENDER BRACKET LOWER LH	\$	SL	15.79
85	1	FENDER INSULATOR LH	\$	SL	130.84
86	1	FENDER INSULATOR RH	\$	SL	130.84
87	1	FENDER PANEL FRT RH	\$	N	783.83
88	1	WHEELARCH FRT RH	\$	SL	278.84
89	1	FENDER BRACKET LOWER RH	\$	SL	15.79
90	1	WIPER RESERVOIR	\$	SL	348.25
91	1	WIPER RESERVOIR NECK	\$	SL	136.11
92	1	WIPER RESERVOIR MOTOR	\$	SL	270.06
93	1	AIR CLEANER LOWER	\$	SL	271.26
94	1	AIR CLEANER HOSE	\$	SL	76.14
95	1	BASE BATTERY TRAY	\$	SL	363.40
96	1	AIR CLEANER BOX	\$	SL	464.20
97	1	TURBO DUCT	\$	SL	1,027.80
98	1	A/C HEATER VALVE	\$	SL	484.50
99	1	SUBFRAME OUTER FRT	\$	SL	2,652.45
100	1	SUBFRAME BRACKET OUTER LH	\$	N	92.36
101	1	SUBFRAME BRACKET OUTER RH	\$	N	92.36
102	1	ENGINE UNDERTRAY	\$	SL	564.98
103	1	A/C CONDENSER	\$	PR	2,020.37
104	1	A/C CONDENSER GARNISH LH UPPER	\$	SL	39.67 X
105	1	A/C CONDENSER GARNISH RH UPPER	\$	SL	39.67 X
106	1	A/C CONDENSER GARNISH LH	\$	SL	58.81 X

Trans-cab Auto Services Pte Ltd

AAD1906-212

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 400M

107	1	A/C CONDENSER GARNISH RH	\$	S _h	59.60
108	1	A/C PIPE CONDENSER TO COMPRESSOR	\$	S _h	208.39
109	1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$	S _h	658.72
110	1	A/C PIPE COMPRESSOR	\$	S _h	334.29
111	1	A/C PIPE	\$	S _h	658.72
112	1	A/C COMRPRESSOR	\$	S _h	2,684.61
113	1	AIR COOLER	\$	S _h	792.60
114	1	AIR INTERCOOLER HOSE (LONG)	\$	S _h	1,014.13
115	1	AIR INTERCOOLER HOSE (Short)	\$	S _h	375.14
116	1	TRANSMISSION COOLER	\$	S _h	1,219.30
117	1	TRANSMISSION COOLER PAD	\$	S _h	17.96
118	1	RADIATOR	\$	S _h	1,202.20
119	2	RADIATOR STUD UPPER	\$	S _h	14.41
120	2	RADIATOR BUSH UPPER	\$	S _h	50.12
121	2	RADIATOR MTG LOWER	\$	S _h	55.85
122	1	RADIATOR FAN COWLING	\$	S _h	820.54
123	1	RADIATOR FAN MOTOR LH	\$	S _h	967.36
124	1	RADIATOR FAN MOTOR RH	\$	S _h	1,479.46
125	1	RADIATOR TANK	\$	S _h	324.62
127	1	RADIATOR HOSE UPPER	\$	S _h	240.56
128	1	RADIATOR HOSE LOWER	\$	S _h	491.18
129	1	RADIATOR TANK HOSE	\$	S _h	61.18
130	1	AUTO COMPUTER	\$	S _h	5,032.17
131	1	INJECTION COMPUTER	\$	S _h	4,706.30
132	1	RHD HYDRAULIC POWER(ROCK&PINION)	\$	S _h	5,154.52
133	1	STEERING PUMP ELECTRIC L70Y	\$	S _h	2,306.90
134	1	STEERING PINION RACK L70Y	\$	S _h	4,413.11

TOTAL \$ 98,370.50**10% \$ 9,837.05****\$ 88,533.45****Special Nett**

1	1SET	PARKING AID	\$	Shan	700.00	40000
2	1SET	REAR BUMPER CLIP	\$	na	66.00	—
3	1SET	BUMPER BRACKET CTR CLIP	\$	na	33.00	—
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	X

Trans-cab Auto Services Pte Ltd

AAD1906-212

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 400M

7	1SET BUMPER RETAINER CLIP LH RR	\$	na	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	na	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	na	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	na	17.82	X
11	1SET BOOT FINISHER CLIP	\$	na	24.20	X
12	1 BOOT INNER TRIM CLIP	\$	na	45.00	X
13	1SET FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	X
14	1SET FENDER WHEELARCH REAR LH CLIP	\$	na	35.00	X
15	1 FENDER INNER TRIM CLIP LH	\$	na	28.00	X
16	1 FENDER INNER TRIM CLIP RH	\$	na	28.00	X
17	1 TAILLAMP CLIP RH	\$	na	5.00	—
18	1 TAILLAMP CLIP LH	\$	na	5.00	—
19	2 REAR WINDSCREEN SEALANT	\$	na	80.00	X
20	1 WINDSCREEN MOULDING	\$	na	100.00	X
21	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	X
22	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	na	385.00	X
23	1 SPARE TYRE	\$	na	330.00	X
24	1SET RADIATOR GRILLE FRAME CLIP	\$	na	52.00	X
25	1SET BUMPER CLIP FRT	\$	na	66.00	✓
26	1 BUMPER BRACKET CLIP FRT LH	\$	na	12.00	} X
27	1 BUMPER SUPPORT CLIP FRT LH	\$	na	10.50	
28	1 BUMPER BRACKET CLIP FRT RH	\$	na	12.00	
29	1 BUMPER SUPPORT CLIP FRT RH	\$	na	10.50	
30	1SET RADIATOR GRILLE SCREW	\$	na	16.00	
31	1SET BUMPER GRILLE LOWER CLIP	\$	na	69.00	
32	1SET FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00	
33	2 FRAME FULL SUPPORT PANEL NUT	\$	na	20.00	
34	2 FRAME FULL SUPPORT PANEL STUD	\$	na	30.00	
35	1 Windscreen moulding	\$	na	100.00	
36	1 FRONT WINDSCREEN SEALANT	\$	na	253.80	} 45na
37	1 FRONT WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
38	1SET Front licence plate with holder	\$	na	80.00	45na
39	1 WHEELARCH CLIP FRT LH	\$	na	30.50	X
40	1 WHEELARCH CLIP FRT RH	\$	na	30.50	X
41	2 BONNET STRUT L70Y	\$	na	88.61	X
42	6 BONNET INSULATOR CLIP L70Y	\$	na	7.30	X
43	2 BONNET CABLE COVER SCREW L70Y	\$	na	10.85	X
44	2 BONNET CABLE CLIP L70Y	\$	na	6.31	X

Trans-cab Auto Services Pte Ltd

AAD1906-212

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 400M

45	1	BOOT STICKER "Trans-cab"	\$	<i>na</i>	30.00	—
46	1	BOOT STICKER "6555-3333"	\$	<i>na</i>	30.00	—
47	1	FRONT RIGHT TYRE	\$	<i>SL</i>	300.00	X
48	1	FRONT RIGHT TYRE RIM	\$	<i>SL</i>	380.00	X
49	1	FRONT LEFT TYRE	\$	<i>SL</i>	300.00	X
50	1	FRONT LEFT TYRE RIM	\$	<i>SL</i>	380.00	X
TOTAL			\$		4,660.90	

TOTAL PARTS \$ 93,194.35**LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	7,500.00	<i>15401</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	7,500.00	<i>18001</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00	<i>901</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>601</i>
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>na</i> 170.00	X
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	380.00	<i>601</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	<i>801</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	<i>601</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>na</i> 170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>na</i> 170.00	X

Trans-cab Auto Services Pte Ltd**AAD1906-212**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 400M

To supply and re-do rear luggage floor panel insulation padding.	\$	380.00	801
To vacuum, replace, refix and recharge air condenser	\$	380.00	1001
To Check Electrical Lighting Concerned.	\$	170.00	401
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	2501
Towing Fees	\$	150.00	501
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	<i>Replaced</i> 380.00	1001 X
To repair and realign rear exhaust pipe.	\$	<i>na</i> 170.00	X
To check steering geometry and computer wheel alignment	\$	<i>na</i> 220.00	X
To apply paint protection system (PPS) maintain and enhancement	\$	<i>na</i> 380.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>na</i> 380.00	X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>na</i> 340.00	X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	<i>na</i> 180.00	X
To transfer of front bonnet fittings, attachment and perform water seepage test.	\$	<i>na</i> 180.00	X
To replace, refix and top up coolant for radiator.	\$	170.00	* 501

Trans-cab Auto Services Pte Ltd**AAD1906-212**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 400M

To transfer of rear bumper fittings, attachment and
perform water seepage test. \$ *na* 180.00 X

To transfer of front windscreen fittings and conduct
water seepage test. \$ *na* 170.00 X

To transfer of tire, rim and on wheel balancing. \$ *na* 170.00 X

To Transfer Of Rear Fender Fittings, Attachments And
Perform Water Seepage Test. \$ *na* 340.00 X

To vacuum, replace, refix and recharge Air Intercooler \$ *na* 170.00 X

TOTAL \$ 21,460.00

Over All Total \$ 114,654.35

Repair Days (PART BY PART)~~30 DAYS~~*16 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: