

INS. CASE OWNER:

CC 3 / 01 190 11370, Kda3n2

LKK:

IDAC:

Surveyor:

KSC

DOI:

ASSIGNMENT

21/6/2019

Date / Time:

21/6/19

Registered in Merimen:

20/6/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

Shh 9908 C

Name of Insured:

Wight Craig Alvin

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

21/6/2019

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L) (YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

Shd 18 J

INSRS:
WSP:
Tel:
Liability:
RMKS:

Trans. Cab

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

Shd 18 J - 02/11/2020 00:20:45 / kmf297 ; ODA: 8/10/10
Shh 9908 C - X

FILE PAS TO TYPE MANDATE

5/3/2020 FILE PAS TO RMK TO (LOR)

STAGE

DATE / PIC

Non-Reporting ltr (1st):
Non-Reporting ltr (2nd):
Non-Reporting ltr (Final):
Notification ltr (if non-pickup):
Call OI:
After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup) ☒ ☐
After call ltr to OI: ☒ ☐
Authorisation To Act: ☒ ☐
Release Voucher: ☒ ☐
Final Repair Bill: ☒ ☐
Car Rental Invoice: ☒ ☐
Towing Invoice: ☐ ☐
LTA / GIA: ☒ ☐
Medical Bill: ☐ ☐
PIR: ☐ ☐
Mandate/Reject Instruction: ☒ ☐
LOD: ☒ ☐
Payment Breakdown Form: ☐ ☐
Post-Repair Photos: ☐ ☐
Others: ☐ ☐

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email ☐Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with: Amanda

Email ☒ Call ☐

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.: 27

If NO or B 28, Ass. Lia:

Repair Cost: (L/GST)

S\$ 5938.50

Loss of Rental (LOR):

S\$ 495.65

(

5 days) x \$99.13

Loss of Use (LOU):

S\$ -

(\$

x

days)

Loss of Income (LOI):

S\$ 250.00

(\$

50

x 5 days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☒

(Tick only one)

GIA/LTA Search

S\$ 7.49

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

Total:

S\$ 6691.64

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐Call ☐

Payee 1:

S\$ 6691.64

Name 1:

Trans-Cab Auto Services Pte Ltd

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle
2) Report Format: TP
3) Survey fee: \$400COPY SENT
6/3/2020

ASS. REC. BY:

REF:

C721

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: S110183 Yr Regn: 06, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Renault Corolla c.c. 1995

Colour: M. White / Red A/C: Insured / Std / NI / NA

Sp. Reading: 378337 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VI-1ABCL15AUC 282688

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: M / S/Rlm / STD A/Rlm or

Tyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. P mm

L/Bal. P mm

D.O.A. 22/6/19

Rear

R/Bal. P mm

L/Bal. P mm

D.O.A. 25/6/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 / File pass to

U/Ly 855501 (Red \$27853.25 / 83%)

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

\$ - RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC3/CTI19011310/Kda3

Date: 26/06/2019

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHD 18J


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 25/06/2019 at the premises of M/s Trans-cab Auto Services Pte Ltd - Ang Mo Kio and have the following to report:-

Workshop Estimate Amount	: S\$	33,403.25
Revised Estimate Amount	: S\$	5,550.00
"Check" Items Amount	: S\$	-
Total (Including Check Items)	: S\$	5,550.00
Market Value	: S\$	- (est.)
LTA Reimbursement Value	: S\$	- (est.)
Nett Value	: S\$	- (est.)

Description of Damage:

The vehicle sustained damages at the
Rear N/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHD18J
Vehicle to be Exported:	Yes
Intended Deregistration Date:	24 Jun 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C002932
Chassis No.:	VF1ABL15AUC282698
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	10 Jun 2016
First Registration Date:	10 Jun 2016
Transfer Count:	0
Actual ARF Paid:	\$19,998.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Jun 2024
PARF Rebate Amount:	\$14,998.00

Intended COE Rebate Details

COE Expiry Date:	09 Jun 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$37,164.00
COE Rebate Amount:	\$23,043.00
Total Rebate Amount:	\$38,041.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 24 Jun 2019

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 18J**AAD1906-211***Not Authorised**1 Pny 855501*

23 JUN 2019

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD 18J

VF1ABL15AUC282698

RENAULT

LATITUDE

22.6.19

CHINA TAIPING

10/6/2016

		PART		LIST	
1	1	BUMPER COVER REAR	\$	<i>RM</i> 1,108.46	✓
2	1	BUMPER LOWER REAR	\$	<i>RM</i> 768.84	✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>RM</i> 113.47	X
4	1	BUMPER BRACKET SIDE RH REAR	\$	<i>RM</i> 135.97	X
5	1	BUMPER RETAINER RH REAR	\$	<i>RM</i> 44.99	X
6	1	BUMPER REFLECTOR RH	\$	<i>RM</i> 43.61	X
7	1	BUMPER BRACKET SIDE LH REAR	\$	<i>RM</i> 135.97	✓
8	1	BUMPER RETAINER LH REAR	\$	<i>RM</i> 44.99	X
9	1	BUMPER REFLECTOR LH	\$	<i>RM</i> 43.61	✓
10	1	BUMPER BEAM REAR	\$	<i>RM</i> 777.52	} X
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>RM</i> 225.95	
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>RM</i> 225.95	
13	1	OUTER PANEL REAR (End Panel)	\$	<i>RM</i> 1,471.77	
14	1	OUTER PANEL REAR (End Panel)TRIM	\$	<i>RM</i> 404.56	
15	1	TAILLAMP RH	\$	<i>RM</i> 552.55	
16	1	TAILLAMP PANEL RH	\$	<i>RM</i> 986.70	
17	1	TAILLAMP LH	\$	<i>RM</i> 552.55	
18	1	TAILLAMP PANEL LH	\$	<i>RM</i> 986.70	
19	1	BOOT REAR	\$	<i>RM</i> 2,872.68	
20	1	BOOT FINISHER	\$	<i>RM</i> 470.06	
21	1	BOOT WHEATERSTRIP	\$	<i>RM</i> 323.05	
22	1	BOOT REFLECTOR LAMP LH	\$	<i>RM</i> 493.35	
23	1	BOOT REFLECTOR LAMP RH	\$	<i>RM</i> 493.35	
24	1	BOOT BADGE 'RENAULT'	\$	<i>RM</i> 225.36	
25	1	BOOT BADGE	\$	<i>RM</i> 225.36	
26	1	BOOT STRUT LH	\$	<i>RM</i> 276.08	
27	1	BOOT STRUT RH	\$	<i>RM</i> 276.08	
28	1	BOOT HINGE LH	\$	<i>RM</i> 367.84	
29	1	BOOT HINGE RH	\$	<i>RM</i> 367.84	

Trans-cab Auto Services Pte Ltd

AAD1906-211

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 18J

30	1	BOOT INNER TRIM	\$	SH 586.45	X
31	1	BOOT SWITCH	\$	SH 168.13	X
32	1	BOOT LOCK	\$	N 202.67	X
33	1	BOOT LOCK CATCH	\$	N 74.40	X
34	1	FENDER PANEL INNER TRIM REAR LH	\$	SH 671.45	X
35	1	FENDER PANEL REAR LH	\$	SH 3,299.13	✓
36	1	WHEELARCH REAR LH	\$	SH 543.47	X
37	1	FUEL FLAP	\$	SH 343.57	X
TOTAL			\$	20,904.50	48
10%			\$	2,090.45	
			\$	18,814.05	

Special Nett

1	1SET	PARKING AID	\$	SH 700.00	4000
2	1SET	REAR BUMPER CLIP	\$	N 66.00	—
3	1SET	BUMPER BRACKET CTR CLIP	\$	N 33.00	—
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	N 10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	N 20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	N 10.00	X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	N 20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	N 22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	N 66.00	✓
10	1	BOOT STICKER "Trans-cab"	\$	N 30.00	X
11	1	BOOT STICKER "6555-3333"	\$	N 30.00	X
12	2	REAR WINDSCREEN SEALANT	\$	N 80.00	4000
13	1	WINDSCREEN MOULDING	\$	N 100.00	—
14	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	N 100.00	3000
15	1	BOOT INNER TRIM CLIP	\$	N 45.00	} X
16	1	FENDER INNER TRIM CLIP LH	\$	N 28.00	
17	1	TAILLAMP CLIP RH	\$	N 5.00	
18	1	TAILLAMP CLIP LH	\$	N 5.00	
19	1SET	FENDER WHEELARCH REAR LH CLIP	\$	N 35.00	
20	1SET	BOOT FINISHER CLIP	\$	N 24.20	
21	1	REAR LEFT TYRE	\$	SH 300.00	
22	1	REAR LEFT TYRE RIM	\$	SH 380.00	
TOTAL			\$	2,109.20	

TOTAL PARTS \$ 20,923.25

Trans-cab Auto Services Pte Ltd

AAD1906-211

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 18J

LABOUR

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,500.00	6001
Putty And Spray Painting Of The Affected Portion.	\$	4,500.00	4401
To transfer of tire, rim and on wheel balancing.	\$	170.00	~ 170.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	1001
To Rust-Proofing Of The Affected Areas.	\$	170.00	301
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	~ 170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	~ 170.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	1201
To check steering geometry and computer wheel alignment	\$	220.00	~ 220.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00	~ 380.00 X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	380.00	~ 380.00 X
To repair and realign rear exhaust pipe.	\$	170.00	~ 170.00 X
To apply paint protection system (PPS) maintain and enhancement	\$	380.00	~ 380.00 X

Trans-cab Auto Services Pte Ltd**AAD1906-211**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 18JLabour charge to mount and dismount vehicle on jig
bench, to facilitate repair.\$ *nn* 380.00 *X*

To reinstall rear bumper parking sensor.

\$ 170.00 *601*

To Check Electrical Lighting Concerned.

\$ 170.00 *151***TOTAL** \$ **12,480.00****Over All Total** \$ **33,403.25****LUMP SUM (REPAIR DAY)****15-DAYS***4 day*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Mei Kwan (LKKAUTO)

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Monday, 8 July, 2019 5:11 PM
To: Mei Kwan (LKKAUTO)
Subject: RE: OUR REF: SNM19D202987/TANKL - Direct Settlement - Accident Involving SGG9908C (OI : CTI - TBA) and SHD18J (TP : LKK REF - CC3/CTI19011310/Kda3) on 22/06/2019
Attachments: SGG9908C.PDF
Categories: HMK

Without Prejudice

Dear Mei Kwan,

We refer to your email dated 26.06.2019.

Attached is our insured's accident report for your necessary action.

Thank you.

Regards

Tan Kah Leong
Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Tan Kah Leong
Sent: Thursday, 27 June, 2019 5:01 PM
To: Mei Kwan (LKKAUTO) <Meikwan@lkkauto.com>
Cc: Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>
Subject: RE: OUR REF: SNM19D202987/TANKL - Direct Settlement - Accident Involving SGG9908C (OI : CTI - TBA) and SHD18J (TP : LKK REF - CC3/CTI19011310/Kda3) on 22/06/2019

Dear Mei Kwan,

Refer to your email below.

Our insured has yet to report the accident.

We will contact our insured to report the accident asap.

Thank you.

Regards

Tan Kah Leong
Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Lim Shu Min
Sent: Thursday, 27 June, 2019 3:09 PM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>; Jia Le (LKK Auto) <JiaLe@lkkauto.com>
Subject: OUR REF: SNM19D202987/TANKL - Direct Settlement - Accident Involving SGG9908C (OI : CTI - TBA) and SHD18J (TP : LKK REF - CC3/CTI19011310/Kda3) on 22/06/2019

Dear Kah Leong,

Please revert.

Insured non reporting.

File with Officer-In-Charge – Tan Kah Leong – 63896193.

Thank you

Lim Shu Min
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 63896156 | F: (65) 62247175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Mei Kwan (LKKAuto) [<mailto:Meikwan@lkkauto.com>]
Sent: Wednesday, 26 June, 2019 7:35 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Jia Le (LKK Auto) <JiaLe@lkkauto.com>
Subject: Direct Settlement - Accident Involving SGG9908C (OI : CTI - TBA) and SHD18J (TP : LKK REF - CC3/CTI19011310/Kda3) on 22/06/2019

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle SHD 18J at M/s Trans-cab Auto Services Pte Ltd - Ang Mo Kio on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:

- TP GIA report
- TP estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Jia Le and she can be contacted at DID: 6749 5792.

To check availability of the case handler , you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



e-Services (/content/policehubhome/homepage.html)

Log in

Status of Driving Licence

Qualified Driving Licence

Qualified Driving Licence Number

S2677712G

Status of Qualified Driving Licence

Valid

Class(es) of Qualified Driving Licence

2,2A,2B,3

Expiry Date

Lifetime unless revoked, suspended or disqualified

Provisional Driving Licence

You are not a valid Provisional Driving Licence Holder.

HOME (<https://www.police.gov.sg/>)

ABOUT US (<https://www.police.gov.sg/about-us>)

SGSECURE (<https://www.police.gov.sg/sgsecure>)

I-WITNESS (<https://www.police.gov.sg/iwitness>)

COMMUNITY PROGRAMMES (<https://www.police.gov.sg/community-programme>)

RESOURCES (<https://www.police.gov.sg/resources>)

NEWS & PUBLICATIONS (<https://www.police.gov.sg/news-and-publications>)

JOIN US (<https://www.police.gov.sg/join-us>)

FAQS (<https://va.ecitizen.gov.sg/cfp/CustomerPages/SPF/explorefaq.aspx>)

CONTACT US (<https://www.police.gov.sg/content/contact-us>)

E-FEEDBACK (/content/policehubfeedback/efeedback.html)

SITEMAP (<https://www.police.gov.sg/sitemap>)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI19011310/Kda3n2		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 09-03-2020		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGG 9908C	Veh. Inspected	SHD 18J	
Policy No.	DMPCSN3044941903	Coverage (\$)	0.00	
Claim No.	SNM19D202987	Excess (\$)	0.00	
Assign From		Assign Date	25/06/2019	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	VF1ABL15AUC282698	Colour	METALLIC WHITE / RED	
Odometer	378337	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GITI	8 mm	
L/H Front Tyre	215/60 R16	GITI	8 mm	
R/H Rear Tyre	215/60 R16	GITI	8 mm	
L/H Rear Tyre	215/60 R16	GITI	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/06/2019	Inspection Date	25/06/2019	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 18J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER COVER REAR	BENT	1,108.46	1,108.46
1	BUMPER LOWER REAR	DENTED / CUT	768.84	768.84
1	BUMPER BRACKET CTR REAR	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR RH	SERVICEABLE	43.61	-
1	BUMPER BRACKET SIDE LH REAR	DISTORTED	135.97	135.97
1	BUMPER RETAINER LH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR LH	SCRATCHED	43.61	43.61
1	BUMPER BEAM REAR	TO REPAIR SEE LABOUR	777.52	-
1	BUMPER BEAM BRACKET LH REAR	TO REPAIR SEE LABOUR	225.95	-
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR	225.95	-
1	OUTER PANEL REAR (END PANEL)	TO REPAIR SEE LABOUR	1,471.77	-
1	OUTER PANEL REAR (END PANEL)TRIM	SERVICEABLE	404.56	-
1	TAILLAMP RH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	986.70	-
1	TAILLAMP LH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	986.70	-
1	BOOT REAR	TO REPAIR SEE LABOUR	2,872.68	-
1	BOOT FINISHER	SERVICEABLE	470.06	-
1	BOOT WEATHERSTRIP	SERVICEABLE	323.05	-
1	BOOT REFLECTOR LAMP LH	SERVICEABLE	493.35	-
1	BOOT REFLECTOR LAMP RH	SERVICEABLE	493.35	-
1	BOOT BADGE 'RENAULT'	NOT NECESSARY	225.36	-
1	BOOT BADGE	NOT NECESSARY	225.36	-
1	BOOT STRUT LH	SERVICEABLE	276.08	-

Report Ref No. CC3/CTI19011310/Kda3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOT STRUT RH	SERVICEABLE	276.08	-
1	BOOT HINGE LH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT HINGE RH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT INNER TRIM	SERVICEABLE	586.45	-
1	BOOT SWITCH	SERVICEABLE	168.13	-
1	BOOT LOCK	TO REPAIR SEE LABOUR	202.67	-
1	BOOT LOCK CATCH	TO REPAIR SEE LABOUR	74.40	-
1	FENDER PANEL INNER TRIM REAR LH	SERVICEABLE	671.45	-
1	FENDER PANEL REAR LH	BUCKLED	3,299.13	3,299.13
1	WHEELARCH REAR LH	SERVICEABLE	543.47	-
1	FUEL FLAP	SERVICEABLE	343.57	-
	LESS 10% DISCOUNT		-2,090.45	-535.60
			18,814.03	4,820.41
SPECIAL NETT ITEMS				
1	SET PARKING AID (SN)	SCRATCHED	700.00	400.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	66.00	66.00
1	BOOT STICKER 'TRANS-CAB' (SN)	NOT NECESSARY	30.00	-
1	BOOT STICKER '6555-3333' (SN)	NOT NECESSARY	30.00	-
2	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	WINDSCREEN MOULDING (SN)	NECESSARY	100.00	100.00
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NECESSARY	100.00	30.00
1	BOOT INNER TRIM CLIP (SN)	NOT NECESSARY	45.00	-
1	FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	28.00	-

Report Ref No. CC3/CTI19011310/Kda3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAILLAMP CLIP RH (SN)	NOT NECESSARY	5.00	-
1	TAILLAMP CLIP LH (SN)	NOT NECESSARY	5.00	-
1	SET FENDER WHEELARCH REAR LH CLIP (SN)	NOT NECESSARY	35.00	-
1	SET BOOT FINISHER CLIP (SN)	NOT NECESSARY	24.20	-
1	REAR LEFT TYRE (SN)	SERVICEABLE	300.00	-
1	REAR LEFT TYRE RIM (SN)	SERVICEABLE	380.00	-
			2,109.20	735.00
	LABOUR			
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BUMPER BEAM REAR,BUMPER BEAM BRACKET LH REAR,BUMPER BEAM BRACKET RH REAR,OUTER PANEL REAR (END PANEL),TAILLAMP PANEL RH,TAILLAMP PANEL LH,BOOT REAR,BOOT HINGE LH,BOOT HINGE RH,BOOT LOCK AND BOOT LOCK CATCH.		4,500.00	600.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION .		4,500.00	440.00
	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR.		380.00	100.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00
	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.		170.00	120.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-

Report Ref No. CC3/CTI19011310/Kda3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	NOT NECESSARY	380.00	-
	LABOUR CHARGE TO MOUNT AND DISMANTLE VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	TO REINSTALL REAR BUMPER PARKING SENSOR .		170.00	60.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	15.00
			12,480.00	1,365.00
	GRAND TOTAL		33,403.23	6,920.41
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,550.00

Report Ref No. CC3/CT119011310/Kda3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.