

# EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

AIG

Owner : SYED SALEH S/O SYED  
MOHIDEEN ABDUL KADER

Accident Date : 24.03.2018

Vehicle No : FX 6299 T

Vehicle Model : PIAGGIO X9

## Estimated Repair Costs

| Qty | Description                | Amount S(\$) |
|-----|----------------------------|--------------|
|     | <u>List Items</u>          |              |
| 1   | Front fender               | \$ 175.00 X  |
| 1   | Front fairing              | \$ 280.00    |
| 1   | Front fairing inner panel  | \$ 185.00    |
| 1   | Windshield-upper           | \$ 135.00    |
| 1   | Windshield ( lower )       | \$ 220.00    |
| 1   | Top inner panel            | \$ 88.00     |
| 1   | Compartment cover          | \$ 85.00     |
| 2   | Side mirrors               | \$ 570.00    |
| 1   | Front fork assy            | \$ 750.00    |
| 1   | Fork under bracket         | \$ 175.00 X  |
| 1   | Front sport rim            | \$ 335.00    |
| 1   | Front brake disc           | \$ 195.00 X  |
| 1   | Handle-bar                 | \$ 110.00    |
| 2   | Handle-bar balancers       | \$ 160.00    |
| 1   | Brake lever                | \$ 48.00 X   |
| 1   | Headlamp                   | \$ 310.00    |
| 1   | Front fairing bracket      | \$ 285.00    |
| 1   | Side cowling               | \$ 280.00    |
| 1   | Side lower panel           | \$ 120.00    |
| 1   | Lower belly cowling        | \$ 195.00    |
| 1   | Centre inner panel         | \$ 135.00    |
| 2   | Footstep panels            | \$ 256.00    |
| 2   | Footstep rubbers           | \$ 90.00     |
| 2   | Rear side panels           | \$ 180.00    |
| 1   | Rear end panel             | \$ 88.00     |
| 2   | Rear tailboards            | \$ 520.00    |
| 1   | Rear taillamp              | \$ 180.00 X  |
| 1   | Rear fender                | \$ 165.00 X  |
| 1   | Side stand                 | \$ 115.00 X  |
| 1   | Main stand                 | \$ 180.00 X  |
| 1   | Engine mounting bracket    | \$ 280.00    |
| 1   | Exhaust                    | \$ 460.00    |
| 1   | Exhaust protector          | \$ 48.00     |
| 1   | Rear box                   | \$ 500.00    |
| 1   | Rear box bracket ( 1 set ) | \$ 280.00    |
|     |                            | \$ 8,178.00  |
|     | Less 10%                   | \$ 817.80    |
|     |                            | \$ 7,360.20  |

not added  
2/5 \$3400  
26/5/19  
Thy. H. P. H. H. H.

265

125

45

90

260

4344

|      |    |          |
|------|----|----------|
| c/f: | \$ | 7,360.20 |
|------|----|----------|

### Special Nett Items

|   |                         |    |        |    |
|---|-------------------------|----|--------|----|
| 1 | Number plate ( 1 set )  | \$ | 28.00  | 10 |
| 2 | Fork oils               | \$ | 60.00  | ✓  |
| 2 | Fork oil seals          | \$ | 112.00 | ✓  |
| 1 | Steering cone ( 1 set ) | \$ | 75.00  | ✓  |
|   |                         | \$ | 275.00 |    |

| <u>S/No.</u> | <u>Labour</u> |
|--------------|---------------|
|--------------|---------------|

|   |                                             |    |        |     |
|---|---------------------------------------------|----|--------|-----|
| 1 | To provide towing service.                  | \$ | 45.00  | 55  |
| 2 | To provide labour.                          | \$ | 380.00 | 350 |
| 3 | To check wiring and reset headlamp focusing | \$ | 80.00  | x   |
|   |                                             | \$ | 505.00 |     |

Grand Total

\$ 8,140.20

4304.6

EROFIA MOTOR TRADING PTE LTD

1. Repairer must immediately notify  
 the Insurance Company of the  
 • Date and time of the accident  
 • Date and time of the survey  
 • Name of the surveyor  
 • Name of the insurance adjuster  
 • Name of the surveyor on a "Without Prejudice" basis  
 • Non-fault modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and  
 is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: